

Thank you for ordering from us!
www.checkvin.eu

Vehicle

BMW 420d, 140KW

WBA4E91030G593458



Development code F36
Colour mineral-grau metallic
Actual integration level F020-18-11-520
Start of warranty 17 March 2016

Delivery stop



Technical Campaigns are available.

Technical campaigns

Status	Campaign number	Description	Reservation
Open	10011150700	Replacing the exhaust gas recirculation cooler (high temperature)  Delivery stop Local campaign number: -	
Open	10011350700	Exhaust gas recirculation cooler customer notification Local campaign number: -	
Open	10013510300	Program control units (DDE) Local campaign number: -	
Open	10032550300	Check the driver's airbag, replace if necessary (conversion SDI)  Delivery stop Local campaign number: -	

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2018-1 (As of: 12 Mar 2020)	-	-	-
Road Map EUROPE EVO 2018-1 (As of: 12 Mar 2020)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2025-1	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	420d
Body	COUPE
Vehicle identification number (last 7 digits)	G593458
Vehicle identification number (17 digits)	WBA4E91030G593458
Development code	F36
Steering	LL
Engine	B47O
Engine number	53509555
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0366337ZRI
Head unit serial number	HB2140J7960514

Drive	HECK
Integration level, works	F020-16-03-501
Production date	9 Mar 2016
Production plant	Dingolfing
Delivery date	11 Mar 2016
Delivering retailer	No information
National-market version	EUR
Paint code	B39
Upholstery code	LCLZ
Model code	4E01
Basic type	4E91
Lead type	4E01

Optional equipment

Optional equipment ex works:


01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 0205 Automatic transmission
 0230 EU-specific additional contents
 0258 Tyres with runflat properties
 02H2 BMW LA wheel, multi spoke 416
 02PA Locking wheel bolt
 02VB Tyre pressure display
 0302 Alarm system
 0320 Deleted, model lettering
 0423 Floor mats velours
 0431 Interior mirror with automatic-dip
 0465 Through-loading system
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04FU Fine wood Fineline anthracite/acc.strip
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0522 Xenon Light
 0524 Adaptive headlights
 0534 Automatic air conditioning
 0544 Cruise control with brake function
 0548 Kilometre speedo
 0563 Light package
 05AC High-beam assistant
 05DA Passenger airbag deactivation
 0609 Navigation system Professional
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06NS Comfort telephony w/ enhanced Smartphone
 06WA Instrument panel with extended scope
 07LE Modell Luxury Line
 07S2 Luxury Line
 0843 Power reduction
 0854 Language version, French
 0881 On-board literature, French
 08KA Oil service interval 24 mths / 30,000 km
 08S3 Automatic locking during starting
 08SM Car ident. number visible from outside
 A090 90 Ah AGM battery
 LEDE Leather equipment

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	11/03/2020	Key	107791 Km	05740	Key 1



—	11/03/2020	Repair	107791 Km	05740 Gregoir Jette , Brussel	Job
---	------------	--------	-----------	-------------------------------	-----


— Job

Description:

Considered as a repeat visit No

Customer's own words

—	13/09/2019	Key	104924 Km	05722	Key 1
---	------------	-----	-----------	-------	-------



—	12/06/2019	Key	94078 Km	23686	Key 1
---	------------	-----	----------	-------	-------



—	12/06/2019	Service	94078 Km	23686 van Osch Hasselt , Hasselt	Automatic
---	------------	---------	----------	----------------------------------	-----------



—	12/06/2019	Repair	94078 Km	23686 A&M Hasselt , Hasselt	Job
---	------------	--------	----------	-----------------------------	-----

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service standaard omvang
Package I 0000105

Service - standard scope
Flat rate unit I 00 00 105

Service motorolie

Package I 0000610

Engine oil service Flat rate unit I 00 00 610	3
Set oil-filter element Part I 11428575211	1
BMW Engine Oil LL04 5W30 Part I 83212405948	5

Service remsysteem, voor
Package I 0000612

Service, front brakes Flat rate unit I 00 00 612	6
Repair kit, brake pads asbestos-free Part I 34106859181	1
Brake pad wear sensor, front left Part I 34356792289	1
Brake cleaner acetone-free Part I 83192413695	1
Brake-pad paste Part I 83192158851	2

Service microfilter
Package I 0000616

Microfilter service Flat rate unit I 00 00 616	2
Microfilter/activated Carbon container Part I 64119237555	1


Service remvloeistof
Package I 0000618

Brake fluid service Flat rate unit I 00 00 618	4
Brake fluid DOT4 LV, low viscosity Part I 83132184843	1

— 15/03/2019 Key 85333 Km 23686 Key 1



— 15/03/2019 Service 85333 Km 23686 van Osch Hasselt, Hasselt Automatic



— 31/10/2018 Key 68240 Km Key 0



— 31/10/2018 Warranty 68240 Km 23686 Job: Headunit High HU-H

— Job: Headunit High HU-H

Description: Headunit High HU-H

Considered as a repeat visit No

Customer's own words

Performing vehicle test Flat rate unit I 00 00 006	4 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
Programming/encoding control unit(s) including deleting fault memories Flat rate unit I 61 00 730	4 FRU
Continuing vehicle test and deleting fault memory Flat rate unit I 61 00 980	2 FRU
Vehicle diagnosis - carrying out the ABL Flat rate unit I 61 00 006	3 FRU
Check headunit for functionality Flat rate unit I 65 12 300	10 FRU
Replace HU-H Flat rate unit I 65 12 816	6 FRU
Headunit High HU-H Defect I 65 12 58 02 00	
RP REMAN Headunit High 2 Part I 65 12 9 391 821	1

— 15/10/2018 Key 65335 Km Key 0



— 15/10/2018 Warranty 65335 Km 23686 Job: Road map navigation

— Job: Road map navigation

Description: Road map navigation

Considered as a repeat visit No

Customer's own words

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Programming/encoding control unit(s) including deleting fault memories Flat rate unit I 61 00 730	4 FRU
Continuing vehicle test and deleting fault memory Flat rate unit I 61 00 980	2 FRU
Road map navigation Defect I 65 90 14 02 00	

— 17/09/2018 Key 61704 Km Key 0

							
90	90	90	90	60000	03/2019	32000	90
09/2019	344	344	344				09/2019

— 17/09/2018 Service 61704 Km 23686 van Automatic
Osch Hasselt , Hasselt

							
90	90	90	90	60000	0	32000	90
01/1970	08/2019	08/2019	08/2019	01/1970	01/1970	01/1970	01/1970
✓	✓	✓	✓				✓

— 17/09/2018 Repair 61704 Km 23686 A&M Job
Hasselt , Hasselt

— Job

Description:

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id ESTIMATE Onderhoudshistorie door middel van Local 0 FRU
ICOM naar het motorvoertuig overdragen !!!
Flat rate unit I -

Service standaard omvang
Package I 0000105

Service - standard scope 2
Flat rate unit I 00 00 105

Service luchtfilterelement
Package I 0000602

Service - air filter element 2
Flat rate unit I 00 00 602

Air filter element 1
Part I 13718511668

Service brandstoffilter
Package I 0000604

Service fuel filter 3
Flat rate unit I 00 00 604

Fuel filter cartridge 1
Part I 13328572522

Service motorolie
Package I 0000610

Engine oil service 3
Flat rate unit I 00 00 610

Set oil-filter element 1
Part I 11428575211

BMW Engine Oil LL04 5W30 5
Part I 83212405948

Service microfilter
Package I 0000616

Microfilter service Flat rate unit I 00 00 616	2
Microfilter/activated Carbon container Part I 64119237555	1
Service voertuig-check Package I 0000624	
Service, vehicle check Flat rate unit I 00 00 624	6

— 17/09/2018 Warranty 61704 Km 23686 Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

— Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Description: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler and clean exhaust gas recirculation pipe Flat rate unit I 00 66 769	26 FRU
---	--------


F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler
Defect I 00 11 83 04 00

exhaust cooler Part I 11 71 8 477 659	1
--	---

Pipe union Part I 11 71 7 799 853	2
--------------------------------------	---

Gasket Steel Part I 11 61 8 571 005	1
--	---

— 24/11/2017 Key 33962 Km 05657 Key 0



— 24/11/2017 Repair 33962 Km 05657 A&M Halen , Halen Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Hoge bezoekfrequentie. Herhalingsreparatie? Controleer de reparatiehistorie. Flat rate unit I -	Local	0 FRU
--	-------	-------

Laadwens van de klant: Full Flat rate unit I -	Local	0 FRU
---	-------	-------

Initiële laadtoestand hoog-voltage accu (SoC): 255% Flat rate unit I -	Local	0 FRU
---	-------	-------

— 20/10/2017 Warranty 32406 Km 22540 Job: F1x F2x F3x B47 programming control units and if

necessary, replacing the EGR valve
Job: Oxygen monitor sensor

- Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Considered as a repeat visit No

Customer's own words

Carrying out the ABL and programming the control units	8 FRU
Flat rate unit I 00 64 941	

F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve
Defect I 00 11 45 04 00

- Job: Oxygen monitor sensor

Description: Oxygen monitor sensor

Considered as a repeat visit No

Customer's own words


Performing vehicle test	2 FRU
Flat rate unit I 00 00 556	

Replacing the monitoring oxygen sensor	4 FRU
Flat rate unit I 13 62 664	


Oxygen monitor sensor
Defect I 11 78 03 14 00

Oxygen sensor	1
Part I 13 62 8 570 230	


- 19/10/2017 Key 32406 Km 22540 Key 0



- 09/09/2017 Key 30829 Km 22540 Key 0



- 09/09/2017 Key 30829 Km 22540 Key 0



- 09/09/2017 Service 30829 Km 22540 van Osch nv van Osch Tienen , Tienen Automatic

