

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 530e iPe, 185KW

WBAJA91030G592051



Development code
Colour
Actual integration level
Start of warranty

G30
black-sapphire metallic
S15A-22-11-520
13 December 2017

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

There are no Campaigns for this vehicle.

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2021-3 (As of: 15 Nov 2022)	-	-	-
Road Map EUROPE EVO 2021-3 (As of: 15 Nov 2022)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2025-1	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	530e iPe
Body	LIM
Vehicle identification number (last 7 digits)	G592051
Vehicle identification number (17 digits)	WBAJA91030G592051
Development code	G30
Steering	LL
Engine	XB1H
Engine number	17969946
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0220963ZXY
Head unit serial number	HB2238H8147659
Drive	HECK
Integration level, works	S15A-17-03-505
Production date	5 Apr 2017
Production plant	Dingolfing
Delivery date	8 Apr 2017
Delivering retailer	No information
National-market version	EUR
Paint code	475
Upholstery code	LCNL
Model code	JA01
Basic type	JA91
Lead type	JA01

Optional equipment

Optional equipment ex works:

Retrofitted optional equipment:

01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 021R BMW LA wheel M double spoke 664 black
 0230 Extra package, EU-specific
 0258 Tyres with runflat properties
 02NH M Sport brake
 02PA Locking wheel bolt
 02TE Automatic transmission w/ shift paddles
 02VB Tyre pressure display
 0302 Alarm system
 0337 M Sports package
 03DE Omission of specific design scopes
 03DS BMW display key
 0420 Sun protection glazing
 0423 Floor mats velours
 0465 Through-loading system
 0481 Sports seat
 0494 Seat heating driver/passenger
 04K7 Interior trim alu.rhomb.w.accent strip
 04NE Blow-by heater
 04T8 Extended mirror package
 04UR Ambient interior light
 0548 Kilometre speedo
 0552 Adaptive LED headlight
 05A1 LED Fog lights
 05AC High-beam assistant
 05AL Active Protection
 05AT Driving Assistant Plus
 05DN Parking assistance system Plus
 0609 Navigation system Professional
 0610 Head-up display
 0650 CD drive
 06AC Intelligent emergency call
 06AE Teleservices
 06AG eDrive services
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06CP Smartphone integration
 06NW Telephony with wireless charging
 06U8 BMW gesture control
 06WB Multifunctional instrument display
 06WD WLAN Hotspot
 0710 M leather steering wheel
 0715 M Aerodynamics package
 0760 High gloss shadow line
 0775 Headlining anthracite
 07S9 Connected Drive Services Paket
 0868 Language version, Dutch
 0886 On-board literature, Dutch
 08BL Deletion of charging cable
 08EK Dummy-SALAPA
 08KA Oil service interval 24 mths / 30,000 km
 08LU Country control France 04834
 08R9 Refrigerant R1234yf
 08S3 Automatic locking during starting
 08TF Active pedestrian protection
 09AA Outer skin protection
 A090 90 Ah AGM battery

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage		Retailer	Overview			
—	15/11/2022	Key	110584 Km		05692	Key 0			
	 16000 03/2024	 16000 03/2024	 16000 03/2024	 16000 03/2024		 03/2024	 03/2024		 16000 03/2024

— 15/11/2022 Warranty 110584 Km 05692 Job: Control unit, charging electronics / convenience charging electronics KLE (hybrid / e-vehicle)

— Job: Control unit, charging electronics / convenience charging electronics KLE (hybrid / e-vehicle)

Description: Control unit, charging electronics / convenience charging electronics KLE (hybrid / e-vehicle)

Considered as a repeat visit No

Customer's own words

Replace convenience charging electronics 0 FRU
Flat rate unit I 61 44 502

Performing vehicle test 4 FRU
Flat rate unit I 00 00 006

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528

Programming/encoding control unit(s) including deleting fault memories 0 FRU
Flat rate unit I 61 00 730

Performing vehicle test 0 FRU
Flat rate unit I 00 00 556

Vehicle diagnosis - carrying out the ABL 0 FRU
Flat rate unit I 61 00 006



Charge the high-voltage battery unit 0 FRU
Flat rate unit I 61 25 911

Control unit, charging electronics / convenience charging electronics KLE (hybrid / e-vehicle)
Defect I 61 44 01 15 00


Control unit KLE 1
Part I 61445A602F7

Expanding nut 1
Part I 07 14 7 306 224



— 08/11/2022 Key 110002 Km 05692 Key 0




— 20/06/2022 Key 101166 Km 05718 Key 0




— 01/04/2022 Key 95006 Km 05681 Key 0



— 01/04/2022 Key 76753 Km 05681 Key 0



— 28/03/2022 Key



— 28/03/2022 Key



— 28/03/2022 Service




95006 Km 05681 Key 1




95006 Km 05681 Key 1




95006 Km 05681 Beliën Lommel, Lommel Automatic



— 24/03/2022 Key




95006 Km 05681 Key 1




— 23/02/2021 Key




78782 Km Key 0




— 19/02/2021 Key




78580 Km Key 0




— 16/06/2020 Key



72221 Km 05681 Key 0



— 16/06/2020 Warranty



72221 Km 05681 Job: Pressure sensor / temperature sensor, fuel tank (hybrid / E-vehicle)

— Job: Pressure sensor / temperature sensor, fuel tank (hybrid / E-vehicle)

Description: Pressure sensor / temperature sensor, fuel tank (hybrid / E-vehicle)

Considered as a repeat visit No

Customer's own words

Performing vehicle test
Flat rate unit | 00 00 006 4 FRU

Supporting the voltage of the vehicle electrical system/recharging the
vehicle electrical system battery 1 FRU
Flat rate unit | 61 21 528

Removing and installing/replacing rear seat 1 FRU
Flat rate unit | 52 24 505

Job time without allowance for / fuel supply 24 FRU
Flat rate unit | 16 99 000

Pressure sensor / temperature sensor, fuel tank (hybrid / E-vehicle)
Defect | 16 11 15 12 00

Pressure-temperature sensor 1
Part | 16 11 7 361 966

—	02/06/2020	Key	71747 Km	05681	Key 0		
	 24000 12/2021		 24000 539		 -61 8.4 %		 60000 12/2023
—	02/06/2020	Service	71747 Km	05681	Beli n Lommel , Lommel	Automatic	
	 24000 11/2021		 24000 11/2021		 04/2020 ✓		 60000 11/2023
—	20/12/2019	Key	65989 Km	05681	Key 0		
	 1000 11/2020	 1000 311	 1000 311		 04/2020		 1000 11/2020
—	20/12/2019	Service	65989 Km	05681	Beli n Lommel , Lommel	Automatic	
	 1000 10/2020 ✓	 1000 10/2020 ✓	 1000 10/2020 ✓		 03/2020		 1000 10/2020 ✓
—	05/12/2018	Key	35926 Km		Key 0		
	 32000 11/2020	 32000 726	 32000 726	 0 04/2020	 0	 0	 32000 11/2020

— 05/12/2018 Warranty 35926 Km 05681 Job: Programming F30 G1x G3x B48 control units (DME data status)
Job: F30 G11 G12 G30 Programming PHEV control units (charging electronics)

— Job: Programming F30 G1x G3x B48 control units (DME data status)

Description: Programming F30 G1x G3x B48 control units (DME data status)

Considered as a repeat visit No

Customer's own words

A different technical campaign or repair is used to invoice programming 1 FRU
Flat rate unit I 00 67 538

Programming F30 G1x G3x B48 control units (DME data status)
Defect I 00 12 80 04 00

— Job: F30 G11 G12 G30 Programming PHEV control units (charging electronics)

Description: F30 G11 G12 G30 Programming PHEV control units (charging electronics)



Considered as a repeat visit No

Customer's own words



Programming control units 8 FRU
Flat rate unit I 00 66 780

F30 G11 G12 G30 Programming PHEV control units (charging electronics)
Defect I 00 61 81 04 00

— 26/11/2018 Key 34965 Km Key 0



— 26/11/2018 Service 34965 Km 05681 Beli n Automatic
Lommel ,
Lommel



— 26/11/2018 Repair 34965 Km 05681 Beliën Job
Lommel ,
Lommel

— Job

Description:

Considered as a repeat visit No

Customer's own words

Laadwens van de klant: Full Local 0 FRU
Flat rate unit I -

Initiële laadtoestand hoog-voltage accu (SoC): 43% Local 0 FRU
Flat rate unit I -

Service - standard scope

Package I 0000105

Service - standard scope
Flat rate unit I 00 00 105

3

Engine oil service
Package I 0000610

Engine oil service
Flat rate unit I 00 00 610

3

Set oil-filter element
Part I 11428575211

1

BMW Engine Oil LL04 5W30
Part I 83212405948

5.25

Microfilter service
Package I 0000616

Microfilter service
Flat rate unit I 00 00 616

2

Set, microfilter/carbon canister
Part I 64116996208


1

— 15/12/2017 Key

7951 Km

05681

Key 0





— 19/10/2017 Key

7162 Km

05681

Key 0




— 27/09/2017 Key

6692 Km

05681

Key 0




— 14/09/2017 Key

6471 Km

05681

Key 0





— 07/09/2017 Key

5739 Km

05718

Key 0




— 20/07/2017 Key

4695 Km

05681


Key 0




— 20/07/2017 Key




4600 Km 05681 Key 0




— 13/07/2017 Key




4565 Km 05718 Key 0




— 18/05/2017 Key



2 Km 05681 Key 0



— 25/04/2017 Service



2 Km 05681 Belien Lommel nv, Lommel Manual

