

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 420d, 140KW

WBA4E91040G795127



Development code
Colour
Actual integration level
Start of warranty

F36
black-sapphire metallic
F020-22-03-552
31 January 2017

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2016-2 (As of: 20 May 2025)	Enabling code valid for navigation maps with release date up to 31 Dec 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	420d
Body	COUPE
Vehicle identification number (last 7 digits)	G795127
Vehicle identification number (17 digits)	WBA4E91040G795127
Development code	F36
Steering	LL
Engine	B47O
Engine number	63849860
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0693877WC7
Head unit serial number	MM01DFG2015724
Drive	HECK
Integration level, works	F020-16-11-502
Production date	9 Jan 2017
Production plant	Dingolfing
Delivery date	2 Feb 2017
Delivering retailer	No information
National-market version	EUR
Paint code	475
Upholstery code	HAAT
Model code	4E01
Basic type	4E91
Lead type	4E01

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 021C BMW LA wheel, M double spoke bicolor
 0230 EU-specific additional contents
 0258 Tyres with runflat properties
 02TB Sport automatic gearbox
 02VB Tyre pressure display
 0337 M Sports package
 0420 Sun protection glazing
 0423 Floor mats velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0481 Sports seat
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04WF Alum. Hexagon accent blue matt
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0522 Xenon Light
 0534 Automatic air conditioning
 0544 Cruise control with brake function
 0548 Kilometre speedo
 0563 Light package
 0575 Additional 12V power socket
 05DA Passenger airbag deactivation
 0606 Navigation system Business
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NH Hands-free system with USB interface
 0704 M Sports suspension
 0710 M leather steering wheel
 0715 M Aerodynamics package
 0760 High gloss shadow line
 0775 Headlining anthracite
 07LF Modell M Sport
 07S9 Connected Drive Services Paket
 0801 German version
 0851 Language version German
 0879 On-board literature, German
 08KA Oil service interval 24 mths / 30,000 km
 08R9 Refrigerant R1234yf
 A090 90 Ah AGM battery
 POLS Cloth cushion

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	20/05/2025	Service	250827 Km	02814 Cloppenburg GmbH , Bad Windsheim	Automatic

 2100 06/2026	 2100 06/2026	 2100 06/2026	 2100 06/2026	 90000 06/2026	 02/2026	 80000 06/2026	 2100 06/2026	 02/2026
---	---	---	---	--	---	--	---	---

— 06/05/2025 Key 250263 Km 02814 Key 0

 2700 06/2026	 2700 06/2026	 2700 06/2026	 2700 06/2026	 90000 06/2026	 02/2026	 90000 06/2026	 2700 06/2026	 02/2026
--	--	--	--	---	--	---	--	--

— 03/02/2025 Key 242591 Km 39796 Key 0

 11000 06/2026	 11000 06/2026	 11000 06/2026	 11000 06/2026	 90000 06/2026	 02/2026	 100000 06/2026	 11000 06/2026	 02/2026
---	---	---	---	---	--	--	---	--

— 03/02/2025 Warranty 8591 Km 39796 Job: Brake disc, front
Job: Brake disc, rear

— Job: Brake disc, front

Description: Brake disc, front

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both front brake discs 8 FRU
Flat rate unit I 34 11 609

Perform brake test on test stand 3 FRU
Flat rate unit I 34 00 509

Brake disc, front
Defect I 34 11 00 57 00

Repair kit brake pads asbestos-free 1
Part I 34 11 8 855 010

Brake pad wear sensor, front left 1
Part I 34 35 6 792 289

Brake disc, ventilated 2
Part I 34 11 8 848 417

Torx screw with washer 4
Part I 34 10 6 864 424

— Job: Brake disc, rear

Description: Brake disc, rear

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both rear brake discs 11 FRU
Flat rate unit I 34 21 928

Brake disc, rear
Defect I 34 21 00 57 00

Inner hex bolt 4
Part I 34 21 1 161 806

Repair kit brake pads asbestos-free Part I 34 21 8 855 013	1
Brake disc, ventilated Part I 34 21 6 864 900	2
Hex screw with collar Part I 34 20 6 850 536	4

—	28/01/2025	Key	242485 Km	39796	Key 0				
									
	11000	11000	11000	11000	90000		100000	11000	
	06/2026	06/2026	06/2026	06/2026		02/2026		06/2026	02/2026
—	14/01/2025	Key	241341 Km	02814	Key 0				
									
	12000	12000	12000	12000	90000		100000	12000	
	06/2026	06/2026	06/2026	06/2026		02/2026		06/2026	02/2026
—	19/12/2024	Key	238470 Km	02814	Key 0				
									
	15000	15000	15000	15000	90000		100000	15000	
	06/2026	06/2026	06/2026	06/2026		02/2026		06/2026	02/2026
—	11/09/2024	Key	230234 Km	02814	Key 0				
									
	23000	23000	23000	23000	3700		7000	23000	
	06/2026	06/2026	06/2026	06/2026		02/2026		06/2026	02/2026
—	29/08/2024	Warranty	229010 Km	02814	Job: Fx Replace driver's airbag, part III (SDI)				

— Job: Fx Replace driver's airbag, part III (SDI)

Description: Fx Replace driver's airbag, part III (SDI)

Considered as a repeat visit No

Customer's own words

Replace driver's airbag Flat rate unit I 00 76 920	3 FRU
Fx Replace driver's airbag, part III (SDI) Defect I 00 32 62 03 00	
Airbag module, driver's side Part I 32305A66F66	1

28/08/2024		Key	229006 Km		02814		Key 0	
								
24000	24000	24000	24000	11000		7000	24000	
06/2026	06/2026	06/2026	06/2026		02/2026		06/2026	02/2026

— 28/08/2024 Repair 229009 Km 02814 , Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sicherheits-Check kostenlos Flat rate unit I 09 04 004	Local	3 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Performing vehicle test Flat rate unit I 00 00 006		4 FRU
---	--	-------

Replacing ignition unit for right xenon headlight Flat rate unit I 63 12 871		2 FRU
---	--	-------

Bulb Xenon light with ignition element Part I 63 21 7 217 509		1
--	--	---

— Job


Description:

Considered as a repeat visit No


Customer's own words

kostenlose Fahrzeugüberwäsc he ohne AW 00000000 Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

— 20/08/2024 Key 228552 Km 02814 Key 0




— 14/06/2024 Key 221935 Km 02814 Key 0



— 14/06/2024 Service 221935 Km 02814 Automatic

Cloppenburg
GmbH , Bad
Windsheim



— 14/06/2024 Repair 221943 Km 02814 , Job
Job

Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sicherheits-Check kostenlos Flat rate unit I 09 04 004	Local	3 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105		2 FRU
--	--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616		2 FRU
---	--	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555		1
--	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610		3 FRU
--	--	-------

Set oil-filter element Part I 11 42 8 575 211		1
--	--	---

BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948		5
--	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche 00000000 Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

Gutschein TA-AGR Kühler 00000000 Flat rate unit I 99 99 999	Local	-1 FRU
--	-------	--------

14/06/2024	Warranty	221935 Km	02814	Job
------------	----------	-----------	-------	-----

— Job

Description:
Considered as a repeat visit No
Customer's own words

Defect I 85 40 00 26 SA

—	06/06/2024	Key		219849 Km	02814	Key 0			
									
	1400		1400		18000	7000	33000		
	09/2025		09/2025		02/2026		09/2027		02/2026
—	13/03/2024	Key		213081 Km	02814	Key 0			
									
	9000		9000		28000	13000	40000		
	09/2025		09/2025		02/2026		09/2027		02/2026
—	13/03/2024	Repair		213093 Km	02814	Job			
					Cloppenburg	Job			
					GmbH , Bad	Job			
					Windsheim				

— Job

Description:
Considered as a repeat visit No
Customer's own words

Service, advisory consultation at vehicle 0 FRU
Flat rate unit I 00 52 050

— Job

Description:
Considered as a repeat visit No
Customer's own words

Removing and installing or replacing oil pressure switch 36 FRU
Flat rate unit I 12 61 280

Removing and installing/replacing front and rear underbody protection 5 FRU
Flat rate unit I 51 47 995

Oil pressure sensor 1
Part I 12 61 8 614 494

O-ring 2
Part I 17 22 8 573 882

Automatic transmission fluid 3+ 1
Part I 83225A12A00

Anti-freeze 4
Part I 83 19 2 218 347

— Job

Description:
Considered as a repeat visit No
Customer's own words

13/02/2024

Key

208947 Km

02814

Key 0



13000

09/2025





13000

09/2025





32000



-43

5.9 %



17000



44000

09/2027



-43

5.9 %

13/02/2024

Service

208947 Km

02814
Cloppenburg
GmbH , Bad
Windsheim

Automatic



13000





13000





32000



✓



17000



44000



13/02/2024

Repair

208961 Km

02814
Cloppenburg
GmbH , Bad
Windsheim

Job
Job
Job
Job
Job

Job

Description:

Considered as a repeat visit No

Customer's own words

Sicherheits-Check kostenlos -Bremsbeläge vo + hi in ca. 10.000 km

Local

3 FRU

Flat rate unit I 09 04 004

Scheibenzusatz

Local

4

Part I 93 12 2 298 207

Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope

2 FRU

Flat rate unit I 00 00 105

Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service

4 FRU

Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity

1

Part I 83 13 2 405 977

Job

Description:

Considered as a repeat visit No

Customer's own words

Vorführung zur Abgasinspektion
Flat rate unit I 09 04 010

Local

4 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Hauptuntersuchung TÜV PKW §29 STVZO #HU2
Flat rate unit I 99 99 999

Local

1 FRU

kostenlose Fahrzeugüberwä sche ohne AW
Flat rate unit I 99 99 999

Local

1 FRU

— 13/02/2024 Repair 208961 Km 02814 Job
Cloppenburg
GmbH , Bad
Windsheim

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing windshield
Flat rate unit I 51 31 011

24 FRU

Additional job with rain/light sensor
Flat rate unit I 61 35 994

3 FRU

Scheibenklebeset
Part I FT66006412

Local

1

Green windscreen
Part I 51 31 7 285 897

1

Cover, windshield, top
Part I 51 31 7 285 915

1

Clamp
Part I 51 43 7 321 215

10

Bump stop
Part I 51 31 7 288 462

11

Cleaner R1
Part I 83 19 2 211 217

1

Sound insulation f apron
Part I 51 48 7 325 890

1

Drip moulding, left
Part I 51 31 7 285 927

1

Drip moulding, right
Part I 51 31 7 285 928

1


Clip, drip moulding
Part I 51 13 7 321 818

10


Clip, drip moulding
Part I 51 13 7 258 183

10

— 30/01/2024 Key 207875 Km 02814 Key 0



— 10/01/2024 Key 205976 Km 02814 Key 0



— 27/09/2023 Warranty 190259 Km 02814 Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve
Flat rate unit I 00 74 635 23 FRU

Additional work: run function test for pressure sensor system
Flat rate unit I 00 74 636 3 FRU

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system
Flat rate unit I 00 74 637 1 FRU

Additional work cleaning the exhaust gas recirculation pipe
Flat rate unit I 00 74 638 2 FRU

F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)
Defect I 00 11 13 07 00

Exhaust gas radiator high temperature
Part I 11 71 7 822 347 1

EGR small parts set
Part I 11 71 8 490 640 1

Vacuum hose black
Part I 11 65 8 595 650 1

Pipe union
Part I 11 71 7 799 853 2

Holder
Part I 61 13 1 369 832 1

Connection piece
Part I 11 65 7 803 012 1

O-ring
Part I 11 61 8 512 681 1

Acoustic cover front
Part I 11 14 8 490 577 1

Pipe
Part I 13 71 7 823 517 1

— 26/09/2023 Key 190251 Km 02814 Key 0

 1200 12/2024	 1200 12/2024	 1200 12/2024	 1200 12/2024	 49000 12/2024	 01/2024	 34000 12/2024	 1200 12/2024	 01/2024
--	--	--	--	---	--	---	---	--

— 26/09/2023 Service 190251 Km 02814 Automatic
Cloppenburg
GmbH , Bad
Windsheim

 1200 12/2024 ✓	 1200 12/2024 ✓	 1200 12/2024 ✓	 1200 12/2024 ✓	 49000 12/2024 ✓	 01/2024	 34000 12/2024 ✓	 1200 12/2024 ✓	 01/2024
---	---	---	---	--	--	--	--	--

— 26/09/2023 Repair 190259 Km 02814 Job
Cloppenburg Job
GmbH , Bad Job
Windsheim Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sicherheits-Check kostenlos Flat rate unit I 09 04 004	Local	3 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element
Part I 11 42 8 575 211

1

BMW Engine Oil LL04 5W30
Part I 83 21 2 405 948

5

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter
Flat rate unit I 00 00 604

3 FRU

Fuel filter cartridge
Part I 13 32 7 822 497

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element
Flat rate unit I 00 00 602

2 FRU

Air filter element
Part I 13 71 8 511 668

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check
Flat rate unit I 00 00 624

6 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugüberwäsc he
Flat rate unit I 99 99 999

Local

1 FRU

—

15/08/2023

Key

184925 Km

Key 0



7000

12/2024



7000

12/2024



7000

12/2024



7000

12/2024



50000



01/2024



38000



7000

12/2024



01/2024

—

16/12/2022

Key

160395 Km

Key 0



80

01/2024





80

01/2024





70000

01/2024





60000



32000

01/2026



01/2024

—


16/12/2022

Service

160395 Km

02814
Cloppenburg

Automatic



— 16/12/2022 Repair 160401 Km 02814 Cloppenburg GmbH , Bad Windsheim Job Job Job Job Job Job

— Job

Description:
Considered as a repeat visit No
Customer's own words

Sicherheits-Check Flat rate unit I 09 04 004	Local	3 FRU
---	-------	-------

— Job

Description:
Considered as a repeat visit No
Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

— Job

Description:
Considered as a repeat visit No
Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:
Considered as a repeat visit No
Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5
--	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job

Description:
Considered as a repeat visit No

Customer's own words

Replace left and right wiper blade
Flat rate unit | 61 61 541 0 FRU

Set of wiper blades
Part | 61615A43587 1

Job


Description:

Considered as a repeat visit No


Customer's own words

kostenlose Fahrzeugoberwäsche
Flat rate unit | 99 99 999 Local 1 FRU

05/12/2022 Key 159560 Km Key 0



07/07/2022 Key 146811 Km Key 1



07/07/2022 Repair 146818 Km 02814 Cloppenburg GmbH , Bad Windsheim Job Job

Job

Description:

Considered as a repeat visit No

Customer's own words

Sicherheits-Check
Flat rate unit | 09 04 004 Local 3 FRU

Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Innenreinigung ohne AW
Flat rate unit | 99 99 999 Local 1 FRU

kostenlose Fahrzeugoberwäsche
Flat rate unit | 99 99 999 Local 1 FRU

07/07/2022 Warranty 146818 Km 02814 Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE) Job

Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Description: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Considered as a repeat visit No

Customer's own words

Program control units 8 FRU
Flat rate unit I 00 71 907

F1x F2x F3x B47O B47K B47U Programming control units (DDE)
Defect I 00 13 50 03 00

— Job

























Description:

Considered as a repeat visit No

Customer's own words

Carrying out fault memory and pressure sensor system functional check
(in conjunction with the above-mentioned TA (programming control
units)) 1 FRU
Flat rate unit I 00 72 677

Defect I 00 13 67 03 00

—	20/06/2022	Key	145296 Km			02814			Key 1
									
	16000		16000		70000		80000	47000	
	01/2024		551		01/2024			01/2026	01/2024
—	17/01/2022	Key	129522 Km			Key 1			
									
	30000		30000		25000		14000	60000	
	704		704		704			1424	704
—	17/01/2022	Key	129509 Km			Key 1			
									
	-2900	-2900	-2900	-2900	25000		14000	-2900	
	11/2022	284	284	284		-16 2.2 %		11/2022	-16 2.2 %
—	17/01/2022	Service	129509 Km			02814 Cloppenburg GmbH , Bad Windsheim			Automatic
									
	-2900	-2900	-2900	-2900	25000		14000	-2900	
	✓	✓	✓	✓				✓	
—	17/01/2022	Repair	129509 Km			02814 Cloppenburg GmbH , Bad Windsheim			Job Job Job Job Job Job Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sicherheits-Check kostenlos	Local	3 FRU
Flat rate unit I 09 04 004		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

BMW Engine Oil LL04 5W30	5
Part I 83 21 2 405 948	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 7 822 497	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
------------------------------	-------

Flat rate unit I 00 00 602

Air filter element 1
Part I 13 71 8 511 668

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service 4 FRU
Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity 1
Part I 83 13 2 405 977

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check 6 FRU
Flat rate unit I 00 00 624

— Job

Description:

Considered as a repeat visit No

Customer's own words

HU + AU TÜV PKW 00000000 Local 1 FRU
Flat rate unit I 99 99 999


kostenlose Innenreinigung 00000000 Local 1 FRU
Flat rate unit I 99 99 999

kostenlose Fahrzeugoberwäsche 00000000 Local 1 FRU
Flat rate unit I 99 99 999

— 08/01/2022 Key

128975 Km

Key 1




— 27/11/2020 Key

95596 Km

02814

Key 1




— 27/11/2020 Service

95596 Km

02814
Cloppenburg
GmbH, Bad
Windsheim

Manual



— 27/11/2020 Repair

95605 Km

02814
Cloppenburg
GmbH , Bad
Windsheim

Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sicherheits-Check Flat rate unit I 09 04 004	Local	1 FRU
Servicepaket Öl, Luft, Waschwasser, AD-Blue Nachfüllen O JA x Nein Flat rate unit I -	Local	0 FRU
Werkstatt-Check Mängel vorhanden? JA O NEIN x Flat rate unit I -	Local	0 FRU
Service consultation with customer at vehicle without service ticket Flat rate unit I 00 52 053		0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105		2 FRU
--	--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610		3 FRU
Set oil-filter element Part I 11 42 8 575 211		1
BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948		5

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616		2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555		1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeug aussaugen	Local	0 FRU
Flat rate unit I 00 99 500		

— Job


Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash		1 FRU
Flat rate unit I 00 11 319		

— 31/03/2020 Key 79851 Km 02814 Key 1



— 31/03/2020 Repair 79851 Km 02814 Cloppenburg GmbH , Bad Windsheim Job Job Job Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sicherheits-Check	Local	3 FRU
Flat rate unit I 09 04 004		

Servicepaket Öl, Luft, Waschwasser, AD-Blue Nachfüllen O JAXX Nein	Local	1 FRU
Flat rate unit I -		

Service consultation with customer at vehicle without service ticket		0 FRU
Flat rate unit I 00 52 053		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing windshield		24 FRU
Flat rate unit I 51 31 011		

SCHEIBENKLEBESET 400ML	Local	1
Part I FT99990048082		

Clip, drip moulding		4
Part I 51 13 7 258 183		

Clip, drip moulding		6
Part I 51 13 7 321 818		

Green windscreen		1
------------------	--	---

Part I 51 31 7 285 897

Cover, windshield, top
Part I 51 31 7 285 915

1

Drip moulding, left
Part I 51 31 7 285 927

1

Drip moulding, right
Part I 51 31 7 285 928

1

Bump stop
Part I 51 31 7 288 462

11

Clamp
Part I 51 43 7 321 215

2

Sound insulation f apron
Part I 51 48 7 325 890

2

Replacement plate driving light sensor
Part I 61 35 9 856 157

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash
Flat rate unit I 00 11 319

3 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No






Customer's own words

— 19/03/2020 Key

79387 Km

02814

Key 1










— 18/03/2020 Key

79270 Km

02814

Key 1









— 13/02/2020 Key

76397 Km

02813

Key 1



— 13/02/2020 Repair 76408 Km 02814 Cloppenburg GmbH , Bad Windsheim Job Job Job Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sicherheits-Check	Local	3 FRU
Flat rate unit I 09 04 004		

Servicepaket Öl, Luft, Waschwasser, AD-Blue Nachfüllen O JA x Nein	Local	1 FRU
Flat rate unit I -		

Service consultation with customer at vehicle without service ticket		0 FRU
Flat rate unit I 00 52 053		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeug aussaugen	Local	0 FRU
Flat rate unit I 00 99 500		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash		3 FRU
Flat rate unit I 00 11 319		

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 13/02/2020 Warranty 76408 Km 02814 Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

— Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Description: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Check label/ replace exhaust-gas recirculation cooler and remount exhaust-gas recirculation valve; clean exhaust-gas recirculation pipe

30 FRU

Flat rate unit I 00 68 166

Performing additional work for pressure sensor function

3 FRU

Flat rate unit I 00 68 742

F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Defect I 00 11 40 05 00

Pipe union

2

Part I 11 71 7 799 853

Exhaust gas radiator high temperature

1

Part I 11 71 8 513 691

Set of small parts

1

Part I 11 71 8 597 652

Oval head screw

2

Part I 35 21 7 685 343

Holder

1

Part I 61 13 1 369 832

29/01/2020 Key75186 Km02813Key 1



19000

08/2021



0



19000

580



0



400



0

01/2020



6000



50000

08/2023



0

01/2020

29/01/2020 Service75186 Km02814Cloppenburg GmbH, Bad WindsheimAutomatic



19000

08/2021



0



19000

08/2021



0



400



0

01/2020



6000



50000

08/2023



0

01/2020

✓

✓

✓

29/01/2020 Repair75192 Km02814Cloppenburg GmbH , Bad WindsheimJobJobJobJobJobJobJobJobJobJob

Job

Description:

Considered as a repeat visit No

Customer's own words

Service consultation with customer at vehicle without service ticket

0 FRU

Flat rate unit I 00 52 053

Job

Description:

Considered as a repeat visit No

Customer's own words

Sicherheits-Check Flat rate unit I 09 04 004	Local	3 FRU
Servicepaket Öl, Luft, Waschwasser, AD-Blue Nachfüllen O JA X Nein Flat rate unit I -	Local	1 FRU
Werkstatt-Check Mängel vorhanden? JA O NEIN x Flat rate unit I -	Local	0 FRU

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

AU-Untersuchung für Diesel und Kat-Fahrzeuge #AU2 Flat rate unit I 00 00 402	Local	8 FRU
Fahrzeug bei Prüfstelle vor fahren #HU2 *kostenlos* Flat rate unit I 00 12 160	Local	3 FRU
Verauslagte Gebühren Hauptuntersuchung § 29 Part I FT00 00 1 216 1	Local	1

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service - standard scope Flat rate unit I 00 00 105		2 FRU
--	--	-------

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Brake fluid service Flat rate unit I 00 00 618		4 FRU
Bremsflüssigkeit DOT4 Niederviskos LV Part I FT99999401078	Local	1

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service, front brakes Flat rate unit I 00 00 612		6 FRU
Spez.Reinig. Part I FT99999407848	Local	1
Repair kit, brake pads asbestos-free Part I 34 10 6 859 181		1
Brake pad wear sensor, front left Part I 34 35 6 792 289		1
Brake-pad paste Part I 83 19 2 158 851		2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes Flat rate unit I 00 00 614		7 FRU
Spez.Reinig. Part I FT99999407848	Local	1
Repair kit, brake pads asbestos-free Part I 34 21 6 873 093		1
Brake-pad sensor, rear Part I 34 35 6 792 292		1
Brake-pad paste Part I 83 19 2 158 851		2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeug aussaugen Flat rate unit I 00 99 500	Local	0 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words
















Vehicle surface wash Flat rate unit I 00 11 319		3 FRU
--	--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	03/01/2020	Key		73172 Km	02814	Key 1			
									
	21000	0	21000	0	1900	0	6000	60000	0
	08/2021		605		01/2020		08/2023		01/2020
—	16/08/2019	Key		62482 Km	02813	Key 1			
									
	40	40	40	40	19000	0	8000	40	0
	05/2020	289	289	289	01/2020		05/2020		01/2020
—	16/08/2019	Service		62482 Km	02814	Automatic			
					Cloppenburg GmbH , Bad Windsheim				

 40 05/2020 ✓	 40 05/2020 ✓	 40 05/2020 ✓	 40 05/2020 ✓	 19000	 0 01/2020	 8000	 40 05/2020 ✓	 0 01/2020
--	--	--	--	---	--	--	---	--

— 16/08/2019 Repair 62490 Km 02814
Cloppenburg
GmbH , Bad
Windsheim
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service consultation with customer at vehicle without service ticket	0 FRU
Flat rate unit I 00 52 053	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sicherheits-Check	Local	3 FRU
Flat rate unit I 09 04 004		
Servicepaket Öl, Luft, Waschwasser prüfen Nachfüllen O JA x Nein	Local	1 FRU
Flat rate unit I -		
Werkstatt-Check Mängel vorhanden? JA O NEIN x	Local	0 FRU
Flat rate unit I -		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	
Set oil-filter element	1
Part I 11 42 8 575 211	
BMW Engine Oil LL04 5W30	5
Part I 83 21 2 405 948	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 8 572 522	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeug aussaugen	Local	0 FRU
Flat rate unit I 00 99 500		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash	3 FRU
Flat rate unit I 00 11 319	

 600 05/2020	 600 292	 600 292	 600 292	 19000	 0 01/2020	 8000	 600 05/2020	 0 01/2020
---	---	---	---	--	---	---	---	---

— 03/01/2019 Key 45558 Km 02814 Key 1

 17000 05/2020	 17000 514	 17000 514	 17000 514	 37000	 0 01/2020	 26000	 17000 05/2020	 0 01/2020
---	---	---	---	--	---	--	---	---

— 22/11/2018 Repair 44623 Km 02814 Cloppenburg GmbH , Bad Windsheim Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugverbringung Flat rate unit 00 00 356	Local	12 FRU
Performing vehicle test Flat rate unit 00 00 556		2 FRU
Carry out Kinematics Diagnosis System wheel alignment with vehicle load up to design position Flat rate unit 32 00 590		16 FRU
Removing and installing front or rear wheel Flat rate unit 36 10 800		1 FRU
Job time without allowance for / body Flat rate unit 41 99 000		1 FRU
Removing and installing/replacing both supports for front bumper panel Flat rate unit 51 11 566		11 FRU
Replacing front bumper panel Flat rate unit 51 11 592		11 FRU
Removing and installing front bumper panel Flat rate unit 51 11 656		9 FRU
Removing and installing/replacing both deformation elements on the top Flat rate unit 51 11 772		24 FRU
Replacing rear bumper panel Flat rate unit 51 12 657		1 FRU
Removing and installing left or right roof trim strip Flat rate unit 51 13 780		1 FRU
Remove and install/replace door pillar trim Flat rate unit 51 13 896		2 FRU
Stripping and refitting work for painting the rear left or right doors Flat rate unit 51 18 850		3 FRU
Stripping and refitting work for painting tailgate Flat rate unit 51 18 870		8 FRU
Removing and installing/replacing the window recess finisher strip of the rear inner door		1 FRU

Flat rate unit | 51 22 830

Removing and installing left or right rear door trim panel
Flat rate unit | 51 42 503

3 FRU

Removing and installing/replacing rear left or right wheel arch cover
Flat rate unit | 51 71 541

3 FRU

Replacing all cooling air routings for coolant radiator
Flat rate unit | 51 71 600

6 FRU

Replacing the vehicle battery – including battery replacement registration
Flat rate unit | 61 21 517

1 FRU

Additional work: headlight washer system
Flat rate unit | 61 67 803

3 FRU

Job time without allowance for / electrical system
Flat rate unit | 61 99 000

2 FRU

Adjusting headlights
Flat rate unit | 63 10 502

2 FRU

Additional work with Park Distance Control
Flat rate unit | 66 20 602

2 FRU

Cavity preservation for wheel arch, rear left or right
Flat rate unit | 97 14 512

2 FRU

Cavity preservation for side panel, rear left or right
Flat rate unit | 97 35 602

2 FRU

Job time without allowance for / cavity sealing - undercoating
Flat rate unit | 97 99 000

3 FRU

Screw
Part | 07 12 9 907 535

4

Blind plug
Part | 07 14 7 127 540

1

Fillister head screw
Part | 07 14 7 127 714

13

Hex nut with plate
Part | 07 14 7 155 614

4

Plastic cap nut with washer
Part | 07 14 7 169 847

16

Blind rivet
Part | 07 14 7 234 212

2

Hex nut
Part | 07 14 7 266 441

4

Snap-lock coupling
Part | 07 14 7 306 640

1

Hex Bolt
Part | 07 14 7 321 202

4

Oval-head screw with washer
Part | 07 14 7 406 384

6

Fillister head screw
Part | 07 14 9 321 070

2

Trunk floor right
Part | 41 00 7 297 910

1

Right rear side panel
Part | 41 00 7 334 022

1

Luggage compartment liner right

1

Part I 41 00 7 376 610

Positioning aid T-bolt Part I 41 21 2 460 147	1
--	---

Reinforcement plate, universal Part I 41 21 7 275 563	2
--	---

Reinforcement plate, D-pillar, right Part I 41 21 7 334 030	1
--	---

Reinforcement plate, sill, right Part I 41 21 7 334 040	1
--	---

Tail trim Part I 41 34 7 333 967	1
-------------------------------------	---

Kerb damper Part I 51 11 7 268 479	2
---------------------------------------	---

Carrier, bumper, front top Part I 51 11 7 275 178	1
--	---

Deformation element, front left Part I 51 11 7 289 907	1
---	---

Deformation element, front right Part I 51 11 7 289 908	1
--	---

Mounting, side panel, front bottom left Part I 51 11 7 294 653	1
---	---

Mounting, side panel, front bottom right Part I 51 11 7 294 654	1
--	---

Mounting, side panel, front top left Part I 51 11 7 294 679	1
--	---

Mounting, side panel, front top right Part I 51 11 7 294 680	1
---	---

Support, central Part I 51 11 7 296 308	1
--	---

Deformation element left Part I 51 11 8 051 189	1
--	---

Deformation element right Part I 51 11 8 051 190	1
---	---

Insert, air inlet, middle Part I 51 11 8 054 503	1
---	---

Bumper grille, front left Part I 51 11 8 054 507	1
---	---

Bumper grille, front right Part I 51 11 8 054 508	1
--	---

Support, fog lamp left Part I 51 11 8 054 511	1
--	---

Support, fog lamp right Part I 51 11 8 054 512	1
---	---

Shock absorber front Part I 51 11 8 054 544	1
--	---

Panel, bumper, primed, front Part I 51 11 8 060 879	1
--	---

Flap, towing eye, primed Part I 51 11 8 061 005	1
--	---

Repair kit, holder, bumper, front	1
-----------------------------------	---

Part I 51 11 8 065 982

Expanding rivet Part I 51 11 8 174 185	4
---	---

Washer-gasket Part I 51 12 7 240 917	2
---	---

Carrier, bumper rear Part I 51 12 7 285 542	1
--	---

Guide for bumper, side, left Part I 51 12 7 285 561	1
--	---

Guide, centre rear Part I 51 12 7 316 350	1
--	---

Cover Part I 51 12 7 338 682	1
---------------------------------	---

Guide for bumper, side, left Part I 51 12 7 428 731	1
--	---

Guide for bumper, side, right Part I 51 12 7 428 732	1
---	---

Trim panel, bumper, rear, bottom Part I 51 12 8 054 563	1
--	---

Reinforcement, bumper, rear bottom Part I 51 12 8 054 565	1
--	---

Flap, towing eye, primed Part I 51 12 8 060 849	1
--	---

Panel, bumper, primed, rear Part I 51 12 8 062 246	1
---	---

Set, mounts, PDC sensor, rear Part I 51 12 8 073 079	1
---	---

Grille, front, left Part I 51 13 7 294 817	1
---	---

Grille, front, right Part I 51 13 7 294 818	1
--	---

Gasket, door joint, C column, right Part I 51 13 7 431 096	1
---	---

Licence plate base Part I 51 13 8 054 576	1
--	---

Lettering Part I 51 14 7 356 330	1
-------------------------------------	---

Lettering Part I 51 14 7 398 499	1
-------------------------------------	---

Expanding rivet Part I 51 16 1 881 149	2
---	---

Plastic cap nut with washer Part I 51 16 1 943 122	4
---	---

Cover pot Part I 51 17 7 270 761	1
-------------------------------------	---

Stop buffer Part I 51 24 7 320 473	2
---------------------------------------	---

Cover, water gutter, rear, right Part I 51 24 7 453 338	1
--	---

Blind rivet nut, flat headed	3
------------------------------	---

Grommet Part I 51 31 8 150 943	10
Sealing, cover, column B right Part I 51 35 7 310 190	1
Channel cover, outer, door, rear right Part I 51 35 7 332 520	1
Cover, column B, door, front right Part I 51 35 7 453 304	1
Hook and loop fastener Part I 51 37 7 164 933	6
Side window, fixed, rear right Part I 51 37 7 412 032	1
Clip, yellow Part I 51 41 7 007 479	10
Clip with washer, natur Part I 51 41 8 224 768	10
Clamp Part I 51 41 8 240 509	5
Clip Natur Part I 51 43 7 001 491	12
Expanding rivet Part I 51 47 1 911 992	8
Support front axle support, left Part I 51 64 7 245 795	1
Support, front axle support, right Part I 51 64 7 245 796	1
Carrier, bumper, front bottom Part I 51 64 8 054 575	1
Sealing sheet Part I 51 71 1 922 189	10
C-clip nut Part I 51 71 7 065 773	12
Cover, wheel housing, rear right Part I 51 71 7 260 748	1
Air duct, radiator Part I 51 74 7 290 610	1
Air duct, brake, left Part I 51 74 8 054 529	1
Air duct, bottom Part I 51 74 8 054 591	1
Underbody panelling, rear left Part I 51 75 7 260 769	1
Underbody panelling, rear right Part I 51 75 7 260 770	1
Clip, roof frame strip Part I 51 76 7 162 587	10
Plaque Part I 51 76 7 288 752	1
Trunk lid gasket	1

Part I 51 76 7 398 238

Supporting ledge right
Part I 51 77 7 320 208

1

Supporting ledge right
Part I 51 77 7 320 210

1

Shrinking hose
Part I 61 13 1 379 833

7

Original BMW AGM-battery
Part I 61 21 6 924 023

1

Battery roll bar
Part I 61 21 7 601 939

1

Battery lead, negative, IBS
Part I 61 21 9 117 877

1

Expanding nut
Part I 63 12 1 374 075

3

Rear reflector, rear left
Part I 63 14 7 847 233

1

Rear reflector, rear right
Part I 63 14 7 847 234

1

Rear light in the side panel, right
Part I 63 21 7 296 098

1

Rear ventilation
Part I 64 22 9 176 945

1

Ultrasonic sensor black
Part I 66 20 9 261 582

4

Cavity protection wax remover
Part I 83 12 0 390 086

1

Blind rivet N3
Part I 83 19 0 301 421

40

Screw
Part I 83 19 0 301 639

13

Body adhesive K5
Part I 83 19 2 157 298

2

Punch rivet
Part I 83 19 2 158 079

34

Body adhesive K5
Part I 83 19 2 158 654

2

Cleaner R1
Part I 83 19 2 211 217

4

Punch rivet N4
Part I 83 19 2 457 307

11

Seam seal
Part I 83 42 2 409 985

2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Stoßfänger V+H, Abschluss- blech, Seitenwand HR, Gepäc k-
Flat rate unit I 99 99 999

Local

1 FRU

Seitenwand HR richten, Gepä ck-raumboden R ersetzen, Richt -
Flat rate unit | 99 99 999

Local

1 FRU

Unfallersatzwagen 21.11.18 - 14.12.18
Flat rate unit | 99 99 999

Local

1 FRU

— 20/11/2018 Key

44623 Km

Key 1

									
18000	18000	18000	18000	38000	0	27000	18000		0
05/2020	557	557	557		01/2020		05/2020		01/2020

— 30/05/2018 Key

31557 Km 02814

Key 1

									
-500	0	-500	0	60000	0	41000	31000		0
01/2019		246			01/2020		01/2021		01/2020

— 30/05/2018 Service

31557 Km 02814
Cloppenburg
GmbH , Bad
Windsheim

Automatic

									
-500	0	-500	0	60000	0	41000	31000		0
01/2019		01/2019			01/2020		01/2021		01/2020
✓		✓							

— 30/05/2018 Repair

31561 Km 02814
Cloppenburg
GmbH , Bad
Windsheim

Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Servicepaket Öl, Luft, Waschwasser prüfen Nachfüllen O JA X Nein
Flat rate unit | -

Local

1 FRU

Service consultation with customer at vehicle without service ticket
Flat rate unit | 00 52 053

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit | 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service
Flat rate unit I 00 00 610 3 FRU

BMW Motoröl 0W-30 TwinPowerTurbo LL-04
Part I 83 21 2 405 675 Local 5

Set oil-filter element
Part I 11 42 8 575 211 1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service
Flat rate unit I 00 00 616 2 FRU

Microfilter/activated Carbon container
Part I 64 11 9 237 555 1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeug aussaugen
Flat rate unit I 00 99 500 Local 2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash
Flat rate unit I 00 11 319 3 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 22/05/2018 Key

30797 Km

02814

Key 1

								
170	0	170	0	60000	0	42000	32000	0
01/2019		253		01/2020			01/2021	01/2020

— 09/05/2018 Key

30038 Km

02814

Key 1

								
1000	0	1000	0	60000	0	43000	32000	0
01/2019		266		01/2020			01/2021	01/2020

— 09/05/2018 Warranty

30038 Km

02814

Job: Exhaust gas recirculation valve (EGR)

— Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)

Considered as a repeat visit No

Customer's own words

Performing vehicle test Flat rate unit 00 00 006	4 FRU
---	-------

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit 61 21 528	1 FRU
---	-------

Vehicle diagnosis - carrying out the ABL Flat rate unit 61 00 006	4 FRU
--	-------

Replace EGR electrovalve Flat rate unit 11 74 555	9 FRU
--	-------

Exhaust gas recirculation valve (EGR) Defect 11 71 01 83 00	
--	--

EGR-valve Part 11 71 8 513 132	1
-------------------------------------	---

Gasket Steel Part 11 71 8 579 364	1
--	---

Oval head screw Part 35 21 7 685 343	2
---	---


Hose clamp Part 07 12 9 952 104	2
--------------------------------------	---

— 30/04/2018 Key

29361 Km

02814

Key 1



— 23/03/2018 Warranty

26801 Km

02814

Job: Exhaust gas recirculation valve (EGR)

— Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)

Considered as a repeat visit No

Customer's own words

Performing vehicle test Flat rate unit 00 00 006	4 FRU
---	-------

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit 61 21 528	1 FRU
---	-------

Vehicle diagnosis - carrying out the ABL Flat rate unit 61 00 006	4 FRU
--	-------

Programming/encoding control unit(s) including deleting fault memories Flat rate unit 61 00 730	4 FRU
--	-------

Exhaust gas recirculation valve (EGR) Defect 11 71 01 83 00	
--	--

— 26/10/2017 Key

18648 Km

02814

Key 1

								
13000	0	13000	0	60000	0	60000	44000	0
01/2019		462			01/2020		01/2021	01/2020