

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 520D xDr, 140KW

WBA5L51020G092726



Development code F11
Colour imperial-blau brillant metallic
Actual integration level F010-17-11-520
Start of warranty 26 April 2016

Delivery stop



Technical Campaigns are available.

Technical campaigns

Status	Campaign number	Description	Reservation
Open	10011350700	Exhaust gas recirculation cooler customer notification Local campaign number: -	
Open	10011600600	Replacing the exhaust gas recirculation cooler (high temperature)  Delivery stop Local campaign number: -	
Open	10032550300	Check the driver's airbag, replace if necessary (conversion SDI)  Delivery stop Local campaign number: -	

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Next 2016-1 (As of: 25 Jan 2022)	Enabling code valid for navigation maps with release date up to 31 Dec 2025 (SWID: 00A9008F).	Road Map EUROPE WEST Next 2025	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	520D xDr
Body	TOUR
Vehicle identification number (last 7 digits)	G092726
Vehicle identification number (17 digits)	WBA5L51020G092726
Development code	F11
Steering	LL
Engine	B47O
Engine number	65619569
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0109170ZSG
Head unit serial number	HB2068G8212865
Drive	ALLR
Integration level, works	F010-16-03-502
Production date	23 Mar 2016
Production plant	Dingolfing
Delivery date	30 Mar 2016

Delivering retailer	No information
National-market version	EUR
Paint code	A89
Upholstery code	LCOX
Model code	5L61
Basic type	5L51
Lead type	5L61

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 01CC Auto start/stop function
 01CD Brake Energy Regeneration
 0205 Automatic transmission
 0230 EU-specific additional contents
 0248 Steering wheel heater
 024F BMW LA wheel, double spoke 609
 0255 Sports leather steering wheel
 0258 Tyres with runflat properties
 02PA Locking wheel bolt
 02VB Tyre pressure display
 0302 Alarm system
 0316 automatic trunk lid mechanism
 0320 Deleted, model lettering
 03AC Trailer coupling
 03AG Reversing camera
 03AT Roof rails aluminium satinated
 03MB Indiv. Ext. Line, burnished aluminium
 0423 Floor mats velours
 0431 Interior mirror with automatic-dip
 0453 Climate-controlled seats, front
 0456 Comfort seat with memory
 0488 Lumbar support, driver and passenger
 0494 Seat heating driver/passenger
 04AT Interior trim finishers black high-gloss
 04U2 Driving experience switch incl. ECO PRO
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0534 Automatic air conditioning
 0548 Kilometre speedo
 05A1 LED Fog lights
 05DF Active cruise control+stop&go function
 0609 Navigation system Professional
 0610 Head-up display
 0688 Harman/Kardon surround sound system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06WB Multifunctional instrument display
 0761 Individual sunshade glazing
 07MG Edition Sport Pro
 07S9 Connected Drive Services Paket
 0868 Language version, Dutch
 0877 Omission of non-combined operation
 0886 On-board literature, Dutch
 08KA Oil service interval 24 mths / 30,000 km
 08S3 Automatic locking during starting
 08SM Car ident. number visible from outside
 08TF Active pedestrian protection

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage			Retailer	Overview
—	19/05/2022	Key	186586 Km			20736	Key 0
	 25000 01/2024   25000 582		  43000 09/2023  462  29000  60000 01/2026				
—	14/02/2022	Key	181269 Km			20736	Key 0
	 29000 677   29000 677		  45000 09/2023  557  32000  60000 1397				
—	25/01/2022	Key	180451 Km				Key 0
	 4100 10/2022  4100 246  4100 246		 4100 246  -80 09/2023  576  7000  4100 10/2022				
—	25/01/2022	Service	180451 Km			20736 Daeninck Latem , St. Martens Latem	Automatic
	 4100 09/2022 ✓  4100 09/2022 ✓  4100 09/2022 ✓		 4100 09/2022 ✓  -80 08/2023 ✓  7000  4100 09/2022 ✓				
—	08/09/2021	Key	169830 Km				Key 0
	 16000 10/2022  16000 383  16000 383		 16000 383  5000  -67 9.2 % 07/2021  16000  16000 10/2022				
—	08/09/2021	Service	169830 Km			20736 Daeninck Latem , St. Martens Latem	Automatic
	 16000 09/2022  16000 09/2022  16000 09/2022		 16000 09/2022  5000  16000 07/2021 ✓  16000  16000 09/2022				
—	12/10/2020	Key	154578 Km			20736	Key 0




— 12/10/2020 Service 154578 Km 20736 Automatic
Daeninck
Latem , St.
Martens Latem




— 08/04/2020 Key 146731 Km 32610 Key 0



— 03/07/2019 Key 120695 Km 20736 Key 0



— 03/07/2019 Service 120695 Km 20736 Automatic
Daeninck
Latem , St.
Martens Latem



— 03/07/2019 Repair 120695 Km 20736 Job
Daeninck
Latem , St.
Martens Latem

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service standaard omvang
Package I 0000105

Service - standard scope
Flat rate unit I 00 00 105

2

Service luchtfilterelement
Package I 0000602

Service - air filter element
Flat rate unit I 00 00 602

1

Air filter element

1

Service brandstoffilter
Package I 0000604

Service fuel filter	5
Flat rate unit I 00 00 604	
Fuel filter cartridge	1
Part I 13327811227	
Hose clamp	1
Part I 16121180240	

Service motorolie
Package I 0000610

Engine oil service	3
Flat rate unit I 00 00 610	
Set oil-filter element	1
Part I 11428575211	
BMW Engine Oil LL04 5W30	5
Part I 83212405948	

Service remsysteem, voor
Package I 0000612

Service, front brakes	7
Flat rate unit I 00 00 612	
Repair kit, brake pads asbestos-free	1
Part I 34116858047	
Brake pad wear sensor, front left	1
Part I 34356791958	
Brake cleaner acetone-free	1
Part I 83192413695	
Brake-pad paste	2
Part I 83192158851	

Service remsysteem, achter
Package I 0000614

Service, rear brakes	8
Flat rate unit I 00 00 614	
Repair kit, brake pads asbestos-free	1
Part I 34216862202	
Brake-pad sensor, rear	1
Part I 34356791963	
Brake cleaner acetone-free	1
Part I 83192413695	
Brake-pad paste	2
Part I 83192158851	

Service microfilter
Package I 0000616

Microfilter service	3
Flat rate unit I 00 00 616	
Set, microfilter/carbon canister	1
Part I 64119272642	


Service remvloeistof
Package I 0000618

Brake fluid service	4
Flat rate unit I 00 00 618	
Brake fluid DOT4 LV, low viscosity	1
Part I 83132184843	

Service voertuig-check
Package I 0000624

Service, vehicle check	7
Flat rate unit I 00 00 624	

— 19/11/2018 Key 98177 Km Key 0



— 19/11/2018 Warranty 91776 Km 20736 Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

— Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Description: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler and clean exhaust gas recirculation pipe	25 FRU
Flat rate unit I 00 66 167	

F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler
Defect I 00 11 83 04 00

exhaust cooler	1
Part I 11 71 8 477 659	


EGR small parts set	1
Part I 11 71 8 490 222	

Pipe union	1
Part I 11 71 7 799 853	


— 27/09/2018 Service 91776 Km 32610 Automatic
Daeninck
Oudenaarde ,
Oudenaarde



— 26/09/2018 Key 91776 Km Key 0



— 15/02/2018 Key 67195 Km 20736 Key 0



— 15/02/2018 Warranty 67195 Km 20736 Job: Exhaust gas recirculation valve (EGR)

— Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)

Considered as a repeat visit No

Customer's own words

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery
Flat rate unit I 61 21 528 1 FRU

Performing vehicle test
Flat rate unit I 00 00 006 4 FRU

Vehicle diagnosis - carrying out the ABL
Flat rate unit I 61 00 006 3 FRU

Replacing exhaust gas recirculation valve
Flat rate unit I 11 71 501 6 FRU

Programming/encoding control unit(s) including deleting fault memories
Flat rate unit I 61 00 730 4 FRU

Exhaust gas recirculation valve (EGR)
Defect I 11 71 01 83 00


EGR-valve
Part I 11 71 8 513 132 1

Gasket Steel
Part I 11 71 8 579 364 1


Oval head screw
Part I 35 21 7 685 343 2

Hose clamp
Part I 07 12 9 952 104 2

— 10/01/2018 Service 63285 Km 20736 Automatic
Daeninck Peter
nv Daeninck
Latem , St.
Martens Latem




— 09/01/2018 Key 63285 Km 20736 Key 0



— 09/01/2018 Service 63285 Km 20736 Automatic
Daeninck Peter
nv Daeninck

Latem , St.
Martens Latem



— 21/03/2017 Warranty 28179 Km 20736 Job: Exhaust gas recirculation valve (EGR)
Job

— Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)

Considered as a repeat visit No

Customer's own words

Performing vehicle test 2 FRU
Flat rate unit I 00 00 556

Replacing exhaust gas recirculation valve 6 FRU
Flat rate unit I 11 71 501

Exhaust gas recirculation valve (EGR)
Defect I 11 71 01 83 00

EGR-valve 1
Part I 11 71 8 513 132

— Job


Description:

Considered as a repeat visit No

Customer's own words

Defect I 87 00 05 00 BO

— 20/03/2017 Key 28179 Km 20736 Key 0



— 20/03/2017 Service 28179 Km 20736 Automatic
Daeninck Peter
nv Daeninck
Latem , St.
Martens Latem



— 26/08/2016 Key 5531 Km 20736 Key 0

