

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 330e, 215KW

WBA5X71020FJ65261



Development code

G20

Colour

Tansanitblau II metallic

Actual integration level

S18A-21-07-520

Start of warranty

26 February 2020

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

There are no Campaigns for this vehicle.

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Live 2019-3 (As of: 7 Oct 2024)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 01559912).	Road Map EUROPE Live 2025-2	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	330e
Body	LIM
Vehicle identification number (last 7 digits)	FJ65261
Vehicle identification number (17 digits)	WBA5X71020FJ65261
Development code	G20
Steering	LL
Engine	XB1G
Engine number	F5483639
Exhaust re-treatment	Euro 6 DG
Transmission	AUT
Transmission number	0574488ZBO
Head unit serial number	ALB314L1326384
Drive	HECK
Integration level, works	S18A-19-11-550
Production date	20 Feb 2020
Production plant	Muenchen
Delivery date	26 Mar 2020
Delivering retailer	Fuhrpark, München, DE
National-market version	EUR
Paint code	C3Z
Upholstery code	KGNL
Model code	5X81
Basic type	5X71
Lead type	5X81

Optional equipment


Optional equipment ex works: 01CB CO2 equipment 01CX Sport-Boost 01DE Exhaust emission standards EU6 RDE 01PP 19" light-all.wheel dbl.spk.791M em.op. 0230 Extra package, EU-speciifc	Retrofitted optional equipment: This vehicle has no retrofits.
--	---

0258 Tyres with runflat properties
02NH M Sport brake
02PA Locking wheel bolt
02TB Sport automatic gearbox
02VB Tyre pressure display
02VF Adaptive M chassis
02VL Variable sport steering
0302 Alarm system
0322 Comfort access
03AC Trailer coupling
0403 Glass roof, electrical
0420 Sun protection glazing
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0459 Seat adjustment, electric, with memory
0465 Through-loading system
0481 Sports seat
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04KL Interior trim finisher alum.mesh effect
04NE Blow-by heater
04U9 Acoustic pedestrian protection
04UR Ambient interior light
0534 Automatic air conditioning
0548 Kilometre speedo
05A1 LED Fog lights
05AC High-beam assistant
05AL Active Protection
05AQ Active guard plus
05AU Driving assistant professional
05AZ BMW Laserlicht
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
05DM Parking assistance system
0610 Head-up display
0676 HiFi speaker system
06AE Teleservices
06AF Statutory emergency call
06AG eDrive services
06AK Connected Drive Services
06C4 Connected Package Professional
06NW Telephony with wireless charging
06U3 BMW Live operating area Professional
06U8 BMW gesture control
06WD WLAN Hotspot
0710 M leather steering wheel
0715 M Aerodynamics package
0760 High gloss shadow line
0775 Headlining anthracite
07LF Modell M Sport
07M9 M Shadow Line with expanded scope
07R7 Innovation package
0801 German version
0851 Language version German
0879 On-board literature, German
08EK Dummy-SALAPA
08KA Oil service interval 24 mths / 30,000 km
08R9 Refrigerant R1234yf
08TF Active pedestrian protection
09D6 Fahrerlebnis package de
A080 80 Ah AGM battery

Control unit software version

Vehicle histories

Date	Type	Vehicle mileage	Retailer	Overview
— 07/10/2024	Key	141758 Km	05722	Key 10



07/10/2024 Repair

141758 Km

05722 , Puurs

Job
Job

Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle diagnosis - carrying out the ABL
Flat rate unit I 61 00 006

12 FRU

Job

Description:

Considered as a repeat visit No


Customer's own words

13/09/2024 Key

140480 Km

05722



Remote KeyRead



16/05/2023 Key

97634 Km

Key 10





16/05/2023 Service

97634 Km

05722 Gregoir
Puurs , Puurs-
Sint-Amands



Automatic



30/08/2022 Key

72939 Km

Remote KeyRead




16/05/2022 Key

62306 Km

05722

Key 10



—	22/04/2022	Key	62078 Km	05722	Key 10					
	 -2700 8.7 % 07/2023	 -2700 429	 -2700 429	 -2700 429	 02/2023	 279	 -2700 4.4 % 07/2023	 -2700 4.4 % 07/2023	 -2700 4.4 % 07/2023	 -2700 4.4 % 07/2023
—	22/04/2022	Service	62078 Km	05722 Gregoir Puurs , Puurs-Sint-Amands	Automatic					
	 -2700 06/2023 ✓	 -2700 06/2023 ✓	 -2700 06/2023 ✓	 -2700 06/2023 ✓	 01/2023	 -2700 06/2023 ✓	 -2700 06/2023 ✓	 -2700 06/2023 ✓	 -2700 06/2023 ✓	 -2700 06/2023 ✓
—	08/04/2022	Key	61294 Km	05722	Key 10					
	 -1900 6.1 % 07/2023	 -1900 443	 -1900 443	 -1900 443	 02/2023	 293	 -1900 3.1 % 07/2023	 -1900 3.1 % 07/2023	 -1900 3.1 % 07/2023	 -1900 3.1 % 07/2023
—	04/04/2022	Key	61293 Km	05722	Key 10					
	 -1900 6.1 % 07/2023	 -1900 447	 -1900 447	 -1900 447	 02/2023	 297	 -1900 3.1 % 07/2023	 -1900 3.1 % 07/2023	 -1900 3.1 % 07/2023	 -1900 3.1 % 07/2023
—	22/02/2022	Service	56967 Km	05722 Gregoir Puurs , Puurs-Sint-Amands	Automatic					
	 2000 06/2023 ✓	 2000 06/2023 ✓	 2000 06/2023 ✓	 2000 06/2023 ✓	 01/2023	 2000 06/2023 ✓	 2000 06/2023 ✓	 2000 06/2023 ✓	 2000 06/2023 ✓	 2000 06/2023 ✓
—	14/12/2021	Key	51595 Km	05722	Key 10					
	 7000 07/2023	 7000 557	 7000 557	 7000 557	 02/2023	 7000 07/2023	 7000 07/2023	 7000 07/2023	 7000 07/2023	 7000 07/2023
—	14/12/2021	Warranty	51595 Km	05722	Job: G20 G21 Checking and if necessary reworking front side panel					

— Job: G20 G21 Checking and if necessary reworking front side panel

Description: G20 G21 Checking and if necessary reworking front side panel

Considered as a repeat visit No

Customer's own words

Checking both front side panels, re-attaching both wheel arch covers
Flat rate unit I 00 71 614

3 FRU

G20 G21 Checking and if necessary reworking front side panel
Defect I 00 41 09 02 00

— 30/07/2021 Warranty 17310 Km 05722 Job: Side airbag, rear

— Job: Side airbag, rear

Description: Side airbag, rear

Considered as a repeat visit No

Customer's own words

Performing vehicle test 4 FRU
Flat rate unit I 00 00 006



Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528

Programming/encoding control unit(s) including deleting fault memories 4 FRU
Flat rate unit I 61 00 730



Continuing vehicle test and deleting fault memory 2 FRU
Flat rate unit I 61 00 980

Side airbag, rear
Defect I 65 77 15 81 00



— 29/07/2021 Key 28612 Km Key 10





— 29/07/2021 Service 28612 Km 05722 Gregoir Puurs , Puurs-Sint-Amans Automatic



— 28/07/2021 Key 28612 Km Key 10



— 22/07/2021 Key 28258 Km Key 10



— 28/04/2021 Warranty 17309 Km 05722 Job: Roof functions centre FZD

— Job: Roof functions centre FZD

Description: Roof functions centre FZD

Considered as a repeat visit No

Customer's own words

Performing vehicle test
Flat rate unit I 00 00 006 4 FRU

Replace roof function centre
Flat rate unit I 61 31 544 2 FRU



Programming/encoding control unit(s) including deleting fault memories
Flat rate unit I 61 00 730 4 FRU

Roof functions centre FZD
Defect I 61 31 74 14 00

— 27/04/2021 Key

17309 Km



Key 10



— 20/04/2021 Key

17163 Km



Key 10



— 15/03/2021 Key

13462 Km



Key 10



— 03/02/2021 Key

11822 Km

Key 10






— 30/12/2020 Key

11816 Km

05719

Key 10



— 23/03/2020 Service

8 Km

30982 ISIS/
ITools int.
Kunden Inlan,
Garching

Manual

