

Vehicle Details



BMW 518d, 150 HP



Vehicle identification number
WBA5E31010G041085



Code
F10

 Production date 19 Nov 2015	 Delivery date 24 Nov 2015	 Steering Left Hand Drive	 Basic Type 5E31
 Engine code B47D2000	 Drivetrain Rear Wheel Drive	 Transmission Automatic	 Transmission number 0274550ZQJ
 Body Sedan	 Color Imperialblau Brillanteffekt Metalli (A89)	 Upholstery Leder Dakota/oyster Exklusivnaht(sw (LCOX)	 Factory Tires Michelin

Technical Campaigns

There's no technical campaigns available

Warranty and Service Contracts

This vehicle has no active warranty or service contracts

Restrictions

This vehicle has no restrictions

Optional Equipment

42 Optionals ^


Code	Description
01CA	Selection Of Cop-relevant Vehicles
01CB	Co2 Equipment
01CC	Auto Start/stop Function
01CD	Brake Energy Regeneration
0205	Automatic Transmission
0230	Extra Package, Eu-speciifc
02K1	Bmw La Wheel, V Spoke 236
02PA	Locking Wheel Bolt
02VB	Tyre Pressure Display
0302	Alarm System
0320	Deleted, Model Lettering
03AC	Trailer Coupling
03AG	Reversing Camera
0423	Floor Mats Velours
0430	Interior/outside Mirror With Auto Dip
0431	Interior Mirror With Automatic-dip
0465	Through-loading System


0430	Interior/outside Mirror With Auto Dip
0431	Interior Mirror With Automatic-dip
0465	Through-loading System
0494	Seat Heating Driver/passenger
04AT	Interior Trim Finishers Black High-gloss
04U2	Driving Experience Switch Incl. Eco Pro
0502	Headlight Cleaning System
0508	Park Distance Control (pdc)
0534	Automatic Air Conditioning
0548	Kilometre Speedo
0609	Navigation System Professional
0610	Head-up Display
0698	Area-code 2 For Dvd
06AC	Intelligent Emergency Call
06AE	Teleservices
06WA	Instrument Panel With Extended Scope
0843	Power Reduction
0868	Language Version, Dutch
0877	Omission Of Non-combined Operation
0886	On-board Literature, Dutch
08KA	Oil Service Interval 24 Mths / 30,000 Km
08S3	Automatic Locking During Starting
08TF	Active Pedestrian Protection
08TH	Road Sign Detection
1115	No Description Available
A105	No Description Available
LCOX	Leather Dakota/oyster/exclusive Seam
LEDE	No Description Available

Retrofitted Optional Equipment

This vehicle has no retrofits.

Mileage Overview





Vehicle history

Period: 18 Jan 2016 - 17 Feb 2025 • 26 entries

17 Feb 2025 • Key • All Good 207,240 km ^

Description	State	Due Date	Remaining Service Life
Brake fluid	Not Due	Mar 2025	12 days
Rear brakes	Not Due		5000 km
Statutory vehicle inspection	Not Due	Jan 2026	318 days
Statutory emissions test	Not Due	Jan 2026	318 days
Engine oil	Not Due	Jun 2026	21000 km • 469 days
Vehicle check	Not Due	Jun 2026	21000 km • 469 days
Front Brake	Not Due		20000 km
Fuel filter	Not Due	Jun 2026	21000 km • 469 days
Air filter element	Not Due	Jun 2026	21000 km • 469 days
Microfilter	Not Due	Jun 2026	21000 km • 469 days
Check gas pressure springs for hood	Not Due	Mar 2025	12 days

17 Feb 2025 • Repair • 17 Jobs 207,240 km ^

, LOCHRISTI		
Replace Exhaust Gas Recirculation Cooler, Including Exhaust Gas Recirculation Valve	Work	N/A
Performing Additional Work For Pressure Sensor Functional Check	Work	N/A
Additional Work: Enter Component Identification Of New Exhaust-gas Recirculation Cooler In Diagnostic System	Work	N/A
Additional Work: Clean Egr Pipe	Work	N/A
Exhaust Gas Cooler High Temperature	Part	1 Unit
Agr Small Parts Set	Part	1 Unit
Vacuum Hose Black	Part	1 Unit
Pipe Union	Part	2 Units
Holder	Part	1 Unit
O-ring	Part	1 Unit
Connection Piece	Part	1 Unit
Acoustic Cover Front	Part	1 Unit
Pipe	Part	1 Unit
Antivries 1l	Part	4 Units
Administrative Effort	Work	N/A
Program Control Units	Work	N/A
Unknown Fru: Stuurwiel Controleren (airbagmodule Niet Beïnvloed)	Work	N/A

17 Feb 2025 • Warranty • 19 Jobs 207,240 km ^

Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replace exhaust-gas recirculation cooler (high temp)		
Replace Exhaust-gas Recirculation Cooler, Including Exhaust-gas Recirculation Valve	Work	N/A
Performing Additional Work For Pressure Sensor Functional Check	Work	N/A

Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replace exhaust-gas recirculation cooler (high temp)

◦ Replace Exhaust-gas Recirculation Cooler, Including Exhaust-gas Recirculation Valve	Work	N/A
◦ Performing Additional Work For Pressure Sensor Functional Check	Work	N/A
◦ Additional Work: Enter Component Identification Of New Exhaust-gas Recirculation Cooler In Diagnostic System	Work	N/A
◦ Additional Work: Clean Egr Pipe	Work	N/A
◦ Exhaust Gas Cooler High Temperature	Part	⊕ 1 Unit
◦ Agr Small Parts Set	Part	⊕ 1 Unit
◦ Vacuum Hose Black	Part	⊕ 1 Unit
◦ Pipe Union	Part	⊕ 2 Units
◦ Holder	Part	⊕ 1 Unit
◦ O-ring	Part	⊕ 1 Unit
◦ Connection Piece	Part	⊕ 1 Unit
◦ Acoustic Cover Front	Part	⊕ 1 Unit
◦ F1x F2x F3x G0x G1x G3x B47o B47k B47u B47t Replace Exhaust-gas Recirculation Cooler (high Temp)	Defect	

Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust-gas recirculation cooler

◦ Administrative Outlay	Work	N/A
◦ E84 Fx Gx Bx7 Nx7 Customer Notification Exhaust-gas Recirculation Cooler	Defect	

Job: G0x G3x B47O Program control units (DDE)

◦ Program Control Units	Work	N/A
◦ G0x G3x B47o Program Control Units (dde)	Defect	

Job: Fx Checking driver's airbag and replacing if necessary (SDI conversion)

◦ Check Steering Wheel (airbag Module Not Affected)	Work	N/A
◦ Fx Checking Driver's Airbag And Replacing If Necessary (sdi Conversion)	Defect	

08 Dec 2022 • Warranty •  11 Jobs

174,040 km ^

Job: Front door

◦ Stripping And Refitting Work On Left Or Right Front Door For Painting	Work	N/A
◦ Stripping And Rebuilding Operations For Painting Side Panel, Left Or Right	Work	N/A
◦ Painting The Side Panel, Left Or Right	Work	N/A
◦ Painting The Front Door, Left Or Right	Work	N/A
◦ Stripping And Refitting Work For Painting Doors, Rear Left Or Right	Work	N/A
◦ Painting Stripping And Refitting Work Of Right Rear Side Panel	Work	N/A
◦ Painting The Rear Quarter Panel, Left Or Right	Work	N/A
◦ Painting The Rear Door, Left Or Right	Work	N/A
◦ Channel Cover,exterior,door, Front Left	Part	⊕ 1 Unit
◦ Outer Weatherstrip, Rear Left Door	Part	⊕ 1 Unit
◦ Front Door	Defect	

08 Dec 2022 • Warranty •  9 Jobs

174,040 km ^

Job: Front door

◦ Stripping And Refitting Work On Left Or Right Front Door For Painting	Work	N/A
◦ Stripping And Rebuilding Operations For Painting Side Panel, Left Or Right	Work	N/A
◦ Painting The Side Panel, Left Or Right	Work	N/A
◦ Painting The Front Door, Left Or Right	Work	N/A

◦ Stripping And Rebuilding Operations For Painting Side Panel, Left Or Right	Work	N/A
◦ Painting The Side Panel, Left Or Right	Work	N/A
◦ Painting The Front Door, Left Or Right	Work	N/A
◦ Stripping And Refitting Work For Painting Doors, Rear Left Or Right	Work	N/A
◦ Painting Stripping And Refitting Work Of Right Rear Side Panel	Work	N/A
◦ Painting The Rear Quarter Panel, Left Or Right	Work	N/A
◦ Painting The Rear Door, Left Or Right	Work	N/A
◦ Front Door	Defect	

10 Aug 2022 • Key • ▲ 2

174,040 km ^

Description	State	Due Date	Remaining Service Life
Statutory vehicle inspection	▲ Due	Jan 2021	-579 days
Statutory emissions test	▲ Due	Jan 2021	-579 days
Engine oil	Not Due	Nov 2023	7000 km • 441 days
Vehicle check	Not Due	Nov 2023	7000 km • 441 days
Brake fluid	Not Due	Feb 2023	171 days
Rear brakes	Not Due		45000 km
Front Brake	Not Due		49000 km
Check gas pressure springs for hood	Not Due	Feb 2023	171 days
Fuel filter	Not Due	Nov 2023	7000 km • 441 days
Air filter element	Not Due	Nov 2023	7000 km • 441 days
Microfilter	Not Due	Nov 2023	7000 km • 441 days

09 Feb 2021 • Key • ▲ 1 • ▲ 3

125,800 km ^

Description	State	Due Date	Remaining Service Life
Brake fluid	▲ Due	Dec 2020	-68 days
Statutory vehicle inspection	▲ Due	Jan 2021	-38 days
Statutory emissions test	▲ Due	Jan 2021	-38 days
Front Brake	▲ Due soon		220 km
Rear brakes	Not Due		5000 km
Engine oil	Not Due	Nov 2022	25000 km • 622 days
Air filter element	Not Due		
Fuel filter	Not Due		
Vehicle check	Not Due		60000 km • 1342 days
Microfilter	Not Due		25000 km • 622 days

11 Jan 2021 • Key • ▲ 3 • ▲ 1

123,740 km ^

Description	State	Due Date	Remaining Service Life
Brake fluid	▲ Due	Dec 2020	-38 days
Front Brake	▲ Due soon		1500 km
Statutory vehicle inspection	▲ Due soon	Jan 2021	-8 days
Statutory emissions test	▲ Due soon	Jan 2021	-8 days
Rear brakes	Not Due		5000 km
Engine oil	Not Due	Nov 2022	28000 km • 652 days
Air filter element	Not Due		
Fuel filter	Not Due		
Vehicle check	Not Due		60000 km • 1372 days
Microfilter	Not Due		28000 km • 652 days

10 Jun 2020 • Key • ▲ 2

108,490 km ^

Description	State	Due Date	Remaining Service Life
Statutory vehicle inspection	▲ Due	Jan 2020	-159 days

10 Jun 2020 • Key • ▲ 2

108,490 km ^

Description	State	Due Date	Remaining Service Life
Statutory vehicle inspection	▲ Due	Jan 2020	-159 days
Statutory emissions test	▲ Due	Jan 2020	-159 days
Rear brakes	Not Due		5000 km
Brake fluid	Not Due	Dec 2020	171 days
Engine oil	Not Due	Aug 2021	13000 km • 411 days
Vehicle check	Not Due	Aug 2021	13000 km • 411 days
Front Brake	Not Due		24000 km
Fuel filter	Not Due		13000 km • 411 days
Air filter element	Not Due		13000 km • 411 days
Microfilter	Not Due		13000 km • 411 days

10 Jun 2020 • Service • ✓ 2

108,490 km ^

Gregoir Jette , Brussel

Description	State	Due Date	Remaining Service Life	Done
Engine oil	Not Due	Jul 2021	13000 km • 411 days	
Front Brake	Not Due		24000 km	
Brake fluid	Not Due	Nov 2020	171 days	
Rear brakes	Not Due		5000 km	
Fuel filter	Not Due	Jul 2021	13000 km • 411 days	
Statutory vehicle inspection	▲ Due	Jan 2020	-159 days	✓
Statutory emissions test	▲ Due	Jan 2020	-159 days	✓
Air filter element	Not Due	Jul 2021	13000 km • 411 days	
Vehicle check	Not Due	Jul 2021	13000 km • 411 days	
Microfilter	Not Due	Jul 2021	13000 km • 411 days	

10 Jun 2020 • Repair • 2 Jobs

108,490 km ^

Gregoir Jette , Brussel

!!! Unknown Bmw-id Estimate Transférer Le Carnet D'entretien Électronique Dans Le Véhicule Via Icom !!!	Work	N/A
§ Emission Test With On-board Diagnosis	Work	N/A

05 Aug 2019 • Key • ▲ 2

90,130 km ^

Description	State	Due Date	Remaining Service Life
Engine oil	▲ Due	Apr 2020	-2600 km • 236 days
Air filter element	Not Due		
Fuel filter	Not Due		
Statutory vehicle inspection	Not Due	Jan 2020	146 days
Statutory emissions test	Not Due	Jan 2020	146 days
Rear brakes	Not Due		17000 km
Vehicle check	Not Due	Apr 2022	29000 km • 956 days
Front Brake	Not Due		33000 km
Brake fluid	Not Due	Dec 2020	476 days
Microfilter	▲ Due		-2600 km • 236 days

05 Aug 2019 • Service • ✓ 2

85,510 km ^

De Mey , Maldegem

Description	State	Due Date	Remaining Service Life	Done
Engine oil	▲ Due soon	Mar 2020	1900 km • 234 days	✓
Front Brake	Not Due		36000 km	
Brake fluid	Not Due	Nov 2020	474 days	
Rear brakes	Not Due		20000 km	
Fuel filter	Not Due			

Front Brake	Not Due		36000 km	
Brake fluid	Not Due	Nov 2020	474 days	
Rear brakes	Not Due		20000 km	
Fuel filter	Not Due			
Statutory vehicle inspection	Not Due	Dec 2019	144 days	
Statutory emissions test	Not Due	Dec 2019	144 days	
Air filter element	Not Due			
Vehicle check	Not Due	Mar 2022	33000 km • 954 days	
Microfilter	⚠ Due soon	Mar 2020	1900 km • 234 days	✓

05 Aug 2019 • Repair • 🛠 1 Job

90,130 km ^

📍 De Mey Maldegem , Maldegem

Technische Acties: 10011830400 Uitvoeren: B47o Uitlaatgasrecirculatiekoeler Vervangen (groep A)	Work	N/A
---	------	-----

05 Aug 2019 • Warranty • 🛠 6 Jobs

90,130 km ^

Job: F10 F11 F25 F26 F31 F34 F36 B47O Replace exhaust-gas recirculation cooler

Additional Work, Check Egr Cooler Label	Work	N/A
Replace Exhaust-gas Recirculation Cooler And Replace Or Remount Exhaust-gas Recirculation Valve; Clean Exhaust-gas Recirculation Pipe	Work	N/A
Exhaust Cooler	Part	🔧 1 Unit
Pipe Union	Part	🔧 2 Units
Hose Clamp	Part	🔧 2 Units
F10 F11 F25 F26 F31 F34 F36 B47o Replace Exhaust-gas Recirculation Cooler	Defect	

24 Dec 2018 • Key • 🔴 1

75,110 km ^

Description	State	Due Date	Remaining Service Life
Brake fluid	🔴 Due	Nov 2018	-53 days
Engine oil	Not Due	Apr 2020	13000 km • 457 days
Air filter element	Not Due		
Fuel filter	Not Due		
Statutory vehicle inspection	Not Due	Jan 2020	367 days
Statutory emissions test	Not Due	Jan 2020	367 days
Rear brakes	Not Due		28000 km
Front Brake	Not Due		43000 km
Vehicle check	Not Due	Apr 2022	44000 km • 1177 days
Microfilter	Not Due		13000 km • 457 days

24 Dec 2018 • Service • 🟢 1

75,110 km ^

📍 De Mey , Maldegem

Description	State	Due Date	Remaining Service Life	Done
Engine oil	Not Due	Jan 1970	13000 km • -17889 days	
Front Brake	Not Due	Jan 1970	43000 km • -17889 days	
Brake fluid	🔴 Due	Jan 1970	-17889 days	✓
Rear brakes	Not Due	Jan 1970	28000 km • -17889 days	
Fuel filter	Not Due	Jan 1970	-17889 days	
Statutory vehicle inspection	Not Due	Jan 1970	-17889 days	
Statutory emissions test	Not Due	Jan 1970	-17889 days	
Air filter element	Not Due	Jan 1970	-17889 days	
Vehicle check	Not Due	Jan 1970	44000 km • -17889 days	
Microfilter	Not Due	Mar 2020	13000 km • 457 days	

03 Apr 2018 • Key • 🔴 5

57,710 km ^

Description	State	Due Date	Remaining Service Life
-------------	-------	----------	------------------------

Microfilter	Not Due	Mar 2020	13000 km • 457 days	
-------------	---------	----------	---------------------	--

03 Apr 2018 • Key • 5

57,710 km ^

Description	State	Due Date	Remaining Service Life
Engine oil	Due soon	Feb 2019	700 km • 298 days
Vehicle check	Due soon	Feb 2019	700 km • 298 days
Fuel filter	Due soon		700 km • 298 days
Air filter element	Due soon		700 km • 298 days
Microfilter	Due soon		700 km • 298 days
Front Brake	Not Due		5000 km
Rear brakes	Not Due		5000 km
Brake fluid	Not Due	Nov 2018	208 days
Statutory vehicle inspection	Not Due	Jan 2020	628 days
Statutory emissions test	Not Due	Jan 2020	628 days

03 Apr 2018 • Service • 6

57,710 km ^

De Mey , Maldegem

Description	State	Due Date	Remaining Service Life	Done
Engine oil	Due soon	Jan 1970	700 km • -17624 days	
Front Brake	Not Due	Jan 1970	5000 km • -17624 days	
Brake fluid	Not Due	Jan 1970	-17624 days	
Rear brakes	Not Due	Jan 1970	5000 km • -17624 days	
Fuel filter	Due soon	Jan 2019	700 km • 298 days	
Statutory vehicle inspection	Not Due	Jan 1970	-17624 days	
Statutory emissions test	Not Due	Jan 1970	-17624 days	
Air filter element	Due soon	Jan 2019	700 km • 298 days	
Vehicle check	Due soon	Jan 1970	700 km • -17624 days	
Microfilter	Due soon	Jan 2019	700 km • 298 days	

03 Apr 2018 • Repair • 1 Job

57,710 km ^

De Mey Maldegem , Maldegem

!!! Unknown Bmw-id Estimate Onderhoudshistorie Door Middel Van Icom Naar Het Motorvoertuig Overdragen !!!	Work	N/A
---	------	-----

03 Apr 2018 • Repair • 1 Job

57,710 km ^

De Mey Maldegem , Maldegem

!!! Unknown Bmw-id Estimate Tc_ !!!	Work	N/A
-------------------------------------	------	-----

03 Apr 2018 • Warranty • 2 Jobs

57,710 km ^

Job: F1x F2x F3x B47 Program control unit, replace exhaust-gas recirculation valve if necessary

Operating Test Module And Programming Control Unit	Work	N/A
F1x F2x F3x B47 Program Control Unit, Replace Exhaust-gas Recirculation Valve If Necessary	Defect	

08 Feb 2017 • Key • 2

30,010 km ^

Description	State	Due Date	Remaining Service Life
Engine oil	Due soon	Nov 2017	450 km • 294 days
Air filter element	Not Due		
Fuel filter	Not Due		
Front Brake	Not Due		5000 km
Rear brakes	Not Due		19000 km
Vehicle check	Not Due	Nov 2019	32000 km • 1024 days
Brake fluid	Not Due	Nov 2018	659 days
Statutory vehicle inspection	Not Due	Jan 2020	1086 days
Statutory emissions test	Not Due	Jan 2020	1086 days

Brake fluid	Not Due	Nov 2018	659 days
Statutory vehicle inspection	Not Due	Jan 2020	1086 days
Statutory emissions test	Not Due	Jan 2020	1086 days
Microfilter	⚠ Due soon		450 km • 294 days

08 Feb 2017 • Service • 2

30,010 km ^

📍 S. De Mey&Zonen nv De Mey , Maldegem

Description	State	Due Date	Remaining Service Life	Done
Engine oil	⚠ Due soon	Nov 2017	450 km • 294 days	✓
Front Brake	Not Due		5000 km	
Brake fluid	Not Due	Nov 2018	659 days	
Rear brakes	Not Due		19000 km	
Fuel filter	Not Due			
Statutory vehicle inspection	Not Due	Jan 2020	1086 days	
Statutory emissions test	Not Due	Jan 2020	1086 days	
Air filter element	Not Due			
Vehicle check	Not Due	Nov 2019	32000 km • 1024 days	
Microfilter	⚠ Due soon	Nov 2017	450 km • 294 days	✓

08 Feb 2017 • Repair • 2 Jobs

30,010 km ^

📍 De Mey Maldegem , Maldegem

◦ Laadwens Van De Klant: Full	Work	N/A
◦ Initiële Laadtoestand Hoog-voltage Accu (soc): 255%	Work	N/A

18 Jan 2016 • Key • All Good

540 km ^

Description	State	Due Date	Remaining Service Life
Engine oil	Not Due	Nov 2017	29000 km • 681 days
Air filter element	Not Due		
Fuel filter	Not Due		
Front Brake	Not Due		48000 km
Rear brakes	Not Due		50000 km
Vehicle check	Not Due	Nov 2019	60000 km • 1411 days
Brake fluid	Not Due	Nov 2018	1046 days
Statutory vehicle inspection	Not Due	Jan 2020	1473 days
Statutory emissions test	Not Due	Jan 2020	1473 days
Microfilter	Not Due		29000 km • 681 days

19 Nov 2015 • Produced in Dingolfing

This Report is provided for informational purposes only on an "as-is" basis. All data originates from independent third-party providers; CheckVIN does not access BMW/MINI/Rolls-Royce internal databases and does not verify, update, or guarantee the accuracy or completeness of any information. Data may be incomplete, approximate, outdated, missing, or contain errors.

This is not an official manufacturer or dealer document and does not replace a professional inspection. Any decisions made using this Report are solely at the User's risk.

BMW, MINI, and Rolls-Royce are registered trademarks of BMW AG. CheckVIN is not affiliated with, endorsed by, or authorized by BMW AG.

By viewing this Report, the User accepts these limitations and releases CheckVIN from liability arising from the use of this information.