

Vehicle

BMW 520d xDrive, 140kW

WBA5E71080GZ93461



Development code	F10
Color	imperial-blau brillant metallic
Actual integration level	F010-18-11-520
Start of warranty	May 21, 2015

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

⚠ An error has occurred. Please try again later.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Next 2015-2 (as of: Jun 27, 2025)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00A9008F).	Road Map EUROPE WEST Next 2025	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	520d xDrive
Body	LIM
Vehicle identification number (last 7 characters)	GZ93461
Vehicle identification number (17 characters)	WBA5E71080GZ93461
Development code	F10
Steering	LL
Engine	B47O
Engine number	68069226
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0039461XA5
Head unit serial number	HB2068F8040341
Drive	ALLR
Integration level	F010-15-03-503
Production date	Apr 16, 2015
Production works	Dingolfing
Delivery date	Apr 21, 2015
Delivering Retailers	No information
National-market version	EUR
Paint code	A89
Upholstery code	LCEZ
Model code	5E81
Base type	5E71
Lead type	5E81

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 01CC Auto start/stop function
 01CD Brake Energy Regeneration
 0230 Extra package, EU-specific
 0255 Sports leather steering wheel
 02K1 BMW LA wheel, V Spoke 236
 02PA Wheel bolt retainer
 02TE Automatic transmission w/ shift paddles
 02VB Tire pressure display
 0302 Alarm system

Retrofitted optional equipment:

This vehicle has no retrofits.

0320 Deleted, model lettering
 03AG Reversing camera
 0423 Floor mats, velours
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0456 Comfort seat with memory
 0465 Through-loading system
 0488 Lumbar support, driver and passenger
 0494 Seat heating driver/passenger
 04B9 Interior strips, alu, satin-polished
 04U2 Driving experience switch incl. ECO PRO
 04UR Ambient interior lighting
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0524 Adaptive Headlights
 0534 Automatic air conditioning
 0548 Kilometer-calibrated speedometer
 05AC High-beam assistant
 05AG Lane-change warning
 05AL Active Protection
 05AT Driving Assistant Plus
 0609 Navigation system Professional
 0610 Head-up display
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06NS Convenience phone, expanded Smartphone
 06WA Instrument cluster, expanded equipment
 0761 Individual sunshade glazing
 0854 Language version French
 0877 Delete cross-pattern operation
 0881 On-board vehicle literature French
 08KA Oil service interval, 24 mos./30,000 km
 08S3 Automatic locking when driving off
 08TF Active pedestrian protection
 09AA Outer skin protection
 A105 105 AH AGM battery
 LEDE Leather trim

▾ Vehicle histories

Date	Type	Vehicle mileage			Dealer	Overview		
— 06/27/2025	Key	217509 km			b2io50025863	Key 0		
								
30000		30000		100000		5000	30000	
06/2027		06/2027		07/2025	07/2025		06/2027	
— 06/27/2025	Service	217509 km			OSS-50025863 garage carrosserie alpina bv, Antwerpen	Automatic		
								
30000		30000		100000		5000	30000	
06/2027	✓	06/2027	✓	07/2025	07/2025		06/2027	

—	06/20/2025	Key	216803 km	b2io50025863	Key 0			
								
3400	3400	3400	3400	100000		5000		35000
09/2026	09/2026	09/2026	09/2026		07/2025	07/2025		09/2028
— 06/20/2025 Service						OSS-50025863 garage carrosserie alpina bv, Antwerpen	Automatic	
								
3400	3400	3400	3400	100000		5000		35000
10/2026	10/2026	10/2026	10/2026		08/2025	08/2025		10/2028
✓								
—	06/11/2025	Key	215882 km	05721	Key 0			
								
4400	4400	4400	4400	100000		5000		36000
09/2026	09/2026	09/2026	09/2026		07/2025	07/2025		09/2028
—	05/30/2025	Key	214552 km	05719	Key 0			
								
6000	6000	6000	6000	100000		5000		37000
09/2026	09/2026	09/2026	09/2026		07/2025	07/2025		09/2028
—	05/26/2025	Key	214076 km	05721	Key 0			
								
7000	7000	7000	7000	100000		5000		38000
09/2026	09/2026	09/2026	09/2026		07/2025	07/2025		09/2028
—	05/22/2025	Key	213721 km	05721	Key 0			
								
7000	7000	7000	7000	100000		5000		38000
09/2026	09/2026	09/2026	09/2026		07/2025	07/2025		09/2028
—	03/06/2025	Repair	205469 km	05721 , MERKSEM (ANTWERPEN)	Job			
— Job								

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing or replacing front stabilizer Flat rate unit 31 35 500	9 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit 61 21 528	2 FRU
Work time without specification/front axle Flat rate unit 31 99 000	9 FRU
Stabilizer front with rubber mounting Part 31 35 6 852 854	1
Hex nut wiht flange Part 37 10 6 789 678	2
Covering plate Part 31 35 6 777 642	2
Stabilizer support Part 31 35 6 775 444	2
Torx bolt, self-threading Part 31 30 6 778 221	2
Torx bolt, self-threading Part 31 30 6 778 220	2

—	02/17/2025	Key	205468 km	05721	Key 0						
											
16000	16000	16000	16000	1600			5000	47000			
09/2026	09/2026	09/2026	09/2026		07/2025	07/2025		09/2028			
—	02/17/2025	Service	205468 km	05721 Jorssen Noord, Merksem	Manual						
											
16000	16000	16000	16000	1600			5000	47000			
09/2026	09/2026	09/2026	09/2026		07/2025	07/2025		09/2028			
—	02/17/2025	Repair	205468 km	05721 , MERKSEM (ANTWERPEN)	Job Job Job Job Job						
— Job											

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit 00 00 105	2 FRU
Controle vloeistoffen	Local 2 FRU

Flat rate unit I 01 00 000

Koelvloeistof HT12 Part I WS10	Local	0
Ruitensproeier Vloeistof Part I WS17	Local	3

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes
Flat rate unit I 00 00 612 7 FRU

Perform brake test on test stand
Flat rate unit I 34 00 509 3 FRU

Brake pad paste
Part I 83 19 2 158 851 2

Brake cleaner, acetone-free
Part I 83 19 2 413 695 1

Repair kit, brake pads
Part I 34 11 8 847 064 1

Brake pad wear sensor, front left
Part I 34 35 6 791 958 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

unknown fru: Stuurwiel controleren (airbagmodule nietbeïnvloed)
Flat rate unit I 00 76 854 Local 1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

								
17000	17000	17000	17000	2500			5000	48000
09/2026	09/2026	09/2026	09/2026		07/2025	07/2025		09/2028

— 11/25/2024 Key 198411 km 05721 Key 0

								
23000	23000	23000	23000	6000			5000	60000
09/2026	09/2026	09/2026	09/2026		07/2025	07/2025		09/2028

— 11/04/2024 Repair 198411 km 05721 ,
MERKSEM
(ANTWERPEN) Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing left or right output shaft 34 FRU
Flat rate unit I 31 60 000

Proefrit / eindcontrole Local 4 FRU
Flat rate unit I 01 00 004

Output shaft left 1
Part I 31 60 7 618 681

Repair kit output radial shaft seal 1
Part I 31 50 8 860 349

Collar screw with spring 1
Part I 31 20 6 795 249

Hex nut wiht flange 2
Part I 37 10 6 789 678

Hexagon screw with flange 1
Part I 07 11 9 906 495

Self-locking collar nut 1
Part I 33 30 6 760 349

Hexagon nut with collar 1
Part I 07 14 6 875 114

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Werkuren Local 36 FRU
Flat rate unit I -

Repair kit bellows, interior 1

Collar screw with spring
Part I 31 20 6 795 249 1

Combination nut
Part I 31 10 6 765 451 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 09/11/2024 Key 191103 km 05721 Key 0

								
30000	30000	30000	30000	11000			8000	60000
09/2026	09/2026	09/2026	09/2026		07/2025	07/2025		09/2028

— 09/04/2024 Key 190461 km 05721 Key 0

								
1500		1500		12000			9000	1500
10/2025		10/2025			07/2025	07/2025		10/2025

— 09/04/2024 Service 190461 km 05721 Jorssen Noord, Merksem Manual

											
1500		1500		12000			9000	1500			
10/2025		10/2025			07/2025	07/2025		10/2025			
✓		✓						✓			

— 08/28/2024 Key 190119 km 05721 Key 0

								
2200		2200		12000			9000	2200
10/2025		10/2025			07/2025	07/2025		10/2025

— 08/12/2024 Repair 190461 km 05721 , MERKSEM (ANTWERPEN) Job
Job
Job
Job
Job

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Standard scope of service 2 FRU

Flat rate unit I 00 00 105

Engine oil service 3 FRU

Flat rate unit I 00 00 610

Set oil-filter element 1

Part I 11 42 8 575 211

BMW Engine Oil LL04 0W30 5

Part I 83 21 2 405 950

Battery 1

Part I 66 12 6 912 985

Ruitensproeier Vloeistof Local 2

Part I WS17

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter 3 FRU

Flat rate unit I 00 00 616

Set, microfilter/activ. charcoal filter 1

Part I 64 11 9 272 642

Vehicle interior filt..f.housing cleaner 1

Part I 83 19 2 451 455

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check service 7 FRU

Flat rate unit I 00 00 624

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

— Job

Description:**Is interpreted as a repeat visit:** No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	07/24/2024	Repair	190119 km	05721 , MERKSEM (ANTWERPEN)	Job Job Job Job Job Job Job
---	------------	--------	-----------	-----------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Proefrit Flat rate unit I 01 00 004	Local	4 FRU
Localizing body complaint(s) Flat rate unit I 51 00 001		8 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 07/03/2024 Key 185160 km 05721 Key 0

								
7000		7000		16000			13000	7000
10/2025		10/2025			07/2025	07/2025		10/2025

— 06/26/2024 Key 184351 km 05721 Key 0

								
8000		8000		16000			13000	8000
10/2025		10/2025			07/2025	07/2025		10/2025

— 06/21/2024 Key 183958 km 05721 Key 0

								
9000		9000		17000			14000	9000
10/2025		10/2025			07/2025	07/2025		10/2025

— 06/21/2024 Repair 184351 km 05721 ,
MERKSEM
(ANTWERPEN) Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing bellows both output shafts 20 FRU
Flat rate unit I 31 60 540

Removing and installing/replacing both output shafts 28 FRU
Flat rate unit I 31 60 005

Replacing one output shaft bellows 8 FRU
Flat rate unit I 31 60 530

Kinematics Diagnosis System wheel alignment with vehicle load up to design position 18 FRU

Flat rate unit | 32 00 150

flens	Local	16 FRU
Flat rate unit -		
Grease 'One Lube Improved'		2
Part 83 23 2 179 708		
Repair kit bellows, exterior		1
Part 31 60 7 606 091		
Lubricat.mat.Optitemp 2 LN 584 LO		2
Part 83 19 0 447 919		
Output shaft right		1
Part 31 60 7 618 680		
Repair kit output radial shaft seal		2
Part 31 50 8 860 349		
Collar screw with spring		2
Part 31 20 6 795 249		
Hex nut wiht flange		4
Part 37 10 6 789 678		
Hex bolt		2
Part 33 17 6 760 342		
Self-locking collar nut		4
Part 33 30 6 760 349		
Hexagon screw with flange		2
Part 07 11 9 906 495		
Combination nut		2
Part 33 30 6 787 062		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	06/21/2024	Repair	183958 km	05721 , MERKSEM (ANTWERPEN)	Job Job
---	------------	--------	-----------	-----------------------------------	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Troubleshooting

Flat rate unit I 12 00 009

15 FRU











— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 03/21/2024 Key 176166 km 05719 Key 0



— 03/21/2024 Repair 176166 km 05719 , SINT-NIKLAAS Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Administrative effort

Flat rate unit I 00 74 758

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace exhaust-gas recirculation cooler, including exhaust-gas
recirculation valve

Flat rate unit I 00 72 377

22 FRU

Performing additional work for pressure sensor functional check	3 FRU
Flat rate unit I 00 73 500	

Additional work: enter component identification of new exhaust-gas recirculation cooler in diagnostic system	1 FRU
Flat rate unit I 00 73 501	

Additional work: clean EGR pipe	6 FRU
Flat rate unit I 00 73 502	

Exhaust gas cooler high temperature	1
Part I 11 71 7 822 347	

Holder	1
Part I 61 13 1 369 832	

Connection piece	1
Part I 11 65 7 803 012	

O-ring	1
Part I 11 61 8 512 681	

Acoustic cover front	1
Part I 11 14 8 490 575	

AGR small parts set	1
Part I 11 71 8 490 640	

Pipe union	2
Part I 11 71 7 799 853	

Vacuum hose black	1
Part I 11 65 8 595 650	

Vacuum hose black	-1
Part I 11 65 8 595 650	

ANTIGEL 1L	Local	5
Part I ANTI		

BMW Natural Air starter kit	1
Part I 83125A7DC77	

Verhuur Mini 2EWF073 (21/03-26/03)	Local	1
Part I VERHUUR MIN		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Verhuur Mini 2EWF073 (21/03-26/03)	Local	5
Part I VERHUUR MIN		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing coolant hose	1 FRU
Flat rate unit I 11 53 770	

Bleed the cooling system and check it for watertightness with the special tool

4 FRU

Flat rate unit I 17 00 539

Pipe cylinder head

1

Part I 11 53 8 514 456

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:


— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:

— 10/20/2023 Key 162249 km 05719 Key 0



— 10/18/2023 Key 162219 km 05719 Key 0



— 10/18/2023 Service 162219 km 05719 De Schepper , St. Niklaas Automatic

								
-700	-700	-700	-700	36000			34000	31000
11/2024	11/2024	11/2024	11/2024		07/2025	07/2025		11/2026
✓	✓	✓	✓					

— 09/18/2023 Key 159209 km 05719 Key 0

								
2300	2300	2300	2300	38000			36000	34000
11/2024	11/2024	11/2024	11/2024	11/2024		07/2025		11/2026

— 07/19/2023 Key 153546 km Key 0

								
8000	8000	8000	8000	42000			41000	39000
11/2024	11/2024	11/2024	11/2024	11/2024		-18 2.5 %	-18 2.5 %	11/2026

— 07/19/2023 Service 153546 km 05719 De Schepper , St. Niklaas Automatic

								
8000	8000	8000	8000	42000			41000	39000
11/2024	11/2024	11/2024	11/2024	11/2024		07/2023	07/2023	11/2026
					✓	✓		

— 05/05/2023 Key 146192 km Key 0

								
16000	16000	16000	16000	48000			46000	47000
11/2024	11/2024	11/2024	11/2024	11/2024		07/2023		11/2026

— 03/10/2023 Key 141430 km Key 0

								
21000	21000	21000	21000	60000			1600	60000
11/2024	11/2024	11/2024	11/2024	11/2024		07/2023		11/2026

— 03/10/2023 Service 141430 km 05719 De Schepper , St. Niklaas Automatic

								
21000	21000	21000	21000	60000			1600	60000
11/2024	11/2024	11/2024	11/2024	11/2024		07/2023		11/2026
							✓	

— 02/13/2023 Key 139095 km Key 0

								
23000	23000	23000	23000	60000			60000	60000
11/2024	11/2024	11/2024	11/2024		07/2023	07/2023		11/2026

— 11/02/2022 Key 130537 km 05719 Key 0

								
6000		6000		70000			60000	6000
02/2024		02/2024			07/2023	07/2023		02/2024

— 11/02/2022 Service 130537 km 05719 De Schepper , St. Niklaas Automatic

								
6000		6000		70000			60000	6000
01/2024		01/2024			06/2023	06/2023		01/2024
✓		✓						✓

— 07/19/2022 Key 119791 km Key 0

								
16000		16000		70000			70000	16000
02/2024		552			07/2023	342		02/2024

— 07/02/2022 Key 118199 km 05719 Key 0

								
18000		18000		70000			70000	18000
02/2024		569			07/2023	359		02/2024

— 06/29/2022 Key 117977 km 05719 Key 0

								
18000		18000		70000			70000	18000
02/2024		572			07/2023	362		02/2024

— 02/15/2022 Key 104770 km 05719 Key 0

								
12000	12000	12000	12000	70000			70000	43000
07/2023	496	496	496		07/2023	496		1216

— 02/15/2022 Service 104770 km 05719 De Schepper , St. Niklaas Automatic

								
12000	12000	12000	12000	70000	70000	70000	43000	
06/2023	06/2023	06/2023	06/2023		06/2023		06/2025	
✓								

— 11/08/2021 Key 95293 km Key 0

								
21000	21000	21000	21000	70000	70000	70000	50000	
07/2023	593	593	593		07/2023		1313	

— 10/08/2021 Key 91937 km Key 0

								
24000	24000	24000	24000	5000		5000	60000	
07/2023	623	623	623		07/2023		1343	

— 10/08/2021 Service 91937 km 05719 De Schepper , St. Niklaas Manual

										
					✓					

— 09/02/2021 Key 90896 km Key 0

								
26000	26000	26000	26000	5000		5000	60000	
07/2023	660	660	660		07/2023		1380	

— 08/23/2021 Key 89983 km Key 0

								
27000	27000	27000	27000	5000		5000	60000	
07/2023	668	668	668		07/2023		1388	

— 07/27/2021 Key 86797 km Key 0

								
30000	30000	30000	30000	5000		5000	60000	
07/2023	694	694	694		07/2023		1414	

— 03/15/2021 Key 74607 km Key 0

								
21000		21000		5000	11/2022	13000		60000
11/2022		586						1306

— 03/15/2021 Repair 74607 km 05719 De Schepper , St. Niklaas Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

ADBLUE 1L Local 15
Part I ADBLUE 1L

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 10/01/2020 Key 62049 km 10028 Key 0

								
4400	4400	4400	4400	5000		21000	4400	
07/2021	270	270	270		07/2021		07/2021	

— 05/18/2020 Key 53574 km 05719 Key 0

								
14000	14000	14000	14000	9000		25000	14000	
07/2021	403	403	403		07/2021		07/2021	

— 05/18/2020 Repair 53574 km 05719 De Schepper , St. Niklaas Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Extra werk AdBlue vullen
Flat rate unit I -

Local

2 FRU

ADBLUE 1L
Part I ADBLUE 1L

Local







13.5

— 09/02/2019 Key

41085 km

10028

Key 0









— 08/13/2019 Key

39881 km

10028

Remote KeyRead






— 07/09/2019 Key

38718 km

10028

Key 0







— 07/09/2019 Service

38718 km

10028 G&A
Motors ,
Turnhout

Automatic



— 07/09/2019 Repair

38718 km

10028 G & A
Motors ,
Turnhout

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Onderhoudshistorie door middel van ICOM naar het motorvoertuig overdragen !!!
Flat rate unit I -

Service standaard omvang

Package I 0000105

Standard scope of service 2
Flat rate unit I 00 00 105

Service motorolie

Package I 0000610

Engine oil service 3
Flat rate unit I 00 00 610

Set oil-filter element 1
Part I 11428575211

BMW Engine Oil LL04 5W30 5
Part I 83212405948

Service microfilter

Package I 0000616

Service - microfilter 3
Flat rate unit I 00 00 616

Set, microfilter/activ. charcoal filter 1
Part I 64119272642


Service remvloeistof

Package I 0000618


Brake fluid service 4
Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity 1
Part I 83132184843

— 02/20/2019 Key 37268 km Key 0



— 01/16/2019 Key 35646 km 05620 Key 0



— 01/16/2019 Service 35646 km 05620 BMW Automatic
Brussels ,
Brussel-Evere

							
6000	6000	6000	6000	6000	6000	21000	6000
11/2018	11/2018	11/2018	11/2018		05/2020		11/2018
✓	✓	✓	✓				✓

—	01/16/2019	Repair	35646 km	05620 BMW Brussels , Evere	Job
---	------------	--------	----------	----------------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Assez haute fréquence de passage à l'atelier. Réparation répétée?
Veuillez vérifier l'historique de réparation.
Flat rate unit | -

Local

0 FRU

Charge souhaitée par le client : Full
Flat rate unit | -

Local

0 FRU

Niveau de charge initial haute tension (SoC) : 255%
Flat rate unit | -

Local

0 FRU

Standard scope of service
Package | 0000105

Standard scope of service
Flat rate unit | 00 00 105

2

Service - air filter insert
Package | 0000602

Service - air filter insert
Flat rate unit | 00 00 602

1

Air filter element
Part | 13718570043

1

Fuel filter service
Package | 0000604

Fuel filter service
Flat rate unit | 00 00 604

5

Fuel filter cartridge
Part | 13327811227

1

Hose clamp
Part | 16121180240

1

Engine oil service
Package | 0000610

Engine oil service
Flat rate unit | 00 00 610

3

Set oil-filter element
Part | 11428575211

1

BMW Engine Oil LL04 5W30
Part | 83212405948

5

Service - microfilter
Package I 0000616

Service - microfilter	3
Flat rate unit I 00 00 616	
Set, microfilter/activ. charcoal filter	1
Part I 64119272642	

Vehicle check service
Package I 0000624

Vehicle check service	7
Flat rate unit I 00 00 624	

—	05/09/2018	Key	29067 km	05620	Key 0		
							
15000	15000	15000	15000	10000	0	25000	15000
11/2018	205	205	205		-9 1.2 %		11/2018

—	05/09/2018	Service	29067 km	05620 BMW Brussels , Brussel-Evere	Automatic		
							
15000	15000	15000	15000	10000		25000	15000
11/2018	11/2018	11/2018	11/2018		04/2018 ✓		11/2018

—	05/09/2018	Repair	29067 km	05620 BMW Brussels , Evere	Job
---	------------	--------	----------	----------------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Assez haute fréquence de passage à l'atelier. Réparation répétée? Veuillez vérifier l'historique de réparation.	Local	0 FRU
Flat rate unit I -		

Charge souhaitée par le client : Full	Local	0 FRU
Flat rate unit I -		

Niveau de charge initial haute tension (SoC) : 255%	Local	0 FRU
Flat rate unit I -		

Standard scope of service
Package I 0000105

Standard scope of service	2
Flat rate unit I 00 00 105	

Brake fluid service
Package I 0000618

Brake fluid service
Flat rate unit I 00 00 618

4

Brake fluid DOT4 LV, low viscosity
Part I 83132184843

1

— 10/26/2017 Key 23919 km 05620 Key 0

							
19000	19000	19000	19000	12000	0	27000	19000
11/2018	400	400	400		04/2018		11/2018

— 09/26/2017 Key 22324 km 05620 Key 0

							
21000	21000	21000	21000	12000	0	27000	21000
11/2018	429	429	429		04/2018		11/2018

— 03/28/2017 Key 17985 km 05620 Key 0

							
28000	28000	28000	28000	15000	0	31000	28000
11/2018	611	611	611		04/2018		11/2018

— 03/28/2017 Repair 17985 km 05620 BMW Brussels , Evere Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Charge souhaitée par le client : Full Local 0 FRU
Flat rate unit I -

Niveau de charge initial haute tension (SoC) : 255% Local 0 FRU
Flat rate unit I -

— 11/23/2016 Key 17058 km 05620 Key 0

							
1700	0	1700	0	16000	0	31000	28000
04/2017		157			04/2018		04/2019

— 11/23/2016 Service 17058 km 05620 BMW Brussels Evere/Meiser BMW Brussels Evere/Meiser , Brussel-Evere Automatic

							
1700		1700		16000	04/2018	31000	28000
04/2017		04/2017					04/2019
✓		✓					

— 11/23/2016 Repair 17058 km 05620 BMW Brussels , Evere Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Charge souhaitée par le client : Full Local 0 FRU
Flat rate unit I -

Niveau de charge initial haute tension (SoC) : 255% Local 0 FRU
Flat rate unit I -

Standard scope of service
Package I 0000105

Standard scope of service 2
Flat rate unit I 00 00 105

Engine oil service
Package I 0000610

Engine oil service 3
Flat rate unit I 00 00 610

Set oil-filter element 1
Part I 11428575211

BMW Engine Oil LL04 5W30 5
Part I 83212405948

Service - microfilter
Package I 0000616

Service - microfilter 3
Flat rate unit I 00 00 616

Set, microfilter/activ. charcoal filter 1
Part I 64119272642

Pollen filter housing cleaner 1
Part I 83192180509

— 04/28/2016 Key 10316 km 05620 Key 0

							
11000	0	11000	0	22000	04/2018	37000	36000
04/2017		367					04/2019

— 04/28/2016 Repair 10316 km 05620 BMW Brussels , Evere Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Charge souhaitée par le client : Full Flat rate unit I -	Local	0 FRU
Niveau de charge initial haute tension (SoC) : 255% Flat rate unit I -	Local	0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

F1x F2x F3x F4x B47 Remplacer l'électrovanne de recyclage des gaz d'échappement Flat rate unit I -	Local	5 FRU
--	-------	-------

— 10/26/2015 Key 5905 km 05620 Key 0

 18000 04/2017	 0	 18000 552	 0	 35000	 0 04/2018	 44000	 44000 04/2019
---	--	---	--	--	---	--	--

— 10/26/2015 Repair 5905 km 05620 BMW Brussels ,
Evere Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: