

Vehicle

BMW 318d, 110kW

WBA8C31050A138635



Development code	F30
Color	black-sapphire metallic
Actual integration level	F020-24-07-520
Start of warranty	March 16, 2017

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

⚠ An error has occurred. Please try again later.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2017-1 (as of: Oct 31, 2025)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	318d
Body	LIM
Vehicle identification number (last 7 characters)	A138635
Vehicle identification number (17 characters)	WBA8C31050A138635
Development code	F30
Steering	LL
Engine	B47U
Engine number	74029911
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0812401ZYI
Head unit serial number	MM01DFH2460029
Drive	HECK
Integration level	F020-17-03-502
Production date	Mar 3, 2017
Production works	Muenchen
Delivery date	Mar 8, 2017
Delivering Retailers	Niederlassung Hamburg, Hamburg, DE
National-market version	EUR
Paint code	475
Upholstery code	BDAT
Model code	8C41
Base type	8C31
Lead type	8C41

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 EU-specific additional contents
 0255 Sports leather steering wheel
 0258 Tire with run-flat functionality
 02FH BMW LA wheel, V Spoke 390
 02VB Tire pressure display
 0320 Deleted, model lettering
 0417 Roller sun vizor, rear door

Retrofitted optional equipment:

This vehicle has no retrofits.

0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0465 Through-loading system
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04CG Interior strips, "satin-silber" matt
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometer-calibrated speedometer
0552 Adaptive LED headlight
0563 Light package
0575 Supplementary 12V sockets
05A1 LED Fog lights
05AC High-beam assistant
05AL Active Protection
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
05DP Park Assistant
0606 Navigation system Business
0676 HiFi speaker system
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NH Hands-free with USB interface
06WA Instrument cluster, expanded equipment
07LC Modell Advantage
07S9 Connected Drive Services Paket
0801 National version Germany
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08R9 Refrigerant R1234yf
08TH Road sign detection
0941 Dummy-SALAPA
09AA Outer skin protection
A090 90 AH AGM battery
POLS Cloth cushion

Vehicle histories

Date		Type	Vehicle mileage			Dealer		Overview	
10/31/2025		Key	234479 km			00887		Key 0	
									
15000	15000	15000	15000	37000	-60	5000	15000	-60	
03/2027	03/2027	03/2027	03/2027		8.2 %		03/2027	8.2 %	
10/31/2025		Service	234479 km			00887 Autohaus J. B. Lell e.K. , Schwandorf		Automatic	

								
15000	15000	15000	15000	37000	09/2025	5000	15000	09/2025
03/2027	03/2027	03/2027	03/2027		✓		03/2027	✓

— 10/31/2025 Repair 234484 km 00887 , Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Nach Windschutzscheiben tausch Kamera kalibrieren

Calibrate KAFAS camera
Flat rate unit I 66 51 525

4 FRU

— 10/31/2025 Repair 234483 km 00887 , Job
Job: Service Standardumfang
Job: Service Bremsflüssigkeit
Job: HU/AU
Job: Kostenlose Fzg Reinigung
Job
Job: Beide Zugstreben aus- und
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

AGR Gutschein
Flat rate unit I 99 99 999

Local

-1 FRU

— Job: Service Standardumfang

Description: MKP 0000105 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang
Package I 0000105

Standard scope of service
Flat rate unit I 00 00 105

2

— Job: Service Bremsflüssigkeit

Description: MKP 0000618 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Bremsflüssigkeit
Package I 0000618

Brake fluid service

4

Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity
Part I 83132184843

1

— Job: HU/AU

Description:

Is interpreted as a repeat visit: No

Customer's own words:

HU/AU

Package I MM01HUAU*BM7K31

Gebühren Hauptuntersuchung sind ein durchlaufender Posten im Sinne §10 Absatz 1 UStG
Flat rate unit I MM50 00 0

Local

0

Fzg. zur Hauptuntersuchung vorfahren #TÜV2
Flat rate unit I MM01 40 5

Local

0

Vorführung zur Abgasuntersuchung (AU) #AU2
Flat rate unit I MM01 40 0

Local

7

Gebühren für Hauptuntersuchung (DEKRA)
Flat rate unit I 99 99 999

Local

1

— Job: Kostenlose Fzg Reinigung

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fzg Reinigung

Package I MM02KLREINIG*BM7K31

Fussraum raussaugen (ohne Berechnung)
Part I FTPT7

Local

1

Wagenwäsche in der Waschanlage (ohne Berechnung)
Part I FTPT8

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/integrated suspension systems
Flat rate unit I 37 99 000

3 FRU

Regulating rod
Part I 37 14 6 852 254

1

Control rod, left
Part I 37 14 6 867 535

1

— Job: Beide Zugstreben aus- und

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Beide Zugstreben aus- und
Package I 3112627

Removing and installing or replacing both tension struts Flat rate unit I 31 12 627	10
Combination nut Part I 33306787062	2
Tension strut with hydraulic mount,right Part I 31126855742	1
Hexagon screw with flange Part I 31106885777	2
Tension strut with hydraulic mount, left Part I 31126855741	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing front left or right brake caliper
Flat rate unit I 34 11 519 7 FRU

AZ without specification/maintenance
Flat rate unit I 00 99 000 3 FRU

Bremssattel Local 1
Part I FT99998888014

— Job

Description: ***** Nachziehen der Radschrauben nach 50-100 km
erford. *****

Is interpreted as a repeat visit: No

Customer's own words:

— 10/24/2025 Key 234008 km 33696 Key 0

 16000 03/2027	 16000 03/2027	 16000 03/2027	 16000 03/2027	 -60 0.2 %	 -53 7.3 %	 5000	 16000 03/2027	 -53 7.3 %
---	---	---	---	---	---	---	--	---

— 10/08/2025 Key 233381 km 33696 Key 0

 16000 03/2027	 16000 03/2027	 16000 03/2027	 16000 03/2027	 1200	 -37 5.1 %	 5000	 16000 03/2027	 -37 5.1 %
---	---	---	---	---	---	---	--	---

— 10/08/2025 Repair 233382 km 33696 , Job
Job: Wagenwäsche Waschanlage

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Adjusting headlight
Flat rate unit I 63 10 004 4 FRU

— Job: Wagenwäsche Waschanlage

Description:


Is interpreted as a repeat visit: No

Customer's own words:


Wagenwäsche Waschanlage Local
Package I MM01WAGENWASCH

Wagenwäsche in der Wasch- anlage (ohne Berechnung) Local 0
Flat rate unit I MM01 15 0

— 09/23/2025 Key 232795 km 33696 Remote KeyRead



— 08/08/2024 Key 202840 km 00887 Key 0



— 08/08/2024 Repair 202845 km 00887 , Job

— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:

Program/encode control unit(s), includes deleting the fault memory 4 FRU
Flat rate unit I 61 00 730

Resume vehicle test and clear fault memory 2 FRU
Flat rate unit I 61 00 980

— 02/28/2023 Key 158822 km Key 0



— 02/28/2023 Service 158822 km 33696 Automatic
Autohaus J. B.

Lell
GmbH&Co. KG
, Weiden

 11000	 11000	 11000	 11000	 -430	 ✓	 20000	 11000	
--	--	--	--	---	--	--	---	---

— 02/28/2023 Repair 158824 km 33696 Autohaus J. B. Lell GmbH & Co. KG , Weiden Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs 3 FRU
Flat rate unit I 34 11 613

Service - front brakes 6 FRU
Flat rate unit I 00 00 612

Torx screw with washer 4
Part I 34 10 6 864 424

Brake disc, ventilated 2
Part I 34 11 6 792 217

Repair kit, brake pads asbestos-free 1
Part I 34 11 6 874 331


Inner hex bolt 2
Part I 34 21 1 161 806

Brake pad wear sensor, front left 1
Part I 34 35 6 792 289


Brake pad paste 2
Part I 83 19 2 158 851

Brake cleaner, acetone-free 1
Part I 83 19 2 413 695

— 07/21/2022 Key 139100 km 33696 Key 0



—	07/21/2022	Service	139100 km	33696	Automatic
				Autohaus J. B. Lell GmbH&Co. KG , Weiden	



—	07/21/2022	Repair	139101 km	33696	Job
				Autohaus J. B. Lell GmbH & Co. KG , Weiden	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

BMW Longlife-04 5W30 Total Part I FT99 99 1 000 0	Local	5
--	-------	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

—	11/30/2021	Key	116551 km				Key 0		
									
20000			20000		42000	48000	60000		
08/2023			601		07/2023		1321		07/2023
—	11/25/2021	Key	116503 km				Key 0		
									
20000			20000		42000	48000	60000		
08/2023			606		07/2023		1326		07/2023
—	08/19/2021	Key	104824 km				Key 0		
									
-1100	-1100		-1100		46000	3000	-1100		
08/2022	342		342		07/2023		08/2022		07/2023
—	08/19/2021	Service	104824 km				33696	Automatic	
							Autohaus J. B. Lell GmbH&Co. KG , Weiden		
									
-1100	-1100		-1100	46000	0	3000	-1100		0
✓	✓		✓				✓		
—	08/19/2021	Repair	104827 km				33696	Job	
							Autohaus J. B. Lell GmbH & Co. KG , Weiden		
							Job Job Job Job Job Job Job		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kennz.verstärker tauschen? ja () nein (XX)
Flat rate unit I 00 99 085

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

BMW Longlife-04 5W30 Total	Local	5
Part I FT99 99 1 000 0		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 8 572 522	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

Vehicle interior filt..f.housing cleaner	1
Part I 83 19 2 451 455	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service 6 FRU
Flat rate unit I 00 00 624

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade 1 FRU
Flat rate unit I 61 61 541

Set of wiper blades 1
Part I 61615A43585

— 07/01/2021 Key 97285 km Key 0

									
7000	7000	7000	7000	-2200	0	22000	7000		0
08/2022	426	426	426		07/2021		08/2022		07/2021

— 07/01/2021 Service 97285 km 33696 Automatic
Autohaus J. B.
Lell GmbH &
Co.KG, Weiden

									
7000	7000	7000	7000	-2200	0	22000	7000		0
08/2022	08/2022	08/2022	08/2022		07/2021		08/2022		07/2021

— 07/01/2021 Repair 97287 km 33696 Job
Autohaus J. B. Job
Lell GmbH & Job
Co. KG , Job
Weiden Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kennz.verstärker tauschen? ja () nein (XXX) Local 0 FRU
Flat rate unit I 00 99 085

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Gebühren für Hauptunter- suchung (DEKRA)
Part I FT99 99 8 888 0

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service
Flat rate unit I 00 00 618

4 FRU

Brake fluid DOT4 LV, low viscosity
Part I 83 13 2 184 843

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes
Flat rate unit I 00 00 612

6 FRU

Removing and installing/replacing both front brake discs
Flat rate unit I 34 11 613

3 FRU

Torx screw with washer
Part I 34 10 6 864 424

4

Brake disc, ventilated
Part I 34 11 6 792 217

2

Repair kit, brake pads asbestos-free
Part I 34 11 6 874 331

1

Inner hex bolt
Part I 34 21 1 161 806

2

Brake pad wear sensor, front left
Part I 34 35 6 792 289

1

Brake pad paste
Part I 83 19 2 158 851

2

Brake cleaner, acetone-free
Part I 83 19 2 413 695

1

— 08/24/2020 Key

73154 km

33696

Key 0

 90 07/2021	 0	 90 341	 0	 23000	 0 07/2021	 1600	 32000 07/2023	 0 07/2021
---	---	---	---	---	--	--	---	--

— 08/24/2020 Service 73154 km 33696 Automatic
Autohaus J. B.
Lell GmbH &
Co.KG, Weiden

 90 07/2021 ✓	 0	 90 07/2021 ✓	 0	 23000	 0 07/2021	 1600 ✓	 32000 07/2023	 0 07/2021
---	--	---	--	--	---	--	--	---

— 08/24/2020 Repair 73164 km 33696 Job
Autohaus J. B. Job
Lell GmbH & Job
Co. KG , Job
Weiden Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter 2 FRU
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service 7 FRU
Flat rate unit I 00 00 614

Repair kit, brake pads asbestos-free 1
Part I 34 21 6 873 093

Brake pad wear sensor, rear 1
Part I 34 35 6 792 292

Brake pad paste 2

Brake cleaner, acetone-free
Part I 83 19 2 413 695

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service

3 FRU

Flat rate unit I 00 00 610

BMW Longlife-04 5W30 Total

Local

5

Part I FT99 99 1 000 0

Set oil-filter element

1

Part I 11 42 8 575 211

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Washer fluid, concentrated

1









Part I 83 12 2 298 203

— 02/24/2020 Key

60925 km

33696

Key 0











— 02/14/2020 Key

60370 km

33696

Key 0











— 07/19/2019 Key

42334 km

00887

Key 0












— 07/19/2019 Key

42333 km

00887

Key 0



— 07/16/2019 Key 42311 km 00887 Key 0

								
20000	20000	20000	20000	60000	0	49000	20000	0
02/2020	228	228	228		03/2020		02/2020	04/2020

— 07/16/2019 Service 42311 km 00887 Automatic
Autohaus J. B.
Lell e.K. ,
Schwandorf

								
20000	20000	20000	20000	60000	0	49000	20000	0
02/2020	02/2020	02/2020	02/2020		03/2020		02/2020	04/2020
✓	✓	✓	✓		✓		✓	

— 07/16/2019 Repair 42333 km 00887 Job
Autohaus J. B. Job
Lell e.K. , Job
Schwandorf Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
Flat rate unit I 00 00 610

BMW Longlife-04 5W30 Total Local 5
Part I FT99991000002

Set oil-filter element 1
Part I 11 42 8 575 211

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602	2 FRU
---	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

BPS/NEXT 360 Grad Check
Flat rate unit I MM01 30 5

Local

12 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fzg. zur Hauptuntersuchung vorfahren #TÜV2
Flat rate unit I MM01 40 5

Local

0 FRU

Abgasuntersuchung #AU2
Flat rate unit I MM01 40 0

Local

7 FRU

Gebühren für Hauptunter- suchung (INTERN)
Part I FT99998888100

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes
Flat rate unit I 00 00 612

6 FRU

Removing and installing/replacing both front brake discs
Flat rate unit I 34 11 613

3 FRU

BREMS.KORR.SCHU
Part I FT99990000600

Local

1

Diesel 8,07l
Part I FT99998888093

Local

8.4

Repair kit, brake pads asbestos-free
Part I 34 11 6 874 331

1

Brake pad wear sensor, front left
Part I 34 35 6 792 289

1

Brake disc, ventilated
Part I 34 11 6 792 217

2

Inner hex bolt
Part I 34 21 1 161 806

2

Set of wiper blades
Part I 61 61 2 241 375

1

Axial securing clip
Part I 51 41 8 201 057

15

Securing plate
Part I 23 21 1 490 120

3

Gasket ring
Part I 13 53 7 584 315

4

BMW Natural Air refill kit, Raindrops
Part I 83 12 2 285 679

1

Fuse

2

Hex nut 8

Part I 32 10 6 774 139

Clamp 3

Part I 51 71 2 234 032

Clamp 4

Part I 51 13 2 251 394

Prestol-cage 4

Part I 07 12 9 925 754

Cable strap with bracket 4

Part I 61 13 9 118 958

Gasket ring 1

Part I 64 53 9 284 018

Gasket ring 1

Part I 64 53 9 284 019

Wiper blade 1

Part I 61 62 7 138 508

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 03/11/2019 Key 41741 km 37132 Key 0

									
21000	21000	21000	21000	60000	0	60000	21000		0
02/2020	395	395	395		03/2020		02/2020		04/2020

— 04/19/2018 Key 37765 km 00886 Key 0

									
25000	25000	25000	25000	60000	0	60000	25000		0
02/2020	681	681	681		03/2020		02/2020		04/2020

— 04/19/2018 Repair 37765 km 00886 Job
 Niederlassung Job
 Hamburg Job
 Filiale City Süd
 BMW AG,
 Hamburg

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder ab-und Sommerräder anbauen V
Flat rate unit I AZ36 00 8

Local

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder auslagern-ins Fahrzeug legen
Flat rate unit I AZ36 01 0

Local

1 FRU

— 02/06/2018 Key 31154 km 00886 Key 0


-190
03/2019


0


-190
418


0


70000


0
03/2020


70000


31000
03/2021


0
04/2020

— 02/06/2018 Service 31154 km 00886 Automatic
Niederlassung
Hamburg
Filiale City Süd
, Hamburg


-190
03/2019
✓


0


-190
03/2019
✓


0


70000


0
03/2020


70000


31000
03/2021


0
04/2020

— 02/06/2018 Repair 31154 km 00886 Job
Niederlassung Job
Hamburg Job
Filiale City Süd Job
BMW AG, Job
Hamburg Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter 2 FRU
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Set oil-filter element 1
Part I 11 42 8 575 211

BMW Engine Oil LL04 0W30 5
Part I 83 21 2 405 950

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW Local 2 FRU
Flat rate unit I IM00 25 0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug Local 1
Part I 52050

— Job










Description:

Is interpreted as a repeat visit: No

Customer's own words:

BMW/MINI Servicewäsche Local 1
Part I 00991

— 10/11/2017 Key 18801 km 00886 Key 0



—	10/11/2017	Repair	18801 km	00886 Niederlassung Hamburg Filiale City Süd BMW AG, Hamburg	Job Job
---	------------	--------	----------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder ab-und Winterräder anbauen V Flat rate unit I AZ36 00 7	Local	6 FRU
--	-------	-------

Sommerräder auslagern abgeholt durch: Flat rate unit I AZ36 00 9	Local	1 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	04/04/2017	Key	6 km	07495	Key 1
---	------------	-----	------	-------	-------



—	03/31/2017	Repair	1 km	07495 Niederlassung Hamburg Filiale Wandsbek BMW AG, Hamburg	Job Job Job
---	------------	--------	------	--	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Feuerlöscher nachrüsten Flat rate unit I AZ61 99 0	Local	6 FRU
---	-------	-------

Integral fire extinguisher with bracket Part I 52 10 0 441 113		1
---	--	---

Right lever short Part I 52 10 0 391 556		1
---	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Behörden Winterräder ins Fahrzeug legen, Winterräder sind im TV reserviert - Berechnung an BMW München,

Winterräder auslagern 2.242.831 ins Fahr Flat rate unit I AZ36 01 0	Local	1 FRU
--	-------	-------

RDCi wheel & tire, winter, light alloy Part I 36 11 0 047 955		1
--	--	---

RDCi wheel & tire, winter, light alloy Part I 36 11 0 047 955		1
--	--	---

RDCi wheel & tire, winter, light alloy Part I 36 11 0 047 955		1
--	--	---

RDCi wheel & tire, winter, light alloy Part I 36 11 0 047 955		1
--	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Termin Verkauf : 05.04.2017 / 16:30 Lieferung Spedition: 03.04.2017 / 18:00,

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
--	-------	-------