

Vehicle

BMW 318d, 110kW

WBA8H71060A125451



Development code	F31
Color	black-sapphire metallic
Actual integration level	F020-23-03-500
Start of warranty	December 11, 2017

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

⚠ An error has occurred. Please try again later.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map cannot be identified. One of the following maps could be installed in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2017-3 (as of: Dec 28, 2023)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2025-2	-
Road Map EUROPE EVO 2017-3 (as of: Dec 28, 2023)	-	-	-

▾ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	318d
Body	TOUR
Vehicle identification number (last 7 characters)	A125451
Vehicle identification number (17 characters)	WBA8H71060A125451
Development code	F31
Steering	LL
Engine	B47U
Engine number	74865178
Exhaust re-treatment	Euro 6 W
Transmission	AUT
Transmission number	1333845Z34
Head unit serial number	HB2240H8204383
Drive	HECK
Integration level	F020-17-11-530
Production date	Nov 24, 2017
Production works	Muenchen
Delivery date	Nov 27, 2017
Delivering Retailers	No information
National-market version	EUR
Paint code	475
Upholstery code	CCL1
Model code	8H81
Base type	8H71
Lead type	8H81

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
01CB CO2 package
0205 Automatic transmission
0216 Hydro steering-servotronic
0230 Extra package, EU-specific

Retrofitted optional equipment:

This vehicle has no retrofits.

0248 Steering wheel heater
0255 Sports leather steering wheel
0258 Tire with run-flat functionality
02FK BMW LA wheel, V Spoke 413
02PA Wheel bolt retainer
02VB Tire pressure display
02XM Individ.steering wheel leath.fine-grain
0302 Alarm system
0320 Deleted, model lettering
0322 Comfort Access
03AT Roof rail, aluminum, satin finish
03L8 Exterior parts, satin-gloss aluminum
0417 Roller sun vizor, rear door
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0441 Smoker package
0481 Sports seat
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04LU Black, highgloss Perlglanz chrome accent
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometer-calibrated speedometer
0552 Adaptive LED headlight
0563 Light package
0575 Supplementary 12V sockets
05A1 LED Fog lights
05AC High-beam assistant
05AG Lane-change warning
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
0609 Navigation system Professional
0688 Harman/Kardon Surround Sound system
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NW Phoning with wireless charging
06WA Instrument cluster, expanded equipment
06WD WLAN Hotspot
0775 Headlining anthracite
07LC Modell Advantage
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08R9 Refrigerant R1234yf
08TH Road sign detection
09AA Outer skin protection
09BM Navigation package, Connected Drive
A090 90 AH AGM battery
POLS Cloth cushion

▾ Vehicle histories

Date


Type

Vehicle mileage


Dealer

Overview


— 02/10/2026 Key 241695 km 04112 Key 0




— 02/10/2026 Service 241695 km 04112 Automatic
Autohaus
Weigl GmbH ,
Merseburg




— 11/11/2025 Key 236479 km 04112 Key 0




— 11/11/2024 Key 217102 km 04112 Key 0




— 09/13/2024 Key 213448 km 04112 Key 0



— 09/13/2024 Service 213448 km 04112 Automatic
Autohaus
Weigl GmbH ,
Merseburg



— 08/28/2024 Key 212127 km 04112 Remote KeyRead



—	12/28/2023	Repair	195806 km	04112 Autohaus Weigl GmbH, Merseburg	Job Job Job Job Job Job
---	------------	--------	-----------	---	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service Flat rate unit I 00 00 614	7 FRU
---	-------

Brake cleaner, acetone-free Part I 83 19 2 413 695	1
---	---

Brake pad wear sensor, rear Part I 34 35 6 792 292	1
---	---

Brake pad paste Part I 83 19 2 158 851	2
---	---

Repair kit brake pads asbestos-free Part I 34 21 8 855 013	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/renewing both brake discs Flat rate unit I 34 21 932	4 FRU
---	-------

Brake disc, ventilated Part I 34 21 6 864 900	2
--	---

Inner hex bolt Part I 34 21 1 161 806	2
Hex screw with collar Part I 34 20 6 850 536	4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612	6 FRU
Brake cleaner, acetone-free Part I 83 19 2 413 695	1
Brake pad paste Part I 83 19 2 158 851	2
Brake pad wear sensor, front left Part I 34 35 6 792 289	1
Repair kit, brake pads Part I 34 11 8 855 002	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
Brake disc, ventilated Part I 34 11 6 792 217	2
Torx screw with washer Part I 34 10 6 864 424	4
Inner hex bolt Part I 34 21 1 161 806	2

—	04/17/2023	Service	181682 km	04112 Autohaus Weigl GmbH, Merseburg	Manual
---	------------	---------	-----------	---	--------



—	03/23/2023	Key	181682 km	Key 0
---	------------	-----	-----------	-------

 1000 11/2023	 	 1000 11/2023	 	 35000 	 11/2023 	 9000 	 1000 11/2023	 	
---	--	---	--	---	---	--	--	--	--

— 03/23/2023 Service 181682 km 04112 Automatic
Autohaus
Weigl GmbH ,
Merseburg

 1000 ✓	 	 1000 ✓	 	 35000 	 	 9000 	 1000 ✓	 	
--	---	--	---	--	---	---	---	---	---

— 03/23/2023 Repair 181895 km 04112
Autohaus
Weigl GmbH ,
Merseburg
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Performing vehicle test 2 FRU
Flat rate unit I 00 00 556

Supporting the voltage of the vehicle electrical system/recharging the
vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528

Work time without specification/engine 11 FRU
Flat rate unit I 11 99 000

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rabatt nach Vereinbarung Autohaus WEIGL Kunden Local -1

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5
--	---

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Kostenlose maschinelle Wagenwäsche zum Servicebesuch in einer Waschanlage Flat rate unit I 00 12 099	Local	0 FRU
--	-------	-------

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Checking CC message/checking exhaust gas recirculation cooler (cooler outlet side) and replacing EGR cooler via service solution (technical campaign stays open) Flat rate unit I 00 73 831	16 FRU
--	--------

Clean intake ports in cylinder head and replace intake plenum Flat rate unit I 11 12 802	47 FRU
---	--------

Exhaust gas cooler high temperature Part I 11 71 7 822 347	1
Acoustic cover front Part I 11 14 8 490 577	1
Gasket Steel Part I 11 61 8 571 005	1
Isa screw with bush Part I 07 14 9 886 429	3
Vacuum hose black Part I 11 65 8 595 650	1
Connection piece Part I 11 65 7 803 012	1
Sensor, charge-air pressure Part I 13 62 8 637 896	1
Intake manifold AGR with flap control Part I 11 61 8 513 655	1
Gasket Part I 11 61 8 576 280	1
Preformed seal Part I 11 61 8 506 782	1
Preformed seal Part I 13 71 8 596 850	2
Hex bolt with washer Part I 07 11 9 905 750	1
Pipe union Part I 11 71 7 799 853	2
Hose clamp Part I 16 12 1 176 918	4
Gasket ring Part I 13 62 7 811 934	2
Gasket Steel Part I 11 62 8 576 287	1
Torx bolt Part I 11 71 2 249 909	2
Torx screw with collar Part I 07 14 7 270 121	2
Hex bolt with washer Part I 31 10 6 854 219	2
Anti-freeze Part I 83 19 2 218 347	4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing exhaust turbocharger Flat rate unit I 11 65 520	18 FRU
Additional work, visual check for exhaust turbocharger exchange Flat rate unit I 11 65 508	1 FRU
Additional work for exhaust turbocharger exchange after vehicle diagnosis Flat rate unit I 11 65 505	4 FRU
Work time without specification/engine Flat rate unit I 11 99 000	14 FRU
Exhaust turbocharger Part I 11 65 8 513 641	1
Hex bolt with washer Part I 07 11 9 905 528	3
Muffler clamp Part I 18 30 8 581 218	1
Pipe Part I 13 71 7 823 517	1
Gasket ring Part I 11 62 8 519 884	1
Clamp Part I 11 62 8 519 885	1
Hollow bolt Part I 07 11 9 907 291	1
Gasket ring Part I 07 11 9 905 041	2
Oil pipe inlet Part I 11 42 8 513 616	1
ISA screw Part I 07 12 9 905 867	5
Gasket Asbestos Free Part I 11 42 7 925 922	1
Return pipe Part I 11 42 8 513 617	1
O-ring Part I 11 12 7 689 563	1
Screw clamp Part I 18 30 8 512 137	1
Gasket Part I 18 30 8 513 651	1
Gasket ring Part I 13 53 2 247 156	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	01/20/2023	Key	177196 km				Remote KeyRead			
										
6000		6000		37000		12000	6000			
11/2023		11/2023			11/2023		11/2023	05/2024	05/2024	
—	09/27/2022	Key	170718 km				04112	Key 0		
										
12000		12000		47000		21000	12000			
11/2023		11/2023			11/2023		11/2023	05/2024	05/2024	
—	05/20/2022	Key	162368 km				04112	Key 0		
										
21000		21000		50000		28000	21000			
11/2023		521			11/2023		11/2023	-19 2.6 %		
—	05/20/2022	Repair	162391 km				04112	Job		
							Autohaus	Job		
							Weigl GmbH ,	Job		
							Merseburg			

—	Job
Description:	
Is interpreted as a repeat visit: No	
Customer's own words:	
Performing vehicle test	2 FRU
Flat rate unit 00 00 556	
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery	1 FRU
Flat rate unit 61 21 528	
Check the cooling system for watertightness with the special tool	2 FRU
Flat rate unit 17 00 509	
Removing and installing or replacing EGR cooler	23 FRU
Flat rate unit 11 71 600	
Work time without specification/engine	7 FRU
Flat rate unit 11 99 000	
Performing vehicle test	2 FRU
Flat rate unit 00 00 556	
Pipe union	2
Part 11 71 7 799 853	
Torx bolt	2
Part 11 71 2 249 909	

Gasket Steel Part I 11 61 8 571 005	1
--	---

Gasket Steel Part I 11 62 8 576 287	1
--	---

Torx-bolt with washer Part I 07 12 9 905 423	3
---	---

Oval head screw Part I 35 21 7 685 343	2
---	---

Gasket Steel Part I 11 71 8 579 364	1
--	---

Hose clamp Part I 16 12 1 176 918	4
--------------------------------------	---

exhaust cooler Part I 11 71 8 596 444	1
--	---

EGR-valve Part I 11 71 8 594 492	1
-------------------------------------	---

Anti-freeze Part I 83 19 2 218 347	4
---------------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Presentation for emission inspection Flat rate unit I 00 00 527	3 FRU
--	-------

— Job


Description:

Is interpreted as a repeat visit: No

Customer's own words:

TÜV HU Gebühren Durchlauf §10 Abs.1 UStG 0 Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

—	09/30/2021	Key	148032 km	Key 0
---	------------	-----	-----------	-------



—	12/18/2020	Repair	134166 km	04112 Autohaus Weigl GmbH, Merseburg	Job Job Job
---	------------	--------	-----------	---	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket
Flat rate unit I 00 52 052

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test
Flat rate unit I 00 00 006

4 FRU

Supporting the voltage of the vehicle electrical system/recharging the
vehicle electrical system battery
Flat rate unit I 61 21 528

1 FRU

Verifying customer concern and diagnosing cause (Mechanical)
Flat rate unit I 00 59 731

3 FRU

Replacing the exhaust-gas recirculation valve
Flat rate unit I 11 71 501

7 FRU

EGR-valve
Part I 11 71 8 513 132

1

Oval head screw
Part I 35 21 7 685 343

2

Gasket Steel
Part I 11 71 8 579 364

1

Hose clamp
Part I 07 12 9 952 104

2

Anti-freeze
Part I 83 19 2 218 347

0.5

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzwagen inkl. Versicher ung1 Werktag 0 11710183981
Flat rate unit I 99 99 999

Local










1 FRU

— 12/17/2020 Key

134150 km

04112

Key 0



— 12/17/2020 Repair

134150 km

04112
Autohaus
Weigl GmbH,
Merseburg

Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Motorlampe während der Fahrt
angegangen, Kunde hat sich langsam aus eigener Kraft ins Autohaus
geschleppt. Pannenfall !!!
Flat rate unit I -

Local 0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01SERVICEBER.1*BM8H81

Local

Service consultation at the vehicle with service ticket
Flat rate unit I 00 52 052

0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Motorlampe leuchtet

Carrying out vehicle test
Flat rate unit I 00 00 006

4 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle diagnosis, ABL
Flat rate unit I 61 00 006

5 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:










!!! unknown BMW-Id ESTIMATE 034633/33643 !!!
Flat rate unit I -














Local 0 FRU

— 12/16/2020 Key

134144 km

Key 0



—	05/18/2020	Service	120175 km	OSS-60005260 B&M Autoservice Alte Messe GbR, Leipzig	Manual				
									
✓					✓	✓	✓	✓	✓
—	03/26/2020	Key	119646 km	00075	Key 0				
									
17000 01/2022		17000 637		44000 11/2020	27000	43000 1357		12/2020	
—	01/10/2020	Service	110255 km	35232 Autohaus Hansa Nord GmbH , Lübeck	Automatic				
									
-2300 04/2021 ✓	-2300 04/2021 ✓	-2300 04/2021 ✓	-2300 04/2021 ✓	50000	0 11/2020	36000	-2300 04/2021 ✓	0 12/2020	
—	01/10/2020	Repair	110255 km	35232 Autohaus Hansa Nord GmbH , Lübeck	Job: Service Motoröl Job: Service Kraftstofffilter Job: Service Fahrzeug-Check Job: Service Luftfiltereinsatz Job: Service Mikrofilter Job Job Job Job Job				

— Job: Service Motoröl

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Motoröl
Package I 0000610

Engine oil service 3
Flat rate unit I 00 00 610

!!! unknown BMW-Id FT99999000006 CASTROL EDGE Local 5
PROFES.CASTROL EDGE PROFES. !!!
Part I FT99999000006

Set oil-filter element 1
Part I 11428575211

— Job: Service Kraftstofffilter

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Kraftstofffilter

Package I 0000604

Fuel filter service	3
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13328572522	

— Job: Service Fahrzeug-Check

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Fahrzeug-Check

Package I 0000624

Vehicle check service	6
Flat rate unit I 00 00 624	

— Job: Service Luftfiltereinsatz

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Luftfiltereinsatz

Package I 0000602

Service - air filter insert	2
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13718511668	

— Job: Service Mikrofilter

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Mikrofilter

Package I 0000616

Service - microfilter	2
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64119237555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Standardumfang !!! Flat rate unit I -	Local	0 FRU
Standard scope of service Flat rate unit I 00 00 105		2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Auftragstasche im Briefkasten, Unterschrift bei Abholung !!! Flat rate unit I -	Local	0 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Anruf KD FZG muss 15 Uhr fertig sein , Rü Frau Lange !!! Flat rate unit I -	Local	0 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01WÄSCHE*BM8H81	Local	
Outside car wash Flat rate unit I 00 11 319		0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Herr Freitag !!! Flat rate unit I -	Local	0 FRU
!!! unknown BMW-Id ESTIMATE 0176-30055341 !!! Flat rate unit I -	Local	0 FRU

—	01/10/2020	Repair	110255 km	35232 Autohaus Hansa Nord GmbH , Lübeck	Job Job Job Job Job
---	------------	--------	-----------	---	---------------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

CASTROL EDGE PROFES. 5W-30 LL04	Local	5
Part I FT99 99 9 000 0		

Set oil-filter element	1
Part I 11 42 8 575 211	

Windshield Washer Antifreeze	1
Part I 83 12 2 409 031	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 8 572 522	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Air filter element
Part I 13 71 8 511 668

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter
Flat rate unit I 00 00 616

2 FRU

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— 01/09/2020 Key 110255 km 35232 Key 0

									
-2300	-2300	-2300	-2300	50000	0	36000	-2300		0
04/2021	476	476	476		11/2020		04/2021		12/2020

— 10/23/2019 Key 101024 km 00914 Key 0

									
7000	7000	7000	7000	48000	0	40000	7000		0
04/2021	555	555	555		11/2020		04/2021		12/2020

— 10/23/2019 Repair 101034 km 00914 Autohaus Steen GmbH , Alt Mölln Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen
Flat rate unit I 00 99 401

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterbereifung aufbauen
Flat rate unit I 36 99 900

Local

6 FRU

Reinigung und Einlagerunginkl. Räderinsp. PLUS
Part I FT3699990

Local

1

— 10/23/2019 Repair 101034 km 00914 Autohaus Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen Flat rate unit I 00 99 401	Local	0 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterbereifung aufbauen Flat rate unit I 36 99 900	Local	6 FRU
Reinigung und Einlagerunginkl. Räderinsp. PLUS Part I FT3699990	Local	1

—	10/23/2019	Repair	101034 km	00914 Autohaus Steen GmbH , Alt Mölln	Job Job
---	------------	--------	-----------	--	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen Flat rate unit I 00 99 401	Local	0 FRU
--	-------	-------

— Job


Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterbereifung aufbauen Flat rate unit I 36 99 900	Local	-6 FRU
Reinigung und Einlagerunginkl. Räderinsp. PLUS Part I FT3699990	Local	-1

—	07/19/2019	Key	93141 km	00914	Key 0
---	------------	-----	----------	-------	-------



—	07/19/2019	Service	93141 km	00914 Autohaus Steen GmbH, Alt Mölln	Automatic
---	------------	---------	----------	---	-----------

								
15000	15000	15000	15000	900	0	50000	15000	0
04/2021	04/2021	04/2021	04/2021	✓	11/2020		04/2021	12/2020

—	07/19/2019	Repair	93147 km	00914 Autohaus Steen GmbH, Alt Mölln	Job
---	------------	--------	----------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

AZ without specification/maintenance
Flat rate unit I 00 99 000

6 FRU

—	07/19/2019	Repair	93147 km	00914 Autohaus Steen GmbH, Alt Mölln	Job
---	------------	--------	----------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

Service - front brakes
Flat rate unit I 00 00 612

6 FRU

Brake pad wear sensor, front left
Part I 34 35 6 792 289

1

Repair kit, brake pads asbestos-free
Part I 34 11 6 874 331

1

—	04/24/2019	Repair	82510 km	00914 Autohaus Steen GmbH, Alt Mölln	Job
---	------------	--------	----------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade
Flat rate unit I 61 61 041

2 FRU

Set of wiper blades
Part I 61 61 2 241 375

1

—	04/01/2019	Key	80792 km	00914	Key 0			
 30000 04/2021	 30000 760	 30000 760	 30000 760	 28000	 0 11/2020	 60000	 30000 04/2021	 0 12/2020
—	04/01/2019	Key	80792 km	00914	Key 0			
 -1400 10/2020	 0	 -1400 579	 0	 28000	 0 11/2020	 24000	 20000 10/2022	 0 12/2020
—	04/01/2019	Key	80792 km	00914	Key 0			
 -1400 10/2020	 0	 -1400 579	 0	 28000	 0 11/2020	 24000	 20000 10/2022	 0 12/2020
—	04/01/2019	Service	80792 km	00914 Autohaus Steen GmbH, Alt Mölln	Automatic			
 -1400 10/2020 ✓	 0	 -1400 10/2020 ✓	 0	 28000	 0 11/2020	 24000 ✓	 20000 10/2022	 0 12/2020
—	04/01/2019	Repair	80798 km	00914 Autohaus Steen GmbH , Alt Mölln	Job Job			

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen
Flat rate unit I 00 99 401

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterbereifung aufbauen Flat rate unit I 36 99 900	Local	6 FRU
Reinigung und Einlagerunginkl. Räderinsp. PLUS Part I FT3699990	Local	1

—	04/01/2019	Repair	80798 km	00914 Autohaus Steen GmbH , Alt Mölln	Job Job
---	------------	--------	----------	--	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
--	---

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

Windshield Washer Antifreeze Part I 83 12 2 409 031	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service Flat rate unit I 00 00 614	7 FRU
---	-------

Removing and installing/renewing both brake discs Flat rate unit I 34 21 932	4 FRU
---	-------

Brake pad wear sensor, rear Part I 34 35 6 792 292	1
---	---

Brake disc, ventilated Part I 34 21 6 864 900	2
--	---

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
--	---

Inner hex bolt Part I 34 21 1 161 806	2
--	---

—	10/02/2018	Key	53967 km	Key 0					
-1100	-1100	-1100	-1100	45000	0	46000	-1100	0	
05/2020	607	607	607		11/2020		05/2020	12/2020	
—	10/02/2018	Service	53967 km	00914 Autohaus Steen GmbH, Alt Mölln	Automatic				
-1100	-1100	-1100	-1100	45000	11/2020	46000	-1100	12/2020	
✓	✓	✓	✓				✓		
—	10/02/2018	Repair	53967 km	00914 Autohaus Steen GmbH , Alt Mölln	Job Job Job				

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen
Flat rate unit I 00 99 401

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/wheels
Flat rate unit I 36 99 000

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung und Einlagerunginkl. Räderinsp. PLUS
Part I FT3699990

Local

1

—	10/02/2018	Repair	53967 km	00914 Autohaus Steen GmbH , Alt Mölln	Job Job Job				
---	------------	--------	----------	--	-------------------	--	--	--	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen	Local	0 FRU
Flat rate unit I 00 99 401		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/wheels	-6 FRU
Flat rate unit I 36 99 000	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung und Einlagerunginkl. Räderinsp. PLUS	Local	-1
Part I FT3699990		

—	10/02/2018	Repair	53967 km	00914	Job
				Autohaus	Job
				Steen GmbH ,	Job
				Alt Mölln	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen	Local	0 FRU
Flat rate unit I 00 99 401		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/wheels	6 FRU
Flat rate unit I 36 99 000	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung und Einlagerunginkl. Räderinsp. PLUS	Local	1
Part I FT3699990		

—	09/05/2018	Key	48431 km	Key 0
---	------------	-----	----------	-------

									
6000	6000	6000	6000	700	0	2000	6000		0
05/2020	634	634	634		11/2020		05/2020		12/2020

— 09/05/2018 Service 48431 km 00914 Automatic
Autohaus
Steen GmbH,
Alt Mölln

									
6000	6000	6000	6000	700	11/2020	2000	6000		12/2020
				✓		✓			

— 05/29/2018 Repair 25130 km 00914 Job
Autohaus
Steen GmbH,
Alt Mölln

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen	Local	0 FRU
Flat rate unit I 00 99 401		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen	Local	0 FRU
Flat rate unit I 00 99 401		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kosten für Ersatzfahrzeug (aus Händler-Fuhrpark) 0	Local	1 FRU
Flat rate unit I 99 99 999		
Work time without specification/wheels		-6 FRU
Flat rate unit I 36 99 000		
Reinigung und Einlagerunginkl. Räderinspektion	Local	-1
Part I FT3600000		

— 05/09/2018 Key 25130 km 00914 Key 0

 -1000 11/2019	 0	 -1000 570	 0	 37000	 0 11/2020	 33000	 26000 11/2021	 0 12/2020
--	---	--	---	---	--	---	---	--

— 05/09/2018 Service 25130 km 00914 Automatic
Autohaus
Steen GmbH,
Alt Mölln

 -1000 ✓	 0	 -1000 ✓	 0	 37000	 11/2020	 33000	 26000	 12/2020
---	--	---	--	--	--	--	---	--

— 05/09/2018 Repair 25130 km 00914 Job
Autohaus
Steen GmbH ,
Alt Mölln Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen Flat rate unit I 00 99 401	Local	0 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen Flat rate unit I 00 99 401	Local	0 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kosten für Ersatzfahrzeug (aus Händler-Fuhrpark) Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

Work time without specification/wheels Flat rate unit I 36 99 000		6 FRU
--	--	-------

Reinigung und Einlagerunginkl. Räderinspektion Part I FT3600000	Local	1
--	-------	---

— 05/09/2018 Repair 25130 km 00914 Job
Autohaus
Steen GmbH ,
Alt Mölln Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen	Local	0 FRU
Flat rate unit I 00 99 401		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service waschen saugen	Local	0 FRU
Flat rate unit I 00 99 401		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kosten für Ersatzfahrzeug (aus Händler-Fuhrpark) 0	Local	1 FRU
Flat rate unit I 99 99 999		
Work time without specification/wheels		6 FRU
Flat rate unit I 36 99 000		
Reinigung und Einlagerunginkl. Räderinspektion	Local	1
Part I FT3600000		

— 02/27/2018 Key 11544 km 00914 Key 0

									
11000	0	11000	0	46000	0	43000	33000	0	0
11/2019		641			11/2020		11/2021		12/2020

— 02/17/2018 Key 10150 km 04373 Key 0

									
12000	0	12000	0	46000	0	43000	34000	0	0
11/2019		651			11/2020		11/2021		12/2020

— 12/22/2017 Key 902 km 00083 Key 0

									
29000	0	29000	0	50000	0	50000	60000	0	0
11/2019		708			11/2020		11/2021		12/2020

— 12/22/2017 Repair 902 km 00083 Niederlassung Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
--	-------	-------

— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words: Räder unter 240819278 reserviert!.,

Montage Neue Komplettträder Flat rate unit I AZ36RAD	Local	6 FRU
---	-------	-------

RDCi wheel & tire, winter, light alloy Part I 36 11 2 456 813		4
--	--	---

—	12/13/2017	Service	2 km	00075 BMW AG NL Frankfurt, Darmstadt	Manual
---	------------	---------	------	---	--------



—	12/08/2017	Repair	1 km	00075 Niederlassung Darmstadt BMW AG, Darmstadt	Job Job
---	------------	--------	------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: WR liefern & montieren,SR ins Fzg.LV.Nr.89308337 Freigabe 751.019,

Beide Vorder- und Hinterräder ab- und an Flat rate unit I 36 50 221	Local	6 FRU
--	-------	-------

Bill template – not to be used for tax-related purposes Flat rate unit I 00 52 044		0 FRU
---	--	-------

RDCi wheel & tire, winter, steel Part I 36 11 2 448 002		1
--	--	---

RDCi wheel & tire, winter, steel Part I 36 11 2 448 002		1
--	--	---

RDCi wheel & tire, winter, steel1

Part I 36 11 2 448 002

RDCi wheel & tire, winter, steel1

Part I 36 11 2 448 002

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PARKSCHEIBELocal1

Part I 80 56 0 443 335

BMW key ring 'Square'1

Part I 80 56 0 443 278

Ice scraper, small1

Part I 83 19 2 329 713