

Vehicle

BMW 320d, 140kW

WBA8H91020K664624



Development code	F31
Color	tansanit-blau metallic
Actual integration level	F020-22-07-530
Start of warranty	December 21, 2015

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

⚠ An error has occurred. Please try again later.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map cannot be identified. One of the following maps could be installed in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2018-3 (as of: Jan 7, 2026)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2025-2	-
Road Map EUROPE EVO 2018-3 (as of: Jan 7, 2026)	-	-	-

▾ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320d
Body	TOUR
Vehicle identification number (last 7 characters)	K664624
Vehicle identification number (17 characters)	WBA8H91020K664624
Development code	F31
Steering	LL
Engine	B47O
Engine number	76219440
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0212148ZRI
Head unit serial number	HB2140F7734216
Drive	HECK
Integration level	F020-15-11-502
Production date	Nov 17, 2015
Production works	Muenchen
Delivery date	Nov 19, 2015
Delivering Retailers	No information
National-market version	EUR
Paint code	X10
Upholstery code	LCSW
Model code	8H01
Base type	8H91
Lead type	8H01

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
01CB CO2 package
0205 Automatic transmission
0216 Hydro steering-servotronic
0230 Extra package, EU-specific

Retrofitted optional equipment:

This vehicle has no retrofits.

0258 Tire with run-flat functionality
02H2 BMW LA wheel, Multispoke 416
02VB Tire pressure display
02VF Adaptive M suspension
0302 Alarm system
0320 Deleted, model lettering
0322 Comfort access
03AC Trailer coupling
03AG Reversing camera
0402 Electric panoramic roof
0420 Sun protection glazing
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0459 Seat adjuster, electric, with memory
0481 Sports seat
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04FW Fine wood 'Fineline' walnut/acc. strip
04M5 Individual leather-covered dashboard
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0548 Kilometer-calibrated speedometer
0552 Adaptive LED headlight
0563 Light package
0575 Additional 12V socket
05A1 LED Fog lights
05AC High-beam assistant
05AG Lane-change warning
05AL Active Protection
05AS Driving Assistant
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
05DF Active cruise control+Stop&Go function
05DL Surround View
0609 Navigation system Professional
0610 Head-up display
0688 Harman/Kardon Surround Sound system
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NS Convenience phone, expanded Smartphone
06WA Instrument cluster, expanded equipment
0710 M leather steering wheel
0778 Door sill finishers with BMW Individual designation
07LE Modell Luxury Line
07R7 Innovation package
07S2 Luxury Line
07XP Navigation package, Connected Drive
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08TH Road sign detection
09BD Business Package
A090 90 AH AGM battery
LEDE Leather trim

Vehicle histories

	Date	Type	Vehicle mileage	Dealer	Overview				
—	01/06/2026	Key	203989 km	33251	Key 0				
	 14000 12/2026	 	 14000 12/2026	 	 -20 0 % 	 02/2027	 70000 	 45000 12/2028	 02/2027
—	01/06/2026	Repair	203989 km	33251 ,	Job: ISPA Paket 01 Job Job				
— Job: ISPA Paket 01									
Description:									
Is interpreted as a repeat visit: No									
Customer's own words:									
ISPA Paket 01 Package I 0100520									
Service consultation at the vehicle Flat rate unit I 00 52 050					0				
— Job									
Description:									
Is interpreted as a repeat visit: No									
Customer's own words:									
Removing and installing front or rear wheel Flat rate unit I 36 10 800					2 FRU				
Replacing a brake pad wear sensor Flat rate unit I 34 35 511					1 FRU				
Brake pad wear sensor, front left Part I 34 35 6 792 289					1				
— Job									
Description:									
Is interpreted as a repeat visit: No									
Customer's own words:									
Outside car wash and interior vehicle cleaning Flat rate unit I 00 11 329					3 FRU				
—	10/21/2025	Key	201346 km	33251	Remote KeyRead				

16000		16000		1900		70000	47000	
12/2026		12/2026			02/2027		12/2028	02/2027

— 02/26/2025 Key 189095 km 33251 Key 0

29000		29000		37000	-25 3.4 %	90000	60000	-25 3.4 %
12/2026		12/2026					12/2028	

— 02/26/2025 Service 189095 km 33251 Automatic
Cloppenburg GmbH , Achim

29000	0	29000	0	37000	0	90000	60000	0
					✓			

— 02/26/2025 Repair 189095 km 33251 , Job: ISPA Paket 01
Job
Job: Bremsflüssigkeit DOT4 LV,
Job: HU + AU TÜV PKW §29
STVZO
Job
Job

— Job: ISPA Paket 01

Description:

Is interpreted as a repeat visit: No

Customer's own words:

ISPA Paket 01
Package I 0100520

Service consultation at the vehicle 0
Flat rate unit I 00 52 050

— Job

Description: MKP 0000105 : Service 5+/C-Card, 30% Nachlass, ab 8 Jahre Nachlass, ab 8 Jahre

Is interpreted as a repeat visit: No

Customer's own words:

Battery 1
Part I 61 31 9 217 643

Service Standardumfang 2
Package I 0000105
Standard scope of service
Flat rate unit I 00 00 105

— Job: Bremsflüssigkeit DOT4 LV,

Description: MKP 0000618 : Service 5+/C-Card, 30% Nachlass, ab 8 Jahre Nachlass, ab 8 Jahre

Is interpreted as a repeat visit: No

Customer's own words:

Bremsflüssigkeit DOT4 LV,
Package I 0000618

Brake fluid service 4
Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity 1
Part I 83132405977

— Job: HU + AU TÜV PKW §29 STVZO

Description:

Is interpreted as a repeat visit: No

Customer's own words:

HU + AU TÜV PKW §29 STVZO
Package I MM01HU11*BMJN81

HU + AU TÜV PKW §29 STVZO Local 1
Flat rate unit I 99 99 999

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reifenmontage 1 Rad zzgl. Räder ab-u. anbauen (HL) Local 3 FRU
Flat rate unit I 09 36 100

Work time without specification/wheels 3 FRU
Flat rate unit I 36 99 000

— Job






Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash and interior vehicle cleaning 3 FRU
Flat rate unit I 00 11 329

— 02/18/2025 Key 188868 km 34455 Remote KeyRead



— 02/03/2025 Key 188537 km 34455 Remote KeyRead

									
29000		29000		38000	-2 0.3 %	90000	60000		-2 0.3 %
12/2026		12/2026					12/2028		

—	12/09/2024	Key	186173 km	33251	Key 0
---	------------	-----	-----------	-------	-------

									
-700 02/2025	-700 02/2025	-700 02/2025	-700 02/2025	38000		90000	-700 1.1 % 02/2025		

—	12/09/2024	Service	186173 km	33251 Cloppenburg GmbH , Achim	Automatic
---	------------	---------	-----------	--------------------------------------	-----------

									
-700 ✓	-700 ✓	-700 ✓	-700 ✓	38000	0	90000	-700 ✓		0

—	12/09/2024	Repair	186179 km	33251 ,	Job: ISPA Paket 01 Job: Service Standardumfang Job: Service Fahrzeug-Check Job: Satz Ölfiltereinsatz Job: Mikrofilter/Aktivkohlefil Job: Luftfiltereinsatz Job: Kraftstofffilterpatrone Job Job
---	------------	--------	-----------	---------	---

—	Job: ISPA Paket 01
---	--------------------

Description:

Is interpreted as a repeat visit: No

Customer's own words:

ISPA Paket 01
Package I 0100520

Service consultation at the vehicle 0
Flat rate unit I 00 52 050

—	Job: Service Standardumfang
---	-----------------------------

Description: MKP 0000105 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang
Package I 0000105

Standard scope of service 2
Flat rate unit I 00 00 105

—	Job: Service Fahrzeug-Check
---	-----------------------------

Description: MKP 0000624 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Fahrzeug-Check
Package I 0000624

Vehicle check service	6
Flat rate unit I 00 00 624	

— Job: Satz Ölfiltereinsatz

Description: MKP 0000610 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Satz Ölfiltereinsatz
Package I 0000610

Engine oil service	3
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11428575211	

BMW TwinPower Turbo LL-19FE 0W-30	5
Part I 83215A65BF8	

— Job: Mikrofilter/Aktivkohlefil

Description: MKP 0000616 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Mikrofilter/Aktivkohlefil
Package I 0000616

Service - microfilter	2
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64119237555	

— Job: Luftfiltereinsatz

Description: MKP 0000602 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Luftfiltereinsatz
Package I 0000602

Service - air filter insert	2
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13718511668	

— Job: Kraftstofffilterpatrone

Description: MKP 0000604 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Kraftstofffilterpatrone

Package I 0000604

Fuel filter service
Flat rate unit I 00 00 604

3

Fuel filter cartridge
Part I 13327822497

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash and interior vehicle cleaning
Flat rate unit I 00 11 329

3 FRU

— Job

Description:

Is interpreted as a repeat visit: No








Customer's own words:

Gutschein AGR
Flat rate unit I 99 99 999








Local

1 FRU








— 11/27/2024 Key 185844 km 34455 Remote KeyRead



— 10/14/2024 Key 183529 km 34455 Remote KeyRead



— 08/12/2024 Key 181207 km 33251 Key 0



— 01/04/2024 Service 144628 km OSS-60006539 S&S Automobile GmbH, Achim Manual

[illegible]

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right radial shaft seal for driven shafts on rear axle differential Flat rate unit I 33 10 024	24 FRU
--	--------

Replace radial shaft seal for drive flange Flat rate unit I 33 11 512	5 FRU
--	-------

Hex bolt Part I 26 11 7 523 709	3
------------------------------------	---

Self-locking hex nut Part I 26 12 7 536 563	3
--	---

ASA-Bolt Part I 26 11 7 621 344	3
------------------------------------	---

Repair kit recessed nut blue Part I 33 12 7 607 158	1
--	---

Gasket set differential Part I 33 10 7 564 416	2
---	---

Assembly ring Part I 31 53 7 502 681	2
---	---

Hypoid axle oil G1 Part I 83 22 2 295 532	2
--	---

Shaft seal Part I 31 50 7 609 535	1
--------------------------------------	---

dustcover plate, small Part I 33 12 1 213 903	1
--	---

Hex bolt with washer Part I 33 17 6 760 343	2
--	---

Self-locking collar nut Part I 33 30 6 760 349	1
---	---

Screw plug with O-ring Part I 33 11 7 525 064	1
--	---

— Job**Description:**

Is interpreted as a repeat visit: No

Customer's own words:

HU + AU TÜV PKW §29 STVZO #HU2 Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

kostenlose Fahrzeugoberwä sche ohne AW Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

 30000 02/2025	 30000 02/2025	 30000 02/2025	 30000 02/2025	 80000	 02/2025	 41000	 30000 02/2025	 -2 0.3 %
--	--	--	--	---	---	---	---	---

— 02/02/2023 Key 154433 km Key 0

 -1100 09/2023 3.5 %		 -1100 09/2023		 80000	 -32 4.4 %	 41000	 30000 09/2025	 -1 0.1 %
--	---	---	---	--	---	--	--	--

— 02/02/2023 Service 154433 km 33251 Automatic
Cloppenburg
GmbH , Achim

 -1100 09/2023 ✓		 -1100 09/2023 ✓		 80000	 01/2023 ✓	 41000	 30000 09/2025	 02/2023
--	---	--	---	--	---	--	--	--

— 02/02/2023 Repair 154434 km 33251 Job
Cloppenburg Job
GmbH , Achim Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
Flat rate unit I 00 00 610

BMW Engine Oil LL04 5W30 5
Part I 83 21 2 405 948

Set oil-filter element 1
Part I 11 42 8 575 211

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
Brake fluid DOT4 LV, low viscosity Part I 83 13 2 405 977	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sicherheits-Check kostenlos Flat rate unit I 09 04 004	Local	3 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Ersatzwagen Rent Case 00000000 Flat rate unit I 99 99 999	Local	1 FRU
kostenlose Fahrzeugoberwä sche ohne AW Flat rate unit I 99 99 999	Local	1 FRU


—

01/25/2023

Key

154122 km

Remote KeyRead




—

01/19/2023

Key

153423 km

Remote KeyRead



—

01/04/2023

Key

152656 km

Remote KeyRead

 700 09/2023	 700 09/2023	 700 09/2023	 80000 -3 0.4 %	 43000 09/2025	 32000 09/2025	 02/2023
--	--	--	--	--	--	--

— 09/26/2022 Key 146461 km 33251 Key 0

 7000 09/2023	 7000 09/2023	 7000 09/2023	 90000 01/2023	 60000 09/2025	 38000 09/2025	 02/2023
--	--	--	---	---	---	---

— 09/26/2022 Repair 146461 km 33251 Job
Cloppenburg Job
GmbH , Achim Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Klimaanlagen Komplettservice W artung und Desinfektion Flat rate unit I 09 64 003	Local	11 FRU
Tracer UV Additiv Kontrastmittel Part I FT83 19 2 232 5	Local	0.1
Pure Fresh Reiniger Klimaanlage Part I FT67100855	Local	1
PAG oil Denso ND8 Part I 83 19 2 199 567		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sicherheits-Check kostenlos Flat rate unit I 09 04 004	Local	3 FRU
Scheibenklar 500ml Fassware mit Frostschutz Part I FT61600145	Local	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

— 09/14/2022 Key 145964 km 33251 Remote KeyRead

 8000 09/2023	 	 8000 09/2023	 	 90000 	 	 60000 	 39000 09/2025	
---	--	---	--	---	--	---	---	--

— 08/31/2021 Key 122354 km Key 0

 -700 01/2022	 -700 152	 -700 152	 -700 152	 60000 	 0 01/2023	 80000 	 -700 01/2022	 0 02/2023
--	--	--	--	--	---	--	---	---

— 08/31/2021 Service 122354 km 33251 Automatic
Cloppenburg
GmbH, Achim

 -700 ✓	 -700 ✓	 -700 ✓	 -700 ✓	 60000 ✓	 0 01/2023	 80000 	 -700 ✓	 02/2023
--	--	--	--	---	---	--	---	--

— 08/31/2021 Repair 122381 km 33251 Job
Cloppenburg Job
GmbH, Achim Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Beratung am Fahrzeug mit iPad und Kunde
Flat rate unit I 00 97 097

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Fuel filter service Flat rate unit I 00 00 604	3 FRU
Fuel filter cartridge Part I 13 32 8 572 522	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - air filter insert Flat rate unit I 00 00 602	2 FRU
Air filter element Part I 13 71 8 511 668	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job**Description:****Is interpreted as a repeat visit:** No

Customer's own words:

Work time without specification/body equipment
Flat rate unit I 51 99 000

3 FRU

— Job**Description:**

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs
Flat rate unit I 34 11 220

10 FRU

ATE Ceramic Bremsbeläge
Part I 435.71.32

Local

1

Brake pad wear sensor, front left
Part I 34 35 6 792 289

1

Brake pad paste
Part I 83 19 2 158 851

1

Inner hex bolt
Part I 34 21 1 161 806

2

Torx screw with washer
Part I 34 10 6 864 424

4

Brake disc, ventilated
Part I 34 11 8 848 417

2

— Job**Description:**

Is interpreted as a repeat visit: No

Customer's own words:

W.O.K. Service Kontrolle der Flüssigkeiten Nachfüllen: O Ja O Nein
Flat rate unit I -

Local

1 FRU

Scheibenklar mit Frostschutz 500ml
Part I FT61600145

Local

4

— Job**Description:**

Is interpreted as a repeat visit: No

Customer's own words:

Fussraum aussaugen (ohne Berechnung)
Flat rate unit I 00 11 001

Local

2 FRU

Maschinelle Außenwäsche (ohne Berechnung)
Flat rate unit I 00 11 002

Local

1 FRU

— Job**Description:**

Is interpreted as a repeat visit: No

Customer's own words:

— 01/13/2021 Key 110417 km Key 0

									
12000	12000	12000	12000	70000	0	6000	12000		0
01/2022	382	382	382		-14 1.9 %		01/2022		-14 1.9 %

— 01/13/2021 Service 110417 km 33251 Cloppenburg GmbH, Achim Automatic

									
12000	12000	12000	12000	70000	12/2020	6000	12000		12/2020
					✓	✓			✓

— 01/13/2021 Repair 110421 km 33251 Cloppenburg GmbH, Achim

Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket 0 FRU
Flat rate unit I 00 52 052

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service 4 FRU
Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity 1
Part I 83 13 0 443 026

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Rear brakes service Flat rate unit I 00 00 614	7 FRU
---	-------

Brake pad wear sensor, rear Part I 34 35 6 792 292	1
---	---

Brake cleaner 2.0 Part I 83 19 2 365 214	1
---	---

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
--	---

Brake pad paste Part I 83 19 2 158 851	2
---	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Hauptuntersuchung §29 A/V Part I FTTÜV1	Local	1
--	-------	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Sicherheits-Check Kontrolle der Flüssigkeiten Nachfüllen: O Ja O Nein Flat rate unit I 09 04 004	Local	3 FRU
---	-------	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Fussraum aussaugen (ohne Berechnung) Flat rate unit I 00 11 001	Local	2 FRU
--	-------	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:****— Job****Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

— 01/13/2020 Key 91037 km 33251 Key 0

								
30000	30000	30000	30000	70000	0	6000	30000	0
01/2022	748	748	748		12/2020		01/2022	12/2020

— 01/06/2020 Key 90672 km 33251 Key 0

								
700	0	700	0	70000	0	6000	32000	0
08/2020		238			12/2020		08/2022	12/2020

— 01/06/2020 Service 90672 km 33251 Automatic
Cloppenburg
GmbH, Achim

								
700	0	700	0	70000	0	6000	32000	0
08/2020		08/2020			12/2020		08/2022	12/2020
✓		✓						

— 01/06/2020 Repair 90680 km 33251 Job
Cloppenburg Job
GmbH, Achim Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Beratung am Fahrzeug mit iPad nur Sichtprüfung Flat rate unit I 00 99 099	Local	0 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105		2 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5
Battery Part I 61 31 9 217 643	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fussraum aussaugen (ohne Berechnung) Flat rate unit I 00 11 001	Local	2 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Maschinelle Außenwäsche (ohne Berechnung) Flat rate unit I 00 11 002	Local	1 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	12/17/2019	Key	89198 km	33251	Key 0	
						
2200	0	2200	0	70000	0	6000
08/2020		257			12/2020	
						
18000	0	18000	0	28000	0	14000
08/2020		503			12/2020	
						
18000	0	18000	0	28000	0	14000
08/2020		503			12/2020	
—	04/15/2019	Repair	73484 km	33251	Job	
				Cloppenburg	Job	
				GmbH , Achim	Job	
					Job	
—	Job					
Description:						
Is interpreted as a repeat visit:	No					
Customer's own words:						
Service Beratung am Fahrzeug mit iPad nur Sichtprüfung				Local		0 FRU
Flat rate unit I 00 99 099						
Kosten Leihfahrzeug DU-RC 619 / X1				Local		1
Part I FTSW3G30097						
—	Job					
Description:						
Is interpreted as a repeat visit:	No					
Customer's own words:						
—	Job					
Description:						
Is interpreted as a repeat visit:	No					
Customer's own words:						
—	Job					
Description:						
Is interpreted as a repeat visit:	No					
Customer's own words:						
—	02/14/2019	Key	69816 km		Key 0	

									
22000	0	22000	0	33000	0	18000	60000		0
08/2020		563			12/2020		08/2022		12/2020

— 02/13/2019 Key 69765 km Key 0

									
22000	0	22000	0	33000	0	18000	60000		0
08/2020		564			12/2020		08/2022		12/2020

— 02/13/2019 Repair 69765 km 33251 Cloppenburg GmbH , Achim Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug mit iPad -Schnellservice- Local 0 FRU
Flat rate unit I 00 96 096

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 08/28/2018 Key 60390 km Key 0

									
600	600	600	600	46000	0	30000	600		0
03/2019	214	214	214		11/2018		03/2019		12/2018

— 08/28/2018 Service 60390 km 33251 Cloppenburg GmbH , Achim Automatic

									
600	600	600	600	46000	0	30000	600		0
03/2019	03/2019	03/2019	03/2019	03/2019	11/2018		03/2019		12/2018
✓	✓	✓	✓				✓		

—	08/28/2018	Repair	60399 km	33251 Cloppenburg GmbH , Achim	Job Job Job Job Job Job Job Job	
---	------------	--------	----------	--------------------------------------	--	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Beratung am Fahrzeug mit iPad und Kunde Flat rate unit I 00 97 097	Local	0 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105		2 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624		6 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610		3 FRU
--	--	-------

BMW MOTORÖL 0W30 LONGL.04 Part I 83 21 2 405 674	Local	5
---	-------	---

Set oil-filter element Part I 11 42 8 575 211		1
--	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter
Flat rate unit I 00 00 616

2 FRU

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert
Flat rate unit I 00 00 602

2 FRU

Air filter element
Part I 13 71 8 511 668

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service
Flat rate unit I 00 00 604

3 FRU

Fuel filter cartridge
Part I 13 32 8 572 522

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fussraum aussaugen (ohne Berechnung)
Flat rate unit I 00 11 001

Local

2 FRU

Maschinelle Außenwäsche (ohne Berechnung)
Flat rate unit I 00 11 002

Local

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No










Customer's own words:

— 11/01/2017 Key

39908 km

33251

Key 0



— 11/01/2017 Repair

39918 km

33251
Cloppenburg
GmbH , Achim

Job
Job
Job

Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Beratung am Fahrzeug mit iPad und Kunde
Flat rate unit I 00 97 097

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fussraum aussaugen (ohne Berechnung)
Flat rate unit I 00 11 001

Local

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Maschinelle Außenwäsche (ohne Berechnung)
Flat rate unit I 00 11 002

Local

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No










Customer's own words:

— 10/13/2017 Key

38979 km

33251

Key 0



22000
03/2019

22000
533

22000
533

22000
533

80000
11/2018

0
11/2018

60000
03/2019

22000
03/2019










0
12/2018

— 10/02/2017 Key

38235 km

33251

Key 0



22000
03/2019

22000
545

22000
545

22000
545

80000
11/2018

0
11/2018

70000
03/2019

22000
03/2019

0
12/2018

—	09/18/2017	Key	37200 km	37018	Key 0
---	------------	-----	----------	-------	-------

								
23000	23000	23000	23000	90000	0	70000	23000	0
03/2019	561	561	561		11/2018		03/2019	12/2018

—	09/18/2017	Repair	37206 km	37018 V & N GmbH , Hamm	Job
---	------------	--------	----------	-------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Tür h.r. ausbeulen und lackieren Flat rate unit I 99 99 999	Local	1 FRU
Free pre-delivery check Flat rate unit I 00 00 009		12 FRU
Statutory emission test Flat rate unit I 00 00 440		6 FRU
Removing and installing rear left or right door Flat rate unit I 41 52 580		3 FRU
HU nach § 29 STZO inkl. Gebühren lt Bescheinigung Part I FT99 99 9 000 0	Local	1
Windshield Washer Antifreeze Part I 83 12 2 298 206		1

—	07/13/2017	Key	36666 km	22134	Key 0
---	------------	-----	----------	-------	-------

								
23000	23000	23000	23000	90000	0	70000	23000	0
03/2019	626	626	626		11/2018		03/2019	12/2018

—	03/29/2017	Key	29963 km	03829	Key 1
---	------------	-----	----------	-------	-------

								
-1800	0	-1800	0	90000	0	70000	28000	0
11/2017		246			11/2018		11/2019	12/2018

—	03/29/2017	Service	29963 km	03829 Autohaus Wigger GmbH , Rostock	Automatic
---	------------	---------	----------	---	-----------

								
-1800	0	-1800	0	90000	0	70000	28000	0
11/2017		11/2017			11/2018		11/2019	12/2018
✓		✓						

—	03/29/2017	Repair	29963 km	03829 Autohaus Wigger GmbH, Rostock	Job: CBS: Standardumfang Job: CBS: Mikrofilter (ggf. weiter Zusatzarbe Job: CBS: Motoröl Job: Kostenlose Wagenoberwäsche Job
---	------------	--------	----------	--	--

— Job: CBS: Standardumfang

Description:

Is interpreted as a repeat visit: No

Customer's own words:

CBS: Standardumfang
Package I 0000105

Standard scope of service	2
Flat rate unit I 00 00 105	

— Job: CBS: Mikrofilter (ggf. weiter Zusatzarbe

Description:

Is interpreted as a repeat visit: No

Customer's own words:

CBS: Mikrofilter (ggf. weiter Zusatzarbe
Package I 0000616

Service - microfilter	2
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64119237555	

— Job: CBS: Motoröl

Description:

Is interpreted as a repeat visit: No

Customer's own words:

CBS: Motoröl
Package I 0000610

Engine oil service	3
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11428575211	

BMW Engine Oil LL04 0W30	5
Part I 83212405950	

— Job: Kostenlose Wagenoberwäsche

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Wagenoberwäsche

Package I MM02 0000200

!!! unknown BMW-Id 0000200 Kostenlose Wagenoberwäsche !!! Flat rate unit I 00 00 200	Local	0
!!! unknown BMW-Id 99001000002 SCHEIBENKLAR,500ML !!! Part I 99001000002	Local	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	03/29/2017	Repair	29963 km	03829 Autohaus Wigger GmbH , Rostock	Job: CBS: Standardumfang Job: CBS: Mikrofilter (ggf. weiter Zusatzarbe Job: CBS: Motoröl Job: Kostenlose Wagenoberwäsche
---	------------	--------	----------	---	---

— Job: CBS: Standardumfang

Description:

Is interpreted as a repeat visit: No

Customer's own words:

CBS: Standardumfang
Package I 0000105

Standard scope of service Flat rate unit I 00 00 105	2
---	---

— Job: CBS: Mikrofilter (ggf. weiter Zusatzarbe

Description:

Is interpreted as a repeat visit: No

Customer's own words:

CBS: Mikrofilter (ggf. weiter Zusatzarbe
Package I 0000616

Service - microfilter Flat rate unit I 00 00 616	2
Microfilter/activated Carbon container Part I 64119237555	1

— Job: CBS: Motoröl

Description:

Is interpreted as a repeat visit: No

Customer's own words:

CBS: Motoröl
Package I 0000610

Engine oil service Flat rate unit I 00 00 610	3
--	---

Set oil-filter element Part I 11428575211	1
BMW Engine Oil LL04 0W30 Part I 83212405950	5

— Job: Kostenlose Wagenoberwäsche

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Wagenoberwäsche
Package I MM02 0000200

!!! unknown BMW-Id 0000200 Kostenlose Wagenoberwäsche !!! Flat rate unit I 00 00 200	Local	0
!!! unknown BMW-Id 99001000002 SCHEIBENKLAR,500ML !!! Part I 99001000002	Local	2

—	12/16/2015	Repair	1 km	00089 Niederlassung Nürnberg BMW AG, Nürnberg	Job Job Job Job
---	------------	--------	------	---	--------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

RDCi wheel & tire, winter, steel Part I 36 11 2 411 436	1
RDCi wheel & tire, winter, steel Part I 36 11 2 411 436	1
RDCi wheel & tire, winter, steel Part I 36 11 2 411 436	1
RDCi wheel & tire, winter, steel Part I 36 11 2 411 436	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Wheel cover Part I 36 13 6 791 806	4
---------------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Snap-in adapter Connect
Part I 84 21 2 289 718

1

BMW warning vest, set of 2
Part I 82 26 2 288 693

1