

Vehicle

BMW 320d, 140kW

WBA8H91050K663788



Development code	F31
Color	black-sapphire metallic
Actual integration level	F020-22-03-552
Start of warranty	November 19, 2015

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

⚠ An error has occurred. Please try again later.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2015-2A (as of: Nov 13, 2023)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00B4008F).	Road Map EUROPE EAST Route 2025	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	320d
Body	TOUR
Vehicle identification number (last 7 characters)	K663788
Vehicle identification number (17 characters)	WBA8H91050K663788
Development code	F31
Steering	LL
Engine	B47O
Engine number	56379416
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0141342ZEN
Head unit serial number	MM01DFF1192485
Drive	HECK
Integration level	F020-15-07-506
Production date	Oct 22, 2015
Production works	Muenchen
Delivery date	Oct 23, 2015
Delivering Retailers	No information
National-market version	EUR
Paint code	475
Upholstery code	BDAT
Model code	8H01
Base type	8H91
Lead type	8H01

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 EU-specific additional contents
 0258 Tire with run-flat functionality
 02L3 BMW LA wheel, V Spoke 395
 02VB Tire pressure display
 0320 Deleted, model lettering
 03AA Roof railing black
 0423 Floor mats, velours

Retrofitted optional equipment:

This vehicle has no retrofits.

0428 Warning triangle and first aid kit
 0431 Interior mirror with automatic-dip
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04CG Interior strips, "satin-silber" matt
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0548 Kilometer-calibrated speedometer
 0552 Adaptive LED headlight
 0575 Supplementary 12V sockets
 05A1 LED Fog lights
 05AC High-beam assistant
 05AL Active Protection
 05AS Driving Assistant
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 05DF Active cruise control+Stop&Go function
 0606 Navigation system Business
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06NH Hands-free with USB interface
 06WA Instrument cluster, expanded equipment
 07LC Modell Advantage
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 08TH Road sign detection
 A090 90 AH AGM battery
 POLS Cloth cushion

▾ Vehicle histories

Date	Type	Vehicle mileage			Dealer	Overview
— 11/13/2023	Key	152473 km			00508	Key 0
 10000 05/2025	 10000 05/2025	 10000 05/2025	 10000 05/2025	 11000 06/2024	 16000 05/2027	 41000 05/2027
— 08/14/2023	Key	140941 km				Remote KeyRead
 21000 05/2025	 21000 05/2025	 21000 05/2025	 21000 05/2025	 21000 06/2024	 25000 05/2027	 50000 05/2027
— 06/29/2022	Key	99534 km			00508	Key 1
 30000 06/2024	 692	 30000	 70000 06/2024	 80000 06/2024	 30000 06/2024	
— 06/29/2022	Repair	99579 km			00508 Autohaus Rolf	Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket 0 FRU
Flat rate unit I 00 52 052

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fußraumreinigung (aussaugen) Local 0 FRU
Flat rate unit I 00 11 320

— Job


Description:

Is interpreted as a repeat visit: No


Customer's own words:

Outside car wash 2 FRU
Flat rate unit I 00 11 319

— 06/21/2022 Key 99001 km 00508 Remote KeyRead



— 02/20/2019 Key 45789 km Key 1



— 02/20/2019 Repair 45794 km 00508 Job
Autohaus Rolf Job
Horn GmbH , Job
Euskirchen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Auslieferungsscheck (GA MINI/ GA BMW ohne Premium Selection) Local 9 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

FEINSTAUB PLA.-Grün Part I FT99 99 1 100 1	Local	1
KENNZEICHENUNTERLAGE NEU Part I FT99 99 1 100 5	Local	1
AUSWEISTASCHE BMW Part I FT99 99 1 100 5	Local	1
SCHLÜSSELTASCHE BMW Part I FT99 99 1 100 5	Local	1
Windshield Washer Antifreeze Part I 83 12 2 409 034		4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

GW Paket 2 1007433731 00000000 Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

—	12/12/2018	Service	45780 km	00508 Autohaus Rolf Horn, Euskirchen	Manual
---	------------	---------	----------	---	--------

 ✓	 ✓	 ✓	 ✓		 ✓		 ✓		
--	--	--	--	---	--	---	---	---	---

—	11/20/2018	Key	45780 km	Key 0
---	------------	-----	----------	-------

 4100 05/2019	 4100 197	 4100 197	 4100 197	 40000	 0 -14 1.9 %	 24000	 4100 05/2019
--	--	--	--	--	--	--	---

—	11/20/2018	Repair	45780 km	00508 Autohaus Rolf Horn GmbH , Euskirchen	Job Job Job Job Job Job Job
---	------------	--------	----------	---	---

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
--	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

Screw plug Part I 11 13 7 535 106	1
--------------------------------------	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 8 572 522	

Clamping bracket	1
Part I 13 32 7 789 220	

Hose clamp	1
Part I 07 12 9 952 104	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

T+R 21.11.-28.11.2018 RG 1800622 00000000	Local	1 FRU
Flat rate unit I 99 99 999		

—	11/20/2018	Repair	45780 km	00508 Autohaus Rolf Horn GmbH , Euskirchen	Job Job
---	------------	--------	----------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

[[Präsentationsdurchsicht GA]]	Local	2 FRU
Flat rate unit I 00 12 200		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	11/14/2018	Key	45780 km	Key 1
---	------------	-----	----------	-------

							
4100	4100	4100	4100	40000	0	24000	4100
05/2019	198	198	198		-14 1.9 %		05/2019

—	04/18/2018	Key	38859 km	00508	Key 0
---	------------	-----	----------	-------	-------

							
13000	13000	13000	13000	44000	0	29000	13000
05/2019	408	408	408		10/2018		05/2019

—	04/18/2018	Repair	38860 km	00508	Job
				Autohaus Rolf	Job
				Horn GmbH ,	Job
				Euskirchen	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder montieren	Local	5 FRU
Flat rate unit I 36 00 009		
Sommerräder wuchten	Local	6 FRU
Flat rate unit I 36 00 011		
Rädereinlagerung Lagernummer:514 oben	Local	6 FRU
Flat rate unit I 36 00 031		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kompakt-Check ohne Berechnung	Local	3 FRU
Flat rate unit I 00 99 500		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fußraumreinigung (aussaugen)	Local	1 FRU
Flat rate unit I 00 11 320		
Outside car wash		3 FRU
Flat rate unit I 00 11 319		

— 11/11/2017 Key 32066 km 00508 Key 0

							
21000	21000	21000	21000	60000	0	36000	21000
05/2019	566	566	566		10/2018		05/2019

— 09/21/2017 Repair 32079 km 00508 Job
Autohaus Rolf Job
Horn GmbH, Job
Euskirchen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing two tire with run-flat technology Flat rate unit I 36 12 055	17 FRU
Dunlop SP Winter Sport 4D ROF Part I 85 45 2 548 383	2
Wheel electr. module RDCi w/ screw valve Part I 36 10 6 881 890	4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder montieren Flat rate unit I 36 00 019	Local	5 FRU
Reinigung-Radsatz Flat rate unit I 36 00 034	Local	2 FRU
Rädereinlagerung Lagernummer: 514 oben Flat rate unit I 36 00 031	Local	6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kompakt-Check ohne Berechnung Flat rate unit I 00 99 500	Local	3 FRU
Fußraumreinigung (aussaugen) Flat rate unit I 00 11 320	Local	1 FRU
Outside car wash Flat rate unit I 00 11 319		3 FRU

— 06/02/2017 Key 24463 km 00508 Key 0

							
29000	29000	29000	29000	60000	0	43000	29000
05/2019	728	728	728		10/2018		05/2019

— 05/04/2017 Key 23726 km 00508 Key 0

							
480	0	480	0	60000	0	45000	32000
10/2017		179			10/2018		10/2019

— 05/04/2017 Service 23726 km 00508 Manual
Autohaus Rolf
Horn,
Euskirchen

										
✓		✓								

— 05/04/2017 Repair 23726 km 00508 Job
Autohaus Rolf
Horn GmbH ,
Euskirchen Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

Engine oil service 3 FRU
Flat rate unit I 00 00 610

BMW Engine Oil LL04 5W30 5
Part I 83 21 2 405 948

Screw plug 1
Part I 11 13 7 535 106

Set oil-filter element 1
Part I 11 42 8 575 211

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter 2 FRU
Flat rate unit I 00 00 616

Pollen filter housing cleaner 1

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kompakt-Check ohne Berechnung
Flat rate unit I 00 99 500

Local

3 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fußraumreinigung (ausaugen)
Flat rate unit I 00 11 320

Local

1 FRU

Outside car wash
Flat rate unit I 00 11 319









3 FRU

— 04/04/2017 Key

22081 km

00508

Key 0



— 04/04/2017 Repair

22081 km

00508
Autohaus Rolf
Horn GmbH ,
Euskirchen

Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder wuchten
Flat rate unit I 36 00 011

Local

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder montieren
Flat rate unit I 36 00 009

Local

5 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung-Radsatz Flat rate unit I 36 00 034	Local	2 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rädereinlagerung Lagernummer: 514 oben Flat rate unit I 36 00 031	Local	6 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kompakt-Check ohne Berechnung Flat rate unit I 00 99 500	Local	3 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fußraumreinigung (aussaugen) Flat rate unit I 00 11 320	Local	1 FRU
--	-------	-------

Outside car wash Flat rate unit I 00 11 319		3 FRU
--	--	-------

—	03/30/2017	Repair	0 km	33329 Autohaus Rolf Horn GmbH , Wesseling	Job
---	------------	--------	------	--	-----

— Job


Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment Flat rate unit I 51 99 000	-1 FRU
--	--------


—	02/08/2017	Key	19695 km	33329	Key 0
---	------------	-----	----------	-------	-------



6000
10/2017




0




6000
265




0




60000



0



10/2018



47000



37000
10/2019

—

02/08/2017 Repair

19695 km

33329
Autohaus Rolf
Horn GmbH,
Wesseling

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Stripping and refitting work for painting side panel, rear left Flat rate unit I 51 18 720	11 FRU
---	--------

Removing and installing rear bumper panel Flat rate unit I 51 12 656	5 FRU
---	-------

Replace rear bumper panel Flat rate unit I 51 12 657	1 FRU
---	-------

Removing and installing/replacing the bumper guide, rear left or right Flat rate unit I 51 12 828	2 FRU
--	-------

Additional work with Park Distance Control Flat rate unit I 66 20 602	5 FRU
--	-------

Removing and installing left-hand rear light Flat rate unit I 63 21 740	1 FRU
--	-------

Removing and installing left or right roof trim strip Flat rate unit I 51 13 780	2 FRU
---	-------

Carrying out vehicle test Flat rate unit I 00 00 006	4 FRU
---	-------

Painting bumper cover, rear Flat rate unit I 99 69 019	34 FRU
---	--------

Painting the rear quarter panel, left or right Flat rate unit I 99 36 509	11 FRU
--	--------

Work time without specification/body equipment Flat rate unit I 51 99 000	12 FRU
--	--------

Kleinteile Part I FT99 99 1 100 5	Local	1
--------------------------------------	-------	---

Bumper trim panel, primed, rear Part I 51 12 7 384 617	1
---	---

Adhesive set K6 Part I 83 19 2 317 925	1
---	---

Kit, mount for PDC/PMA sensor, rear Part I 51 12 7 445 160	1
---	---

Liftover edge protective film Part I 51 91 2 355 461	1
---	---

Reflector, rear left Part I 63 14 7 400 207	1
Reflector, rear right Part I 63 14 7 400 208	1
Cover, towing eye, primed, rear Part I 51 12 7 428 436	1
Guide for bumper, side, left Part I 51 12 7 384 479	1
Ultrasonic sensor, black Part I 66 20 9 261 582	1
Rear light in the side panel, left Part I 63 21 7 372 209	1
Rear light in trunk lid, left Part I 63 21 7 369 119	1
Fillister head screw Part I 07 14 7 127 714	8
Expanding nut Part I 63 12 1 374 075	2
Fillister head screw Part I 07 14 7 118 369	2

—	12/03/2016	Key	17128 km	00508	Key 0
---	------------	-----	----------	-------	-------

							
9000	0	9000	0	60000	0	50000	40000
10/2017		332			10/2018		10/2019

—	12/03/2016	Repair	17128 km	00508	Job Autohaus Rolf Horn GmbH , Euskirchen	Job Job Job Job Job
---	------------	--------	----------	-------	---	---------------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder wuchten Flat rate unit I 36 00 021	Local	6 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder montieren Flat rate unit I 36 00 020	Local	5 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung-Radsatz	Local	2 FRU
Flat rate unit I 36 00 033		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rädereinlagerung Lagernummer: 514 oben	Local	6 FRU
Flat rate unit I 36 00 030		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kompakt-Check ohne Berechnung	Local	3 FRU
Flat rate unit I 00 99 500		


— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	04/21/2016	Key	7324 km	00508	Key 0
---	------------	-----	---------	-------	-------



—	04/21/2016	Repair	7324 km	00508	Job
				Autohaus Rolf	Job
				Horn GmbH ,	Job
				Euskirchen	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder montieren	Local	5 FRU
Flat rate unit I 36 00 009		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung-Radsatz Flat rate unit I 36 00 034	Local	2 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rädereinlagerung Flat rate unit I 36 00 031	Local	6 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No


Customer's own words:

Kompakt-Check ohne Berechnung Flat rate unit I 00 99 500	Local	3 FRU
---	-------	-------

Fußraumreinigung (aussaugen) Flat rate unit I 00 11 320	Local	1 FRU
--	-------	-------

Outside car wash Flat rate unit I 00 11 319		3 FRU
--	--	-------

—	02/05/2016	Key	3595 km	00508	Key 0
---	------------	-----	---------	-------	-------



—	02/05/2016	Repair	3595 km	00508 Autohaus Rolf Horn GmbH , Euskirchen	Job
---	------------	--------	---------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing door window glass, fixed, in the window frame, rear, left or right Flat rate unit I 51 34 190	18 FRU
---	--------

Work time without specification/body equipment Flat rate unit I 51 99 000	6 FRU
--	-------

Fixed door window, left Part I 51 35 7 269 555	1
---	---

Adhesive primer VP 206
Part I 83 19 9 407 777

1

Repair flat rate, window, cold, 1 hr.
Part I 83 19 2 289 285

1

— 02/05/2016 Repair 3595 km 00508 Job
Autohaus Rolf
Horn GmbH ,
Euskirchen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kompakt-Check ohne Berechnung
Flat rate unit I 00 99 500

Local

3 FRU

Outside car wash
Flat rate unit I 00 11 319

3 FRU

— 12/28/2015 Repair 1 km 00508 Job
Autohaus Rolf
Horn GmbH ,
Euskirchen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing four tires
Flat rate unit I 36 12 071

12 FRU

Screw-in valve RDC
Part I 36 14 6 792 830

4

Wheel electronics module, RDC 433MHZ
Part I 36 10 6 874 830

4

— 11/27/2015 Repair 1 km 00508 Job
Autohaus Rolf
Horn GmbH ,
Euskirchen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug EU-BB 4731 18.11.15-20.11.15
Part I VS0000160

Local

1

—	11/05/2015	Repair	0 km	00508 Autohaus Rolf Horn GmbH , Euskirchen	Job Job Job
---	------------	--------	------	---	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Free pre-delivery check	9 FRU
Flat rate unit I 00 00 009	

KENNZEICHENUNTERLAGE NEU	Local	1
Part I FT99 99 1 100 5		

FEINSTAUB PLA.-Grün	Local	1
Part I FT99 99 1 100 1		

AUSWEISTASCHE BMW	Local	1
Part I FT99 99 1 100 5		

SCHLÜSSELTASCHE BMW	Local	1
Part I FT99 99 1 100 5		

Windshield Washer Antifreeze	8
Part I 83 12 2 296 207	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Installing navigation map(s)	2 FRU
Flat rate unit I 65 90 600	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Aufbereitung Neufahrzeug	Local	1 FRU
Flat rate unit I 99 99 999		

—	11/05/2015	Repair	0 km	00508 Autohaus Rolf Horn GmbH , Euskirchen	Job Job
---	------------	--------	------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder montieren vom Altfahrzeug F656926 montieren	Local	5 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rädereinlagerung SR auf das neue Fzg. einlagern	Local	6 FRU
Flat rate unit I 36 00 031		