

Vehicle

BMW 325d, 165kW

WBA8D31090K512106



Development code	F30
Color	black-sapphire metallic
Actual integration level	F020-24-11-500
Start of warranty	January 12, 2018

 There are active service contracts present.

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 An error has occurred. Please try again later.

▼ Service contracts

Description	Issuer	Billing as of	Duration	Vehicle mileage
UC Service Inclusive for Used Cars - 3 years / 40,000 km	AG	Oct 11, 2024	to Oct 10, 2027	to 213186 km

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map cannot be identified. One of the following maps could be installed in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2020-3 (as of: Jun 13, 2025)	-	-	-
Road Map EUROPE EVO 2020-3 (as of: Jun 13, 2025)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2025-2	-

▾ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	325d
Body	LIM
Vehicle identification number (last 7 characters)	K512106
Vehicle identification number (17 characters)	WBA8D31090K512106
Development code	F30
Steering	LL
Engine	B47T
Engine number	55675196
Exhaust re-treatment	Euro 6 W
Transmission	AUT
Transmission number	1450446Z37
Head unit serial number	HB2241H8218354
Drive	HECK
Integration level	F020-17-11-540
Production date	Dec 12, 2017
Production works	Muenchen
Delivery date	Jan 18, 2018
Delivering Retailers	Großkunden, München, DE
National-market version	EUR
Paint code	475
Upholstery code	LCRZ
Model code	8D41
Base type	8D31
Lead type	8D41

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 0216 Hydro steering-servotronic
 0230 EU-specific additional contents
 0255 Sports leather steering wheel
 0258 Tire with run-flat functionality
 02H2 BMW LA wheel, Multispoke 416
 02PA Wheel bolt retainer
 02TB Sport automatic transmission
 02VB Tire pressure display

Retrofitted optional equipment:

This vehicle has no retrofits.

0302 Alarm system
0320 Deleted, model lettering
0322 Comfort access
03AG Reversing camera
03DZ Delete extra external lettering
03L8 Exterior parts, satin-gloss aluminum
0403 Glass roof, electrical
0420 Sun protection glazing
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0459 Seat adjuster, electric, with memory
0465 Through-loading system
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04FW Fine wood 'Fineline' walnut/acc. strip
0507 Park Distance Control (PDC), rear
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometer-calibrated speedometer
0552 Adaptive LED headlight
0563 Lights package
05A1 LED Fog lights
05AC High-beam assistant
05AS Driving Assistant
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
0609 Navigation system Professional
0610 Head-up display
0654 DAB tuner (DAB-enabled)
0688 Harman/Kardon Surround Sound system
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06CP Smartphone integration
06FV Online Entertainment
06NW Phoning with wireless charging
06WA Instrument cluster, expanded equipment
06WD WLAN Hotspot
0775 Headlining anthracite
07B2 Edition Luxury Line
07R7 Innovation package
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08R9 Refrigerant R1234yf
08TH Road sign detection
0941 Dummy-SALAPA
09BM Navigation package, Connected Drive
09D5 Entertainment package de
09D8 Exclusive package de
A090 90 AH AGM battery
LEDE Leather trim

▾ Vehicle histories

	Date	Type	Vehicle mileage			Dealer		Overview		
—	11/05/2025	Key	205328 km			02766		Key 0		
										
	25000	25000	25000	80000	25000	29000	25000			
	09/2027	09/2027	09/2027		04/2027		09/2027		04/2027	
—	11/05/2025	Repair	205328 km			02766 ,		Job: Eingelagerte Räder montie Job: ISPA Paket 03		
— Job: Eingelagerte Räder montie										
Description:										
Is interpreted as a repeat visit: No										
Customer's own words:										
Eingelagerte Räder montie Package I 0499108										
	Eingelagerte Räder montieren und ins Fahrzeug legen					Local	6			
	Flat rate unit I -									
	Räder ins Fahrzeug legen. Keine Haftung für dadurch ent- standene Local						0			
	Schäden im Fahrzeug!									
	Flat rate unit I -									
— Job: ISPA Paket 03										
Description: Hinweis Räder ins Fahrzeug legen: Hiermit wird der auf dem Auftrag angegebene Kunde darauf hingewiesen, dass sein/ihr Fahrzeug zum heutigen Zeitpunkt nicht entsprechend §22 StVO und den anerkannten Technischen Regeln der VDI- 2700 Richtlinie für Ladungssicherung auf Straßenfahrzeugen beladen ist. Begründung: Die geladenen Räder wurden nicht sicherheits- gemäß nach den anerkannten Regeln der Technik geladen und können im Falle eines Unfalls zu schwereren Personen- und Sachschäden führen. Hiermit wurden Sie über die Gefahren ausdrücklich und hinreichend informiert. Das ungesicherte Verladen der Räder erfolgte auf ausdrücklichen Wunsch des Kunden/ der Kundin.										
Is interpreted as a repeat visit: No										
Customer's own words:										
ISPA Paket 03 Package I 0499113										
	Räder ins Fahrzeug legen. Keine Haftung für dadurch ent- standene Local						0			
	Schäden im Fahrzeug!									
	Flat rate unit I -									
—	09/16/2025	Key	201223 km			02766		Key 0		
										
	200		200		80000	34000	29000			
	10/2026		10/2026		04/2027		10/2028		04/2027	
—	09/16/2025	Service	201223 km			02766 AH Rhein Würzburg Zw.- Nl. der AH		Automatic		

 200 ✓	 0	 200 ✓	 0	 80000	 0	 34000	 29000	 0
---	--	---	--	--	--	--	---	--

— 09/16/2025 Repair 201223 km 02766 , Job
Job: Mikrofilter/Aktivkohlefil
Job: Service Standardumfang

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Inclusive - Pauschale Vergütung Flat rate unit I 99 99 999	Local	1 FRU
Satz Ölfiltereinsatz Package I 0000610		
Engine oil service Flat rate unit I 00 00 610		3
Set oil-filter element Part I 11428575211		1
Shell Helix Ultra ECT SAE 0W-30 BMW Longlife 04 Part I FT9030	Local	5

— Job: Mikrofilter/Aktivkohlefil

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Mikrofilter/Aktivkohlefil Package I 0000616		
Service - microfilter Flat rate unit I 00 00 616		2
Microfilter/activated Carbon container Part I 64119237555		1

— Job: Service Standardumfang

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang Package I 0000105		
Standard scope of service Flat rate unit I 00 00 105		2

—	06/10/2025	Key	189994 km	02766	Key 0			
 11000 10/2026		 11000 10/2026		 70000	 04/2027	 41000	 38000 10/2028	 04/2027
—	06/10/2025	Repair	190007 km	02766 ,	Job Job Job			

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test Flat rate unit I 00 00 006	4 FRU
Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Verbringungskosten Lackiererei Flat rate unit I -	Local 6 FRU
Carry out Kinematics Diagnosis System wheel alignment with vehicle load up to design position Flat rate unit I 32 00 590	16 FRU
Replace bumper cover, front Flat rate unit I 51 11 592	12 FRU
Removing and installing front bumper panel Flat rate unit I 51 11 656	9 FRU
Adjusting headlights Flat rate unit I 63 10 502	2 FRU
Finsih-/Polierarbeiten durchführen Flat rate unit I -	Local 2 FRU
Zeitzuschlag für eine Hauptarbeit Flat rate unit I -	Local 2 FRU
Scheinwerfer rechts aus-/einbauen Flat rate unit I -	Local 3 FRU
Scheinwerfer rechts ersetzen Flat rate unit I -	Local 4 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Painting bumper cover, front Flat rate unit I 99 68 529	0 FRU
Work time without specification/paintwork Flat rate unit I 99 99 000	0 FRU

Lackierarbeiten 31 AW inkl. 40% Lackiermaterial
Flat rate unit I 99 99 999

Local

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Set of mounted parts, bumper, front
Part I 51 11 2 471 536

1

Mount, side wall front, upper right
Part I 51 11 7 255 362

1

Mount, side wall front, lower right
Part I 51 11 7 279 712

1

Support, fog lamp right
Part I 51 11 7 386 362

1

Partially open grid, right
Part I 51 11 7 396 878

1

Air inlet finisher, right
Part I 51 11 7 404 626

1

Trim cover, bumper, primed, front
Part I 51 11 7 427 120

1

Badge
Part I 51 76 7 288 752

1

Headlight, LED, AHL, right
Part I 63 11 7 419 628






1

— 05/23/2025 Key

188772 km

02766

Key 0












— 05/23/2025 Service

188772 km

02766 AH
Rhein
Würzburg Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Würzburg

Automatic



— 05/23/2025 Repair

188772 km

02766 ,

Job: Service Standardumfang
Job: Bremsenreiniger, acetonfr
Job

— Job: Service Standardumfang

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang

Package I 0000105

Standard scope of service	2
Flat rate unit I 00 00 105	

— Job: Bremsenreiniger, acetonfr

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Bremsenreiniger, acetonfr

Package I 0000612

Service - front brakes	6
Flat rate unit I 00 00 612	

Brake cleaner, acetone-free	1
Part I 83192413695	

Repair kit brake pads asbestos-free	1
Part I 34118855010	

Brake pad wear sensor, front left	1
Part I 34356792289	

Brake pad paste	2
Part I 83192158851	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Odor remover	1
Part I 83 19 2 469 491	


Refrigerant R1234yf	4
Part I 83 19 2 287 039	

KÄLTEMASCHIENENÖL SANDEM SP-A2 1 ml	Local	13
Part I FT83222339920		


Klimacheck inkl. Desinfek

Package I 0199201

BMW Klimaanlage-Service inkl. Desinfektion	Local	9
Flat rate unit I -		



—	04/04/2025	Service	184655 km	02766 AH Rhein Würzburg Zw.- Nl. der AH Heermann u. Rhein GmbH, Würzburg	Automatic
---	------------	---------	-----------	--	-----------



—	04/04/2025	Repair	184655 km	02766 ,	Job: Räder-Komplettpaket Räder Job
---	------------	--------	-----------	---------	---------------------------------------

— Job: Räder-Komplettpaket Räder

Description: *** Bitte Räder nach 50 km nachziehen ***

Is interpreted as a repeat visit: No

Customer's own words:

Räder-Komplettpaket Räder
Package I 0499104

Räder-Komplettpaket Rädermontage 163673105 Flat rate unit I -	Local	6
Einlagerung + Reinigung Räder (ext. Dienstleister) Flat rate unit I 99 99 999	Local	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hauptuntersuchung § 29 + Abgasuntersuchung Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

—	04/04/2025	Repair	184655 km	02766 ,	Job: Service Bremsflüssigkeit Job: Service Standardumfang
---	------------	--------	-----------	---------	--

— Job: Service Bremsflüssigkeit

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Bremsflüssigkeit
Package I 0000618

Brake fluid service

Flat rate unit I 00 00 618

Bremsflüssigkeit DOT4
Part I FT9999000011

Local 1

— Job: Service Standardumfang

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang
Package I 0000105

Standard scope of service 2
Flat rate unit I 00 00 105

— 01/13/2025 Repair 177264 km 02766 , Job

— Job

Description: *** Bitte Räder nach 50 km nachziehen ***

Is interpreted as a repeat visit: No

Customer's own words:

Goodyear Ultra Grip Performance G1 ROF 4
Part I 85 45 2 729 079

Vier Reifen ersetzen bis
Package I 0499184

Vier Reifen ersetzen bis einschl. 18 Zoll Local 24
Flat rate unit I -

Reifenentsorgung Local 4
Flat rate unit I 99 99 999

— 01/03/2025 Key 177264 km 02766 Key 0



26000
10/2026



26000
10/2026



17000
04/2025



60000
10/2028



60000
04/2025

— 11/25/2024 Repair 175367 km 02766 , Job

— Job

Description: Radsatz 161561821

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung + Reinigung Räder (ext. Dienstleister) Local 1 FRU
Flat rate unit I 99 99 999

— 11/12/2024 Repair 175367 km 02766 , Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing radial shaft seal for input flange of rear axle differential 18 FRU
Flat rate unit I 33 11 021

Recharging vehicle battery 1 FRU
Flat rate unit I 61 21 509


Shaft seal 1
Part I 33 10 7 609 536

Screw plug with O-ring 2
Part I 33 11 7 525 064


Repair kit recessed nut blue 1
Part I 33 12 7 607 158

Hypoid axle oil G1 1
Part I 83 22 2 295 532


— 11/11/2024 Key 175367 km 02766 Key 0



— 10/25/2024 Key 174874 km 02766 Key 0




— 10/11/2024 Key 173186 km 02766 Key 0



— 10/11/2024 Service 173186 km 02766 AH Automatic

Rhein
Würzburg Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Würzburg



—	10/11/2024	Repair	173186 km	02766 ,	Job
---	------------	--------	-----------	---------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
---------------------------	-------

Flat rate unit I 00 00 105

Fuel filter service	3 FRU
---------------------	-------

Flat rate unit I 00 00 604

Service - air filter insert	2 FRU
-----------------------------	-------

Flat rate unit I 00 00 602

Service - microfilter	2 FRU
-----------------------	-------

Flat rate unit I 00 00 616

Engine oil service	3 FRU
--------------------	-------

Flat rate unit I 00 00 610

Service Inclusive - Pauschale Vergütung	Local	1 FRU
---	-------	-------

Flat rate unit I 99 99 999

Vehicle check service	6 FRU
-----------------------	-------

Flat rate unit I 00 00 624

Fuel filter cartridge	1
-----------------------	---

Part I 13 32 7 822 497

Air filter element	1
--------------------	---

Part I 13 71 8 511 668

Microfilter/activated Carbon container	1
--	---

Part I 64 11 9 237 555

Set oil-filter element	1
------------------------	---

Part I 11 42 8 575 211

Shell Helix Ultra ECT SAE 0W-30 BMW Longlife 04	Local	5
---	-------	---

Part I FT9030

—	10/11/2024	Repair	173186 km	02766 ,	Job Job
---	------------	--------	-----------	---------	------------

— Job

Description: Kommentar:GA Service Inclusive für Kommentar: Gebrauchtwagen - 3 Jahre / Kommentar: 40.000 km 36 Monate / Kommentar: 213186 km Kommentar:11.10.2024 - 10.10.2027 Kommentar: (U7US)

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description: HINWEISE: - neuer Termin -> HAG Getriebe mitte undicht - Verbandskasten abgelaufen - kunde kümmert sich selbst - Wischer schmieren leicht - Verschleißanzeige VoLi ausgehängt - erledigt

Is interpreted as a repeat visit: No

Customer's own words:

—	09/18/2024	Repair	0 km	02766 ,	Job
---	------------	--------	------	---------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Control unit for front light electronics
Part | 63 11 8 494 844

1

—	07/25/2024	Key	163294 km	02766	Key 0
---	------------	-----	-----------	-------	-------

										
6000	6000	6000	6000	29000	70000	6000				
08/2025	08/2025	08/2025	08/2025		04/2025		08/2025			04/2025

—	05/21/2024	Key	159274 km	02766	Key 0
---	------------	-----	-----------	-------	-------

										
10000	10000	10000	10000	34000	80000	10000				
08/2025	08/2025	08/2025	08/2025		04/2025		08/2025			04/2025

—	05/21/2024	Repair	159275 km	02766 ,	Job Job Job Job
---	------------	--------	-----------	---------	--------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Performing vehicle test
Flat rate unit | 00 00 556
2 FRU

Verbringungskosten Lackiererei
Flat rate unit | -
Local
12 FRU

Batteriestützbetrieb durhführe
Flat rate unit | -
Local
1 FRU

Removing and installing/replacing support for front bumper cover
Flat rate unit | 51 11 551
10 FRU

Replace bumper cover, front
Flat rate unit | 51 11 592
12 FRU

Removing and installing front bumper panel
Flat rate unit | 51 11 656
9 FRU

Adjusting headlights	2 FRU
Flat rate unit I 63 10 502	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Painting bumper cover, front	0 FRU
Flat rate unit I 99 68 535	

Work time without specification/paintwork	0 FRU
Flat rate unit I 99 99 000	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Screw	4
Part I 07 12 9 907 535	

Oval-head screw with spring washer	6
Part I 07145A48F73	

Hex bolt	1
Part I 07 14 9 126 886	

Fillister head screw	4
Part I 07 14 9 227 852	

Fillister head screw	2
Part I 07 14 9 321 070	

Expanding rivet	8
Part I 51 11 1 908 077	

Mount, side wall front, upper left	1
Part I 51 11 7 255 361	

Insert, air intake, center	1
Part I 51 11 7 386 152	

Support, fog lamp left	1
Part I 51 11 7 386 361	

Air inlet finisher, left	1
Part I 51 11 7 396 841	

Partially open grid, left	1
Part I 51 11 7 396 877	

Shock absorber front	1
Part I 51 11 7 396 916	

Trim cover, bumper, primed, front	1
Part I 51 11 7 427 120	

C-clip nut	6
Part I 51 71 7 065 773	

Badge	1
-------	---

Headlight, LED, AHL, left Part I 63 11 7 419 627	1
Front fog lamp, LED, left Part I 63 17 7 315 559	1
Klein- und Verbrauchsmaterial Part I FT99 99 9 999 0	Local1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Lackierarbeiten 27 AW inkl. 40% Lackiermaterial 00000000 Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

— 05/13/2024 Key 158508 km 02766 Key 0

 11000 08/2025	 11000 08/2025	 11000 08/2025	 11000 08/2025	 35000 08/2025	 80000 04/2025	 11000 08/2025	 04/2025
---	---	---	---	---	---	---	--

— 10/31/2023 Key 146477 km 02766 Key 0

 24000 08/2025	 24000 08/2025	 24000 08/2025	 24000 08/2025	 49000 08/2025	 7000 04/2025	 24000 08/2025	 04/2025
---	---	---	---	---	--	---	--

— 10/31/2023 Service 146477 km 02766 AH Automatic

Rhein
Würzburg Zw.-
Nl. der AH
Heermann u.
Rhein GmbH,
Würzburg

 24000	 24000	 24000	 24000	 49000	 7000 ✓	 24000	
--	--	--	--	--	--	--	---

— 10/31/2023 Repair 146477 km 02766 AH Job

Rhein
Würzburg Zw.-
Nl. der AH
Heermann u.
Rhein GmbH,
Würzburg

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/renewing both brake discs	4 FRU
Flat rate unit I 34 21 932	
Rear brakes service	7 FRU
Flat rate unit I 00 00 614	
Hex screw with collar	4
Part I 34 20 6 850 536	
Inner hex bolt	2
Part I 34 21 1 161 806	
Brake disc, ventilated	2
Part I 34 21 6 864 900	
Repair kit brake pads asbestos-free	1
Part I 34 21 8 855 013	
Brake pad wear sensor, rear	1
Part I 34 35 6 792 292	
Brake pad paste	2
Part I 83 19 2 158 851	
Brake cleaner, acetone-free	1
Part I 83 19 2 413 695	

— 08/01/2023 Key 139723 km Key 0

 200 11/2023	 200 11/2023	 200 11/2023	 60000 04/2025	 7000 11/2025	 31000 04/2025	 04/2025
---	---	---	---	--	---	--

— 08/01/2023 Service 139723 km 02766 AH Automatic

Rhein
Würzburg Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Würzburg

 200 ✓	 200 ✓	 200 ✓	 60000	 7000	 31000	
---	---	---	--	---	--	---

— 08/01/2023 Repair 139723 km 02766 AH Job
Rhein Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Shell Helix Ultra ECT SAE 0W-30 BMW Longlife 04 Part I FT9030	Local	5
--	-------	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

Windshield Washer Antifreeze Part I 83 12 2 181 287	1
--	---

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Inclusive - Pauschale Vergütung 00000000 87000200007 Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

— 05/08/2023 Key

131674 km

Key 0


9000
11/2023


9000
11/2023


9000
11/2023


60000
04/2025


60000
04/2025


7000
11/2025


39000
04/2025


39000
04/2025


39000
04/2025

— 05/04/2023 Key

131501 km

Key 0


9000
11/2023


9000
11/2023


9000
11/2023


60000
04/2025


60000
04/2025


7000
11/2025


39000
04/2025



39000
04/2025


39000
04/2025


— 04/25/2023 Key

130438 km

Key 0



— 04/25/2023 Service 130438 km 02766 AH Automatic
Rhein
Würzburg Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Würzburg



— 04/25/2023 Repair 130438 km 02766 AH Job
Rhein
Würzburg Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Würzburg

— Job

Description:

Is interpreted as a repeat visit: No


Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

Brake fluid service 4 FRU
Flat rate unit I 00 00 618

Bremsflüssigkeit DOT4 Local 1
Part I FT99 99 0 000 0

— 11/22/2021 Key 109915 km Key 0



— 11/22/2021 Service 106153 km 02766 AH Automatic
Rhein
Würzburg Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Würzburg

								
2000	2000	2000	2000	2800		19000	2000	
✓	✓	✓	✓	✓			✓	

— 05/14/2021 Key 94085 km Key 0

								
15000	15000	15000	15000	35000	0	35000	15000	0
07/2022	442	442	442		01/2023		07/2022	-15 2.1 %

— 04/21/2021 Repair 93400 km 02766 AH Rhein Würzburg Zw.-NI. der AH Heermann u. Rhein GmbH , Würzburg Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01154*BM8D41

Local

Statutory emission test
Flat rate unit I 00 00 440

4

!!! unknown BMW-Id 155 Hauptuntersuchung §29 !!!
Part I 155

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 0171/8181085 !!!
Flat rate unit I -

Local

0 FRU

— 01/11/2021 Key 87503 km Key 0

								
19000	19000	19000	19000	36000	0	37000	19000	0
07/2022	566	566	566		-11 1.5 %		07/2022	04/2021

— 01/11/2021 Service 87503 km 02766 AH Rhein Würzburg Zw.-NI. der AH Heermann u. Rhein GmbH , Würzburg Automatic

									
19000	19000	19000	19000	36000	0	37000	19000		0
07/2022	07/2022	07/2022	07/2022		12/2020		07/2022		04/2021
					✓				

—	01/11/2021	Repair	87503 km	02766 AH Rhein Würzburg Zw.- Nl. der AH Heermann u. Rhein GmbH , Würzburg	Job Job
---	------------	--------	----------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 4 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service 4 FRU
Flat rate unit I 00 00 618

Bremsflüssigkeit DOT4 Local 1
Part I FT99 99 0 000 0

—	01/11/2021	Repair	87503 km	02766 AH Rhein Würzburg Zw.- Nl. der AH Heermann u. Rhein GmbH , Würzburg	Job Job
---	------------	--------	----------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: TA: Agr kühler prüfen ggf ersetzen

Work time without specification/engine 0 FRU
Flat rate unit I 11 99 000

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 0171/8181085 !!!
Flat rate unit I -

Local

0 FRU

—	10/26/2020	Key	85222 km	02766	Key 0
---	------------	-----	----------	-------	-------

 21000 07/2022	 21000 643	 21000 643	 21000 643	 37000	 0 12/2020	 38000	 21000 07/2022	 0 04/2021
---	---	---	---	--	---	--	--	---

—	10/26/2020	Repair	85222 km	02766 AH Rhein Würzburg Zw.- Nl. der AH Heermann u. Rhein GmbH , Würzburg	Job Job Job Job
---	------------	--------	----------	---	--------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test
Flat rate unit I 00 00 006 4 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Car play ohne FunktionOnline prüfen Software prüfen

Work time without specification/engine electrical system
Flat rate unit I 12 99 000 0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Navi hängt Spor. Navi prüfen Software prüfen und iSS

Work time without specification / vehicle electrical system
Flat rate unit I 61 99 000 0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 0171/8181085 !!!
Flat rate unit I - Local 0 FRU

—	10/02/2020	Key	84334 km	02766	Key 0
---	------------	-----	----------	-------	-------

23000	23000	23000	23000	38000	0	39000	23000		0
07/2022	667	667	667		12/2020		07/2022		04/2021

— 07/13/2020 Service 79183 km OSS-60038621 Manual
Autoservice Siegli GmbH, Weingarten

✓										

— 12/02/2019 Key 65660 km 02766 Key 0

13000	0	13000	0	45000	0	46000	41000		0
04/2021		515			12/2020		04/2023		04/2021

— 11/15/2019 Key 63780 km 02766 Key 0

15000	0	15000	0	46000	0	47000	44000		0
04/2021		532			12/2020		04/2023		04/2021

— 11/15/2019 Repair 63780 km 02766 AH Job
Rhein Job
Würzburg Zw.- Job
Nl. der AH Job
Heermann u.
Rhein GmbH ,
Würzburg

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM040000003*BM8D41

Local

Winterräder montieren
Flat rate unit I 00 00 003

Local

6

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM040099042*BM8D41

Local

Räder ins Fahrzeug legen.
Flat rate unit I 00 99 042

Local

0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM0436000036*BM8D41

Local

Bitte nach 50 km Radmuttern
Flat rate unit I 36 00 036

Local

0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 0171/8181085 !!!
Flat rate unit I -

Local

0 FRU

—	11/15/2019	Repair	63780 km	02766 AH Rhein Würzburg Zw.- Nl. der AH Heermann u. Rhein GmbH , Würzburg	Job: Replace windshield Job
---	------------	--------	----------	---	--------------------------------

— Job: Replace windshield

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace windshield
Package I 5131011

Replace windshield
Flat rate unit I 51 31 011

24

Cover, windshield, top
Part I 51317258053

1

Green windshield
Part I 51317258055

1

Drip moulding, left
Part I 51317258187

1

Drip molding, right
Part I 51317258188

1

Bump stop
Part I 51317288462

11

Clamp
Part I 51437321215

2

Sound insulation f apron

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 0171/8181085 !!!

Local

0 FRU

Flat rate unit I -

— 11/07/2019 Key 63202 km 02766 Key 0

								
16000	0	16000	0	46000	0	47000	45000	0
04/2021		540			12/2020		04/2023	04/2021

— 08/09/2019 Key 59325 km 02766 Key 0

								
20000	0	20000	0	45000	0	46000	49000	0
04/2021		630			12/2020		04/2023	04/2021

— 08/01/2019 Key 58933 km 02766 Key 0

								
20000	0	20000	0	45000	0	46000	49000	0
04/2021		637			12/2020		04/2023	04/2021

— 04/03/2019 Key 49451 km 38793 Key 1

								
6000	6000	6000	6000	40000	0	41000	6000	0
09/2020	545	545	545		12/2020		09/2020	04/2021

— 04/03/2019 Service 49451 km 38793 Automatic

Autohaus
Rhein
Schweinfurt
Zw.Nl der AH
Heermann u.
Rhein GmbH ,
Schweinfurt

								
6000	6000	6000	6000	40000	0	41000	6000	0
09/2020	09/2020	09/2020	09/2020		12/2020		09/2020	04/2021
✓	✓	✓	✓				✓	

—	04/03/2019	Repair	49451 km	38793	Job
				Autohaus	Job
				Rhein	Job
				Schweinfurt	Job
				Zw.NI der AH	Job
				Heermann u.	Job
				Rhein GmbH ,	Job
				Schweinfurt	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service	3 FRU
---------------------	-------

Flat rate unit I 00 00 604

Fuel filter cartridge 1
Part I 13 32 8 572 522

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Shell Helix Ultra ECT SAE 0W-30 BMW Longlife 04 Local 5
Part I FT9030

Set oil-filter element 1
Part I 11 42 8 575 211

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 12/13/2018 Key 43792 km 00131 Key 1

								
12000	12000	12000	12000	-2700	0	-800	12000	0
09/2020	657	657	657		12/2020		09/2020	01/2021

— 12/13/2018 Service 43792 km 00131 Automatic
Autohaus Karl
+ Co.
GmbH&Co. KG
, Mainz

								
12000	12000	12000	12000	-2700	0	-800	12000	0
09/2020	09/2020	09/2020	09/2020		12/2020		09/2020	01/2021

— 12/13/2018 Repair 43792 km 00131 Job
Autohaus Karl Job
+ Co. GmbH & Job
Co. KG , Mainz Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service Flat rate unit I 00 00 614	7 FRU
Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
Brake pad wear sensor, rear Part I 34 35 6 792 292	1
Brake pad paste Part I 83 19 2 158 851	2
Brake cleaner, acetone-free Part I 83 19 2 413 695	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612	6 FRU
Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
Brake pad wear sensor, front left Part I 34 35 6 792 289	1
Brake pad paste Part I 83 19 2 158 851	2
Brake cleaner, acetone-free Part I 83 19 2 413 695	1

— Job

Description:

Is interpreted as a repeat visit: No


Customer's own words:

Mietwagen P.E. Autoverm. FD-MZ 29 00000000	Local	1 FRU
Flat rate unit I 99 99 999		

— 09/04/2018 Key

30905 km

Key 1



—	09/04/2018	Service	30905 km	00131 Autohaus Karl + Co., Mainz	Manual				
									
✓		✓							
—	09/04/2018	Repair	0 km	00131 Autohaus Karl + Co. GmbH & Co. KG , Mainz	Job Job Job Job				

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
Engine oil service Flat rate unit I 00 00 610	3 FRU
Motoröl 5W-30 Castrol Edge LL 04 1000 mltr. Part I FT83 21 0 398 5	Local 5
Set oil-filter element Part I 11 42 8 575 211	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing two tire with run-flat technology Flat rate unit I 36 12 055	17 FRU
Gewicht Part I FT99 99 8 888 9	Local 2
Rep. kit, screw valve for RDCi Part I 36 10 6 876 673	2
Pirelli Cinturato P7 r-f	2

Customer's own words:

3 FRU


0
01/2018
✓

							
15000	15000	15000	15000	35000	0	36000	15000
07/2022	466	466	466		01/2023		07/2022