

Vehicle

BMW 320d, 140kW

WBA8H91080K747801



Development code

Color

Actual integration level

Start of warranty

F31

glacier-silber metallic

F020-22-07-530

June 2, 2016

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2016-1 (as of: Aug 29, 2023)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

▼ Vehicle details

Vehicle type

Passenger car

Brand	BMW
Model	320d
Body	TOUR
Vehicle identification number (last 7 characters)	K747801
Vehicle identification number (17 characters)	WBA8H91080K747801
Development code	F31
Steering	LL
Engine	B47O
Engine number	73139610
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0348137ZRI
Head unit serial number	MM01DFG1568933
Drive	HECK
Integration level	F020-16-03-504
Production date	May 6, 2016
Production works	Muenchen
Delivery date	May 7, 2016
Delivering Retailers	No information
National-market version	EUR
Paint code	A83
Upholstery code	CCL1
Model code	8H01
Base type	8H91
Lead type	8H01

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 EU-specific additional contents
 0258 Tire with run-flat functionality
 02DW BMW LA wheel, Star Spoke 393
 02VB Tire pressure display
 0302 Alarm system
 0320 Deleted, model lettering
 0322 Comfort Access


Retrofitted optional equipment:

This vehicle has no retrofits.


03AC Trailer coupling
 03AT Roof rail, aluminum, satin finish
 0423 Floor mats, velours
 0428 Warning triangle and first aid kit
 0431 Interior mirror with automatic-dip
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04CG Interior strips, "satin-silber" matt
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometer-calibrated speedometer
 0575 Supplementary 12V sockets
 05A2 LED headlight
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 0606 Navigation system Business
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06NH Hands-free with USB interface
 06WA Instrument cluster, expanded equipment
 07LC Modell Advantage
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 08TH Road sign detection
 09AA Outer skin protection
 09BD Business Package
 A090 90 AH AGM battery
 POLS Cloth cushion

▾ Vehicle histories

Date	Type	Vehicle mileage				Dealer				Overview
— 04/24/2026	Key	206134 km				02815				Key 0
 13000 11/2026	 13000 11/2026	 13000 11/2026	 100000 11/2026	 6000 11/2028	 44000 10/2027					
— 02/05/2026	Key	203003 km				00027				Remote KeyRead
 16000 11/2026	 16000 11/2026	 16000 11/2026	 100000 11/2026	 6000 11/2028	 47000 10/2027					
— 10/17/2025	Key	201032 km				00027				Key 0



— 10/17/2025 Service 201032 km 00027 Automatic
Niederlassung
Düsseldorf ,
Düsseldorf



— 10/17/2025 Repair 201032 km 00027 , Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenfreie Wäsche Part I 0011319	Local	1
--------------------------------------	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hauptuntersuchung nach § 29 StVZO Part I 0012159	Local	1
---	-------	---

— Job


Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorführung gem. Anlage VIIIb zu §29 Part I 0012173	Local	1
---	-------	---

— 10/09/2024 Key 187676 km 22772 Remote KeyRead



— 08/29/2023 Key 164148 km 00027 Key 0

									
22000	22000	22000	22000	32000	-28 3.8 %	6000	22000		-59 8.1 %
02/2025	02/2025	02/2025	02/2025				02/2025		

—	08/29/2023	Service	164148 km	00027 Niederlassung Düsseldorf , Düsseldorf	Automatic
---	------------	---------	-----------	--	-----------

									
22000	22000	22000	22000	32000	08/2023	6000	22000		07/2023
02/2025	02/2025	02/2025	02/2025		✓		02/2025		✓

—	08/29/2023	Repair	164148 km	00027 Niederlassung Düsseldorf BMW AG, Düsseldorf	Job Job Job Job Job Job
---	------------	--------	-----------	---	--

—	Job
---	-----

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorführung gem.Anlage VIIIb zu §29 StVZO Part I 0012173	Local	1
Überprüfung nach § 29 STVZO Part I 0012159	Local	1

—	Job
---	-----

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

—	Job
---	-----

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
Brake fluid DOT4 LV, low viscosity Part I 83 13 0 443 030	1

—	Job
---	-----

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 74 635	23 FRU
---	--------

Performing additional work for pressure sensor functional check Flat rate unit I 00 74 636	3 FRU
---	-------

Additional work: enter component identification of new exhaust-gas recirculation cooler in diagnostic system Flat rate unit I 00 74 637	1 FRU
--	-------

Additional work: clean EGR pipe Flat rate unit I 00 74 638	2 FRU
---	-------

Exhaust gas cooler high temperature Part I 11 71 7 822 347	1
---	---

AGR small parts set Part I 11 71 8 490 640	1
---	---

Pipe union Part I 11 71 7 799 853	2
--------------------------------------	---

Vacuum hose black Part I 11 65 8 595 650	1
---	---

Connection piece Part I 11 65 7 803 012	1
--	---

Acoustic cover front Part I 11 14 8 490 577	1
--	---

Anti-freeze Part I 83 19 2 218 347	3
---------------------------------------	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:****— Job****Description:****Is interpreted as a repeat visit:** No**Customer's own words:****— Job****Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Füllmengen prüfen und ergänzen Flat rate unit I AZ00 00 4	Local	1 FRU
--	-------	-------

Fahrzeug-Außen-Wäsche (kostenlos)	Local	1
-----------------------------------	-------	---

Part I 0011319

Ersatzfahrzeug (24 Stunden) Auf GW
Part I 0000160

Local

1








Windshield Washer Antifreeze
Part I 83125A85517

1

— 05/08/2023 Key

156926 km

Key 0



— 05/08/2023 Repair

156926 km

00027
Niederlassung
Düsseldorf
BMW AG,
Düsseldorf

Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Depotservice Rädermontage Sommerräder an
Flat rate unit I AZ36 00 2

Local

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Außen-Wäsche (kostenlos)
Part I 0011319

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: O-Ton Mechaniker:,-Kühlmittelstand ist auf Maximum.,-Fehlerspeicher ausgelesen kein Fehler code 39166257 vorahnden.,-Fehlerspeicher gelöscht.,,

Read out coolant Check Control message (OK)
Flat rate unit I 00 73 827

4 FRU

— 10/24/2022 Key

150515 km

00027

Key 0



7000
08/2023




7000
08/2023




47000



08/2023



6000



35000
08/2025



07/2023

—

10/24/2022 Repair

150515 km

00027
Niederlassung
Düsseldorf
BMW AG,
Düsseldorf

Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Füllmengen prüfen und ergänzen
Flat rate unit I AZ00 00 4

Local

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Depotservice Rädermontage
Flat rate unit I AZ36 00 2

Local

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Außen-Wäsche (kostenlos)
Part I 0011319

Local

1

— Job

Description:

Is interpreted as a repeat visit: No


Customer's own words:

Servicewäsche Upgrade
Part I 0011324


Local

1

— 08/22/2022 Key 148362 km 00027 Key 0



— 08/22/2022 Key 148361 km 00027 Key 0



— 08/22/2022 Repair 148362 km 00027 Niederlassung
Düsseldorf
BMW AG,
Düsseldorf Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Program control units
Flat rate unit I 00 71 349

9 FRU

— Job

Description:

Is interpreted as a repeat visit: No


Customer's own words: Fahrzeug nicht waschen!,,Füllstände auf Kundenwunsch nichtprüfen,

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054

Local

0 FRU

— 10/29/2021 Key 130981 km Key 0



— 10/29/2021 Repair 130981 km 00027 Niederlassung
Düsseldorf Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: WR legen im Fahrzeug, SR ins Fahrzeug,

Depotservice Rädermontage Flat rate unit I AZ36 00 2	Local	6 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Füllmengen prüfen und ergänzen Flat rate unit I AZ00 00 4	Local	1 FRU
--	-------	-------

Windshield Washer Antifreeze Part I 83125A1A166		1
--	--	---

— 08/20/2021 Key 128406 km Key 0



— 08/20/2021 Repair 128409 km	00027	Job
	Niederlassung	Job
	Düsseldorf	Job
	BMW AG,	Job
	Düsseldorf	Job
		Job
		Job
		Job
		Job
		Job
		Job
		Job
		Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602	2 FRU
---	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Ölzuschlag für Service Inklusive Part I 0000162	Local	1
--	-------	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
--	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Windshield Washer Antifreeze Part I 83125A1A166	1
--	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

kostenlose Fahrzeugoberwäsche Part I 0011319	Local	1
---	-------	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
---	-------	-------

Zusatz zum Fahrzeugcheck / Inspektion Flat rate unit I AZ10 00 1	Local	2 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Set of wiper blades Part I 61615A43585	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade Flat rate unit I 61 61 541	1 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Füllmengen prüfen und ergänzen Flat rate unit I AZ00 00 4	Local	1 FRU
--	-------	-------

—	08/20/2021	Repair	128406 km	00027 Niederlassung Düsseldorf BMW AG, Düsseldorf	Job
---	------------	--------	-----------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Nachrüstung Service-Inclusive 3Jahre /16 Part I 5100102	Local	1
--	-------	---

—	08/19/2021	Service	128406 km	00027 Niederlassung Düsseldorf , Düsseldorf	Automatic
---	------------	---------	-----------	--	-----------

-3600	-3600	-3600	-3600	80000	0	12000	-3600	0
01/2022	01/2022	01/2022	01/2022		06/2021		01/2022	06/2021
✓	✓	✓	✓		✓		✓	

— 02/24/2020 Key 96268 km 00081 Key 1

30000	30000	30000	30000	60000		45000	30000	
01/2022	667	667	667		06/2021		01/2022	06/2021

— 02/24/2020 Repair 96268 km 00081
 Niederlassung
 Berlin BMW
 AG, Berlin
 Job
 Job
 Job
 Job
 Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Q085389///Laut der Rep.-Anleitung sind beide Radialdichtringe zu,ers./Bilder sind unter der Auftragsnummer im Netz gespeichert!!!,

Replace left and right radial shaft seal for driven shafts on rear axle differential 24 FRU
 Flat rate unit I 33 10 024

ASA-Bolt 3
 Part I 26 11 7 621 344

Repair kit recessed nut blue 1
 Part I 33 12 7 607 158

Screw plug with O-ring 1
 Part I 33 11 7 525 064

Gasket set differential 2
 Part I 33 10 7 564 416

Assembly ring 2
 Part I 31 53 7 502 681

Hex bolt with washer 2
 Part I 33 17 6 760 343

Bolt 1
 Part I 33 17 6 872 924

Self-locking collar nut 1
 Part I 33 30 6 760 349

Torx bolt 2
 Part I 33 30 6 861 221

Hex nut wiht flange 1
 Part I 31 31 6 771 889

Muffler clamp	1
Part I 18 30 8 581 218	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug	Local	1
Part I 52050		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Standard Fahrzeugpflege	Local	1
Part I 00200		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	02/24/2020	Repair	96268 km	00081 Niederlassung Berlin BMW AG, Berlin	Job
---	------------	--------	----------	--	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

HandlingCharge GWL/WTY	Local	1
Part I 99 99 7 777 701		

—	01/31/2020	Key	95970 km	00081	Key 1
---	------------	-----	----------	-------	-------

 -4300 09/2020	 	 -4300 210	 	 60000	 06/2021	 45000	 26000 09/2022	 06/2021
--	--	--	--	---	---	---	---	---

— 01/31/2020 Key 95968 km 00081 Key 1

 -4300 09/2020	 	 -4300 210	 	 60000	 06/2021	 45000	 26000 09/2022	 06/2021
---	---	---	---	--	--	--	--	--

— 01/31/2020 Service 95968 km 00081 Automatic
Niederlassung
Berlin , Berlin

 -4300 09/2020 ✓	 0	 -4300 09/2020 ✓	 0	 60000	 0 06/2021	 45000	 26000 09/2022	 0 06/2021
--	--	--	--	--	---	--	--	---

— 01/31/2020 Repair 95968 km 00081
Niederlassung
Berlin BMW
AG, Berlin
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter
Flat rate unit I 00 00 616

2 FRU

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Beide Wischerblätter vorn ersetzen (Sond Flat rate unit I NL61 00 1	Local	2 FRU
--	-------	-------

Set of wiper blades Part I 61 61 2 241 375	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Flüssigkeitsstände im Motorraum prüfen Flat rate unit I AZ00 00 9	Local	1 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug Part I 52050	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorwäsche
Part I 0099351

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Servicewäsche Plus
Part I 0099620

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No










Customer's own words:

— 06/19/2019 Key

81988 km

26796

Key 0












— 06/19/2019 Service

81988 km

26796

Automatic

Niederlassung
Berlin Filiale
Marzahn ,
Berlin



— 06/19/2019 Repair

81988 km

26796

Job

Niederlassung
Berlin Filiale
Marzahn BMW
AG, Berlin
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service		2 FRU
Flat rate unit I 00 00 105		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service		4 FRU
Flat rate unit I 00 00 618		

Brake fluid DOT4 LV, low viscosity		1
Part I 83 13 2 184 843		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Überprüfung nach § 29 STVZO	Local	1
Part I 0012159		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Flüssigkeitsstände im Motorraum prüfen	Local	1 FRU
Flat rate unit I AZ00 00 9		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug	Local	1
Part I 52050		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Standard Fahrzeugpflege	Local	1
Part I 00200		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	11/13/2018	Key	66341 km				Key 1		
									
27000	0	27000	0	60000	0	70000	60000		0
09/2020		686			05/2019		09/2022		06/2019

—	10/12/2018	Key	63277 km				Key 1		
									
29000	0	29000	0	60000	0	70000	60000		0
09/2020		719			05/2019		09/2022		06/2019

—	10/12/2018	Repair	66341 km	35658	Job
				Autohaus Fink	Job
				GmbH & Co.	Job
				KG , Kempten	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorder- und hinter Räder wuchten (Ohne Berechnung)	Local	8 FRU
Flat rate unit I 36 00 008		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Wagenwäsche kostenlos Fußräume aussaugen (ohne Berechnung)	Local	0 FRU
Flat rate unit I 99 11 111		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	09/28/2018	Key	62513 km	Key 1				
								
30000	0	30000	0	60000	0	70000	60000	0
09/2020		733			05/2019		09/2022	06/2019
—	09/28/2018	Repair	62513 km	00664	Job			
				Niederlassung	Job			
				München	Job			
				Filiale	Job			
				Fröttmaning	Job			
				BMW AG,				
				München				

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: 0011830400 : B47O AGR-Kühler ersetzen,F10 F11 F25 F26 F31 F34 F36,Achtung!!! Fahrzeug wurde eingeschleppt. Fahrzeug hat Kühlmittelverlust,„Ausgleichbehälter ist leer. Fahrzeug zeigt bei starten "Kühlm ittelstand,prüfen" an. Motor hat beim Rückwärtsfahren geruckelt und ist ausgegangen,und weißer Rauch kam aus dem Auspuff,bitte prüfen ob weiterer Schadenvorliegt,

Replace exhaust gas recirculation cooler and clean exhaust gas recirculation pipe	26 FRU
Flat rate unit I 00 66 769	

exhaust cooler	1
Part I 11 71 8 477 659	

AGR small parts set	1
Part I 11 71 8 490 222	

Pipe union	2
Part I 11 71 7 799 853	

Anti-freeze	4
Part I 83 19 2 211 358	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Füllstände prüfen und nicht ergänzen	Local	1 FRU
Flat rate unit I AZ00 33 4		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Endkontrolle	Local	1 FRU
Flat rate unit I AZ00 45 0		

Service consultation at the vehicle		1 FRU
-------------------------------------	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche Part I 0011319	Local	1
---	-------	---


— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:

—	09/20/2018	Key	62137 km	Key 1
---	------------	-----	----------	-------



—	09/20/2018	Service	62137 km	35658 Fink GmbH u. Co.KG, Kempten	Automatic
---	------------	---------	----------	-----------------------------------	-----------



—	09/20/2018	Repair	62137 km	35658 Autohaus Fink GmbH & Co. KG , Kempten	Job Job Job Job Job Job Job Job Job
---	------------	--------	----------	---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Glass cleaner without antifreeze Part I 83 12 2 452 029	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

BMW Engine Oil LL04 0W30	5
Part I 83 21 2 405 950	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

Vehicle interior filt..f.housing cleaner	1
Part I 83 19 2 451 455	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service	3 FRU
Flat rate unit I 00 00 604	

Entsorgung	Local	1
Part I FT99199000000		

Fuel filter cartridge	1
Part I 13 32 8 572 522	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service 6 FRU
Flat rate unit I 00 00 624

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Beanstandung : Meldung Kühlwasser nachfüllen/ nachgefüllt,kommt Local 0 FRU
wieder
Flat rate unit I -

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Check the cooling system for watertightness with the special tool 3 FRU
Flat rate unit I 17 00 509

Anti-freeze 0.5
Part I 83 19 2 218 347

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Wagenwäsche kostenlos Fußräume aussaugen (ohne Berechnung) Local 0 FRU
Flat rate unit I 99 11 111

— 07/30/2018 Key 57887 km 35658 Key 0

								
6000	6000	6000	6000	2800	0	5000	6000	0
08/2019	396	396	396		05/2019		08/2019	06/2019

— 06/06/2018 Repair 0 km 26842 BMW Job
Mobiler Service
Einsatzleitzentrale
, München

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 06/01/2018 Key 54016 km 00027 Key 0



10000
08/2019



10000
455



10000
455



10000
455



11000



0
05/2019



5000



10000
08/2019



0
06/2019

— 06/01/2018 Repair 53996 km 26842 BMW Mobiler Service Einsatzleitzentrale, München Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 06/01/2018 Repair 54016 km 00027 Niederlassung Düsseldorf BMW AG, Düsseldorf Job Job Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test 4 FRU
Flat rate unit I 00 00 006

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle diagnosis, ABL 0 FRU
Flat rate unit I 61 00 006

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

TC: 10011450400 Local 1 FRU
Flat rate unit I -

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01000462

Local

Sichtkontrolle Flüssigkeiten nachfüllen JA / NEIN

Local

2

Flat rate unit I AZ00 00 0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02000323

Local

Service Standard Fahrzeugpflege

Local

1

Part I IF00200

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 0162/2546215 !!!

Local

0 FRU










Flat rate unit I -

— 09/12/2017 Key

36467 km

35658

Key 1



— 09/12/2017 Repair

36468 km

35658

Job

Autohaus Fink
GmbH & Co.
KG, Kempten

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder montieren Sommerräder waschen und ins Fahrzeug legen Local

6 FRU










Flat rate unit I 36 00 004

— 08/16/2017 Key

35029 km

35658

Key 0












— 08/16/2017 Service

35029 km

35658 Fink
GmbH u.
Co.KG,
Kempten

Automatic



-7000
05/2018

0

-7000
05/2018

0

29000

0
05/2019

20000

20000
05/2020

0
06/2019

—	08/16/2017	Repair	35034 km	35658	Job
				Autohaus Fink	Job
				GmbH & Co.	Job
				KG , Kempten	Job
					Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

BMW Engine Oil LL04 0W30	5
Part I 83 21 2 405 950	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Entsorgung	Local	1
Part I FT99199000000		

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

Pollen filter housing cleaner	1
Part I 83 19 2 180 509	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job


Description:

Is interpreted as a repeat visit: No

Customer's own words:

Wagenwäsche kostenlos Fußräume ausgesaugt (ohne Berechnung) Local 1 FRU
Flat rate unit I 99 11 111

— 04/11/2017 Key 22251 km 02815 Key 1



— 04/11/2017 Repair 22251 km 02815 Job
Niederlassung
Düsseldorf
Filiale Rath
BMW AG,
Düsseldorf

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm Local 0 FRU
Flat rate unit I 00 52 054

Radsatz auslagern 10784804 angeliefert a Local 2 FRU
Flat rate unit I AZ36 00 1

— 12/16/2016 Repair 11582 km 02815 Job
Niederlassung Job
Düsseldorf Job
Filiale Rath
BMW AG,
Düsseldorf

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

RDCi wheel & tire, winter, steel 4
Part I 36 11 2 448 002

Wheel cover 4
Part I 36 13 6 791 806

Railing carrier 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Depotservice Rädermontage Flat rate unit I AZ36 00 2	Local	6 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerungskosten Part I 0036007	Local	1
--------------------------------------	-------	---