

Vehicle

BMW 320d xDrive, 140kW

WBA8J11050K624527



Development code	F31
Color	black-sapphire metallic
Actual integration level	F020-22-03-552
Start of warranty	August 27, 2015

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE WEST Route 2021-1 (as of: Jun 3, 2025)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	320d xDrive
Body	TOUR
Vehicle identification number (last 7 characters)	K624527
Vehicle identification number (17 characters)	WBA8J11050K624527
Development code	F31
Steering	LL
Engine	B47O
Engine number	50549337
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0047778ZEL
Head unit serial number	MM01DFF0908359
Drive	ALLR
Integration level	F020-15-07-503
Production date	Aug 4, 2015
Production works	Muenchen
Delivery date	Sep 14, 2015
Delivering Retailers	No information
National-market version	EUR
Paint code	475
Upholstery code	CCL1
Model code	8J21
Base type	8J11
Lead type	8J21

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 EU-specific additional contents
 0258 Tire with run-flat functionality
 02VB Tire pressure display
 02XE Sport leather steering wheel
 0302 Alarm system
 0322 Comfort Access
 03AA Roof railing black
 0423 Floor mats, velours

Retrofitted optional equipment:

This vehicle has no retrofits.

0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0441 Smoker package
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04LU Black, highgloss Perlglanz chrome accent
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometer-calibrated speedometer
 0563 Light package
 0575 Supplementary 12V sockets
 05A1 LED Fog lights
 05A2 LED headlight
 05AC High-beam assistant
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 0606 Navigation system Business
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NH Hands-free with USB interface
 06WA Instrument cluster, expanded equipment
 07AC Sport Line
 07LD Modell Sport Line
 07S9 Connected Drive Services Paket
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 0931 Winter instead of summer tires ex-fact.
 09AA Outer skin protection
 09BD Business Package
 A090 90 AH AGM battery
 POLS Cloth cushion

▾ Vehicle histories

	Date	Type	Vehicle mileage	Dealer	Overview
—	06/02/2025	Key	196031 km	00525	Key 1



15000
06/2026



15000
06/2026



21000
✓



06/2026



5000



44000
06/2028



06/2026

—	06/02/2025	Repair	196034 km	00525 ,	Job: Service Standardumfang Job: Service Bremse vorn Job: Beide Bremsscheiben vorn Job Job
---	------------	--------	-----------	---------	--

— Job: Service Standardumfang

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang
Package I 0000105

Standard scope of service	2
Flat rate unit I 00 00 105	

— Job: Service Bremse vorn

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Bremse vorn
Package I 0000612

Service - front brakes	6
Flat rate unit I 00 00 612	
Repair kit brake pads asbestos-free	1
Part I 34 11 8 855 010	
Brake pad wear sensor, front left	1
Part I 34 35 6 792 289	
Brake pad paste	2
Part I 83 19 2 158 851	
Brake cleaner, acetone-free	1
Part I 83 19 2 413 695	

— Job: Beide Bremsscheiben vorn

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Beide Bremsscheiben vorn
Package I 3411613

Removing and installing/replacing both front brake discs	3
Flat rate unit I 34 11 613	

Torx screw with washer Part I 34 10 6 864 424	4
Brake disc, ventilated Part I 34 11 8 848 417	2
Inner hex bolt Part I 34 21 1 161 806	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing fluid in brake system Flat rate unit I 34 00 527	6 FRU
---	-------

Work time without specification/brakes Flat rate unit I 34 99 000	24 FRU
--	--------

Pipe - DSC - hydraulic unit- Part I 34 32 6 865 581	1
--	---

Pipe - DSC - hydraulic unit- Part I 34 32 6 865 583	1
--	---

Clip Part I 34 34 1 163 565	2
--------------------------------	---

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

Überwurfschraube 24.3516-0010.1 Part I SALL	Local	4
--	-------	---

Zwischenstück,Bremsl. 9306.0303 Part I SALL	Local	2
--	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Painting 20 percent extra Flat rate unit I 99 99 001	2 FRU
---	-------

— 05/20/2025 Key 195460 km 00525 Key 1

 16000 06/2026		 16000 06/2026		 21000	 06/2026	 5000	 45000 06/2028	 06/2026
---	---	---	---	--	--	---	--	--

— 05/20/2025 Repair 196034 km 00525 , Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment Flat rate unit I 51 99 000	1 FRU
Replacing windshield Flat rate unit I 51 31 511	23 FRU
Additional work with rain/light sensor Flat rate unit I 61 35 994	3 FRU
Windshield, green, rain/light/fog Part I 51 31 7 258 063	1
Repair flat rate, window, cold, 1 hr. Part I 83 19 2 289 285	1
Cover, windshield, top Part I 51 31 7 258 053	1
Clamp Part I 51 43 7 321 215	2
Bump stop Part I 51 31 7 288 462	11
Cleaner R1 Part I 83 19 2 211 217	1
Sound insulation f apron Part I 51 48 7 325 890	1
Drip moulding, left Part I 51 31 7 258 187	1
Drip molding, right Part I 51 31 7 258 188	1
Replacemt.small plates, low beam sensor Part I 61 35 9 856 157	1
Clip, drip molding Part I 51 13 7 258 183	10

—	05/20/2025	Repair	195461 km	00525 ,	Job Job Job Job
---	------------	--------	-----------	---------	--------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder montieren, Winterr äder einlagern Flat rate unit I 36 00 001	Local	5 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räder Reinigen / einlagern
Flat rate unit I 36 00 005

Local

5 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash
Flat rate unit I 00 11 319

2 FRU

Painting 20 percent extra
Flat rate unit I 99 99 001

2 FRU


— Job

Description: Info: Bremse vorne kurz vor Verschleiß Zugstrebenlager rissig li+re Bremsleitungen hinten aufgequollen
Zusatzdämpfer Stoßdämpfer hinten defekt


Is interpreted as a repeat visit: No

Customer's own words:

— 04/28/2025 Key 194482 km 00525 Remote KeyRead



— 11/14/2024 Key 187770 km 00525 Key 1



— 11/14/2024 Repair 187773 km 00525 , Job

— Job

Description: Die Sommerräder wurden angeliefert und neu eingelagert.

Is interpreted as a repeat visit: No


Customer's own words:

Rädereinlagerung Saison incl. Reinigung
Flat rate unit I 36 00 006

Local

6 FRU

— 06/04/2024 Key 181740 km 00525 Key 1



—	06/04/2024	Service	181740 km	00525 Autohaus Konrad Fink e. K., Immenstadt	Automatic
---	------------	---------	-----------	--	-----------

								
2100 05/2024	2100 05/2024	2100 05/2024	2100 05/2024	34000	05/2024	5000	2100 05/2024	05/2024
✓	✓	✓	✓		✓		✓	✓

—	06/04/2024	Repair	181743 km	00525 ,	Job Job Job Job Job Job Job Job Job Job Job Job Job Job
---	------------	--------	-----------	---------	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

Battery Part I 61 31 9 217 643	1
BMW TwinPower Turbo LL-19FE 0W-30 Part I 83215A65BF8	5
Entsorgung Part I FT99 19 9 000 0	Local 5

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	3 FRU
Fuel filter cartridge Part I 13 32 7 822 497	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602	2 FRU
Air filter element Part I 13 71 8 511 668	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Sommerräder montieren, Winterräder einlagern
Flat rate unit I 36 00 001

Local

9 FRU

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Räder Reinigen / einlagern
Flat rate unit I 36 00 005

Local

5 FRU

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Presentation for emission inspection
Flat rate unit I 00 00 527

5 FRU

(statutory) general inspection
Flat rate unit I 00 12 159

1 FRU

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Outside car wash
Flat rate unit I 00 11 319

1 FRU

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Painting 20 percent extra
Flat rate unit I 99 99 001

2 FRU

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

TÜV Gebühren 00000000
Flat rate unit I 99 99 999

Local

1 FRU

								
2700	2700	2700	2700	34000	-5 0.7 %	5000	2700	-5 0.7 %
-5 0.7 %	-5 0.7 %	-5 0.7 %	-5 0.7 %		-5 0.7 %		-5 0.7 %	-5 0.7 %

— 10/10/2023 Key 172692 km 00525 Key 1

								
12000	12000	12000	12000	43000		13000	12000	
05/2024	05/2024	05/2024	05/2024	05/2024	05/2024	05/2024	05/2024	05/2024

— 10/10/2023 Service 172692 km 00525 Automatic
Autohaus
Konrad Fink e.
K. ,
Immenstadt

								
12000	12000	12000	12000	43000		13000	12000	
05/2024	05/2024	05/2024	05/2024	05/2024	05/2024	05/2024	05/2024	05/2024
						✓		

— 10/10/2023 Repair 172695 km 00525 Job
Autohaus Job
Konrad Fink e. Job
K. , Job
Immenstadt Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service Flat rate unit I 00 00 614	7 FRU
Repair kit brake pads asbestos-free Part I 34 21 8 855 013	1
Brake pad wear sensor, rear Part I 34 35 6 792 292	1
Brake pad paste Part I 83 19 2 158 851	2
Brake cleaner, acetone-free Part I 83 19 2 413 695	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/renewing both brake discs Flat rate unit I 34 21 932	4 FRU
Hex screw with collar Part I 34 20 6 850 536	4
Inner hex bolt Part I 34 21 1 161 806	2
Brake disc, ventilated Part I 34 21 6 864 900	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder montieren,Sommer- räder einlagern Flat rate unit I 36 00 003	Local	6 FRU
Rädereinlagerung Saison incl. Reinigung LAGERORT: / Flat rate unit I 36 00 006	Local	5 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash Flat rate unit I 00 11 319	2 FRU
Painting 20 percent extra Flat rate unit I 99 99 001	2 FRU

								
17000	17000	17000	17000	47000		18000	17000	
05/2024	05/2024	05/2024	05/2024		05/2024		05/2024	05/2024

—	05/15/2023	Repair	167925 km	00525	Job
				Autohaus	Job
				Konrad Fink e.	Job
				K. ,	
				Immenstadt	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räder Reinigen / einlagern	Local	5 FRU
Flat rate unit I 36 00 005		
Sommerräder montieren, Winterr äder einlagern	Local	9 FRU
Flat rate unit I 36 00 001		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kundenbeanstandung: Hupe ohne Funktion bitte Prüfen	Local	12 FRU
Flat rate unit I 00 00 043		
Work time without specification / vehicle electrical system		3 FRU
Flat rate unit I 61 99 000		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Painting 20 percent extra		2 FRU
Flat rate unit I 99 99 001		

—	10/18/2022	Key	160422 km	00525	Key 1
---	------------	-----	-----------	-------	-------

								
25000	25000	25000	25000	60000		28000	25000	
05/2024	05/2024	05/2024	05/2024		05/2024		05/2024	05/2024

—	10/18/2022	Repair	160423 km	00525	Job
				Autohaus	Job
				Konrad Fink e.	
				K. ,	
				Immenstadt	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder montieren,Sommer- räder einlagern
Flat rate unit I 36 00 003

Local

6 FRU

Einlagerungsgebühr Saison incl . Räderreinigung
Flat rate unit I 36 00 005

Local

5 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Painting 20 percent extra
Flat rate unit I 99 99 001


2 FRU

— 06/23/2022 Key

155980 km

00525

Key 0




— 05/13/2022 Key

155043 km

00525

Key 0




— 05/13/2022 Service

155043 km

00525

Automatic

Autohaus
Konrad Fink e.
K. ,
Immenstadt



— 05/04/2022 Repair

155045 km

00525

Autohaus
Konrad Fink e.
K. ,
Immenstadt

Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing four tires with run-flat technology Flat rate unit I 36 12 076	30 FRU
---	--------

Entsorgung Part I FT99 19 9 000 0	Local	3
--------------------------------------	-------	---

Continental SportContact 5 SSR Part I 85 45 2 548 316	1
--	---

Continental SportContact 5 SSR Part I 85 45 2 593 793	2
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder montieren, Winter- räder einlagern Flat rate unit I 36 00 001	Local	5 FRU
--	-------	-------

Einlagerungsgebühr Saison incl. Räderreinigung 18`` und größer Flat rate unit I 36 00 006	Local	4 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

BMW Engine Oil LL04 0W30	5
Part I 83 21 2 405 950	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Statutory emission test	4 FRU
Flat rate unit I 00 00 440	

(statutory) general inspection	1 FRU
Flat rate unit I 00 12 159	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Replace left and right wiper blade	2 FRU
Flat rate unit I 61 61 541	

Set of wiper blades	1
Part I 61615A43585	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Oberwäsche ohne Berechnung	Local	2 FRU
Flat rate unit I 00 00 003		

Painting 20 percent extra	2 FRU
---------------------------	-------

— Job


Description:

Is interpreted as a repeat visit: No

Customer's own words:

TÜV Gebühren 00000000	Local	1 FRU
Flat rate unit 99 99 999		

10/28/2021	Key	148529 km	Key 0
------------	-----	-----------	-------



10/28/2021	Repair	148530 km	00525	Job
			Autohaus	Job
			Konrad Fink e.	Job
			K. ,	Job
			Immenstadt	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder montieren, Sommerr äder einlagern	Local	6 FRU
Flat rate unit 36 00 003		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räder Reinigen / einlagern	Local	5 FRU
Flat rate unit 36 00 005		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Checking lighting system for function		1 FRU
Flat rate unit 63 00 009		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	05/27/2021	Key	143106 km				Key 1	
								
10000		10000		70000		48000	40000	
12/2021		184			12/2021		12/2023	05/2022

—	05/27/2021	Repair	143107 km	00525 Autohaus Konrad Fink e. K. , Immenstadt	Job Job Job Job
---	------------	--------	-----------	---	--------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kundenbeanstandung:	Local	0 FRU
Flat rate unit I 00 00 043		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Remove and attach/replace left front center ultrasonic sensor	2 FRU
Flat rate unit I 66 20 517	

Ultrasonic sensor, black	1
Part I 66 20 9 261 582	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Performing vehicle test	2 FRU
Flat rate unit I 00 00 556	

— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:


Fahrzeugdesinfektion	Local	1 FRU
Flat rate unit I 00 00 096		

Painting 20 percent extra	2 FRU	
Flat rate unit I 99 99 001		

— 05/11/2021 Key 142488 km Key 1



— 05/11/2021 Service 142488 km 00525 Automatic
Autohaus
Konrad Fink e.
K. ,
Immenstadt



— 05/11/2021 Repair 142490 km 00525 Job
Autohaus Job
Konrad Fink e. Job
K. , Job
Immenstadt

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes 6 FRU
Flat rate unit I 00 00 612

Removing and installing/replacing both front brake discs 3 FRU
Flat rate unit I 34 11 613

KORR.SCHUTZ Local 1
Part I FT99 19 9 000 0

Entsorgung Local 1
Part I FT99 19 9 000 0

Brake pad paste 2
Part I 83 19 2 158 851

Brake pad wear sensor, front left 1
Part I 34 35 6 792 289

Brake cleaner, acetone-free 1
Part I 83 19 2 413 695

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
Brake disc, ventilated Part I 34 11 6 792 219	2
Inner hex bolt Part I 34 21 1 161 806	2
Torx screw with washer Part I 34 10 6 864 424	4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder montieren,Winter- räder einlagern Flat rate unit I 36 00 001	Local	5 FRU
Einlagerungsgebühr Saison incl. Räderreinigung Flat rate unit I 36 00 005	Local	4 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Oberwäsche ohne Berechnung Flat rate unit I 00 00 003	Local	2 FRU
Fahrzeugdesinfektion Flat rate unit I 00 00 096	Local	1 FRU
Painting 20 percent extra Flat rate unit I 99 99 001		2 FRU

— 11/30/2020 Key 135847 km 00525 Key 0

								
17000	0	17000	0	2900	0	60000	48000	0
12/2021		395			12/2021		12/2023	05/2021

— 11/30/2020 Key 135844 km 00525 Key 1

								
18000	0	18000	0	3000	0	70000	49000	0
12/2021		396			12/2021		12/2023	05/2021

— 11/30/2020 Repair 135847 km 00525 Job
Autohaus Job
Konrad Fink e. Job
K. , Job
Immenstadt Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right radial shaft seal for driven shafts on rear axle differential Flat rate unit I 33 10 524	19 FRU
Assembly ring Part I 31 53 7 502 681	2
Gasket set differential Part I 33 10 7 564 416	2
Screw plug with O-ring Part I 33 11 7 525 064	1
Repair kit recessed nut blue Part I 33 12 7 607 158	1
Hex bolt with washer Part I 33 17 6 760 343	2
Dust guard ring, plastic Part I 33 21 7 616 458	2
Collar nut Part I 33 40 6 799 223	2
Hypoid axle oil G1 Part I 83 22 2 295 532	0.5

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing front or rear wheel Flat rate unit I 36 10 800	1 FRU
Rep. kit, screw valve for RDCi Part I 36 10 6 876 673	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification / vehicle electrical system Flat rate unit I 61 99 000	0 FRU
Enable code HU-B Nav map Eur. Route Upd. Part I 65 90 2 409 897	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Oberwäsche ohne Berechnung	Local	2 FRU
Flat rate unit I 00 00 003		

— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugdesinfektion	Local	1 FRU
Flat rate unit I 00 00 096		

Painting 20 percent extra		2 FRU
Flat rate unit I 99 99 001		


— 11/09/2020 Key 135074 km 00525 Key 1



— 12/12/2016 Service 29093 km OSS-60004067 Manual
Bosch Car
Service Henry
Bauer, Lindau



— 10/25/2016 Key 22143 km 33952 Key 1



— 10/25/2016 Repair 22413 km 33952 Job
Autohaus
Unterberger
GmbH, Lindau

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Komplettträger wechseln	Local	6 FRU
Flat rate unit I 36 99 011		

Inzahlungnahme gebr. V-Speiche 390
Part I FT36 11 0 000 0


Local

-1

RDCi Winter wheel and tire Ferricgrey
Part I 36 11 2 289 747

4

— 05/20/2016 Key 11493 km 33952 Key 0



— 05/20/2016 Repair 11493 km 33952
Autohaus
Unterberger
GmbH , Lindau Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kompleträder wechseln Flat rate unit I 36 99 011	Local	6 FRU
Hauptuntersuchung §29 intern Flat rate unit I 99 99 999	Local	1 FRU
(statutory) general inspection Flat rate unit I 00 12 159		0 FRU
Exhaust emission inspection Flat rate unit I 00 00 542		3 FRU
Display inspection Flat rate unit I 00 00 008		9 FRU
Perform brake test on test stand Flat rate unit I 34 00 009		4 FRU
Recharging vehicle battery Flat rate unit I 61 21 509		1 FRU
Scheibenreiniger-Tab ohne Frostschutz 1 Tab Part I 83 92 2 148 601	Local	1