

Vehicle

BMW 425d, 165kW

WBA4F31040G189871



Development code	F36
Color	imperial-blau brillant metallic
Actual integration level	F020-22-11-510
Start of warranty	August 30, 2016

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map cannot be identified. One of the following maps could be installed in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2016-2 (as of: Feb 14, 2024)	-	-	-
Road Map EUROPE EVO 2016-2 (as of: Feb 14, 2024)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2025-2	-

▾ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	425d
Body	COUPE
Vehicle identification number (last 7 characters)	G189871
Vehicle identification number (17 characters)	WBA4F31040G189871
Development code	F36
Steering	LL
Engine	B47T
Engine number	52279722
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0505617WC9
Head unit serial number	HB2240G7902232
Drive	HECK
Integration level	F020-16-07-504
Production date	Aug 22, 2016
Production works	Dingolfing
Delivery date	Aug 25, 2016
Delivering Retailers	No information
National-market version	EUR
Paint code	A89
Upholstery code	LCLX
Model code	4F41
Base type	4F31
Lead type	4F41

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
0205 Automatic transmission
0230 EU-specific additional contents
0258 Tire with run-flat functionality
02H2 BMW LA wheel, Multispoke 416

Retrofitted optional equipment:

This vehicle has no retrofits.

02VB Tire pressure display
0320 Deleted, model lettering
0403 Glass roof, electrical
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0465 Through-loading system
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04FW Fine wood 'Fineline' walnut/acc. strip
0502 Headlight cleaning system
0508 Park Distance Control (PDC)
0521 Rain sensor
0522 Xenon Light
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometer-calibrated speedometer
0563 Lights package
0575 Supplementary 12V sockets
05AC High-beam assistant
05DA Passenger airbag deactivation
05DP Park Assistant
0609 Navigation system Professional
0610 Head-up display
0688 Harman/Kardon Surround Sound system
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06NH Hands-free with USB interface
06WA Instrument cluster, expanded equipment
07LE Modell Luxury Line
07S2 Luxury Line
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08R9 Refrigerant R1234yf
08TH Road sign detection
09AA Outer skin protection
A090 90 AH AGM battery
LEDE Leather trim

▾ Vehicle histories

Date		Type	Vehicle mileage		Dealer	Overview	
— 07/08/2024		Key	183226 km		33274	Key 1	
							
14000		14000		60000	10/2025	6000	44000
01/2026		01/2026				01/2028	10/2025
— 02/14/2024		Key	170061 km		33274	Key 1	
							
25000		25000		60000	10/2025	6000	60000
01/2026		01/2026				01/2028	10/2025

—	01/29/2024	Key	168305 km	33274	Remote KeyRead						
28000		28000		60000		7000	60000				
01/2026		01/2026			10/2025		01/2028				
—	01/03/2024	Service	166422 km	OSS- 60140221 Kai & Uwe Stroh KFZ- Meisterbetrieb GbR, Lahnau	Manual						
✓	✓	✓	✓				✓				
—	10/04/2023	Key	158673 km	33274	Key 1						
3900	3900	3900	3900	-470 0.8 %	-33 4.5 %	13000	3900	-33 4.5 %			
01/2025	01/2025	01/2025	01/2025				01/2025				
—	10/04/2023	Service	158673 km	33274 Alfred Wahl GmbH&Co. KG , Wetzlar	Automatic						
3900	3900	3900	3900	-470	0	13000	3900	0			
01/2025	01/2025	01/2025	01/2025	10/2023	09/2023	10/2023	01/2025	09/2023			
				✓	✓						
—	10/04/2023	Repair	158673 km	33274 Alfred Wahl GmbH & Co. KG , Wetzlar	Job Job Job Job Job Job Job Job Job Job						
— Job											

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket
Flat rate unit I 00 52 052

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Battery Part I 61 31 9 217 643	1
-----------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test Flat rate unit I 00 00 006	4 FRU
---	-------

Removing and installing/replacing an injection system injector Flat rate unit I 13 53 314	14 FRU
--	--------

Work time without specification / vehicle electrical system Flat rate unit I 61 99 000	24 FRU
---	--------

RP injector Part I 13 53 8 514 151	1
---------------------------------------	---

Injector lubricating grease Part I 83 23 8 854 223	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Presentation for emission inspection Flat rate unit I 00 00 527	5 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service Flat rate unit I 00 00 614	7 FRU
---	-------

Repair kit brake pads asbestos-free Part I 34 21 8 855 013	1
---	---

Brake pad wear sensor, rear Part I 34 35 6 792 292	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612	6 FRU
--	-------

Removing and installing/replacing both front brake discs Flat rate unit I 34 11 612	3 FRU
--	-------

Repair kit brake pads asbestos-free Part I 34 11 8 855 010	1
---	---

Brake pad wear sensor, front left Part I 34 35 6 792 289	1
---	---

Brake disc, ventilated Part I 34 11 6 792 221	2
--	---

Inner hex bolt Part I 34 21 1 161 806	2
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Verbandtasche schwarz Part I FT94 99 0 002 9	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing both mounts for rear McPherson struts/shock absorbers Flat rate unit I 33 52 632	10 FRU
---	--------

Guide support Part I 33 50 6 864 452	2
---	---

Auxiliary shock absorber, rear Part I 33 53 6 857 730	2
--	---

Gasket Part I 33 50 6 866 038	2
----------------------------------	---

Self-locking collar nut Part I 33 32 6 760 668	2
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade	0 FRU
Flat rate unit I 61 61 041	

Set of wiper blades	1
Part I 61615A43587	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

HU Geb. n. §29 StVZO (zur ext. Verrechnung) #TÜV2	Local	1 FRU
Flat rate unit I 99 99 999		

Räder maschinell reinigen (Oberflächenreinigung)	Local	1 FRU
Flat rate unit I 99 99 999		

—	10/04/2023	Repair	158673 km	33274 Alfred Wahl GmbH & Co. KG , Wetzlar	Job Job
---	------------	--------	-----------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace windshield	24 FRU
Flat rate unit I 51 31 011	

Additional work with KAFAS camera	5 FRU
Flat rate unit I 66 51 990	

Green windshield	1
Part I 51 31 7 285 901	

Repair flat rate, window, cold, 1 hr.	1
Part I 83 19 2 289 285	

Cover, windshield, top	1
Part I 51 31 7 285 915	

Clamp	2
Part I 51 43 7 321 215	

Bump stop	10
Part I 51 31 7 288 462	

Cleaner R1	1
Part I 83 19 2 211 217	

Sound insulation f apron	1
Part I 51 48 7 325 890	

Drip moulding, left
Part I 51 31 7 285 927 1

Drip molding, right
Part I 51 31 7 285 928 1

Replacemt.small plates, low beam sensor
Part I 61 35 9 856 157 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Feinstaubplakette 00000000 Local 1 FRU
Flat rate unit I 99 99 999

— 09/29/2023 Key 158219 km 00319 Key 0



— 09/25/2023 Key 157748 km 33274 Remote KeyRead



— 03/14/2023 Repair 140382 km 33274 Job
Autohaus Wahl Job
Mittelhessen Job
GmbH & Co. Job
KG , Wetzlar Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Pirelli Cinturato P7 r-f 4
Part I 85 45 2 593 762

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing four tires with run-flat technology 0 FRU
Flat rate unit I 36 12 577

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Check Kompakt Annahme
Flat rate unit I 00 11 200

Local

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Scheibenklar auffüllen JA () NEIN (X)
Flat rate unit I 00 00 246

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölstand prüfen, ggf. ergänzen JA (X) NEIN ()
Flat rate unit I 00 00 247

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räder maschinell reinigen (Oberflächenreinigung) 00000000
Flat rate unit I 99 99 999

Local

1 FRU

—	03/14/2023	Repair	134735 km	33274 Autohaus Wahl Mittelhessen GmbH & Co. KG , Wetzlar	Job
---	------------	--------	-----------	--	-----

— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:


Replacing four tires with run-flat technology
Flat rate unit I 36 12 577

23 FRU

—	01/09/2023	Key	134735 km		Key 1
---	------------	-----	-----------	--	-------



—	01/09/23	Service	134735 km	33274 Autohaus Wahl Mittelhessen GmbH&Co. KG , Wetzlar	Automatic
---	----------	---------	-----------	--	-----------



—	01/09/2023	Repair	134735 km	33274 Autohaus Wahl Mittelhessen GmbH & Co. KG , Wetzlar	Job Job
---	------------	--------	-----------	--	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
Engine oil service Flat rate unit I 00 00 610	3 FRU
Original BMW Motorenöl LL04 0W-30 Part I FT97 99 0 000 0	Local 5
Set oil-filter element Part I 11 42 8 575 211	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

—	12/16/2022	Key	132579 km	Remote KeyRead
---	------------	-----	-----------	----------------

 1700 12/2023		 1700 12/2023		 37000	 09/2023	 39000	 31000 12/2025	 09/2023
---	--	---	--	---	---	---	---	---

— 11/22/2022 Key 130945 km 33274 Key 1

 3400 12/2023		 3400 12/2023		 39000	 09/2023	 41000	 33000 12/2025	 09/2023
--	---	--	---	--	--	--	--	--

— 09/07/2022 Repair 111674 km 33274 Job
Autohaus Wahl
Mittelhessen
GmbH & Co.
KG , Wetzlar

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing four tires with run-flat technology
Flat rate unit I 36 12 076

30 FRU

— 03/28/2022 Key 111674 km 33274 Key 1

 23000 12/2023		 23000 603		 60000	 09/2023	 60000	 60000 12/2025	 09/2023
---	---	---	---	--	--	--	--	--

— 12/27/2021 Key 104268 km Key 1

 -500 11/2022	 -500 304	 -500 304	 -500 304	 60000	 09/2023	 80000	 -500 11/2022	 09/2023
--	--	--	--	--	--	--	---	--

— 12/27/2021 Service 104268 km 33274 Automatic
Autohaus Wahl
Mittelhessen
GmbH&Co. KG
, Wetzlar

 -500 ✓	 -500 ✓	 -500 ✓	 -500 ✓	 60000	 0	 80000	 -500 ✓	 0
--	--	--	--	--	--	--	---	--

— 12/27/2021 Repair 104268 km 33274 Job
Autohaus Wahl
Mittelhessen
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Original BMW Motorenöl LL04 0W-30	Local	5
Part I FT97 99 0 000 0		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 7 822 497	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade	2 FRU
Flat rate unit I 61 61 041	

Set of wiper blades	1
Part I 61615A43587	

—	10/23/2021	Repair	0 km	33274	Job
				Autohaus Wahl	Job
				Mittelhessen	Job
				GmbH & Co.	
				KG , Wetzlar	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kompakt-Check Ablaufdatum Verbandskasten (10 / 21)	Local	1 FRU
Flat rate unit I 00 52 000		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Scheibenklar auffüllen JA () NEIN (X)	Local	0 FRU
Flat rate unit I 00 00 246		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölstand prüfen, ggf. ergänzen JA () NEIN (X)	Local	0 FRU
--	-------	-------

—	10/08/2021	Repair	0 km	46476 Autohaus Wahl Mittelhessen GmbH & Co. KG, Dautphetal	Job
---	------------	--------	------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment 0 FRU
Flat rate unit I 51 99 000

Painting bumper cover, front 39 FRU
Flat rate unit I 99 68 035

—	10/04/2021	Key	97910 km	Key 1
---	------------	-----	----------	-------

								
6000	6000	6000	6000	60000		80000	6000	
11/2022	388	388	388		09/2023		11/2022	09/2023

—	10/04/2021	Repair	97910 km	33274 Autohaus Wahl Mittelhessen GmbH & Co. KG, Wetzlar	Job Job Job
---	------------	--------	----------	---	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle 0 FRU
Flat rate unit I 00 52 050

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Dismantling and assembling the bumper, front 5 FRU
Flat rate unit I 51 11 005

— Job

Customer's own words:

Lackierarbeiten (Ho) 00000000
Flat rate unit | 99 99 999

Local

1 FRU

— 09/13/2021 Key

96104 km

Key 1




— 09/13/2021 Service

96104 km

33274
Autohaus Wahl
Mittelhessen
GmbH&Co. KG
, Wetzlar

Automatic



— 09/13/2021 Repair

96108 km

33274
Autohaus Wahl
Mittelhessen
GmbH & Co.
KG, Wetzlar

Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle
Flat rate unit | 00 52 050

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit 1 00 00 105

2 FRU

Service - front brakes
Flat rate unit 1 00 00 612

6 FRU

Removing and installing/replacing both front brake discs

Flat rate unit I 34 11 612

3 FRU

A.Reiniger

Local

1

Part I FT99 99 0 000 0

Brake disc, ventilated Part I 34 11 6 792 221	2
--	---

Inner hex bolt Part I 34 21 1 161 806	2
--	---

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
--	---

Brake pad paste Part I 83 19 2 158 851	2
---	---

Brake pad wear sensor, front left Part I 34 35 6 792 289	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service Flat rate unit I 00 00 614	7 FRU
---	-------

Removing and installing/renewing both brake discs Flat rate unit I 34 21 931	2 FRU
---	-------

* A.Reiniger Part I FT99 99 0 000 0	Local	1
--	-------	---

Brake disc, ventilated Part I 34 21 6 864 900	2
--	---

Inner hex bolt Part I 34 21 1 161 806	2
--	---

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
--	---

Brake pad wear sensor, rear Part I 34 35 6 792 292	1
---	---

Brake pad paste Part I 83 19 2 158 851	2
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Presentation for emission inspection 5 FRU
Flat rate unit I 00 00 527

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing or replacing pressure pipe 4 FRU
Flat rate unit I 11 61 750

Charge air line 1
Part I 11 61 8 518 475

Preformed seal 2
Part I 13 71 8 596 850

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

HU Geb. n. §29 StVZO (zur ext. Verrechnung) 00000000 Local 1 FRU
Flat rate unit I 99 99 999

— 05/03/2021 Key 84474 km Key 1

 18000 11/2022	 18000 576	 18000 576	 18000 576	 27000	 0 09/2021	 27000	 18000 11/2022	 0 09/2021
---	---	---	---	--	---	--	--	---

— 05/03/2021 Repair 84474 km 33274 Alfred Wahl GmbH & Co. KG , Wetzlar Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kompakt-Check Ablaufdatum Verbandskasten 10/21 Local 1 FRU
Flat rate unit I 00 52 000

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash and interior vehicle cleaning
Flat rate unit I 00 11 329

0 FRU

—	11/05/2020	Key	75212 km	33274	Key 1			
 1600 09/2021	 0	 1600 328	 0	 39000	 0 09/2021	 39000	 30000 09/2023	 0 09/2021
—	11/05/2020	Service	75212 km	33274 ASW Wahl GmbH&Co. KG , Wetzlar	Automatic			
 1600 09/2021 ✓	 0	 1600 09/2021 ✓	 0	 39000	 0 09/2021	 39000	 30000 09/2023	 0 09/2021
—	11/05/2020	Repair	75212 km	33274 Alfred Wahl GmbH & Co. KG , Wetzlar	Job Job Job			

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle
Flat rate unit I 00 52 050

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

Engine oil service
Flat rate unit I 00 00 610

3 FRU

Original BMW Motorenöl LL04 0W-30
Part I FT97 99 0 000 0

Local

5

Set oil-filter element
Part I 11 42 8 575 211

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter
Flat rate unit I 00 00 616

2 FRU

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— 08/03/2020 Key 70410 km 33274 Key 1

									
7000	0	7000	0	43000	0	44000	36000		0
09/2021		423			09/2021		09/2023		09/2021

— 07/17/2020 Key 69550 km Key 1

									
8000	0	8000	0	44000	0	45000	37000		0
09/2021		440			09/2021		09/2023		09/2021

— 07/17/2020 Repair 69550 km 33274 Alfred Wahl GmbH & Co. KG, Wetzlar Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle
Flat rate unit I 00 52 050

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body
Flat rate unit I 41 99 000

2 FRU

Work before/after painting front left or right side panel
Flat rate unit I 51 18 619

5 FRU

Stripping and refitting work for painting the front left or right door
Flat rate unit I 51 18 750

9 FRU

Removing and installing front bumper panel
Flat rate unit I 51 11 656

9 FRU

Replace bumper cover, front
Flat rate unit I 51 11 592

11 FRU

Additional work with Park Distance Control
Flat rate unit I 66 20 614

5 FRU

Additional work, headlight cleaning system Flat rate unit I 61 67 803		3 FRU
Work time without specification/electronic transmitter/receiver Flat rate unit I 66 99 000		3 FRU
Removing and installing headlight, right Flat rate unit I 63 12 522		5 FRU
Remove and install/replace left or right side sill trim panel Flat rate unit I 51 71 947		4 FRU
Removing and installing/replacing the sound insulation at the front left or right door Flat rate unit I 51 48 560		7 FRU
A.Reiniger Part I FT99 99 0 000 0	Local	1
Trim cover, bumper, primed, front Part I 51 11 7 363 275		1
Channel cover,exterior,door, front right Part I 51 35 7 310 202		1
Sound insulation, door, front right Part I 51 48 7 410 006		1
Badge Part I 51 76 7 288 752		1
Supporting ledge right Part I 51 77 7 294 888		1
Supporting ledge right Part I 51 77 7 320 206		1
Supporting ledge right Part I 51 77 7 320 208		1
Supporting ledge right Part I 51 77 7 320 210		1
Adhesive set K6 Part I 83 19 2 317 925		1
Set of mounts, front PDC / PMA sensor Part I 51 11 7 387 126		1
Expanding rivet, black Part I 51 77 7 171 004		10
Clip Part I 07 14 7 130 112		10
Blind compression rivet Part I 07 14 7 378 241		10
Expanding rivet Part I 07 14 9 807 127		16
Open grid, left Part I 51 11 7 309 621		1
Partially open grid, right Part I 51 11 7 309 622		1

Inscription, side Part I 51 14 7 418 530	1
Finisher, rod, left Part I 51 11 7 294 841	1
Finisher, rod, right Part I 51 11 7 294 842	1
Finisher, rod, left Part I 51 11 7 315 105	1
Finisher, rod, right Part I 51 11 7 315 106	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash and interior vehicle cleaning Flat rate unit I 00 11 329	0 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Lackierarbeiten LZ Siegerland 00000000 Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

— 05/06/2020 Key 65398 km 33274 Key 1

									
12000		12000		49000		50000	41000		
09/2021		475			09/2021		09/2023		09/2021

— 05/02/2020 Repair 0 km 33274 Alfred Wahl GmbH & Co. KG , Wetzlar Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kompakt-Check Flat rate unit I 00 52 000	Local	1 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Scheibenklar auffüllen JA () NEIN (X)
Flat rate unit I 00 00 246

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölstand prüfen, ggf. ergänzen JA () NEIN (X)
Flat rate unit I 00 00 247

Local

0 FRU

—	03/30/2020	Key	63285 km	33274	Key 1			
								
14000	0	14000	0	60000	0	60000	42000	0
09/2021		549			09/2021		09/2023	09/2021
—	01/31/2020	Key	59842 km	33274	Key 1			
								
18000		18000		60000		60000	47000	
09/2021		570			09/2021		09/2023	09/2021
—	11/14/2019	Key	53054 km	33274	Key 1			
								
24000	0	24000	0	70000	0	70000	60000	0
09/2021		686			09/2021		09/2023	09/2021
—	10/30/2019	Key	52082 km	33274	Key 1			
								
25000	0	25000	0	70000	0	70000	60000	0
09/2021		700			09/2021		09/2023	09/2021
—	08/30/2019	Key	49201 km	33274	Key 0			
								
8000	8000	8000	8000	12000	0	12000	8000	0
12/2019	124	124	124		08/2019		12/2019	11/2020
—	08/30/2019	Service	49201 km	33274 ASW Wahl GmbH & Co.KG, Wetzlar	Automatic			

								
8000	8000	8000	8000	12000	0	12000	8000	0
01/2020	01/2020	01/2020	01/2020		09/2019		01/2020	12/2020
✓	✓	✓	✓		✓		✓	✓

—	08/30/2019	Repair	49201 km	33274 Alfred Wahl GmbH & Co. KG , Wetzlar	Job: Standard scope of service Job: Engine oil service Job: Service - microfilter Job: Service - air filter insert Job: Fuel filter service Job: Brake fluid service Job: Vehicle check service Job Job Job
---	------------	--------	----------	---	--

— Job: Standard scope of service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Package I 0000105

Standard scope of service	2
Flat rate unit I 00 00 105	

— Job: Engine oil service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service
Package I 0000610

Engine oil service	3
Flat rate unit I 00 00 610	

!!! unknown BMW-Id FT97990000040 Original BMW Motorenöl Original BMW Motorenöl !!! Part I FT97990000040	Local	5
--	-------	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job: Service - microfilter

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter
Package I 0000616

Service - microfilter	2
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
--	---

— Job: Service - air filter insert

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - air filter insert

Package I 0000602

Service - air filter insert	2
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job: Fuel filter service

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Fuel filter service

Package I 0000604

Fuel filter service	3
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 8 572 522	

— Job: Brake fluid service

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Brake fluid service

Package I 0000618

Brake fluid service	4
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 2 184 843	

— Job: Vehicle check service

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check service

Package I 0000624

Vehicle check service	6
Flat rate unit I 00 00 624	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

§ emission test with on-board diagnosis	1 FRU
Flat rate unit I 00 00 528	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

(Mandatory) general inspection	0 FRU
Flat rate unit I 00 12 559	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Package I MM04007*BM4F41	Local	
BPS Durchsicht	Local	0
Flat rate unit I 00 00 020		
Auslieferungs-Durchsicht	Local	0
Flat rate unit I 00 00 030		
Eingangs-Durchsicht	Local	6
Flat rate unit I 00 00 031		
Karosserie auf Schäden	Local	0
Flat rate unit I 00 00 032		
Starterpaket ins Fzg. legen	Local	0
Flat rate unit I 11 99 200		
AL Geschenk: Schlüsselanhänger	Local	0
Flat rate unit I 72 99 100		
Aufbereitung Herr Galbas	Local	0
Flat rate unit I 11 99 100		
Remoteverbindung prüfen und	Local	0
Flat rate unit I AZ03 09 1		
Remoteverbindung prüfen und	Local	0
Flat rate unit I AZ03 09 1		
Offene technische Aktionen	Local	0
Flat rate unit I AZ03 09 2		
Service Telematik und	Local	0
Flat rate unit I AZ03 09 3		
Haltbarkeit Verbandskasten u.	Local	0
Flat rate unit I AZ03 09 4		
Mobility Set erneuern	Local	0
Flat rate unit I AZ03 09 5		
Free pre-delivery check		9

—	08/30/2019	Repair	49212 km	33274 Alfred Wahl GmbH & Co. KG , Wetzlar	Job Job Job Job Job Job Job Job Job
---	------------	--------	----------	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Original BMW Motorenöl LL04 0W-30 Part I FT97 99 0 000 0	Local	5
---	-------	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

Gasket ring Part I 07 11 9 905 041	4
---------------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602	2 FRU
---	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Front brake/rear brake service Flat rate unit I 00 00 613		13 FRU
A.Reiniger Part I FT99 99 0 000 0	Local	2
Clip Part I 34 10 6 790 927		2
Repair kit, brake pads asbestos-free Part I 34 10 6 859 181		1
Clip Part I 34 21 6 850 853		2
Repair kit, brake pads asbestos-free Part I 34 21 6 873 093		1
Brake pad wear sensor, front left Part I 34 35 6 792 289		1
Brake pad wear sensor, rear Part I 34 35 6 792 292		1
Brake pad paste Part I 83 19 2 158 851		4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

§ emission test with on-board diagnosis Flat rate unit I 00 00 528	1 FRU
---	-------

(Mandatory) general inspection Flat rate unit I 00 12 559	0 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

BPS Durchsicht Flat rate unit I 00 00 020	Local	9 FRU
--	-------	-------

Auslieferungs-Durchsicht Öl, Wasser, Kühlmittel, Luft prüfen und Batterie laden Flat rate unit I 00 00 030	Local	0 FRU
---	-------	-------

Karosserie auf Schäden überprüfen (Lack und Dellen) Flat rate unit I 00 00 032	Local	0 FRU
---	-------	-------

Aufbereitung Herr Galbas Flat rate unit I 11 99 100	Local	0 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

HU Geb. n. §29 StVZO 00000000
Flat rate unit I 99 99 999

Local

1 FRU

— 07/29/2019 Repair 49250 km 33274 Alfred Wahl GmbH & Co. KG, Wetzlar Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Eingangs-Durchsicht Gebrauchtwagen Öl, Wasser, Luft, Batterie
Flat rate unit I 00 00 031

Local

6 FRU

Karosserie auf Schäden überprüfen (Lack und Dellen)
Flat rate unit I 00 00 032

Local

2 FRU

Performing vehicle test
Flat rate unit I 00 00 556

2 FRU

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery
Flat rate unit I 61 21 528

1 FRU

Scheibenklar ohne Frostschutz 1 Liter
Part I FT94 99 0 002 9

Local

1

Set wheel locks
Part I 36 13 6 776 076

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Stripping and refitting work for painting bonnet
Flat rate unit I 51 18 860

0 FRU

Stripping and refitting work for painting tailgate
Flat rate unit I 51 18 870

8 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Dent removal without painting
Flat rate unit I 41 99 010

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Aufbereitung Firma OCC
Flat rate unit I 11 99 101

Local

0 FRU

— 07/08/2019 Key 48984 km 33274 Key 0

									
8000	8000	8000	8000	12000	0	12000	8000		0
12/2019	176	176	176		08/2019		12/2019		11/2020

— 10/31/2018 Key 45932 km Key 1

									
11000	11000	11000	11000	14000	0	14000	11000		0
12/2019	426	426	426		08/2019		12/2019		09/2019

— 10/31/2018 Repair 45926 km 00081
Niederlassung
Berlin BMW
AG, Berlin Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Überprüfung §29 STVZO incl Abgasunters.
Part I 0005652

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Auslieferung Premium über B&B Liefersche
Part I 0000156

Local

1

Battery
Part I 61 31 9 217 643

2

Tire Mobility Set
Part I 71 10 2 333 674

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 09/07/2018 Repair 45901 km 00081 Job
Niederlassung Job
Berlin BMW
AG, Berlin

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm Local 0 FRU
Flat rate unit I 00 52 054

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

***** Local 1
Part I 0000156

— 09/05/2018 Key 45901 km Key 1

									
11000	11000	11000	11000	14000	0	14000	11000		0
12/2019	482	482	482		08/2019		12/2019		09/2019

— 09/05/2018 Repair 45901 km 00081 Job
Niederlassung Job
Berlin BMW Job
AG, Berlin Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: 098487 Langnese,,

Replace windshield 24 FRU

Flat rate unit I 51 31 011

Additional work with rain/light sensor 3 FRU

Flat rate unit I 61 35 994

Cover, windshield, top 1

Part I 51 31 7 285 915

Drip moulding, left 1

Part I 51 31 7 285 927

Drip molding, right 1

Part I 51 31 7 285 928

Bump stop 11

Part I 51 31 7 288 462

Clamp 2

Part I 07 14 7 142 116

Repair flat rate, window, cold, 1 hr. 1

Part I 83 19 2 289 285

Sound insulation f apron 1

Part I 51 48 7 325 890

Green windshield 1

Part I 51 31 7 285 901

Paint activator, stick 1

Part I 83 19 2 154 458

Adhesive tape 1

Part I 83 19 2 157 772

Adhesive primer VP 206 1

Part I 83 19 9 407 777

Clip, drip molding 6

Part I 51 13 7 321 818

Clip, drip molding 4

Part I 51 13 7 258 183

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	02/06/2018	Key	31456 km	00074	Key 2			
								
25000	25000	25000	25000	25000	0	25000	25000	0
12/2019	693	693	693		08/2019		12/2019	09/2019
—	12/22/2017	Key	29047 km	00077	Key 1			
								
-800	0	-800	0	28000	0	28000	26000	0
08/2018		252			08/2019		08/2020	09/2019
—	12/22/2017	Service	29047 km	00077	Manual			
				Niederlassung Offenbach, Offenbach				
								
✓		✓						
—	12/22/2017	Repair	29047 km	00077	Job			
				Niederlassung Offenbach BMW AG, Offenbach	Job Job Job Job Job			
— Job								

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Aktion Scheibenklar + Eiskratzer
Part I 99 99 2 409 032

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW
Flat rate unit I IM00 25 0

Local

2 FRU

Engine oil service
Flat rate unit I 00 00 610

3 FRU

Set oil-filter element
Part I 11 42 8 575 211

1

BMW Engine Oil LL04 0W30
Part I 83 21 2 405 950

5

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Bordnetzstabilisierung Flat rate unit I NL61 10 0	Local	1 FRU
Standard scope of service Flat rate unit I 00 00 105		2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616		2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555		1
Vehicle interior filt..f.housing cleaner Part I 83 19 2 451 455		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Servicewäsche PLUS Part I 00800	Local	1
------------------------------------	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle Flat rate unit I 00 52 050		0 FRU
---	--	-------

— 02/23/2017 Key 10841 km 00081 Key 1

 17000 08/2018	 0	 17000 553	 0	 48000	 0 08/2019	 48000	 44000 08/2020	 0 09/2019
---	--	---	--	--	---	--	--	---

— 02/23/2017 Repair 10845 km 00081 Niederlassung Berlin BMW AG, Berlin Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Ersatzfahrzeug Sixt,MINI() 1er(x) 3er() 5er() 7er(),Verrechnung:,Kunde() GW(x) Gutschein()
BXA5() TV() NA() GA(),MobCare() Koop.Vers.(),Business/Leasing Card Nr:

„Mietdauer: (1) Tage ab

23.02.2017/15:00,Unterschrift:_____,Vermerk:_____,Joschko_____

_____”

Operating test module and programming control unit

10 FRU

Flat rate unit I 00 64 246

Ersatzfahrzeug TA Sixt Beleg 9352076355

Local

1

Part I 0000158

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm

Local

0 FRU

Flat rate unit I 00 52 054

—

09/01/2016 Repair

6 km

00081

Niederlassung

Berlin BMW

AG, Berlin

Job

Job

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm

Local

0 FRU

Flat rate unit I 00 52 054