

Vehicle

BMW 520d, 140kW

WBA5L31000G079865



Development code	F11
Color	Jatoba metallic
Actual integration level	F010-24-11-520
Start of warranty	April 23, 2015

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Next 2015-2 (as of: Mar 13, 2025)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00A9008F).	Road Map EUROPE WEST Next 2025	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	520d
Body	TOUR
Vehicle identification number (last 7 characters)	G079865
Vehicle identification number (17 characters)	WBA5L31000G079865
Development code	F11
Steering	LL
Engine	B47O
Engine number	72679203
Exhaust re-treatment	EURO6;W;PI/Ci; M, N1 I
Transmission	AUT
Transmission number	0091505XA3
Head unit serial number	HB2068H8321844
Drive	HECK
Integration level	F010-15-03-502
Production date	Mar 21, 2015
Production works	Dingolfing
Delivery date	Mar 25, 2015
Delivering Retailers	No information
National-market version	EUR
Paint code	B65
Upholstery code	LCEZ
Model code	5L41
Base type	5L31
Lead type	5L41

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 01CC Auto start/stop function
 01CD Brake Energy Regeneration
 0205 Automatic transmission
 0230 EU-specific additional contents
 0255 Sports leather steering wheel
 0258 Tire with run-flat functionality
 02K1 BMW LA wheel, V Spoke 236
 02VB Tire pressure display
 0316 automatic trunk lid mechanism

Retrofitted optional equipment:

This vehicle has no retrofits.

0320 Deleted, model lettering
 0322 Comfort access
 0386 Roof railing
 03AG Reversing camera
 0418 Luggage compartment package
 0423 Floor mats, velours
 0428 Warning triangle and first aid kit
 0431 Interior mirror with automatic-dip
 0459 Seat adjuster, electric, with memory
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0494 Seat heating driver/passenger
 04AT Interior trim finishers black high-gloss
 04U2 Driving experience switch incl. ECO PRO
 04UR Ambient interior lighting
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0534 Automatic air conditioning
 0536 Auxiliary heating
 0548 Kilometer-calibrated speedometer
 0575 Supplementary 12V sockets
 05DF Active cruise control+Stop&Go function
 0609 Navigation system Professional
 0688 Harman/Kardon Surround Sound system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NS Convenience phone, expanded Smartphone
 07XP Navigation package, Connected Drive
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 08TF Active pedestrian protection
 08TH Road sign detection
 09BD Business Package
 A105 105 AH AGM battery
 LEDE Leather trim

▾ Vehicle histories

	Date	Type	Vehicle mileage			Dealer	Overview			
—	03/13/2025	Key	186759 km			00086	Key 0			
	12000 08/2025		12000 08/2025		16000 08/2025			0	41000 08/2027	-313 42.8 %
—	03/05/2025	Repair	186759 km			00074 ,	Job Job Job Job Job			
	— Job									

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace exhaust-gas recirculation cooler, including exhaust-gas recirculation valve Flat rate unit I 00 74 057	22 FRU
---	--------

Performing additional work for pressure sensor functional check Flat rate unit I 00 74 636	3 FRU
---	-------

Additional work: enter component identification of new exhaust-gas recirculation cooler in diagnostic system Flat rate unit I 00 74 637	1 FRU
--	-------

Additional work: clean EGR pipe Flat rate unit I 00 74 638	6 FRU
---	-------

Exhaust gas cooler high temperature Part I 11 71 7 822 347	1
---	---

Pipe union Part I 11 71 7 799 853	2
--------------------------------------	---

AGR small parts set Part I 11 71 8 490 640	1
---	---

Connection piece Part I 11 65 7 803 012	1
--	---

Vacuum hose black Part I 11 65 8 595 650	0.5
---	-----

Holder Part I 61 13 1 369 832	1
----------------------------------	---

O-ring Part I 11 61 8 512 681	1
----------------------------------	---

Acoustic cover front Part I 11 14 8 490 575	1
--	---

Ersatzfahrzeug (24 Stunden) Part I 0000160	Local	1
---	-------	---

Anti-freeze Part I 83 19 2 218 347	3
---------------------------------------	---

Pipe Part I 13 71 7 823 517	1
--------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Kompakt-Check mit CBS-Daten Flüssigkeiten ergänzen:nein,

Kompakt-Check mit CBS-Daten Flüssigkeite Flat rate unit I AZ00 01 8	Local	1 FRU
--	-------	-------

Dokumentationsaufwand SVC Flat rate unit I AZ00 15 2	Local	2 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Administrative effort
Flat rate unit I 00 74 758

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Program control units
Flat rate unit I 00 71 907

8 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

unknown fru: null
Flat rate unit I 00 76 854

Local







1 FRU

— 10/16/2020 Key

139537 km

00086

Key 0










— 10/07/2020 Key

139177 km

00086

Key 0










— 10/29/2019 Key

128299 km

00086

Key 0










— 08/05/2019 Key

123453 km

00086

Key 0



— 06/28/2019 Key

121438 km

00086

Key 0

								
14000	0	14000	0	24000	0	70000	42000	0
04/2020		307			04/2020		04/2022	04/2020

—	06/28/2019	Repair	121438 km	00086	Job
				Niederlassung	Job
				Kassel BMW	Job
				AG, Kassel	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: **Freigabe EUROPlus Garantie: 4193607**, **AGR Ventil und Dtg. auf Auftrag**, **Flüssigkeitsverlust prüfen - Spuren in der Garage**, Funktionsprüfung der Digitalen Diesel Elektronik (DDE), #*E. Motor hat verminderte Leistung und ruckelt beim Beschleunigen. div., AGR Fehler im Schlüssel gespeichert,

Carrying out vehicle test 4 FRU
Flat rate unit I 00 00 006

Functional check of Digital Diesel Electronics (DDE) 1 FRU
Flat rate unit I 13 00 003

Replacing the exhaust-gas recirculation valve 6 FRU
Flat rate unit I 11 71 501

EGR-valve 1
Part I 11 71 8 513 132

Gasket Steel 1
Part I 11 71 8 579 364

Oval head screw 2
Part I 35 21 7 685 343

Hose clamp 2
Part I 07 12 9 952 104

Expanding rivet 1
Part I 51 47 1 911 992

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 09/07/2018 Service 109688 km 00086 Manual
Niederlassung
Kassel, Kassel



— 09/07/2018 Repair 109687 km 00086 Job
Niederlassung Job
Kassel BMW Job
AG, Kassel Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Bordnetzstabilisierung Flat rate unit I NL61 10 0	Local	1 FRU
Fehlerspeicher löschen. Flat rate unit I NL00 16 1	Local	2 FRU
Performing vehicle test Flat rate unit I 00 00 556		3 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Beide Bremsscheiben hinten aus- und einbauen/ersetzen unter Maß, Min. Maß 18.4mm
Ist. 18.2mm,

Rear brakes service Flat rate unit I 00 00 614	8 FRU
Standard scope of service Flat rate unit I 00 00 105	2 FRU

Removing and installing/renewing both brake discs Flat rate unit I 34 21 931	2 FRU
Brake pad wear sensor, rear Part I 34 35 6 791 963	1
Repair kit, brake pads asbestos-free Part I 34 21 6 862 202	1
Brake disc, lightweight, ventilated Part I 34 21 6 775 287	2
Inner hex bolt Part I 34 21 1 161 806	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Nachfüllservice Incl.Scheibenwaschwasser Luftdruck Prüfen,

Nachfüllservice Incl.Scheibenwaschwasser Flat rate unit I AZ00 81 1	Local	1 FRU
Washer fluid, concentrated Part I 83 12 2 298 203		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Radnaben am Felgensitz entrostet Flat rate unit I AZ34 06 0	Local	3 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

CBS-Daten mit Tester korrigieren (ohne w Flat rate unit I NL00 50 1	Local	2 FRU
--	-------	-------

— 09/06/2018 Key 109687 km Key 0

 27000 04/2020	 0	 27000 603	 0	 60000	 0 04/2020	 6000	 60000 04/2022
---	--	---	--	--	---	---	--

— 08/14/2018 Repair 123 km 00086 Niederlassung Kassel BMW AG, Kassel Job

— Job

Customer's own words:

Sonstige Leistungen 18111211880 G 10889
Part I 0000156

Local

1

—	07/11/2018	Key	109608 km		00086	Key 0			
 28000 04/2020	 0	 28000 700	 0	 60000	 0 04/2020	 6000	 60000 04/2022		
—	04/19/2018	Key	105964 km		29429	Key 0			
 3600 08/2019	 3600 499	 3600 499	 3600 499	 70000	 0 -19 2.6 %	 6000	 3600 08/2019	 0 04/2018	 0 04/2018
—	04/19/2018	Service	105964 km		29429 B&K GmbH & Co. KG, Kronberg	Automatic			
 3600 ✓	 3600 ✓	 3600 ✓	 3600 ✓	 70000	 0 03/2018 ✓	 6000	 3600 ✓	 04/2018 ✓	 04/2018 ✓
—	02/02/2018	Key	98905 km		29429	Key 0			
 9000 08/2019	 9000 575	 9000 575	 9000 575	 70000	 0 03/2018	 6000	 9000 08/2019	 0 04/2018	 0 04/2018
—	02/02/2018	Repair	98915 km		29429 B&K GmbH , Kronberg	Job Job Job Job Job Job			
— Job									

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Freigabe: 7 6 1 6 9 7
Flat rate unit | 99 99 999

Local

1 FRU

Fremdleist
Flat rate unit | 99 99 999

Local

1 FRU

Fahrzeug eingeschleppt
Flat rate unit I 99 99 999

Local

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einbruch-/Diebstahlschaden
Flat rate unit I 99 99 999

Local

1 FRU

beseitigen
Flat rate unit I 99 99 999

Local

1 FRU

Kaskoschaden vom 02.02.2018
Flat rate unit I 99 99 999

Local

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reparatur gemäss Freigabe-
Flat rate unit I 99 99 999

Local

1 FRU

bedingungen der Leasing
Flat rate unit I 99 99 999

Local

1 FRU

durchführen
Flat rate unit I 99 99 999

Local

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing the carpet for the vehicle interior, rear
Flat rate unit I 51 47 316

10 FRU

Removing and installing left or right rear door trim panel
Flat rate unit I 51 42 503

4 FRU

Removing and installing/replacing the sound insulation at the rear left or
right door
Flat rate unit I 51 48 570

3 FRU

Replacing left or right rear door window
Flat rate unit I 51 34 671

3 FRU

Replacing door window fixed in left or right rear window frame
Flat rate unit I 51 34 691

3 FRU

Removing and installing or replacing luggage compartment trim panel for
left wheel housing
Flat rate unit I 51 47 651

2 FRU

Removing and installing/replacing roller cover for luggage compartment
Flat rate unit I 51 47 645

1 FRU

Remove and replace headlining Flat rate unit I 51 44 502	32 FRU
Removing and installing trim panel for roof pillar, rear left or right Flat rate unit I 51 43 759	2 FRU
Removing and installing driver's seat Flat rate unit I 52 16 501	9 FRU
Removing and installing front passenger seat Flat rate unit I 52 16 502	7 FRU
Removing and installing/replacing rear seat Flat rate unit I 52 26 505	2 FRU
Removing and installing trim panel for instrument panel Flat rate unit I 51 45 529	38 FRU
Replacing centre console Flat rate unit I 51 16 666	4 FRU
Replace the centre console trim Flat rate unit I 51 16 661	3 FRU
Removing and installing right decor strip on instrument panel Flat rate unit I 51 45 880	2 FRU
Removing and installing front controller Flat rate unit I 61 31 695	1 FRU
Removing and installing gear selector lever Flat rate unit I 61 31 842	3 FRU
Performing vehicle test Flat rate unit I 00 00 556	3 FRU
Program/encode control unit(s), includes deleting the fault memory Flat rate unit I 61 00 730	4 FRU
Resume vehicle test and clear fault memory Flat rate unit I 61 00 980	2 FRU
Work time without specification/radio and special devices Flat rate unit I 65 99 000	2 FRU
Work time without specification/radio and special devices Flat rate unit I 65 99 000	12 FRU
Work time without specification/radio and special devices Flat rate unit I 65 99 000	2 FRU
Work time without specification/radio and special devices Flat rate unit I 65 99 000	2 FRU
Work time without specification/radio and special devices Flat rate unit I 65 99 000	2 FRU
Work time without specification / vehicle electrical system Flat rate unit I 61 99 000	6 FRU
Work time without specification/radio and special devices Flat rate unit I 65 99 000	24 FRU
Installing navigation map(s) Flat rate unit I 65 90 600	2 FRU

Work time without specification/body equipment Flat rate unit I 51 99 000		6 FRU
ISOLIERBAND Part I 99 99 9 400 128	Local	1
QUETSCHVERBINDER Part I 99 99 0 000 099	Local	10
Side window,green fixed,left rear door Part I 51 35 7 311 249		1
Sound insulating door rear left Part I 51 48 7 366 707		1
Butyl tape Terostat 81 Part I 83 19 0 153 321		1
Sound insulation, side panel, rear left Part I 51 48 9 168 517		1
Controller Part I 65 82 9 350 723		1
Fillister head self-tapp.screw w collar Part I 07 14 6 957 954		3
Cover center console Part I 51 16 9 206 372		1
Oval-head screw with washer Part I 07 14 9 185 673		7
Center console Part I 51 16 9 288 907		1
Hex screw with collar Part I 07 14 9 224 428		2
Rep. kit for radio/climate cont. panel Part I 61 31 9 328 425		1
Central information display Part I 65 50 9 289 008		1
Cover Part I 65 50 9 301 374		1
RP Head Unit High Part I 65 12 6 826 783		1
Spacer left Part I 65 12 9 250 691		1
Spacer right Part I 65 12 9 250 692		1
Oval-head screw with washer Part I 07 14 9 250 688		6
Gear selector switch Part I 61 31 9 296 904		1
screw for plastic Part I 07 14 9 204 847		4
USB Update Road Map Europe Next		1

Connection cable, Headunit High - CID

1

Part I 61 11 9 339 598

Rep.module Teleservices

1

Part I 61 11 9 340 212

HSD line head unit - base plate

1

Part I 61 11 9 340 629

HSD wire

1

Part I 61 11 9 339 798

Rep. guide Bluetooth cable antenna

1

Part I 61 11 9 278 968

Rep.module aerial lines AM/ FM2

1

Part I 61 11 9 340 097

Rep.module aerial GPS

1

Part I 61 11 9 340 099

Rep.module aerial lines AM/ FM2

1

Part I 61 11 6 823 261

Outer weatherstrip, rear left door

1

Part I 51 35 7 208 567

Fresh air grille center

1

Part I 64 22 9 209 136

Rep. kit for socket housing

1

Part I 61 13 2 360 043

Trim, armrest lock mechanism, chrome

1

Part I 51 16 9 277 348

Telestart handheld transmitter

1

Part I 61 31 9 245 066

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hinweis Handsender:

Local

1 FRU

Flat rate unit I 99 99 999

Der beim Einbruch entwendete

Local

1 FRU

Flat rate unit I 99 99 999

Handsender der Standheizung

Local

1 FRU

Flat rate unit I 99 99 999

61 31 9 245 066 wurde am

Local

1 FRU

Flat rate unit I 99 99 999

22.02.18 / 16.30 Uhr durch

Local

1 FRU

Flat rate unit I 99 99 999

Herrn Werner (AutoFleetControl)

Local

1 FRU

Flat rate unit I 99 99 999

zur Erneuerung freigegeben.

Local

1 FRU

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Hinweis Pfandpauschale: Flat rate unit I 99 99 999	Local	1 FRU
Die Berechnung der AT-Pfand- Flat rate unit I 99 99 999	Local	1 FRU
pauschale wurde fällig, weil Flat rate unit I 99 99 999	Local	1 FRU
das Altteil aufgrund des Flat rate unit I 99 99 999	Local	1 FRU
Diebstahles nicht zurückge- Flat rate unit I 99 99 999	Local	1 FRU
geben werden konnte. Flat rate unit I 99 99 999	Local	1 FRU

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

4 Tage Mietfahrzeug Starcar Flat rate unit I 99 99 999	Local	1 FRU
Wi-FM 1795 vom 02.02.18 Flat rate unit I 99 99 999	Local	1 FRU
bis 06.02.18 Flat rate unit I 99 99 999	Local	1 FRU

—	02/02/2018	Repair	98915 km	29429 B&K GmbH , Kronberg	Job Job
---	------------	--------	----------	---------------------------------	------------

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Freigabe: 7 6 1 6 9 7 Flat rate unit I 99 99 999	Local	1 FRU
Fremdleist Flat rate unit I 99 99 999	Local	1 FRU
Fahrzeug eingeschleppt Flat rate unit I 99 99 999	Local	1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

4 Tage Mietfahrzeug Starcar Flat rate unit I 99 99 999	Local	1 FRU
Wi-FM 1795 vom 02.02.18 Flat rate unit I 99 99 999	Local	1 FRU
bis 06.02.18 Flat rate unit I 99 99 999	Local	1 FRU

—	11/06/2017	Key	88517 km	29429	Key 0				
									
20000	20000	20000	20000	80000	0	6000	20000	0	0
08/2019	662	662	662		03/2018		08/2019	04/2018	04/2018
—	11/02/2017	Repair	88517 km	29429 B&K GmbH , Kronberg	Job Job Job				

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fast service with compact check or service consultation at the vehicle Flat rate unit I 00 52 055	4 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Eingelagerte Winterräder montieren, Sommerräder einlagern Flat rate unit I 36 10 366	Local	6 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerungsgebühr für Sommerräder Flat rate unit I 99 99 999	Local	1 FRU
Fa.4Wheels "Store" Flat rate unit I 99 99 999	Local	1 FRU
Einlagerung, Reinigung Flat rate unit I 99 99 999	Local	1 FRU
Einlagerungs-Nr.: 135660103	Local	1 FRU

—	08/02/2017	Service	78829 km	29429 B&K GmbH & Co. KG, Kronberg	Automatic
---	------------	---------	----------	-----------------------------------	-----------

										
900		900		5000	03/2018	13000	29000		04/2018	04/2018
✓		✓		✓						

—	08/02/2017	Repair	78836 km	29429 B&K GmbH, Kronberg	Job Job
---	------------	--------	----------	--------------------------	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Laub entfernen oberhalb der Flat rate unit | 99 99 999 Local 1 FRU

Motorhaube Flat rate unit | 99 99 999 Local 1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Wagenwäsche durchführen und Fußraum Flat rate unit | 00 11 005 Local 1 FRU

vorn aussaugen (ohne Berechnung) Flat rate unit | 00 11 005 Local 1 FRU

—	08/01/2017	Key	78829 km	29429	Key 0
---	------------	-----	----------	-------	-------

										
900	0	900	0	5000	03/2018	13000	29000	0	0	0
10/2018		455					10/2020	04/2018	04/2018	

—	03/17/2017	Key	65645 km	29429	Key 0
---	------------	-----	----------	-------	-------

										
13000	0	13000	0	6000	03/2018	26000	40000	0	0	0
10/2018		592					10/2020	04/2018	04/2018	

—	03/16/2017	Repair	65645 km	29429 B&K GmbH, Kronberg	Job Job Job Job
---	------------	--------	----------	--------------------------	--------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fast service with compact check or service consultation at the vehicle 4 FRU
Flat rate unit I 00 52 055

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Eingelagerte Sommerräder montieren, Winterräder einlagern Local 6 FRU
Flat rate unit I 36 10 368

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerungsgebühr für Winterräder Local 1 FRU
Flat rate unit I 99 99 999

Fa.4Wheels "Store" Local 1 FRU
Flat rate unit I 99 99 999

Einlagerung, Reinigung Local 1 FRU
Flat rate unit I 99 99 999

Einlagerungs-Nr.:124862456 Local 1 FRU
Flat rate unit I 99 99 999

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:










Wagenwäsche durchführen und Fußraum vorn aussaugen (ohne Berechnung) Local 1 FRU
Flat rate unit I 00 11 005

— 03/13/2017 Key

65105 km

29429

Key 0



— 02/01/2017 Key

61624 km

29429

Key 0

									
18000	0	18000	0	10000	0	30000	45000	0	0
10/2018		638			03/2018		10/2020	04/2018	04/2018

—	10/20/2016	Repair	52486 km	29429 B&K GmbH , Kronberg	Job Job
---	------------	--------	----------	---------------------------	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Eingelagerte Winterräder montieren, Flat rate unit I 36 10 366	Local	6 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerungsgebühr für Sommerräder Flat rate unit I 99 99 999	Local	1 FRU
Fa.4Wheels "Store" Flat rate unit I 99 99 999	Local	1 FRU
Einlagerung, Reinigung Flat rate unit I 99 99 999	Local	1 FRU
Einlagerungs-Nr.:126470410 Flat rate unit I 99 99 999	Local	1 FRU

—	10/20/2016	Repair	52482 km	29429 B&K GmbH , Kronberg	Job
---	------------	--------	----------	---------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Interne Qualitätssicherung -ohne Berechnung- Flat rate unit I 00 99 113	Local	4 FRU
--	-------	-------

—	10/19/2016	Key	52482 km	29429	Key 0
---	------------	-----	----------	-------	-------

									
700	700	700	700	18000	0	39000	700	0	0
01/2018	468	468	468		03/2018		01/2018	04/2018	04/2018

— 10/13/2016 Key 51525 km 29429 Key 0

										
1600	1600	1600	1600	19000	0	40000	1600		0	0
01/2018	474	474	474		03/2018		01/2018		04/2018	04/2018

— 08/11/2016 Key 43237 km 29429 Key 0

										
10000	10000	10000	10000	25000	0	46000	10000		0	0
01/2018	537	537	537		03/2018		01/2018		04/2018	04/2018

— 08/11/2016 Repair 43432 km 29429 B&K GmbH , Kronberg Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

1 Liter aufgefüllt. Flat rate unit I 99 99 999	Local	1 FRU
Vermutlich AGR-Kühler defekt. Flat rate unit I 99 99 999	Local	1 FRU
Kunde macht schnellstmöglich einen Flat rate unit I 99 99 999	Local	1 FRU
Termin. Flat rate unit I 99 99 999	Local	1 FRU
Anti-freeze Part I 83 19 2 211 191		1

— 04/08/2016 Key 34174 km 29429 Key 0

										
20000	20000	20000	20000	35000	0	60000	20000		0	0
01/2018	663	663	663		03/2018		01/2018		04/2018	04/2018

— 04/08/2016 Repair 34174 km 29429 B&K GmbH , Kronberg Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Eingelagerte Sommerräder montieren, Winterräder einlagern Flat rate unit I 36 10 368	Local	6 FRU
Vier Sommerräder stationär auswuchten Flat rate unit I 36 10 569	Local	7 FRU
WUCHTGEWICHT Part I 99 99 3 000 080	Local	8

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerungsgebühr für Winterräder Flat rate unit I 99 99 999	Local	1 FRU
Fa.4Wheels "Store" Flat rate unit I 99 99 999	Local	1 FRU
Einlagerung, Reinigung Flat rate unit I 99 99 999	Local	1 FRU
Einlagerungs-Nr.: 124862281 Flat rate unit I 99 99 999	Local	1 FRU

— Job

Description:

Is interpreted as a repeat visit: No


Customer's own words:

AZ without specification/maintenance Flat rate unit I 00 99 000		0 FRU
--	--	-------

— 01/25/2016 Key 25864 km 29429 Key 0

 1100 03/2017	 0	 1100 431	 0	 44000	 0 03/2018	 60000	 28000 03/2019	 0 04/2018	 0 04/2018
--	--	--	--	--	---	--	--	---	---

— 01/25/2016 Service 25864 km 29429 B & K GmbH & Co. KG, Kronberg Manual



—

10/21/2015 Repair

16157 km

29429 B&K
GmbH,
Kronberg

Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Eingelagerte Winterräder montieren, Sommerräder einlagern
Flat rate unit I 36 10 366

Local

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerungsgebühr für Sommerräder
Flat rate unit I 99 99 999

Local

1 FRU

Fa.4Wheels "Store"
Flat rate unit I 99 99 999

Local

1 FRU

Einlagerung, Reinigung
Flat rate unit I 99 99 999

Local

1 FRU

Einlagerungs-Nr.: 124860550
Flat rate unit I 99 99 999

Local

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Safety-First-Check
Flat rate unit I 00 99 112

Local

4 FRU

SCHEIBENKLAR
Part I 99 99 2 298 206

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

AZ without specification/maintenance
Flat rate unit I 00 99 000

0 FRU

AZ without specification/maintenance

0 FRU

—	10/21/2015	Repair	16157 km	29429 B&K GmbH , Kronberg	Job Job
---	------------	--------	----------	---------------------------------	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Safety-First-Check Flat rate unit I 00 99 112	Local	4 FRU
--	-------	-------

SCHEIBENKLAR Part I 99 99 2 298 206	Local	1
--	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

AZ without specification/maintenance Flat rate unit I 00 99 000		0 FRU
--	--	-------

AZ without specification/maintenance Flat rate unit I 00 99 000		0 FRU
--	--	-------

—	04/28/2015	Repair	224 km	29429 B&K GmbH , Kronberg	Job
---	------------	--------	--------	---------------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerungsgebühr für Winterräder Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

Fa.4Wheels "Store" Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

Einlagerung, Reinigung Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

Einlagerungs-Nr.:124218790 Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------