

Vehicle

BMW 320d EffDyn Edition, 120kW

WBA8D11030K776667



Development code

Color

Actual integration level

Start of warranty

F30

Jatoba metallic

F020-22-11-510

January 19, 2017

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2016-2 (as of: Feb 13, 2026)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

▼ Vehicle details

Vehicle type

Passenger car

Brand	BMW
Model	320d EffDyn Edition
Body	LIM
Vehicle identification number (last 7 characters)	K776667
Vehicle identification number (17 characters)	WBA8D11030K776667
Development code	F30
Steering	LL
Engine	B47O
Engine number	75419824
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0267574WC7
Head unit serial number	MM01DFG2818487
Drive	HECK
Integration level	F020-16-11-502
Production date	Dec 2, 2016
Production works	Muenchen
Delivery date	Jan 9, 2017
Delivering Retailers	No information
National-market version	EUR
Paint code	B65
Upholstery code	CCL1
Model code	8D21
Base type	8D11
Lead type	8D21

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 Extra package, EU-specific
 0248 Steering wheel heater
 02FH BMW LA wheel, V Spoke 390
 02VB Tire pressure display
 02VF Adaptive M suspension
 0302 Alarm system
 0322 Comfort access


Retrofitted optional equipment:

This vehicle has no retrofits.

03AC Trailer coupling
 03AG Reversing camera
 0403 Glass roof, electrical
 0420 Sun protection glazing
 0423 Floor mats, velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0459 Seat adjuster, electric, with memory
 0465 Through-loading system
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04CG Interior strips, "satin-silber" matt
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0548 Kilometer-calibrated speedometer
 0552 Adaptive LED headlight
 0563 Light package
 0575 Supplementary 12V sockets
 05A1 LED Fog lights
 05AC High-beam assistant
 05AG Lane-change warning
 05AL Active Protection
 05AS Driving Assistant
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 05DF Active cruise control+Stop&Go function
 05DP Park Assistant
 0606 Navigation system Business
 0610 Head-up display
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NS Convenience phone, expanded Smartphone
 06WA Instrument cluster, expanded equipment
 0710 M leather steering wheel
 07LC Modell Advantage
 07R7 Innovation package
 07S9 Connected Drive Services Paket
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 08R9 Refrigerant R1234yf
 08TH Road sign detection
 09AA Outer skin protection
 09BD Business Package
 A090 90 AH AGM battery
 POLS Cloth cushion

▾ Vehicle histories

	Date	Type	Vehicle mileage	Dealer	Overview
—	02/16/2026	Key	253659 km	52482	Remote KeyRead



— 02/13/2026 Key 253546 km 52482 Key 0




— 02/13/2026 Service 253546 km 52482 Automatic
Raymond Götz GmbH,
Hohenbrunn




— 02/09/2026 Key 253418 km 52482 Remote KeyRead




— 03/07/2025 Service 232996 km 52482 Automatic
Raymond Götz GmbH,
Hohenbrunn



— 03/06/2025 Key 232996 km 52482 Key 0



— 09/09/2024 Key 223106 km 31165 Key 0



— 09/09/2024 Service 223106 km 31165 Automatic
Radulovic

Beograd ,
Belgrade

 16000 03/2026	 16000 03/2026	 16000 03/2026	 16000 03/2026	 6000	 08/2024 ✓	 6000	 16000 03/2026
---	---	---	---	---	---	---	--

— 03/15/2024 Key 211322 km 52482 Key 0

 700 02/2025		 700 02/2025		 11000	 08/2024	 6000	 31000 02/2027
---	---	---	---	--	--	---	--

— 03/15/2024 Service 211322 km 52482 Automatic
Raymond Götz
GmbH ,
Hohenbrunn

 700 02/2025 ✓		 700 02/2025 ✓		 11000	 08/2024	 6000	 31000 02/2027
--	---	--	---	--	--	---	--

— 02/20/2023 Service 185675 km 42092 Manual
Raymond Götz
GmbH,
Hohenbrunn

 ✓	 ✓	 ✓	 ✓			 ✓			
--	--	--	--	---	---	--	--	---	---

— 08/25/2022 Key 179604 km 31165 Key 0

 7000 05/2023	 7000 05/2023	 7000 05/2023	 7000 05/2023	 45000	 -234 32 %	 29000	 7000 05/2023	 -234 32 %
--	--	--	--	--	---	--	---	---

— 08/25/2022 Service 179604 km 31165 Automatic
Radulovic d.o.o
, Belgrade

 7000 04/2023	 7000 04/2023	 7000 04/2023	 7000 04/2023	 45000	 01/2022 ✓	 29000	 7000 04/2023	 01/2022 ✓
--	--	--	--	--	---	--	---	---

— 05/10/2021 Key 157534 km Key 0

 350 11/2021		 350 171		 70000	 01/2022	 48000	 29000 11/2023	 01/2022
--	--	--	--	---	---	---	---	---

— 05/10/2021 Service 157534 km 31165 Automatic
Radulovic d.o.o
, Belgrade

 350 10/2021 ✓		 350 10/2021 ✓		 70000	 12/2021	 48000 10/2023	 29000 12/2021	 12/2021
--	---	--	---	--	--	---	--	--

— 05/26/2020 Key 147970 km 02815 Key 0

 11000 11/2021		 11000 530		 100000	 01/2022	 90000 11/2023	 40000 11/2023	 01/2022
---	---	---	---	---	--	---	--	--

— 05/26/2020 Repair 147970 km 02815 Job
Niederlassung Job
Düsseldorf Job
Filiale Rath
BMW AG,
Düsseldorf

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Beide Stoßdämpfer hinten aus- / einbauen / Zusatzdämpfer ersetzen,

Replacing both rear shock absorbers Flat rate unit I 33 52 030	12 FRU
---	--------

Auxiliary shock absorber, rear Part I 33 53 6 857 730	2
--	---

Hex nut with plate Part I 07 11 9 905 949	8
--	---

Torx screw with collar Part I 07 11 9 907 372	2
--	---

Self-locking collar nut Part I 33 32 6 760 668	2
---	---

Star-socket screw Part I 07 11 9 907 137	6
---	---

Gasket
Part I 33 50 6 866 038

2

Hex nut wiht flange
Part I 07 11 9 907 135

2

— Job

Description:

Is interpreted as a repeat visit: No








Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054









Local

0 FRU

— 01/15/2020 Key 136438 km 26861 Key 1



— 01/15/2020 Service 136438 km 26861 Automatic
May&Olde GmbH, Elmshorn



— 01/15/2020 Repair 136445 km 26861 May & Olde GmbH, Elmshorn Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fahrzeugwäsche inklusive aussaugen
Flat rate unit I 51 99 004

Local

2 FRU

— 01/15/2020 Repair 136445 km 26861 May & Olde GmbH, Elmshorn Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Presentation for emission inspection Flat rate unit I 00 00 527	5 FRU
--	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job


Description:

Is interpreted as a repeat visit: No


Customer's own words:

HU gemäß §29 StVZO 00000000 87990100007 Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

11/05/2019	Key	128507 km	26861	Key 1
------------	-----	-----------	-------	-------



11/05/2019	Service	128507 km	26861 May & Olde GmbH, Elmshorn	Automatic
------------	---------	-----------	---------------------------------	-----------



11/05/2019	Repair	128512 km	26861 May & Olde GmbH, Elmshorn	Job Job
------------	--------	-----------	---------------------------------	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder montieren Sommerräder prüfen, reinigen und einlagern; Lagerort: C4E2 Flat rate unit I 36 00 008	Local	12 FRU
---	-------	--------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fahrzeugwäsche inklusive aussaugen Flat rate unit I 51 99 004	Local	2 FRU
---	-------	-------

—	11/05/2019	Repair	128512 km	26861 May & Olde GmbH, Elmshorn	Job
---	------------	--------	-----------	------------------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

Service - air filter insert Flat rate unit I 00 00 602	2 FRU
---	-------

Fuel filter service Flat rate unit I 00 00 604	3 FRU
---	-------

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Replace left and right wiper blade Flat rate unit I 61 61 541	1 FRU
--	-------

Service - front brakes Flat rate unit I 00 00 612	4 FRU
--	-------

Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
--	-------

Rear brakes service Flat rate unit I 00 00 614	5 FRU
---	-------

Removing and installing/renewing both brake discs Flat rate unit I 34 21 932	4 FRU
---	-------

MOTORÖL CASTROL Longlife-04 BMW Part I FT99 99 9 000 0	Local	5
---	-------	---

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

Air filter element Part I 13 71 8 511 668	1
--	---

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

1	1	1	2	2	1	1	2	2
---	---	---	---	---	---	---	---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing front right side panel	0 FRU
Flat rate unit I 41 35 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body	0 FRU
Flat rate unit I 41 99 000	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing left or right front door	0 FRU
Flat rate unit I 41 51 580	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace front left or right door	32 FRU
Flat rate unit I 41 51 501	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Adjusting front left or right door	0 FRU
Flat rate unit I 41 51 504	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing the window recess finisher strip on the outer rear left or right door	0 FRU
Flat rate unit I 51 22 800	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Remove and install/replace left or right side sill trim panel Flat rate unit I 51 71 947	0 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body Flat rate unit I 41 99 000	0 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/vehicle underbody preservation Flat rate unit I 97 99 000	0 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Cavity sealant for the front door, left or right Flat rate unit I 97 51 501	2 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Painting the side panel, left or right Flat rate unit I 99 35 519	0 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Painting the front door, left or right Flat rate unit I 99 51 548	0 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Painting left or right door sill trim panel	0 FRU
Flat rate unit I 99 64 519	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Painting the rear quarter panel, left or right	0 FRU
Flat rate unit I 99 36 529	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/paintwork	0 FRU
Flat rate unit I 99 99 000	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/paintwork	0 FRU
Flat rate unit I 99 99 000	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/paintwork	0 FRU
Flat rate unit I 99 99 000	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Blind plug	2
Part I 07 14 7 127 540	

Door front right	1
Part I 41 00 7 298 566	

Side panel, front right	1
Part I 41 00 7 438 440	

Positioning aid T-bolt	1
Part I 41 21 2 460 145	

T-welding stud Part I 41 31 8 412 638	20
Supporting ledge right Part I 51 77 7 240 874	1
Supporting ledge right Part I 51 77 7 256 916	1
Supporting ledge right Part I 51 77 7 256 918	1
Rocker panel trim, primed, right Part I 51 77 7 312 752	1
Sound insulation, door, front right Part I 51 48 7 286 656	1
Door weatherstrip front Part I 51 33 7 258 329	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

9AW A 13,80.- 00000000 Flat rate unit I 99 99 999	Local	1 FRU
120AW a 13,80.- 00000000 Flat rate unit I 99 99 999	Local	1 FRU
3AW a 13,80.- 00000000 Flat rate unit I 99 99 999	Local	1 FRU
32AW a 13,80.- 00000000 Flat rate unit I 99 99 999	Local	1 FRU
2AW A 13,80.- 00000000 Flat rate unit I 99 99 999	Local	1 FRU
1AW a 13,80.- 00000000 Flat rate unit I 99 99 999	Local	1 FRU
4AW a 13,80.- 00000000 Flat rate unit I 99 99 999	Local	1 FRU
2AW a 13,80.- 00000000 Flat rate unit I 99 99 999	Local	1 FRU
3AW a 13,80.- 00000000 Flat rate unit I 99 99 999	Local	1 FRU
2AW a 13,80.- 00000000 Flat rate unit I 99 99 999	Local	1 FRU
Lackierung 10AW a 15,23.- zzgl. 35% Lackmaterial 00000000 Flat rate unit I 99 99 999	Local	1 FRU
Lackierung 15AW a 15,23.- zzgl. 35% Lackmaterial 00000000 Flat rate unit I 99 99 999	Local	1 FRU
Lackierung 7AW a 15,23.- zzgl. 35% Lackmaterial 00000000 Flat rate unit I 99 99 999	Local	1 FRU

Lackierung 10AW a 15,23.- zzgl. 35% Lackmaterial 00000000 Flat rate unit I 99 99 999	Local	1 FRU
7AW a 15,23.- zzgl. 35% Lackmaterial 00000000 Flat rate unit I 99 99 999	Local	1 FRU
3AW a 15,23.- zzgl. 35% Lackmaterial 00000000 Flat rate unit I 99 99 999	Local	1 FRU
2AW a 15,23.- zzgl. 35% Lackmaterial 00000000 Flat rate unit I 99 99 999	Local	1 FRU
Zeitzuschlag für eine Hauptarbeit Lack 00000000 Flat rate unit I 99 99 999	Local	1 FRU
28AW a 15,23.- 00000000 Flat rate unit I 99 99 999	Local	1 FRU
Lackmaterial 35% 00000000 Flat rate unit I 99 99 999	Local	1 FRU
Ersatzfahrzeug (E) 6 Tage 00000000 Flat rate unit I 99 99 999	Local	1 FRU

—	05/03/2019	Repair	103011 km	24342 May & Olde GmbH , Itzehoe	Job
---	------------	--------	-----------	---------------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

(Annual) vehicle inspection as part of DGUV Regulation 70 Flat rate unit I 00 12 170	4 FRU
---	-------

—	04/23/2019	Key	103011 km	26861	Key 0
---	------------	-----	-----------	-------	-------

									
23000	23000	23000	23000	6000	0	6000	23000	23000	0
02/2021	677	677	677		01/2020		02/2021		01/2020

—	04/23/2019	Repair	103011 km	26861 May & Olde GmbH , Elmshorn	Job
---	------------	--------	-----------	----------------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 2 Silber Sommerräder wuchten u. montieren, Winter- räder prüfen,reinigen,lagern Flat rate unit I 36 00 009	Local	20 FRU
---	-------	--------

—	04/23/2019	Repair	103011 km	26861 May & Olde GmbH ,	Job
---	------------	--------	-----------	-------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 2 Silber Sommerräder wuchten u. montieren, Winter- räder
prüfen,reinigen,lagern Local -20 FRU
Flat rate unit I 36 00 009

— 04/23/2019 Repair 103011 km 26861 May & Olde GmbH , Elmshorn Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 2 Silber Sommerräder wuchten u. montieren, Winter- räder
prüfen,reinigen,lagern Local 20 FRU
Flat rate unit I 36 00 009

— 03/08/2019 Key 98682 km Key 1

								
27000	27000	27000	27000	6000	0	6000	27000	0
02/2021	722	722	722		01/2020		02/2021	01/2020

— 03/04/2019 Key 97973 km 24342 Key 1

								
28000	28000	28000	28000	6000	0	6000	28000	0
02/2021	726	726	726		01/2020		02/2021	01/2020

— 02/14/2019 Key 95439 km 26861 Key 1

								
-1000	0	-1000	0	7000	0	7000	30000	0
05/2020		472			01/2020		05/2022	01/2020

— 02/14/2019 Service 95439 km 26861 May&Olde GmbH , Elmshorn Automatic

 -1000 05/2020 ✓	 0	 -1000 05/2020 ✓	 0	 7000	 0 01/2020	 7000	 30000 05/2022	 0 01/2020
---	---	---	---	--	--	--	---	--

— 02/14/2019 Repair 95439 km 26861 May & Olde GmbH, Elmshorn Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fahrzeugwäsche inklusive aussaugen Flat rate unit I 51 99 004	Local	2 FRU
---	-------	-------

— 02/14/2019 Repair 95440 km 26861 May & Olde GmbH, Elmshorn Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105		2 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616		2 FRU
---	--	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555		1
--	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610		3 FRU
--	--	-------

Castrol Edge Prof. 0W30 LL04 Leichtlauföl Part I FT99 99 9 000 0	Local	5
---	-------	---

Set oil-filter element Part I 11 42 8 575 211		1
--	--	---

—	01/31/2019	Key	93640 km	Key 1
---	------------	-----	----------	-------

									
800	0	800	0	7000	0	7000	32000		0
05/2020		485			01/2020		05/2022		01/2020

—	10/23/2018	Key	82457 km	Key 1
---	------------	-----	----------	-------

									
12000	0	12000	0	17000	0	7000	43000		0
05/2020		585			01/2020		05/2022		01/2020

—	10/23/2018	Repair	82457 km	26861 May & Olde GmbH, Elmshorn	Job
---	------------	--------	----------	---------------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 2 Silber Winterräder wuchten u. montieren, Sommer- räder prüfen,reinigen,lagern
Flat rate unit I 36 00 009

Local

20 FRU

—	09/27/2018	Key	79068 km	Key 1
---	------------	-----	----------	-------

									
16000	0	16000	0	20000	0	7000	47000		0
05/2020		611			01/2020		05/2022		01/2020

—	05/23/2018	Key	63450 km	26861	Key 1
---	------------	-----	----------	-------	-------

									
-1000	-1000	-1000	-1000	36000	0	16000	-1000		0
08/2019	465	465	465		01/2020		08/2019		01/2020

—	05/23/2018	Service	63450 km	26861 May&Olde GmbH, Elmshorn	Automatic
---	------------	---------	----------	-------------------------------	-----------

									
-1000	-1000	-1000	-1000	36000	0	16000	-1000		0
08/2019	08/2019	08/2019	08/2019		01/2020		08/2019		01/2020
✓	✓	✓	✓				✓		

—	05/23/2018	Repair	63451 km	26861 May & Olde GmbH, Elmshorn	Job Job Job Job Job Job Job Job Job Job
---	------------	--------	----------	---------------------------------	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kosten Serviceersatz (E) PI-MO 4222 Part I FT0000158	Local	1
Haftungsreduzierung Part I FT0000138	Local	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Aufbereitung Part I FT0000170	Local	1
----------------------------------	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

—	05/23/2018	Repair	63451 km	26861 May & Olde GmbH , Elmshorn	Job
---	------------	--------	----------	----------------------------------	-----

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
Service - microfilter Flat rate unit I 00 00 616	2 FRU
Vehicle check service Flat rate unit I 00 00 624	6 FRU
Service - air filter insert Flat rate unit I 00 00 602	2 FRU
Fuel filter service Flat rate unit I 00 00 604	3 FRU

Engine oil service Flat rate unit I 00 00 610		3 FRU
Replace left and right wiper blade Flat rate unit I 61 61 541		1 FRU
Castrol Edge Prof. 0W30 LL04 Leichtlauföl Part I FT99 99 9 000 0	Local	5
Microfilter/activated Carbon container Part I 64 11 9 237 555		1
Air filter element Part I 13 71 8 511 668		1
Fuel filter cartridge Part I 13 32 8 572 522		1
Set oil-filter element Part I 11 42 8 575 211		1
Set of wiper blades Part I 61 61 2 241 375		1

— 05/23/2018 Repair 63451 km 26861 May & Olde GmbH, Elmshorn Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 2 Silber Sommerräder wuchten u. montieren, Winter- räder prüfen, reinigen, lagern Local 12 FRU
Flat rate unit I 36 00 012

— 04/18/2018 Key 60066 km 26861 Key 0

								
2400	2400	2400	2400	40000	0	20000	2400	0
08/2019	499	499	499		01/2020		08/2019	01/2020

— 01/31/2018 Repair 37980 km 26861 May & Olde GmbH, Elmshorn Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 2 Silber Winterräder wuchten u. montieren, Sommer- räder prüfen, reinigen, lagern Local -18 FRU
Flat rate unit I 36 00 009

—	01/30/2018	Repair	37980 km	26861 May & Olde GmbH, Elmshorn	Job Job
---	------------	--------	----------	---------------------------------	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time for specifications from damage calculation systems Flat rate unit I 00 99 999	0 FRU
--	-------

Work time for specifications from damage calculation systems Flat rate unit I 00 99 999	0 FRU
--	-------

Windshield Washer Antifreeze Part I 83 12 2 409 031	-1
--	----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 2 Silber Winterräder wuchten u. montieren, Sommer- räder prüfen,reinigen,lagern Flat rate unit I 36 00 009	Local	-18 FRU
---	-------	---------

—	01/02/2018	Key	45915 km	26861	Key 0
---	------------	-----	----------	-------	-------

 17000 08/2019	 17000 606	 17000 606	 17000 606	 60000	 0 01/2020	 35000	 17000 08/2019	 0 01/2020
---	---	---	---	--	---	--	--	---

—	01/02/2018	Key	45915 km	26861	Key 0
---	------------	-----	----------	-------	-------

 17000 08/2019	 17000 606	 17000 606	 17000 606	 60000	 0 01/2020	 35000	 17000 08/2019	 0 01/2020
---	---	---	---	--	---	--	--	---

—	01/02/2018	Repair	45915 km	26861 May & Olde GmbH, Elmshorn	Job
---	------------	--------	----------	---------------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

(Annual) vehicle inspection as part of DGUV Regulation 70 Flat rate unit I 00 12 170	4 FRU
---	-------

—	01/02/2018	Repair	45915 km	26861 May & Olde GmbH, Elmshorn	Job
— Job					
Description:					
Is interpreted as a repeat visit: No					
Customer's own words:					
(Annual) vehicle inspection as part of DGUV Regulation 70					-4 FRU
Flat rate unit I 00 12 170					
—	01/02/2018	Repair	45915 km	26861 May & Olde GmbH, Elmshorn	Job
— Job					
Description:					
Is interpreted as a repeat visit: No					
Customer's own words:					
(Annual) vehicle inspection as part of DGUV Regulation 70					4 FRU
Flat rate unit I 00 12 170					
—	10/25/2017	Key	37980 km	26861	Key 1
 25000 08/2019  25000 674  25000 674  25000 674  60000  0 01/2020  39000  25000 08/2019  0 01/2020					
—	10/25/2017	Repair	37980 km	26861 May & Olde GmbH, Elmshorn	Job Job
— Job					
Description:					
Is interpreted as a repeat visit: No					
Customer's own words:					
Flat rate unit I -					Local 0 FRU
Flat rate unit I -					Local 0 FRU
Windshield Washer Antifreeze Part I 83 12 2 409 031					1
— Job					
Description:					
Is interpreted as a repeat visit: No					
Customer's own words:					

PAKET 2 Silber Winterräder wuchten u. montieren, Sommer- räder Local 18 FRU
 prüfen,reinigen,lagern
 Flat rate unit I 36 00 009

— 10/25/2017 Repair 37980 km 26861 May & Olde GmbH, Elmshorn Job

— Job


Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 2 Silber Winterräder wuchten u. montieren, Sommer- räder Local 18 FRU
 prüfen,reinigen,lagern
 Flat rate unit I 36 00 009

— 08/28/2017 Key 31435 km 26861 Key 1



— 08/28/2017 Repair 31440 km 26861 May & Olde GmbH, Elmshorn Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
 Flat rate unit I 00 00 610

Standard scope of service 2 FRU
 Flat rate unit I 00 00 105

Service - microfilter 2 FRU
 Flat rate unit I 00 00 616

Replace left and right wiper blade 1 FRU
 Flat rate unit I 61 61 541

Castrol Edge Prof. 0W30 LL04 Leichtlauföl Local 5
 Part I FT99 99 9 000 0

Set oil-filter element 1
 Part I 11 42 8 575 211

Microfilter/activated Carbon container 1
 Part I 64 11 9 237 555

Set of wiper blades 1
 Part I 61 61 2 241 375

Windshield Washer Antifreeze 1

—	08/15/2017	Key	29982 km	26861	Key 1	
						
1000	0	1000	0	60000	0	49000
12/2018		503			01/2020	32000
						12/2020
						01/2020
—	07/06/2017	Repair	11012 km	26861 May & Olde GmbH, Elmshorn	Job Job Job	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 1 BRONZE (Lagerort) Sommerräder montieren, Winter- räder Local -12 FRU
 prüfen, reinigen lagern
 Flat rate unit I 36 00 008

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

C.a.F. Zur internen Verrechnung Local -6 FRU
 Flat rate unit I 00 99 550

Windshield Washer Antifreeze -1
 Part I 83 12 2 409 031

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fahrzeugwäsche inklusive aussaugen Local -2 FRU
 Flat rate unit I 51 99 004

—	07/06/2017	Repair	11012 km	26861 May & Olde GmbH, Elmshorn	Job Job Job	
---	------------	--------	----------	---------------------------------	-------------------	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 1 BRONZE (Lagerort) Sommerräder montieren, Winter- räder prüfen, reinigen lagern Local -12 FRU
Flat rate unit I 36 00 008

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

C.a.F. Zur internen Verrechnung Local -6 FRU
Flat rate unit I 00 99 550

Windshield Washer Antifreeze -1
Part I 83 12 2 409 031

— Job








Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fahrzeugwäsche inklusive aussaugen Local -2 FRU
Flat rate unit I 51 99 004

— 04/11/2017 Key 11012 km 26861 Key 0



— 04/11/2017 Repair 11012 km 26861 May & Olde GmbH, Elmshorn Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 1 BRONZE (Lagerort) Sommerräder montieren, Winter- räder prüfen, reinigen lagern Local 12 FRU
Flat rate unit I 36 00 008

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

C.a.F. Zur internen Verrechnung Local 6 FRU
Flat rate unit I 00 99 550

Windshield Washer Antifreeze 1
Part I 83 12 2 409 031

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fahrzeugwäsche inklusive aussaugen	Local	2 FRU
Flat rate unit I 51 99 004		

—	04/11/2017	Repair	11012 km	26861 May & Olde GmbH , Elmshorn	Job Job Job
---	------------	--------	----------	--	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 1 BRONZE (Lagerort) Sommerräder montieren, Winter- prüfen, reinigen lagern	Local	12 FRU
Flat rate unit I 36 00 008		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

C.a.F. Zur internen Verrechnung	Local	6 FRU
Flat rate unit I 00 99 550		

Windshield Washer Antifreeze	1
Part I 83 12 2 409 031	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fahrzeugwäsche inklusive aussaugen	Local	2 FRU
Flat rate unit I 51 99 004		

—	04/11/2017	Repair	11012 km	26861 May & Olde GmbH , Elmshorn	Job Job Job
---	------------	--------	----------	--	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 1 BRONZE Sommerräder montieren, Winter- räder prüfen, reinigen lagern Flat rate unit I 36 00 008	Local	12 FRU
--	-------	--------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

C.a.F. Zur internen Verrechnung Flat rate unit I 00 99 550	Local	6 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fahrzeugwäsche inklusive aussaugen Flat rate unit I 51 99 004	Local	2 FRU
---	-------	-------

—	01/25/2017	Repair	37980 km	26861 May & Olde GmbH, Elmshorn	Job
---	------------	--------	----------	---------------------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

PAKET 2 Silber Winterräder wuchten u. montieren, Sommer- räder prüfen,reinigen,lagern Flat rate unit I 36 00 009	Local	18 FRU
--	-------	--------

—	01/18/2017	Repair	3 km	02815 Niederlassung Düsseldorf Filiale Rath BMW AG, Düsseldorf	Job Job Job
---	------------	--------	------	---	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

BMW warning vest, set of 2 Part I 82 26 2 288 693	1
--	---

Floor mats, all-weather, front Part I 51 47 2 219 799	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Depotservice Rädermontage Flat rate unit I AZ36 00 2	Local	6 FRU
RDCi wheel & tire, winter, light alloy Part I 36 11 2 448 003		4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Freie AW Mechanik/Sommerräder reinigen Flat rate unit I AZME000	Local	4 FRU
--	-------	-------