

Vehicle

BMW 320d, 140kW

WBA8H91050K748176



Development code	F31
Color	black-sapphire metallic
Actual integration level	F020-22-07-530
Start of warranty	July 11, 2016

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map cannot be identified. One of the following maps could be installed in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2016-1 (as of: Mar 4, 2024)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2025-2	-
Road Map EUROPE EVO 2016-1 (as of: Mar 4, 2024)	-	-	-

▾ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320d
Body	TOUR
Vehicle identification number (last 7 characters)	K748176
Vehicle identification number (17 characters)	WBA8H91050K748176
Development code	F31
Steering	LL
Engine	B47O
Engine number	65509629
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0351891ZRI
Head unit serial number	HB2140G7848765
Drive	HECK
Integration level	F020-16-03-504
Production date	May 20, 2016
Production works	Muenchen
Delivery date	Jun 15, 2016
Delivering Retailers	No information
National-market version	EUR
Paint code	475
Upholstery code	LCDY
Model code	8H01
Base type	8H91
Lead type	8H01

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
01CB CO2 package
0205 Automatic transmission
0216 Hydro steering-servotronic
0230 Extra package, EU-specific

Retrofitted optional equipment:

This vehicle has no retrofits.

0255 Sports leather steering wheel
0258 Tire with run-flat functionality
02VB Tire pressure display
0302 Alarm system
0322 Comfort access
03AA Roof railing black
03AC Trailer coupling
0402 Electric panoramic roof
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0441 Smoker package
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04GA Ashgrain Perlglanz chrome accent
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometer-calibrated speedometer
0563 Light package
0575 Supplementary 12V sockets
05A1 LED Fog lights
05A2 LED headlight
05AC High-beam assistant
05AL Active Protection
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
0609 Navigation system Professional
0676 HiFi speaker system
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NS Convenience phone, expanded Smartphone
06WA Instrument cluster, expanded equipment
07LE Modell Luxury Line
07S2 Luxury Line
07XP Navigation package, Connected Drive
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08TH Road sign detection
0931 Winter instead of summer tires ex-fact.
09AA Outer skin protection
09BD Business Package
A090 90 AH AGM battery
LEDE Leather trim

▾ Vehicle histories

Date	Type	Vehicle mileage	Dealer	Overview
— 04/29/2026	Repair	196716 km	33364 ,	Job
—	Job			

Description: eingebaut am 21.04.26

Is interpreted as a repeat visit: No

Customer's own words:

Battery
Part I 61 31 9 217 643

1

—	04/21/2026	Key	196709 km	33364	Key 0		
 1200 11/2026		 1200 11/2026		 39000 06/2027	 21000	 33000 11/2028	 06/2027
—	04/21/2026	Service	196709 km	33364 AHAG Münsterland GmbH , Dülmen	Automatic		
 1200 11/2026 ✓	 0	 1200 11/2026 ✓	 0	 39000 06/2027	 21000	 33000 11/2028	 0 06/2027
—	04/21/2026	Repair	196716 km	33364 ,	Job Job: Service Standardumfang (M Job: Service Motoröl (MKP) Job: Service Mikrofilter (MKP) Job		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket
Flat rate unit I 00 52 052

0 FRU

— Job: Service Standardumfang (M

Description: MKP 000010518H010 : BMW Service 5+, 20% Nachlass undefined Nachlass undefined

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang (M
Package I 0000105

Standard scope of service
Flat rate unit I 00 00 105

2

— Job: Service Motoröl (MKP)

Description: MKP 000061018H010 : BMW Service 5+, 20% Nachlass undefined Nachlass undefined

Is interpreted as a repeat visit: No

Customer's own words:

Service Motoröl (MKP)

Package I 0000610

Engine oil service	3
Flat rate unit I 00 00 610	
Set oil-filter element	1
Part I 11 42 8 575 211	
BMW Engine Oil LL04 5W30	5
Part I 83 21 2 405 948	

— Job: Service Mikrofilter (MKP)

Description: MKP 000061618H010 : BMW Service 5+, 20% Nachlass undefined Nachlass undefined

Is interpreted as a repeat visit: No

Customer's own words:

Service Mikrofilter (MKP)
Package I 0000616

Service - microfilter	2
Flat rate unit I 00 00 616	
Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job


Description:

Is interpreted as a repeat visit: No

Customer's own words:


SERVICE-GUTSCHEIN *SORRY-MAßNAHME*	Local	-1 FRU
Flat rate unit I 99 99 999		

— 06/11/2025 Key 181900 km 33364 Key 0



— 06/11/2025 Service 181900 km 33364 AHAG Automatic

Münsterland
GmbH ,
Dülmen



— 06/11/2025 Repair 181909 km 33364 , Job: Service Standardumfang
Job: Service Bremsflüssigkeit
Job
Job

— Job: Service Standardumfang

Description: MKP 0000105 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang

Package I 0000105

Standard scope of service	2
Flat rate unit I 00 00 105	

— Job: Service Bremsflüssigkeit

Description: MKP 0000618 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Bremsflüssigkeit

Package I 0000618

Brake fluid service	4
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 2 184 843	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hauptuntersuchung nach §29 StV ZO	Local	1 FRU
Flat rate unit I 99 99 999		

(statutory) general inspection	0 FRU
Flat rate unit I 00 12 159	

§ emission test with on-board diagnosis	3 FRU
Flat rate unit I 00 00 128	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing all wiper blades	0 FRU
Flat rate unit I 61 61 047	

Set of wiper blades	1
Part I 61615A43585	

Wiper blade	1
Part I 61 62 7 356 763	

								
20000		20000		60000		39000	60000	
11/2026		11/2026			06/2025		11/2028	06/2025

— 11/05/2024 Key 170921 km 33364 Key 0

								
-410	-410	-410	-410	70000		49000	-410	
06/2025	06/2025	06/2025	06/2025		06/2025		06/2025	06/2025

— 11/05/2024 Service 170921 km 33364 AHAG Automatic
Münsterland
GmbH ,
Dülmen

								
-410	-410	-410	-410	70000		49000	-410	
06/2025	06/2025	06/2025	06/2025		06/2025		06/2025	06/2025
✓	✓	✓	✓				✓	

— 11/05/2024 Repair 170939 km 33364 , Job
Job: Service Motoröl
Job: Service Kraftstofffilter
Job: Service Luftfiltereinsatz
Job: Service Mikrofilter
Job: Service Fahrzeug-Check

— Job

Description: MKP 0000105 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Battery 1
Part I 61 31 9 217 643

Service Standardumfang 2
Package I 0000105
Standard scope of service
Flat rate unit I 00 00 105

— Job: Service Motoröl

Description: Nachlass MKP 0000610 : BMW Service 5+, 20% Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Motoröl
Package I 0000610
Engine oil service 3
Flat rate unit I 00 00 610
Set oil-filter element 1
Part I 11 42 8 575 211

— Job: Service Kraftstofffilter

Description: MKP 0000604 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Kraftstofffilter
Package I 0000604

Fuel filter service 3
Flat rate unit I 00 00 604

Fuel filter cartridge 1
Part I 13 32 7 822 497

— Job: Service Luftfiltereinsatz

Description: MKP 0000602 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Luftfiltereinsatz
Package I 0000602

Service - air filter insert 2
Flat rate unit I 00 00 602

Air filter element 1
Part I 13 71 8 511 668

— Job: Service Mikrofilter

Description: MKP 0000616 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Mikrofilter
Package I 0000616

Service - microfilter 2
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— Job: Service Fahrzeug-Check

Description: MKP 0000624 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Fahrzeug-Check
Package I 0000624

Vehicle check service 6
Flat rate unit I 00 00 624

— 10/24/2024 Key 170571 km 33364 Key 0

 -50 0.2 % 06/2025	 -50 06/2025	 -50 06/2025	 -50 06/2025	 70000 06/2025	 06/2025	 49000 06/2025	 -50 0.1 % 06/2025	 06/2025
--	---	---	---	---	--	---	---	--

— 10/09/2024 Key 170092 km 33364 Key 1

 700 06/2025	 700 06/2025	 700 06/2025	 700 06/2025	 70000 06/2025	 06/2025	 50000 06/2025	 700 06/2025	 06/2025
---	---	---	---	---	--	---	--	--

— 03/04/2024 Key 156397 km 33364 Key 1

 15000 06/2025	 15000 06/2025	 15000 06/2025	 15000 06/2025	 90000 06/2025	 06/2025	 70000 06/2025	 15000 06/2025	 06/2025
---	---	---	---	---	--	---	--	--

— 06/07/2023 Key 141681 km Key 1

 -1200 3.9 % 11/2023	 06/2025	 -1200 11/2023	 06/2025	 100000 07/2023	 07/2023	 80000 11/2025	 30000 11/2025	 07/2023
--	--	---	--	--	--	---	--	--

— 06/07/2023 Service 141681 km 33364 AHAG Münsterland GmbH , Dülmen Automatic

 -1200 11/2023 ✓	 06/2025	 -1200 11/2023 ✓	 06/2025	 100000 07/2023 ✓	 07/2023	 80000 11/2025	 30000 11/2025	 07/2023
--	--	--	--	---	--	---	--	--

— 06/07/2023 Repair 141681 km 33364 AHAG Münsterland GmbH , Dülmen Job Job Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

BMW group LL-04 0w-30	5
Part I 83 21 2 465 858	

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 2 184 843	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Presentation for emission inspection	5 FRU
Flat rate unit I 00 00 527	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Hauptuntersuchung nach §2 9 StVZO	Local	1 FRU
Flat rate unit I 99 99 999		

 -410 1.3 % 11/2023		 -410 11/2023		 100000	 07/2023	 90000	 31000 11/2025	 07/2023
--	--	---	--	--	---	---	---	---

— 08/15/2022 Key 125625 km 33364 Key 0

 18000 11/2023		 18000 11/2023		 130000	 07/2023	 110000	 49000 11/2025	 07/2023
---	---	---	---	---	--	---	--	--

— 07/29/2022 Key 125184 km 33364 Key 1

 18000 11/2023		 18000 11/2023		 130000	 07/2023	 110000	 49000 11/2025	 07/2023
---	---	---	---	---	--	---	--	--

— 11/16/2021 Key 112797 km Key 1

 1200 04/2022	 1200 135	 1200 135	 1200 135	 130000	 07/2023	 120000	 1200 04/2022	 07/2023
--	--	--	--	---	--	---	---	--

— 11/16/2021 Service 112797 km 33364 AHAG Dülmen GmbH , Dülmen Automatic

 1200 03/2022 ✓	 1200 03/2022 ✓	 1200 03/2022 ✓	 1200 03/2022 ✓	 130000	 06/2023	 120000	 1200 03/2022 ✓	 06/2023
---	---	---	---	---	--	---	--	--

— 11/16/2021 Repair 112803 km 33364 AHAG Münsterland GmbH , Dülmen Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Fuel filter service Flat rate unit I 00 00 604	3 FRU
Fuel filter cartridge Part I 13 32 8 572 522	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - air filter insert Flat rate unit I 00 00 602	2 FRU
Air filter element Part I 13 71 8 511 668	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

 1500 04/2022	 1500 139	 1500 139	 1500 139	 130000 07/2023	 120000 07/2023	 1500 04/2022	 07/2023
---	---	---	---	---	---	---	---

— 07/07/2021 Key 105274 km Key 1

 9000 04/2022	 9000 297	 9000 297	 9000 297	 70 07/2021	 0 07/2021	 8000 04/2022	 9000 04/2022	 0 07/2021
--	--	--	--	--	---	--	--	---

— 07/07/2021 Service 105274 km 33364 AHAG Automatic
Dülmen GmbH , Dülmen

 9000 04/2022	 9000 04/2022	 9000 04/2022	 9000 04/2022	 70 07/2021	 0 07/2021	 8000 04/2022	 9000 04/2022	 0 07/2021
--	--	--	--	--	---	--	--	---

— 07/07/2021 Repair 105274 km 33364 AHAG Job
Münsterland Job
GmbH , Job
Dülmen Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service
Flat rate unit I 00 00 618

4 FRU

Brake fluid DOT4 LV, low viscosity
Part I 83 13 2 184 843

1

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Rear brakes service Flat rate unit I 00 00 614	7 FRU
---	-------

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
--	---

Brake pad paste Part I 83 19 2 158 851	2
---	---

Brake cleaner, acetone-free Part I 83 19 2 413 695	1
---	---

Brake pad wear sensor, rear Part I 34 35 6 792 292	1
---	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

(statutory) general inspection Flat rate unit I 00 12 159	6 FRU
--	-------

Demonstration for state emissions inspection Flat rate unit I 00 00 127	7 FRU
--	-------

Gebühr HU Part I FT99 99 0 000 1	Local	1
-------------------------------------	-------	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - front brakes Flat rate unit I 00 00 612	6 FRU
--	-------

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
--	---

Brake cleaner, acetone-free Part I 83 19 2 413 695	1
---	---

Brake pad paste Part I 83 19 2 158 851	2
---	---

Brake pad wear sensor, front left Part I 34 35 6 792 289	1
---	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

—	06/30/2021	Key	105041 km			Key 1		
10000	10000	10000	10000	290	0	8000	10000	0
04/2022	303	303	303		07/2021		04/2022	07/2021
—	04/29/2020	Key	86318 km			33364	Key 0	
1000		1000		11000		8000	32000	
11/2020		182		07/2021			11/2022	07/2021
—	04/29/2020	Service	86318 km			33364 AHAG Dülmen GmbH , Dülmen	Automatic	
1000	0	1000	0	11000	0	8000	32000	0
11/2020		11/2020		07/2021		11/2022		07/2021
✓		✓						
—	04/29/2020	Repair	86318 km			33364 AHAG Münsterland GmbH , Dülmen	Job Job Job Job Job Job Job Job	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder montieren liegen im Fahrzeug inkl. Analyse
Flat rate unit I 36 99 012

Local

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing all wiper blades Flat rate unit I 61 61 047	0 FRU
Set of wiper blades Part I 61 61 2 241 375	1
Wiper blade Part I 61 62 7 356 763	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Endkontrolle am Fahrzeug Flat rate unit I 00 99 099	Local	0 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Description:

Is interpreted as a repeat visit: No

Customer's own words:

(Mandatory) general inspection 0 FRU
Flat rate unit I 00 12 559

Demonstration for state emissions inspection 7 FRU
Flat rate unit I 00 00 127

Gebühr HU Local 1
Part I FT99 99 0 000 1

— Job


Description:

Is interpreted as a repeat visit: No


Customer's own words:

Endkontrolle am Fahrzeug Local 0 FRU
Flat rate unit I 00 99 099


— 07/02/2019 Key 70727 km 33364 Key 1




— 01/21/2019 Key 61643 km 33364 Key 1



— 01/18/2019 Key 61590 km Key 1



— 11/14/2018 Key 58393 km Key 1



— 11/14/2018 Service 58393 km 33364 AHAG Automatic
Dülmen GmbH , Dülmen

								
-1300 07/2019 ✓	-1300 07/2019 ✓	-1300 07/2019 ✓	-1300 07/2019 ✓	38000 07/2019	0 05/2019	22000 07/2019	-1300 07/2019 ✓	0 07/2019

—	11/14/2018	Repair	58393 km	33364 AHAG Münsterland GmbH, Dülmen	Job Job Job Job Job Job Job Job Job Job Job
---	------------	--------	----------	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Endkontrolle am Fahrzeug	Local	0 FRU
Flat rate unit I 00 99 099		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 11/02/2018 Key 57241 km Key 1

								
-170	-170	-170	-170	39000	0	23000	-170	0
07/2019	270	270	270		05/2019		07/2019	07/2019

— 07/25/2017 Key 26205 km 33364 Key 1

								
30000	30000	30000	30000	44000	0	35000	30000	0
07/2019	736	736	736		05/2019		07/2019	07/2019

— 07/24/2017 Repair 26102 km 33364 AHAG Münsterland GmbH, Dülmen Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Stoßfängerecke vorne und hinten lackieren
Part I FT0000154

Local

1

— 07/13/2017 Service 26100 km 38476 AHAG Bochum GmbH, Bochum Manual

									
✓		✓						✓	✓

— 07/06/2017 Key 26099 km 38476 Key 1

								
2700	0	2700	0	44000	0	35000	33000	0
05/2018		377			05/2019		05/2020	06/2019

—	07/06/2017	Repair	26102 km	38476 AHAG Bochum GmbH, Bochum	Job Job Job Job Job
---	------------	--------	----------	---	---------------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

BMW Engine Oil LL04 0W30	5
Part I 83 21 2 405 950	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

TÜV-Rheinland Abnahme nach § 29 STVZO Part I FT0000186	Local	1
Washer fluid, concentrated Part I 83 12 2 298 203		2

—	07/06/2017	Repair	26102 km	38476 AHAG Bochum GmbH , Bochum	Job
---	------------	--------	----------	--	-----

—	Job
---	-----

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Auslieferungsscheck Flat rate unit I 00 99 014	Local	9 FRU
---	-------	-------