

Vehicle

BMW 318d, 110kW

WBA8C310X0K687712



Development code	F30
Color	alpinweiss 3
Actual integration level	F020-24-11-520
Start of warranty	February 1, 2016

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2016-1 (as of: Mar 11, 2025)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	318d
Body	LIM
Vehicle identification number (last 7 characters)	K687712
Vehicle identification number (17 characters)	WBA8C310X0K687712
Development code	F30
Steering	LL
Engine	B47U
Engine number	53549498
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0222252ZQB
Head unit serial number	MM01DFG1022222
Drive	HECK
Integration level	F020-15-11-505
Production date	Jan 12, 2016
Production works	Muenchen
Delivery date	Jan 13, 2016
Delivering Retailers	No information
National-market version	EUR
Paint code	300
Upholstery code	CCL2
Model code	8C41
Base type	8C31
Lead type	8C41

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 Extra package, EU-specific
 0255 Sports leather steering wheel
 0258 Tire with run-flat functionality
 02A6 BMW LA wheel, Double Spoke 392
 02PA Wheel bolt retainer
 02VB Tire pressure display
 03AG Reversing camera

Retrofitted optional equipment:

This vehicle has no retrofits.

03BE Mirror caps, black
 0423 Floor mats, velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0441 Smoker package
 0465 Through-loading system
 0481 Sports seat
 0493 Storage compartment package
 04AE Armrest front, retractable
 04LV Black high-gloss, korall-rot accent
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometer-calibrated speedometer
 0563 Light package
 05A2 LED headlight
 05DA Passenger airbag deactivation
 0606 Navigation system Business
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06NH Hands-free with USB interface
 06UH Traffic Information
 06WA Instrument cluster, expanded equipment
 0760 High gloss shadow line
 0775 Headlining anthracite
 07AC Sport Line
 07LD Modell Sport Line
 0854 Language version French
 0881 On-board vehicle literature French
 08KA Oil service interval, 24 mos./30,000 km
 08S3 Automatic locking when driving off
 A090 90 AH AGM battery
 POLS Cloth cushion

▾ Vehicle histories

Date	Type	Vehicle mileage			Dealer	Overview
— 03/11/2025	Key	214356 km			53158	Key 0
 12000 06/2026	 12000 06/2026	 12000 06/2026	 12000 06/2026	 90000 06/2025	 45000 06/2025	 43000 06/2028
— 02/10/2020	Key	61322 km			04849	Key 1
 19000 05/2021	 19000 441	 19000 441	 5000 01/2021	 6000 05/2023	 50000 05/2023	 50000 05/2023
— 02/10/2020	Service	61322 km			04849 PANEL MELUN , VERT SAINT DENIS	Automatic

							
19000		19000		5000		6000	50000
04/2021		04/2021		✓	12/2020	✓	04/2023

— 01/16/2020 Key 61300 km 04849 Key 0

							
19000		19000		5000		6000	50000
05/2021		465			01/2021		05/2023

— 05/22/2019 Key 50015 km 04849 Key 0

							
240	240	240	240	11000	0	10000	240
11/2019	192	192	192		01/2021		11/2019

— 05/22/2019 Service 50015 km 04849 PANEL MELUN, VERT SAINT DENIS Automatic

							
240	240	240	240	11000	01/2021	10000	240
✓	✓	✓	✓				✓

— 05/22/2019 Repair 50015 km 04849 PANEL MELUN MELUN , VERT SAINT DENIS Job
 Job: Service huile moteur
 Job: Entretien filtre à carburant
 Job: Service contrôle véhicule
 Job: Service cartouche de filtre à air
 Job: Service microfiltre
 Job: Service prestations standard
 Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

ISPA CT-1-0011830400
 Flat rate unit I -

Local

14 FRU

— Job: Service huile moteur

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service huile moteur
 Package I 0000610

Engine oil service

Flat rate unit I 00 00 610

!!! unknown BMW-Id 0030 HUILE MOTEUR YACCO 00W30 LUBE Local 5
DE BMW LL04 (1L) !!!
Part I 0030

Set oil-filter element 1
Part I 11 42 8 575 211

— Job: Entretien filtre à carburant

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Entretien filtre à carburant
Package I 0000604

Fuel filter service 3
Flat rate unit I 00 00 604

Fuel filter cartridge 1
Part I 13 32 8 572 522

— Job: Service contrôle véhicule

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service contrôle véhicule
Package I 0000624

Vehicle check service 6
Flat rate unit I 00 00 624

— Job: Service cartouche de filtre à air

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service cartouche de filtre à air
Package I 0000602

Service - air filter insert 2
Flat rate unit I 00 00 602

Air filter element 1
Part I 13 71 8 511 668

— Job: Service microfiltre

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service microfiltre
Package I 0000616

Service - microfilter 2

Flat rate unit I 00 00 616

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job: Service prestations standard

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service prestations standard
Package I 0000105

Standard scope of service
Flat rate unit I 00 00 105

2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Location vehicule de courtoisie
Flat rate unit I -

Local

1 FRU

— 01/15/2019 Key 41734 km Key 0

							
10000	10000	10000	10000	17000	0	17000	10000
11/2019	319	319	319		01/2019		11/2019

— 01/15/2019 Service 41734 km 04849 PANEL MELUN, VERT SAINT DENIS Automatic

							
10000	10000	10000	10000	17000	01/2019	17000	10000
					✓		

— 01/15/2019 Repair 41734 km 04849 PANEL MELUN MELUN , VERT SAINT DENIS
Job: Service liquide de frein
Job: Service prestations standard
Job

— Job: Service liquide de frein

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service liquide de frein
Package I 0000618

Brake fluid service
Flat rate unit I 00 00 618

4

— Job: Service prestations standard

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service prestations standard
Package I 0000105

Standard scope of service
Flat rate unit I 00 00 105

2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

ISPA CT-1-0011100500
Flat rate unit I -

Local

1 FRU

— 01/08/2019 Key 41269 km Key 0

							
11000	11000	11000	11000	17000	0	17000	11000
11/2019	326	326	326		01/2019		11/2019

— 07/03/2018 Key 32105 km 04849 Key 0

							
18000	18000	18000	18000	19000	0	19000	18000
11/2019	515	515	515		01/2019		11/2019

— 07/03/2018 Repair 32105 km 04849 PANEL Job
MELUN
MELUN , VERT
SAINT DENIS

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

ISPA CT-1-0011450400
Flat rate unit I -

Local

20 FRU

— 06/19/2018 Key 31881 km 04849 Key 0

								
18000	18000	18000	18000	19000	0	19000	18000	18000
11/2019	528	528	528		01/2019			11/2019

— 11/13/2017 Key 24464 km 04849 Key 0

								
420	0	420	0	27000	0	27000	28000	28000
01/2018		79			01/2019		01/2020	

— 11/13/2017 Service 24464 km 04849 PANEL MELUN, VERT SAINT DENIS Automatic

								
420		420		27000	01/2019	27000	28000	
✓		✓						

— 11/13/2017 Repair 24464 km 04849 PANEL MELUN MELUN , VERT SAINT DENIS
 Job: Service prestations standard
 Job: Service huile moteur
 Job: Service microfiltre

— Job: Service prestations standard

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service prestations standard
 Package I 0000105

Standard scope of service 2
 Flat rate unit I 00 00 105

— Job: Service huile moteur

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service huile moteur
 Package I 0000610

Engine oil service 10
 Flat rate unit I 00 00 610

!!! unknown BMW-Id 0030 HUILE MOTEUR YACCO 00W30 LUBE Local 5
 DE HOMOLOGUE BMW LL04 (L) !!!
 Part I 0030

Set oil-filter element 1
 Part I 11 42 8 575 211

— Job: Service microfiltre

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service microfiltre

Package I 0000616

Service - microfilter 3

Flat rate unit I 00 00 616


Microfilter/activated Carbon container 1

Part I 64 11 9 237 555

Vehicle interior filt..f.housing cleaner 1

Part I 83 19 2 451 455

— 10/11/2017 Key 23256 km 04849 Key 0



— 10/12/2016 Repair 10443 km 04849 PANEL MELUN
Job
Job
MELUN , VERT SAINT DENIS

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Travaux selon diagnostic Local 18 FRU

Flat rate unit I -

— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:

Anomalie equipement interieur carrosserie Local 5 FRU

Flat rate unit I -

— 10/11/2016 Key 10443 km 04849 Key 0



— 09/28/2016 Key 9866 km 04849 Key 0



18000

01/2018



0



18000

489



0



47000



0

01/2019



48000



47000

01/2020

—

02/04/2016

Key

2 km

04849

Key 0



0

-4
0.5 %