

Vehicle

BMW 320i xDrive, 135kW

WBA8G51070K390400



Development codeF31

Colorblack-sapphire metallic

Actual integration levelF020-15-11-504

Start of warrantyJanuary 20, 2016

 There are active service contracts present.

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

Description	Issuer	Billing as of	Duration	Vehicle mileage
UC Service Inclusive for Used Cars - 3 years / 40,000 km	AG	Nov 1, 2024	to Oct 31, 2027	to 188527 km

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map cannot be identified. One of the following maps could be installed in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2015-3+ (as of: Apr 23, 2026)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2026-1	-
Road Map EUROPE EVO 2015-3+ (as of: Apr 23, 2026)	-	-	-

▾ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320i xDrive
Body	TOUR
Vehicle identification number (last 7 characters)	K390400
Vehicle identification number (17 characters)	WBA8G51070K390400
Development code	F31
Steering	LL
Engine	B48M
Engine number	21589443
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0022799ZLN
Head unit serial number	HB2140F7690614
Drive	ALLR
Integration level	F020-15-11-504
Production date	Nov 24, 2015
Production works	Muenchen
Delivery date	Jan 7, 2016
Delivering Retailers	No information
National-market version	EUR
Paint code	475
Upholstery code	CCL2
Model code	8G61
Base type	8G51
Lead type	8G61

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 0216 Hydro steering-servotronic
 0230 EU-specific additional contents
 0258 Tire with run-flat functionality
 02TB Sport automatic transmission
 02VB Tire pressure display
 02XE Sport leather steering wheel
 0302 Alarm system
 0322 Comfort access

Retrofitted optional equipment:

This vehicle has no retrofits.

03AA Roof railing black
 03AC Trailer coupling
 0402 Electric panoramic roof
 0423 Floor mats, velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0441 Smoker package
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04LU Black, highgloss Perlglanz chrome accent
 04NE Blow-by heater
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometer-calibrated speedometer
 0563 Lights package
 0575 Supplementary 12V sockets
 05A1 LED Fog lights
 05A2 LED headlight
 05AC High-beam assistant
 05AL Active Protection
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 0609 Navigation system Professional
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NS Convenience phone, expanded Smartphone
 06WA Instrument cluster, expanded equipment
 07AC Sport Line
 07LD Modell Sport Line
 07XP Navigation package, Connected Drive
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 08TH Road sign detection
 0931 Winter instead of summer tires ex-fact.
 09BD Business Package
 A090 90 AH AGM battery
 POLS Cloth cushion

▾ Vehicle histories

Date	Type	Vehicle mileage		Dealer	Overview			
— 04/13/2026	Key	168521 km		52605	Key 0			
 14000 11/2026	 14000 11/2026	 14000 11/2026	 14000 11/2026	 80000 11/2026	 80000 11/2026	 80000 11/2026	 14000 11/2026	 14000 11/2026

—	11/08/2025	Key	161533 km	52605	Key 0
---	------------	-----	-----------	-------	-------

								
20000	20000	20000	20000	80000	80000	80000	20000	
11/2026	11/2026	11/2026	11/2026		11/2026		11/2026	11/2026

—	11/08/2025	Repair	161533 km	52605 ,	Job Job
---	------------	--------	-----------	---------	------------

— Job

Description: Räderpaket 2 - Premium

Is interpreted as a repeat visit: No

Customer's own words:

unknown fru: Räder wechseln, reinigen, einlagern
Flat rate unit I 01 36 052

Local 12 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

unknown fru: Sicherheitscheck
Flat rate unit I 01 00 002

Local 12 FRU

—	06/20/2025	Key	157685 km	52605	Key 0
---	------------	-----	-----------	-------	-------

								
24000	24000	24000	24000	70000	70000	70000	24000	
11/2026	11/2026	11/2026	11/2026		11/2026		11/2026	11/2026

—	06/20/2025	Repair	157685 km	52605 ,	Job Job Job
---	------------	--------	-----------	---------	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Check the cooling system for watertightness with the special tool
Flat rate unit I 17 00 009

4 FRU

— Job

Description: Marderschaden!

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Draining and topping up coolant for high-temperature circuit Flat rate unit I 17 00 508		8 FRU
Replacing coolant hose, coolant radiator heat management module Flat rate unit I 17 12 551		1 FRU
Bleed the cooling system and check it for watertightness with the special tool Flat rate unit I 17 00 540		6 FRU
01 Schlauch Kühler oben-Thermostat Part I 17 12 8 616 524	Local	1
Kühlerfrostschutz 1000ML, TU Part I 83 19 2 218 348	Local	2

—	05/22/2025	Key	156859 km	52605	Key 0		
							
25000	25000	25000	25000	70000		70000	25000
11/2026	11/2026	11/2026	11/2026		11/2026		11/2026
—	05/22/2025	Repair	156859 km	52605 ,	Job		
—	Job						

Description: Kühlmittelverlust prüfen Marderschaden

Is interpreted as a repeat visit: No

Customer's own words:

Vent the cooling system and check for watertightness with the special tool Flat rate unit I 17 00 039		8 FRU
Draining and topping up coolant for high-temperature circuit Flat rate unit I 17 00 508		8 FRU
Replacing the coolant hose, coolant radiator connecting bracket, engine block Flat rate unit I 17 12 548		8 FRU
Schlauch Kühler oben-Thermostat Part I 17 12 8 616 524	Local	1
Kühlerfrostschutz 1000ML, TU Part I 83 19 2 218 348	Local	4

—	05/05/2025 Key				156486 km		52605		Key 0	
										
25000	25000	25000	25000		70000		70000	25000		
11/2026	11/2026	11/2026	11/2026			11/2026		11/2026		11/2026

— 05/05/2025 Key 156478 km 52605 Key 0

								
25000	25000	25000	25000	340	11/2026	4000	25000	11/2026
11/2026	11/2026	11/2026	11/2026				11/2026	

— 05/05/2025 Service 156478 km 52605 Automatic
Langenhan GmbH , Jena

								
25000	25000	25000	25000	340	11/2026	4000	25000	11/2026
11/2026	11/2026	11/2026	11/2026	✓		✓	11/2026	

— 05/05/2025 Repair 156478 km 52605 , Job
Job
Job
Job
Job
Job

— Job

Description: Standardumfang

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description: Bremse vorn

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes 6 FRU
Flat rate unit I 00 00 612

BREMSENREINIGER, ACETONFREI Local 1
Part I 83 19 2 413 695

BREMSBELAGFÜHLER VORNE LINKS Local 1
Part I 34 35 6 792 289

Reparatursatz Bremsbeläge Local 1
Part I 34 11 8 855 002

BREMSKLOTZPASTE Local 2
Part I 83 19 2 158 851

— Job

Description: Beide Brems Scheiben vorn aus- und einbauen/ersetzen

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs 3 FRU
Flat rate unit I 34 11 613

INNENSECHSKANTSCHRAUBE Local 2
Part I 34 21 1 161 806

BREMSSCHEIBE BELÜFTET Local 2
Part I 34 11 6 792 217

TORX-SCHRAUBE MIT SCHEIBE Local 4
Part I 34 10 6 864 424

— Job

Description: Räder wechseln, reinigen, einlagern

Is interpreted as a repeat visit: No

Customer's own words:

Räder einlagern Local 12 FRU
Flat rate unit I RÄDEREI

— Job

Description: Bremse hinten

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service 7 FRU
Flat rate unit I 00 00 614

BREMSENREINIGER, ACETONFREI Local 1
Part I 83 19 2 413 695

BREMSBELAGFÜHLER HINTEN Local 1
Part I 34 35 6 792 292

REPARATURSATZ BREMSBELÄGE Local 1
Part I 34 21 8 855 013

BREMSKLOTZPASTE Local 2
Part I 83 19 2 158 851

— Job

Description: Beide Bremsscheiben hinten aus- und einbauen/ersetzen

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/renewing both brake discs 4 FRU
Flat rate unit I 34 21 932

INNENSECHSKANTSCHRAUBE Local 2
Part I 34 21 1 161 806

BREMSSCHEIBE BELÜFTET Local 2
Part I 34 21 6 864 900

SECHSKANTSCHRAUBE MIT BUND Local 4
Part I 34 20 6 850 536

26000	26000	26000	26000
11/2026	11/2026	11/2026	11/2026

1000		4500	26000		
	11/2026		11/2026		11/2026

— 11/01/2024 Key 148527 km 52605 Key 0

8000			8000
11/2024			11/2024

17000		22000	41000		
	11/2024		11/2026		11/2024

— 11/01/2024 Service 148527 km 52605 Automatic
Langenhan GmbH, Jena

8000			8000
11/2024			11/2024
✓			✓

17000		22000	41000		
	11/2024		11/2026		11/2024
	✓				

— 11/01/2024 Repair 148527 km 52605 , Job
Job
Job
Job

— Job

Description: Standardumfang

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description: Motoröl

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
Flat rate unit I 00 00 610

BMW TwinPower Turbo LL-19FE 0W-30 1000ML, TU Local 5.25
Part I 83215A65BF8

SATZ ÖLFILTEREINSATZ Local 1
Part I 11 42 8 575 211

Sondervereinbarung Local 1
Part I FL000008

Scheibenklar mit Frostschutz 1L, TU Local 1.36
Part I 83 12 2 413 058

— Job

Description: Mikrofilter (ggf. weiter Zusatzarbeit(en) beachten)

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter		2 FRU
Flat rate unit I 00 00 616		

MIKROFILTER/AKTIVKOHLEFILTER	Local	1
Part I 64 11 9 237 555		

— Job

Description: Bremsflüssigkeit

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service		4 FRU
Flat rate unit I 00 00 618		

BREMSFLÜSSIGKEIT DOT4 LV, NIEDERVISKOS 1000ml, TU	Local	1
Part I 83 13 2 184 843		

—	11/01/2024	Repair	148527 km	52605 ,	Job Job Job
---	------------	--------	-----------	---------	-------------------

— Job

Description: Wischerblatt links und rechts ersetzen

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade		1 FRU
Flat rate unit I 61 61 541		

SATZ WISCHERBLÄTTER	Local	1
Part I 61615A43585		

— Job

Description: Räder wechseln, reinigen, einlagern

Is interpreted as a repeat visit: No

Customer's own words:

unknown fru: Räder wechseln, reinigen, einlagern	Local	12 FRU
Flat rate unit I RÄDERUE		

— Job

Description: HU/AU GTÜ

Is interpreted as a repeat visit: No

Customer's own words:

Abgasuntersuchung mit OBD und Sonde Flat rate unit I AU-OBDD-	Local	12 FRU
unknown part: Hauptuntersuchung nach §29 StVZO extern Part I HU-GTÜ	Local	1

10/01/2024	Key	148282 km	52605	Remote KeyRead
 8000 11/2024    8000 11/2024  18000  11/2024  22000  41000 11/2026  11/2024				
04/25/2024	Key	142421 km	52605	Key 0
 14000 11/2024    14000 11/2024  22000  11/2024  26000  47000 11/2026  11/2024				
04/25/2024	Repair	142421 km	52605 ,	Job
Job				
Description:				
Is interpreted as a repeat visit: No				
Customer's own words:				
unknown fru: Räder wechseln, reinigen, einlagern Flat rate unit I RÄDERUE		Local	12 FRU	
01/11/2024	Repair	136680 km	52605 Langenhan Jena GmbH , Jena	Job
Job				
Description:				
Is interpreted as a repeat visit: No				
Customer's own words:				
Unfallersatzfahrzeug J-AF 281 28.08.2023 - 31.08.2023 Part I FL000001		Local	1	
11/30/2023	Key	136678 km	52605	Key 1
 19000 11/2024    19000 11/2024  29000  11/2024  34000  60000 11/2026  11/2024				

—	11/30/2023	Repair	136678 km	52605	Job
				Langenhan	Job
				Jena GmbH ,	Job
				Jena	

— Job

Description: Räder wechseln, reinigen, einlagern

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description: Vier Reifen mit Runflat-Technologie ersetzen (Räder abgebaut)

Is interpreted as a repeat visit: No

Customer's own words:

Replacing four tires with run-flat technology 17 FRU
Flat rate unit I 36 12 577

Goodyear Ultra Grip Performance G1 ROF 205/60R16 96H * RSC Local 4
Part I 85 45 2 729 124

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id RÄDERUE Räder wechseln, reinigen, einlagern !!! Local 12 FRU
Flat rate unit I RÄDERUE

—	11/17/2023	Key	135822 km	52605	Remote KeyRead
---	------------	-----	-----------	-------	----------------

								
20000			20000	29000		34000	60000	
11/2024			11/2024	11/2024		11/2026		11/2024



—	08/28/2023	Key	134295 km	52605	Key 0
---	------------	-----	-----------	-------	-------

								
22000			22000	33000		38000	60000	
11/2024			11/2024	11/2024		11/2026		11/2024

—	06/22/2023	Key	129466 km		Key 0
---	------------	-----	-----------	--	-------

								
26000			26000	32000		37000	60000	
11/2024			11/2024	11/2024		11/2026		11/2024

—	05/26/2023	Key	129160 km		Key 0
---	------------	-----	-----------	--	-------



—	05/26/2023	Repair	129160 km	04111 Autohaus Fiebig GmbH , Jena	Job
---	------------	--------	-----------	--	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:


Vorder- und Hinterräder ab- und anbauen
Flat rate unit I 36 10 361

Local 4 FRU


Einlagerungsgebühr
Part I FT0000153

Local 1

—	11/03/2022	Key	122640 km	04111	Key 1
---	------------	-----	-----------	-------	-------



—	11/03/2022	Service	122640 km	04111 Autohaus Fiebig GmbH , Jena	Automatic
---	------------	---------	-----------	--	-----------



—	11/03/2022	Repair	122640 km	04111 Autohaus Fiebig GmbH , Jena	Job Job Job
---	------------	--------	-----------	--	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Presentation for emission inspection
Flat rate unit I 00 00 527

5 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorder- und Hinterräder ab- und anbauen Flat rate unit I 36 10 361	Local	4 FRU
Einlagerungsgebühr Part I FT0000153	Local	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hauptuntersuchung GTÜ Flat rate unit I 99 99 999	Local	1 FRU
Service Inclusive Paket 3 Jahre/40000 km 00000000 Flat rate unit I 99 99 999	Local	1 FRU

—	11/03/2022	Repair	122640 km	04111 Autohaus Fiebig GmbH, Jena	Job Job Job Job Job Job Job Job
---	------------	--------	-----------	---	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5.25

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602	1 FRU
Air filter element Part I 13 71 8 605 164	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Spark plugs service Flat rate unit I 00 00 622	11 FRU
Spark plug, High Power Part I 12 12 0 040 551	4
Torx screw with collar Part I 07 14 7 270 121	2
Hex bolt with washer Part I 31 10 6 854 219	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 842	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Windshield Washer Antifreeze
Part I 83 12 2 413 058

2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ölpauschale 00000000 87000200007
Flat rate unit I 99 99 999

Local

1 FRU

— 10/12/2022 Key 121153 km 04111 Remote KeyRead

								
4500	4500	4500	4500	43000		49000	4500	
11/2022	11/2022	11/2022	11/2022		11/2022		11/2022	-41 5.6 %

— 06/14/2022 Key 118312 km 04111 Key 0

								
7000	7000	7000	7000	44000		49000	7000	
11/2022	137	137	137		11/2022		11/2022	09/2022

— 06/02/2022 Key 118289 km 04111 Key 0

								
8000	8000	8000	8000	44000		49000	8000	
11/2022	149	149	149		11/2022		11/2022	09/2022

— 06/02/2022 Key 118289 km 04111 Key 0

								
8000	8000	8000	8000	44000		49000	8000	
11/2022	150	150	150		11/2022		11/2022	09/2022

— 06/02/2022 Repair 118312 km 04111 Job
Autohaus
Fiebig GmbH ,
Jena

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Check the cooling system for watertightness with the special tool Flat rate unit I 17 00 009	4 FRU
Removing and installing/replacing cylinder head-expansion tank coolant line Flat rate unit I 17 12 512	15 FRU
Replacing coolant hose for expansion tank heat management module Flat rate unit I 17 12 550	1 FRU
Bleed the cooling system and check it for watertightness with the special tool Flat rate unit I 17 00 539	6 FRU
Hose, cylinder head-expansion tank Part I 17 12 9 845 173	1
Seal for intake system Part I 11 61 8 637 800	4
Hex bolt with washer Part I 31 10 6 854 219	2
Torx screw with collar Part I 07 14 7 270 121	2
Hose f engine inlet-changeover valve Part I 17 12 8 616 914	1
Anti-freeze Part I 83 19 2 218 348	7

—	04/04/2022	Key	114734 km	04111	Key 0			
								
11000	11000	11000	11000	44000		49000	11000	
11/2022	207	207	207	11/2022			11/2022	09/2022
—	04/04/2022	Repair	114734 km	04111 Autohaus Fiebig GmbH , Jena	Job			
—	Job	Description: Is interpreted as a repeat visit: No Customer's own words:						
Vorder- und Hinterräder ab- und anbauen Flat rate unit I 36 10 361				Local	4 FRU			
Einlagerungsgebühr Part I FT0000153				Local	1			
—	10/18/2021	Key	106800 km		Key 0			



15000
11/2022



15000
373



15000
373



15000
373



60000
11/2022



60000
11/2022



60000
11/2022



15000
11/2022



15000
09/2022

—	10/18/2021	Repair	106800 km	04111 Autohaus Fiebig GmbH , Jena	Job Job
---	------------	--------	-----------	--	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace bumper cover, front Flat rate unit I 51 11 157	13 FRU
---	--------

Additional work with Park Distance Control Flat rate unit I 66 20 614	5 FRU
--	-------

Work time without specification/lights Flat rate unit I 63 99 000	2 FRU
--	-------

Performing vehicle test Flat rate unit I 00 00 556	2 FRU
---	-------

Set of mounts, front PDC / PMA sensor Part I 51 11 7 445 076	1
---	---

Trim cover, bumper, primed, front Part I 51 11 7 445 135	1
---	---

Adhesive set K6 Part I 83 19 2 317 925	1
---	---

Headlight, LED technology, left Part I 63 11 7 419 633	1
---	---

Badge Part I 51 76 7 288 752	1
---------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Lackierungskosten 00000000 Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

—	10/18/2021	Repair	106800 km	04111 Autohaus Fiebig GmbH , Jena	Job Job
---	------------	--------	-----------	--	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorder- und Hinterräder ab- und anbauen Flat rate unit I 36 10 361	Local	4 FRU
Einlagerungsgebühr Part I FT0000153	Local	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Mietwagenrechnung 00000000 Flat rate unit I 99 99 999	Local	1 FRU
Reduzierung SB Mietwagen auf 0,00 Euro 00000000 Flat rate unit I 99 99 999	Local	1 FRU

— 09/15/2021 Key 105361 km Key 0

								
16000	16000	16000	16000	60000	11/2022	60000	16000	09/2022
11/2022	406	406	406				11/2022	

— 05/21/2021 Key 98115 km Key 0

								
24000	24000	24000	24000	60000	11/2022	70000	24000	09/2022
11/2022	520	520	520				11/2022	

— 05/21/2021 Key 98114 km Key 0

								
24000	24000	24000	24000	60000	11/2022	70000	24000	09/2022
11/2022	520	520	520				11/2022	

— 04/29/2021 Repair 98115 km 04111 Autohaus Fiebig GmbH, Jena Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/wheels Flat rate unit I 36 99 000	13 FRU
--	--------

Goodyear EfficientGrip ROF

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorder- und Hinterräder ab- und anbauen Flat rate unit I 36 10 361	Local	4 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

BMW Reifengarantie 36 Monate inklusive 00000000 Flat rate unit I 99 99 999	Local	0 FRU
Einlagerungsgebühr 00000000 Flat rate unit I 99 99 999	Local	1 FRU

—	04/29/2021	Repair	98115 km	04111 Autohaus Fiebig GmbH , Jena	Job
---	------------	--------	----------	--	-----

— Job


Description:

Is interpreted as a repeat visit: No


Customer's own words:

Work time without specification/wheels Flat rate unit I 36 99 000	6 FRU
--	-------

—	11/25/2020	Key	92588 km	Key 1
---	------------	-----	----------	-------



—	11/25/2020	Service	92588 km	04111 Autohaus Fiebig GmbH, Jena	Automatic
---	------------	---------	----------	---	-----------



—	11/25/2020	Repair	92588 km	04111 Autohaus	Job Job Job
---	------------	--------	----------	-------------------	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

BMW Engine Oil LL04 0W30	5.3
Part I 83 21 2 405 950	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Vehicle interior filt..f.housing cleaner	1
Part I 83 19 2 451 455	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 2 184 842	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorder- und Hinterräder ab- und anbauen Flat rate unit I 36 10 361	Local	4 FRU
Einlagerungsgebühr Part I FT0000153	Local	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Windshield Washer Antifreeze Part I 83 12 2 413 058	1
--	---

— 09/18/2020 Key 88936 km 04111 Key 1

 3400 03/2021	 0	 0	 3400 194	 70000	 0 11/2020	 80000	 27000 03/2023	 0 09/2020
--	--	--	--	--	---	--	--	---

— 09/18/2020 Service 88936 km 04111 Automatic
Autohaus
Fiebig GmbH,
Jena

 3400 03/2021	 0	 0	 3400 03/2021	 70000	 0 11/2020	 80000	 27000 03/2023	 0 09/2020 ✓
--	--	--	--	--	---	--	--	--

— 09/18/2020 Repair 88936 km 04111 Job
Autohaus
Fiebig GmbH,
Jena Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
Presentation for emission inspection Flat rate unit I 00 00 527	5 FRU
Hauptuntersuchung Part I FT09999700000	Local 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Resume vehicle test and clear fault memory
Flat rate unit I 61 00 980

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No









Customer's own words:

— 05/11/2020 Key

80990 km

04111

Key 0



— 05/11/2020 Repair

80990 km

04111
Autohaus
Fiebig GmbH,
Jena

Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorder- und Hinterräder ab- und anbauen
Flat rate unit I 36 10 361

Local

4 FRU

Einlagerungsgebühr
Part I FT0000153

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Windshield Washer Antifreeze
Part I 83 12 2 413 058

2

— 11/01/2019 Key

73924 km

04111

Key 0

			
16000	0	0	16000
03/2021			516

			
4800	0	7000	41000
	11/2020		03/2023


0
09/2020

—	11/01/2019	Service	73924 km	04111 Autohaus Fiebig GmbH , Jena	Automatic
---	------------	---------	----------	--	-----------

			
16000	0	0	16000
03/2021			03/2021

			
4800	0	7000	41000
✓	11/2020	✓	03/2023


0
09/2020

—	11/01/2019	Repair	73924 km	04111 Autohaus Fiebig GmbH , Jena	Job Job Job Job
---	------------	--------	----------	--	--------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Rear brakes service Flat rate unit I 00 00 614	7 FRU
---	-------

Removing and installing/renewing both brake discs Flat rate unit I 34 21 932	4 FRU
---	-------

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
--	---

Brake pad wear sensor, rear Part I 34 35 6 792 292	1
---	---

Brake pad paste Part I 83 23 0 140 233	2
---	---

Brake cleaner, acetone-free Part I 83 19 2 413 695	1
---	---

Hex screw with collar Part I 34 20 6 850 536	4
---	---

Inner hex bolt Part I 34 21 1 161 806	2
--	---

Brake disc, ventilated Part I 34 21 6 864 900	2
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612	6 FRU
Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
Repair kit, brake pads asbestos-free Part I 34 11 6 874 331	1
Brake pad wear sensor, front left Part I 34 35 6 792 289	1
Brake pad paste Part I 83 23 0 140 233	2
Brake cleaner, acetone-free Part I 83 19 2 413 695	1
Torx screw with washer Part I 34 10 6 864 424	4
Brake disc, ventilated Part I 34 11 6 792 217	2
Inner hex bolt Part I 34 21 1 161 806	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	10/22/2019	Key	73699 km	04111	Key 0		
							
16000	0	0	5000	0	7000	41000	0
03/2021		526		11/2020		03/2023	09/2020
—	10/22/2019	Repair	73699 km	04111	Job	Job	Job
				Autohaus	Job	Job	Job
				Fiebig GmbH ,			
				Jena			

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test	4 FRU
Flat rate unit I 00 00 006	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorder- und Hinterräder ab- und anbauen	Local	4 FRU
Flat rate unit I 36 10 361		
Einlagerungsgebühr	Local	1
Part I FT0000153		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenloser Lichttest	Local	0 FRU
Flat rate unit I -		


— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:

—	03/21/2019	Key	62099 km	04111	Key 0
---	------------	-----	----------	-------	-------



—	03/21/2019	Service	62099 km	04111 Autohaus Fiebig GmbH, Jena	Automatic
---	------------	---------	----------	---	-----------



—	03/21/2019	Repair	62104 km	04111 Autohaus	Job Job Job
---	------------	--------	----------	-------------------	-------------------

Fiebig GmbH ,
Jena
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5.25
--	------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

Vehicle interior filt..f.housing cleaner Part I 83 19 2 451 455	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602	1 FRU
---	-------

Air filter element Part I 13 71 8 605 164	1
--	---

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Spark plugs service Flat rate unit I 00 00 622	11 FRU
---	--------

Torx screw with collar Part I 07 14 7 270 121	4
--	---

Spark plug, High Power Part I 12 12 0 040 551	4
--	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Vorder- und Hinterräder ab- und anbauen Flat rate unit I 36 10 361	Local	4 FRU
---	-------	-------

Einlagerungsgebühr Part I FT0000153	Local	1
--	-------	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Performing vehicle test Flat rate unit I 00 00 556	2 FRU
---	-------

Initializing rain/light sensor Flat rate unit I 61 35 679	1 FRU
--	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Replace left and right wiper blade Flat rate unit I 61 61 541	1 FRU
--	-------

Set of wiper blades Part I 61 61 2 241 375	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash

Flat rate unit I 00 11 319

0 FRU

— Job

Description:










Is interpreted as a repeat visit: No

Customer's own words:

— 11/13/2018 Key

55414 km

Key 0











— 11/13/2018 Service

55414 km

04111
Autohaus
Fiebig GmbH,
Jena

Automatic



— 11/13/2018 Repair

55426 km

04111
Autohaus
Fiebig GmbH,
Jena

Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Windshield Washer Antifreeze

Part I 83 12 2 413 058

2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Check the cooling system for watertightness with the special tool

Flat rate unit I 17 00 509

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorder- und Hinterräder ab- und anbauen Flat rate unit I 36 10 361	Local	4 FRU
Einlagerungsgebühr Part I FT0000153	Local	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	11/13/2018	Repair	55426 km	04111 Autohaus Fiebig GmbH, Jena	Job Job
---	------------	--------	----------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 842	1

—	09/18/2018	Key	53969 km	Key 1
---	------------	-----	----------	-------



6000
06/2019



6000
285



6000
285



6000
285



21000
11/2018



0
11/2018



22000
06/2019



6000
06/2019



0
09/2020

—	09/11/2018	Key	53466 km	Key 0
---	------------	-----	----------	-------

								
6000	6000	6000	6000	21000	0	23000	6000	0
06/2019	292	292	292		11/2018		06/2019	09/2018

—	09/11/2018	Service	53466 km	04111 Autohaus Fiebig GmbH, Jena	Automatic
---	------------	---------	----------	---	-----------

								
6000	6000	6000	6000	21000	0	23000	6000	0
06/2019	06/2019	06/2019	06/2019		11/2018		06/2019	09/2018
								✓

—	09/11/2018	Repair	53466 km	04111 Autohaus Fiebig GmbH , Jena	Job Job Job
---	------------	--------	----------	--	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	09/11/2018	Repair	53466 km	04111 Autohaus Fiebig GmbH , Jena	Job
---	------------	--------	----------	--	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/wheels
Flat rate unit I 36 99 000

11 FRU

Continental SportContact 5 SSR

2

—	09/11/2018	Repair	53466 km	04111 Autohaus Fiebig GmbH , Jena	Job Job
---	------------	--------	----------	--	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Presentation for emission inspection Flat rate unit I 00 00 527	5 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hauptuntersuchung 87990100007 Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

—	09/10/2018	Repair	55414 km	04111 Autohaus Fiebig GmbH , Jena	Job
---	------------	--------	----------	--	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/wheels Flat rate unit I 36 99 000	13 FRU
--	--------

Goodyear Ultra Grip 8 Performance ROF Part I 85 45 2 593 576	4
---	---

—	09/10/2018	Repair	55414 km	04111 Autohaus Fiebig GmbH , Jena	Job
---	------------	--------	----------	--	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/wheels
Flat rate unit I 36 99 000

6 FRU

— 04/27/2018 Key 44495 km 04111 Key 0

								
13000	13000	13000	13000	27000	0	28000	13000	0
06/2019	429	429	429		11/2018		06/2019	09/2018

— 04/27/2018 Repair 44495 km 04111 Autohaus Fiebig GmbH, Jena Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorder- und Hinterräder ab- und anbauen
Flat rate unit I 36 10 361

Local

4 FRU

Einlagerungsgebühr
Part I FT0000153

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 02/05/2018 Repair 40842 km 26842 BMW Mobiler Service Einsatzleitzentrale, München Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 11/24/2017 Key 36705 km 04111 Key 1

								
21000	21000	21000	21000	35000	0	38000	21000	0
06/2019	582	582	582		11/2018		06/2019	09/2018

—	11/24/2017	Repair	36705 km	04111 Autohaus Fiebig GmbH, Jena	Job
---	------------	--------	----------	---	-----

— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:

Vorder- und Hinterräder ab- und anbauen Flat rate unit I 36 10 361	Local	4 FRU
---	-------	-------

Einlagerungsgebühr Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

—	06/16/2017	Key	30236 km	04111	Key 0
---	------------	-----	----------	-------	-------



—	06/16/2017	Service	30236 km	04111 Autohaus Fiebig GmbH, Jena	Manual
---	------------	---------	----------	---	--------



—	06/16/2017	Repair	30241 km	04111 Autohaus Fiebig GmbH, Jena	Job Job
---	------------	--------	----------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5.25
Pollen filter housing cleaner Part I 83 19 2 180 509	1

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

Fremdleistung 87000200007 Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

—	06/16/2017	Repair	30241 km	04111 Autohaus Fiebig GmbH , Jena	Job
---	------------	--------	----------	--	-----

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

Vorder- und Hinterräder ab- und anbauen (neue SKR) Flat rate unit I 36 10 361	Local	4 FRU
--	-------	-------

09/21/2016				Key		17089 km		04569		Key 1	
											
12000	0	0	12000	50000	0	60000	39000	0			
11/2017			434		11/2018		11/2019	12/2018			

—	09/21/2016	Repair	17089 km	04569 Niederlassung Chemnitz BMW AG, Chemnitz	Job Job Job Job
---	------------	--------	----------	---	--------------------------

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

BMW-Übergabedurchsicht "Premiumselektion" Flat rate unit I NL00 00 8	Local	18 FRU
---	-------	--------

Glass cleaner without antifreeze Part I 83 12 2 361 702	1
--	---

BMW Motorsport umbrella Part I 80 23 2 285 873	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Überprüfung nach § 29 STVZO
Part I 0012159

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

§ emission test with on-board diagnosis
Flat rate unit I 00 00 528

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: