

Vehicle

BMW 320d, 140kW

WBA8Y71020G715420



Development code	F34
Color	black-sapphire metallic
Actual integration level	F020-22-03-552
Start of warranty	June 29, 2016

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2016-1 (as of: Jul 25, 2024)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	320d
Body	SAT
Vehicle identification number (last 7 characters)	G715420
Vehicle identification number (17 characters)	WBA8Y71020G715420
Development code	F34
Steering	LL
Engine	B47O
Engine number	64569632
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0419818ZRI
Head unit serial number	MM01DFG1618214
Drive	HECK
Integration level	F020-16-03-504
Production date	May 25, 2016
Production works	Dingolfing
Delivery date	May 30, 2016
Delivering Retailers	No information
National-market version	EUR
Paint code	475
Upholstery code	LCSW
Model code	8Y81
Base type	8Y71
Lead type	8Y81

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 EU-specific additional contents
 0255 Sports leather steering wheel
 0258 Tire with run-flat functionality
 02DX BMW LA wheel, Star Spoke 394
 02VB Tire pressure display
 0302 Alarm system
 0320 Deleted, model lettering

Retrofitted optional equipment:

This vehicle has no retrofits.

0321 Exterior parts in vehicle color
0322 Comfort access
03AC Trailer coupling
03AG Reversing camera
0402 Electric panoramic roof
0420 Sun protection glazing
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
0496 Seat heating, rear
04AE Armrest front, retractable
04CG Interior strips, "satin-silber" matt
0502 Headlight cleaning system
0508 Park Distance Control (PDC)
0520 Fog lights
0521 Rain sensor
0522 Xenon Light
0524 Adaptive Headlights
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometer-calibrated speedometer
0563 Light package
0575 Supplementary 12V sockets
05AC High-beam assistant
05AL Active Protection
05DA Passenger airbag deactivation
0606 Navigation system Business
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NS Convenience phone, expanded Smartphone
06WA Instrument cluster, expanded equipment
07LC Modell Advantage
07S9 Connected Drive Services Paket
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08TF Active pedestrian protection
08TH Road sign detection
0941 Dummy-SALAPA
09AA Outer skin protection
A090 90 AH AGM battery
LEDE Leather trim

Vehicle histories

Date		Type	Vehicle mileage		Dealer	Overview			
—	07/25/2024	Key	180049 km		01911	Key 0			
									
6000	6000	6000	6000	7000	-24 3.3 %	-24 3.3 %	80000	6000	
04/2025	04/2025	04/2025	04/2025					04/2025	10/2024

—	07/26/2022	Key	127343 km	01911	Key 1			
	 21000 02/2024		 21000 545		 50000 07/2024	 695	 36000 02/2026	 09/2022
—	02/07/2022	Service	117162 km	OSS-60018668 MB-Autoservice Ulf Löhmann, Krefeld	Manual			
	 ✓	 ✓	 ✓	 ✓			 ✓	
—	10/14/2020	Service	86077 km	OSS-60018668 MB-Autoservice Ulf Löhmann, Krefeld	Manual			
	 ✓						 ✓	
—	03/02/2020	Key	69521 km	01911	Key 1			
	 12000 08/2021		 12000 509		 2800	 08/2021	 6000 08/2023	 06/2020
—	02/18/2020	Key	68470 km	01911	Key 1			
	 13000 08/2021		 13000 523		 3400 08/2021		 6000 08/2023	 06/2020
—	02/10/2020	Key	67653 km	01911	Key 1			
	 14000 08/2021		 14000 531		 13000 08/2021		 6000 08/2023	 06/2020
—	10/30/2019	Repair	57963 km	01911 Fett & Wirtz Automobile	Job Job Job Job			

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I BMW_MM02_001_10000	Local	
Fahrzeug maschinell waschen und Flat rate unit I 00 11 000	Local	3

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 0173/3219694 !!! Flat rate unit I -	Local	0 FRU
--	-------	-------

—	10/30/2019	Repair	57969 km	01911 Fett & Wirtz Automobile GmbH & Co. KG , Moers	Job Job Job
---	------------	--------	----------	---	-------------------

— Job

Description: Erreichbar unter

Is interpreted as a repeat visit: No

Customer's own words:

0173/3219694 Flat rate unit I ESTIMAT	Local	0 FRU
--	-------	-------

— Job

Description: Technische Aktion 0011830400 AGR Kühler bearbeiten

Is interpreted as a repeat visit: No

Customer's own words:

Replace exhaust-gas recirculation cooler and replace or remount
exhaust-gas recirculation valve; clean exhaust gas recirculation pipe
Flat rate unit I 00 66 955

28 FRU

Additional work, perform pressure sensor system function
Flat rate unit I 00 67 695

3 FRU

exhaust cooler
Part I 11 71 8 596 444

1

Set of small parts
Part I 11 71 8 597 652

1

Pipe union
Part I 11 71 7 799 853

2

O-ring
Part I 11 61 8 512 681

1

Oval head screw
Part I 35 21 7 685 343

1

Anti-freeze
Part I 83 19 2 304 069

2

— Job

Description: Fahrzeug maschinell waschen/aussaugen (kostenlos) / .

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0011000 Fahrzeug maschinell waschen und
aussaugen (kostenlos) !!!
Flat rate unit I 00 11 000

Local










3 FRU

— 10/29/2019 Key

57963 km

01911

Key 1



— 08/01/2019 Service

49864 km

OSS-
60018668
MB-
Autoservice Ulf
Löhmann,
Krefeld

Manual












— 06/29/2018 Key

19607 km

33379

Key 0



—	06/29/2018	Key	19607 km	33379	Key 0				
 9000 -29 4 %	 0	 9000 -29 4 %	 0	 44000	 0 05/2019	 35000	 37000 05/2020	 0 07/2019	
—	06/27/2018	Service	19598 km	33379 Fett & Wirtz Automobile, Geldern	Manual				
									
✓									
—	06/25/2018	Service	19598 km	33379 Fett & Wirtz Automobile, Geldern	Manual				
									
✓		✓							
—	06/25/2018	Repair	19901 km	33379 Fett & Wirtz Automobile GmbH & Co. KG , Geldern	Job Job Job Job				

— Job

Description: Probefahrt/Laufzettel abarbeiten u. unterschreiben bei Wartung Serviceheft in Auftrag legen

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id A000024 intern 360° Fahrzeugcheck BMW Premium Selection / MINI GW Next !!!
Flat rate unit I A00 00 24

Windshield Washer Antifreeze
Part I 83 12 2 409 037

— Job

Description: Service Motoröl durchführen

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

Engine oil service
Flat rate unit I 00 00 610

Set oil-filter element Part I 11 42 8 575 211	1
Screw plug Part I 11 13 7 535 106	1
BMW group LL-04 0w-30 Part I 83 21 2 407 830	5

— Job

Description: Service Mikrofilter durchführen

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

Vehicle interior filt..f.housing cleaner Part I 83 19 2 451 455	0.25
--	------

— Job

Description: Abgasuntersuchung / DEKRA-Abnahme


Is interpreted as a repeat visit: No

Customer's own words:


Bereitstellung zur Hauptuntersuchung Flat rate unit I -	Local	0 FRU
--	-------	-------

!!! unknown BMW-Id A000008 intern AU durchführen !!! Flat rate unit I A00 00 08	Local	3 FRU
--	-------	-------

— 06/22/2018 Key	19598 km	33379	Key 0
------------------	----------	-------	-------



— 12/18/2017 Key	19525 km	33379	Key 0
------------------	----------	-------	-------



— 10/27/2017 Repair	19900 km	33379 Fett & Wirtz Automobile GmbH & Co. KG , Geldern	Job Job
---------------------	----------	--	------------

— Job

Description: Serienverbesserungs-Maßnahme durchführen programmieren, ggf AGR ersetzen

Is interpreted as a repeat visit: No

Customer's own words:

Operating test module and programming control unit
Flat rate unit I 00 64 941

8 FRU

— Job

Description: Stoßstange hinten instandsetzen und lackieren

Is interpreted as a repeat visit: No

Customer's own words:


Replace rear bumper panel
Flat rate unit I 51 12 157

7 FRU


Additional work with Park Distance Control
Flat rate unit I 66 20 602

2 FRU


— 10/16/2017 Key 19524 km 33379 Key 0



— 07/27/2017 Key 19519 km 00083 Key 0



— 10/11/2016 Key 7682 km 00901 Key 0



— 10/11/2016 Repair 7690 km 00901 Job
STADAC Job
GmbH , Stade Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Angelieferte Winterräder montieren/Profil abgebaute Räder. VL 6,0/ VR 6,0/ Local
HL 6,0/ HR 6,0
Flat rate unit I 36 28 000

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/wheels	2 FRU
Flat rate unit I 36 99 000	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Lichtwoche und Frostschutzttest	Local	2 FRU
Flat rate unit I -		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Servicewäsche incl. aussaugen	Local	3 FRU
Flat rate unit I -		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	06/30/2016	Repair	1 km	07495 Niederlassung Hamburg Filiale Wandsbek BMW AG, Hamburg	Job Job
---	------------	--------	------	--	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

RDCi wheel & tire, winter, light alloy	1
Part I 36 11 2 289 702	

RDCi wheel & tire, winter, light alloy	1
Part I 36 11 2 289 702	

RDCi wheel & tire, winter, light alloy	1
Part I 36 11 2 289 702	

RDCi wheel & tire, winter, light alloy	1
Part I 36 11 2 289 702	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm	Local	0 FRU
Flat rate unit I 00 52 054		

—	06/29/2016	Key	4 km	07495	Key 0
---	------------	-----	------	-------	-------



0

-29
4 %