

Vehicle

BMW 520d, 140kW

WBA5E51030G060801



Development code	F10
Color	black-sapphire metallic
Actual integration level	F010-22-07-540
Start of warranty	February 5, 2015

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Next 2015-1 (as of: Nov 10, 2023)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00A9008F).	Road Map EUROPE WEST Next 2025	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	520d
Body	LIM
Vehicle identification number (last 7 characters)	G060801
Vehicle identification number (17 characters)	WBA5E51030G060801
Development code	F10
Steering	LL
Engine	B47O
Engine number	66509135
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0047046WAE
Head unit serial number	HB2068E7980413
Drive	HECK
Integration level	F010-14-11-505
Production date	Jan 15, 2015
Production works	Dingolfing
Delivery date	Jan 19, 2015
Delivering Retailers	No information
National-market version	EUR
Paint code	475
Upholstery code	LCSW
Model code	5E61
Base type	5E51
Lead type	5E61

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 01CC Auto start/stop function
 01CD Brake Energy Regeneration
 0205 Automatic transmission
 0223 Adaptive chassis and suspension
 0230 EU-specific additional contents
 0258 Tire with run-flat functionality
 02K1 BMW LA wheel, V Spoke 236
 02VB Tire pressure display
 0302 Alarm system

Retrofitted optional equipment:

This vehicle has no retrofits.

0320 Deleted, model lettering
 0322 Comfort access
 03AG Reversing camera
 0415 Sun-blind, rear
 0416 Roller sun vizor, rear lateral
 0423 Floor mats, velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0441 Smoker package
 0464 Ski bag
 0465 Through-loading system
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0494 Seat heating driver/passenger
 04B9 Interior strips, alu, satin-polished
 04NB Autom. climate control with 4-zone ctrl
 04U2 Driving experience switch incl. ECO PRO
 04UR Ambient interior lighting
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0524 Adaptive Headlights
 0548 Kilometer-calibrated speedometer
 0575 Supplementary 12V sockets
 05A1 LED Fog lights
 05AC High-beam assistant
 05AL Active Protection
 05AR Traffic congestion assistant
 05AT Driving Assistant Plus
 05DL Surround View
 0609 Navigation system Professional
 0610 Head-up display
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NS Convenience phone, expanded Smartphone
 06WA Instrument cluster, expanded equipment
 07A2 Innovation Package II
 07XP Navigation package, Connected Drive
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 08TF Active pedestrian protection
 08TH Road sign detection
 09AA Outer skin protection
 09BD Business Package
 A105 105 AH AGM battery
 LEDE Leather trim

▾ Vehicle histories

	Date	Type	Vehicle mileage	Dealer	Overview
—	03/26/2026	Key	183928 km	00319	Key 0

										
15000	15000	15000	15000	5000	-84 11.5 %	-84 11.5 %	60000	15000		
05/2027	05/2027	05/2027	05/2027					05/2027		07/2026

—	05/19/2025	Service	169886 km	OSS-60242364 DeKro Automobile, Frankfurt am Main	Manual
---	------------	---------	-----------	--	--------

											
✓											

—	11/10/2023	Key	145034 km	28454	Key 0
---	------------	-----	-----------	-------	-------

										
9000	9000	9000	9000	5000			5000	9000		
09/2024	09/2024	09/2024	09/2024	09/2024	09/2024	09/2024		09/2024		06/2024

—	03/13/2023	Key	133711 km		Key 0
---	------------	-----	-----------	--	-------

										
21000	21000	21000	21000	5000			5000	21000		
09/2024	09/2024	09/2024	09/2024	09/2024	09/2024	09/2024		09/2024		06/2024

—	03/13/2023	Repair	133720 km	28454 Euler Hofheim GmbH Autohaus, Hofheim	Job Job
---	------------	--------	-----------	--	------------

—	Job
---	-----

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing or replacing both rear coil springs
Flat rate unit I 33 53 575 20 FRU

Sechskantschraube mit Scheibe M16x1,5x110 Local 2
Part I 07 11 9 907 031

Rear coil spring 2
Part I 33 53 6 794 659

Spring pad lower 2
Part I 33 53 6 856 172

Spring pad upper 2
Part I 33 53 6 775 751

Auxiliary shock absorber Part I 33 53 6 789 387	2
Self-locking hex nut Part I 32 21 6 769 539	2
Self-locking collar nut Part I 07 11 9 905 374	6

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung Standard im Wert von 19,00 EURO für unsere Kunden
kostenlos
Flat rate unit I 01 00 001

Local

2 FRU

— 09/05/2022 Key 126396 km Key 0

 4000 -274 37.5 %		 4000 -274 37.5 %		 5000	 -244 33.4 %	 -244 33.4 %	 7000	 31000 12/2023	 -244 33.4 %
---	---	---	---	---	---	---	--	---	---

— 09/05/2022 Service 126396 km 00131 Manual
Autohaus Karl
+ Co., Mainz

 ✓		 ✓			 ✓					
--	---	--	---	---	--	---	--	---	---	---

— 08/22/2022 Key 125403 km 00131 Key 0

 5000 -261 35.7 %		 5000 -261 35.7 %		 5000	 -231 31.6 %	 -231 31.6 %	 8000	 32000 12/2023	 -231 31.6 %
---	---	---	---	---	---	---	--	---	---

— 08/22/2022 Repair 126396 km 00131 Job
Autohaus Karl
+ Co. GmbH &
Co. KG , Mainz

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Performing vehicle test
Flat rate unit I 00 00 556

3 FRU

Removing and installing rear bumper panel Flat rate unit I 51 12 156	7 FRU
Removing and installing/replacing the support for the rear bumper cover Flat rate unit I 51 12 552	3 FRU
Replace rear bumper panel Flat rate unit I 51 12 657	3 FRU
Removing and installing/replacing the bumper guide, rear, center Flat rate unit I 51 12 825	3 FRU
Removing and installing/replacing the bumper guide, rear left or right Flat rate unit I 51 12 828	2 FRU
Removing and installing/replacing the bumper guide, rear left or right Flat rate unit I 51 12 828	2 FRU
Resume vehicle test and clear fault memory Flat rate unit I 61 00 980	2 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
Additional work with Park Distance Control Flat rate unit I 66 20 602	2 FRU
Painting bumper cover, rear Flat rate unit I 99 69 015	34 FRU
Work time without specification/paintwork Flat rate unit I 99 99 000	3 FRU
Work time without specification/paintwork Flat rate unit I 99 99 000	0 FRU
Set of mounts for PDC sensor, rear Part I 51 12 2 349 990	1
Set of mounted parts, bumper, rear Part I 51 12 2 452 063	1
Gasket Part I 51 12 7 183 888	10
Carrier, bumper rear Part I 51 12 7 184 769	1
Guide, center rear Part I 51 12 7 331 600	1
Mount, rear left Part I 51 12 7 331 607	1
Mount, rear right Part I 51 12 7 331 608	1
Bumper trim panel, primed, rear Part I 51 12 7 332 764	1
Cover, towing eye, primed, rear Part I 51 12 7 332 776	1
Reflector, rear left Part I 63 14 7 318 555	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle	0 FRU
Flat rate unit I 00 52 050	

—	08/22/2022	Repair	126396 km	00131	Job
				Autohaus Karl	Job
				+ Co. GmbH &	Job
				Co. KG , Mainz	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Motoröl 5W-30 Castrol Edge LL 04 1000 mltr.	Local	5
Part I FT83 21 0 398 5		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	3 FRU
Flat rate unit I 00 00 616	

Set, microfilter/activ. charcoal filter	1
Part I 64 11 9 272 642	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:


Brake fluid service
Flat rate unit I 00 00 618

4 FRU

Brake fluid DOT4 LV, low viscosity
Part I 83 13 2 184 842

1.25

—	06/02/2022	Key	123285 km	29428	Remote KeyRead
---	------------	-----	-----------	-------	----------------



—	06/09/2021	Repair	116980 km	01548 Autohaus Euler GmbH, Frankfurt am Main	Job
---	------------	--------	-----------	--	-----

— Job

Description:

Is interpreted as a repeat visit: No


Customer's own words:

Räder auslagern CQDC LT 07.06.2021
Flat rate unit I 36 10 364

Local

0 FRU

—	12/14/2020	Key	117348 km	Key 0
---	------------	-----	-----------	-------



—	12/14/2020	Repair	117348 km	00074 Niederlassung Frankfurt BMW AG, Frankfurt am Main	Job Job Job Job
---	------------	--------	-----------	---	--------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Prod.-datum: alt 17.10.17,

Visual insp. of EGR cooler outlet and inlet (OK) Check the Control
message about coolant level (OK) and note the production date of the
installed EGR cooler
Flat rate unit I 00 70 024

14 FRU

Ersatzfahrzeug (24 Stunden)
Part I 0000160

Local

1

Oval head screw
Part I 35 21 7 685 343

2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugdesinfektion für die Werkstatt Flat rate unit I NL88 00 1	Local	1 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Flüssigkeitsstände prüfen ggf. ergänzen: Flat rate unit I AZ00 54 2	Local	1 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Servicewäsche PLUS Part I 00800	Local	1
------------------------------------	-------	---


— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	10/26/2020	Key	116980 km	01548	Key 0
---	------------	-----	-----------	-------	-------



—	10/26/2020	Repair	116980 km	01548 Autohaus Euler GmbH , Frankfurt am Main	Job Job Job
---	------------	--------	-----------	---	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung Standard im Wert von 19,00 EURO für unsere Werkstattkunden kostenlos
Flat rate unit I 01 00 001

Local

2 FRU

Service consultation at the vehicle
Flat rate unit I 00 52 050

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Eingel. Winterräder montieren
Flat rate unit I 01 10 359

Local

6 FRU

Sommerräder einlagern inkl. Datenerfassung
Flat rate unit I 36 10 362

Local

1 FRU

Räderhotel-Einlagerung Sommerräder CQDC
Part I FL3610360

Local

1

— Job

Description:

Is interpreted as a repeat visit: No








Customer's own words:

— 07/31/2020 Key

114145 km

00074

Key 0



— 07/31/2020 Repair

114145 km

00074
Niederlassung
Frankfurt BMW
AG, Frankfurt
am Main

Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugdesinfektion
Flat rate unit I NL88 00 1

Local

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing BMW emblem front
Flat rate unit I 51 14 001

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02001932

Local

Flüssigkeiten ergänzen : NEINKundenwunsch
Flat rate unit I NL00 00 3

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02002912

Local

!!! unknown BMW-Id FL00112:BMW Fahrzeug nicht waschen. !!!
Part I FL00112:BMW

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE +49 15207811716 !!!
Flat rate unit I -

Local

0 FRU

— 05/05/2020 Key

110481 km

01548

Key 0


23000
12/2021


23000
566


23000
566


5000
01/2022


23000
12/2023


49000
12/2023


-94
12.9 %


-94
12.9 %


-94
12.9 %

— 05/05/2020 Repair

110481 km

01548
Autohaus Euler
GmbH ,
Frankfurt am
Main

Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at vehicle with Service Ticket
Flat rate unit I 00 52 049

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung Standard im Wert von 19,00 EURO für unsere Werkstattkunden kostenlos Flat rate unit I 01 00 001	Local	2 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Eingel. Sommerräder montieren Flat rate unit I 01 10 360	Local	6 FRU
Winterräder einlagern inkl. Datenerfassung Flat rate unit I 36 10 363	Local	2 FRU
Räderhotel-Einlagerung Winterräder CIVW Part I FL3610359	Local	1

— 01/31/2020 Key 109576 km 01548 Key 0

 25000 12/2021	 0	 25000 660	 0	 100	 02/2020	 24000	 50000 12/2023	 02/2020
---	--	---	--	--	--	--	---	--

— 01/31/2020 Service 109576 km 01548 Automatic
Autohaus Euler GmbH, Frankfurt

 25000 12/2021	 0	 25000 12/2021	 0	 100	 0 02/2020	 24000	 50000 12/2023	 0 02/2020
				✓	✓			

— 01/31/2020 Repair 109579 km 01548 Job
Autohaus Euler Job
GmbH , Job
Frankfurt am Job
Main Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle Flat rate unit I 00 52 050	0 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung Standard im Wert von 19,00 EURO für unsere Werkstattkunden kostenlos Flat rate unit I 01 00 001	Local	2 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Preliminary check to statutory vehicle inspection Flat rate unit I 00 12 600		0 FRU
---	--	-------

(statutory) general inspection Flat rate unit I 00 12 159		0 FRU
--	--	-------

Presentation for emission inspection Flat rate unit I 00 00 527		5 FRU
--	--	-------

TÜV-SÜD Part I FT0206000	Local	1
-----------------------------	-------	---

AU-Bindesiegel Part I FT99993100100	Local	1
--	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service
Flat rate unit I 00 00 618

4 FRU

Bremsflüssigkeit
Part I FT99 99 9 999 1

Local

1

— 12/02/2019 Key 108367 km 01548 Key 0

									
200	200	200	200	11000	0	26000	200	0	0
02/2020	88	88	88	02/2020	02/2020	02/2020	02/2020	02/2020	02/2020

— 12/02/2019 Service 108367 km 01548 Automatic
Autohaus Euler
GmbH,
Frankfurt

									
200	200	200	200	11000	0	26000	200	0	0
02/2020	02/2020	02/2020	02/2020	02/2020	02/2020	02/2020	02/2020	02/2020	02/2020
✓	✓	✓	✓				✓		

— 12/02/2019 Repair 108367 km 01548 Job
Autohaus Euler Job
GmbH , Job
Frankfurt am Job
Main Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Castrol Prof.MP 5 W 30 Longlifeoil	Local	5
Part I FT99999924836		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	3 FRU
Flat rate unit I 00 00 616	

Set, microfilter/activ. charcoal filter	1
Part I 64 11 9 272 642	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service	7 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	1 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 570 043	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	5 FRU
---	-------

Fuel filter cartridge Part I 13 32 7 811 227	1
---	---

Hose clamp Part I 16 12 1 180 240	1
--------------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Elektronisches Serviceheft eintragen Flat rate unit I 00 00 699	Local	0 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Eingel. Winterräder montieren Flat rate unit I 01 10 359	Local	6 FRU
---	-------	-------

Sommerräder einlagern inkl. Datenerfassung B52H Flat rate unit I 36 10 362	Local	1 FRU
---	-------	-------

Räderhotel-Einlagerung Sommerräder B52H Part I FL3610360	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung Standard im Wert von 19,00 EURO für unsere Werkstattkunden kostenlos Flat rate unit I 01 00 001	Local	2 FRU
---	-------	-------

Keine Mobilität gewünscht Flat rate unit I 00 99 101	Local	0 FRU
---	-------	-------

Service consultation at vehicle with Service Ticket Flat rate unit I 00 52 049		0 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	11/06/2019	Repair	104978 km	01548 Autohaus Euler GmbH, Frankfurt am Main	Job Job
---	------------	--------	-----------	--	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räder auslagern Flat rate unit I 36 10 364	Local	0 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	11/04/2019	Key	107420 km	00319	Key 0
---	------------	-----	-----------	-------	-------

										
1700	1700	1700	1700	13000	0	28000	1700		0	
02/2020	116	116	116		02/2020		02/2020		02/2020	

—	07/30/2019	Key	104978 km	01548	Key 0
---	------------	-----	-----------	-------	-------

										
6000	6000	6000	6000	20000	0	33000	6000		0	
02/2020	214	214	214	02/2020	02/2020		02/2020		02/2020	

—	07/30/2019	Key	104976 km	01548	Key 0
---	------------	-----	-----------	-------	-------

										
6000	6000	6000	6000	600	0	33000	6000		0	
02/2020	214	214	214		02/2020		02/2020		02/2020	

—	07/30/2019	Service	104976 km	01548 Autohaus Euler GmbH, Frankfurt	Automatic
---	------------	---------	-----------	--	-----------

										
6000	6000	6000	6000	600	0	33000	6000		0	
02/2020	02/2020	02/2020	02/2020	✓	02/2020		02/2020		02/2020	

—	07/30/2019	Repair	104978 km	01548 Autohaus Euler GmbH, Frankfurt am Main	Job Job Job Job
---	------------	--------	-----------	--	--------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung Standard im Wert von 19,00 EURO für unsere Werkstattkunden kostenlos Flat rate unit I 01 00 001	Local	2 FRU
Keine Mobilität gewünscht Flat rate unit I 00 99 101	Local	0 FRU
Service consultation at vehicle with Service Ticket Flat rate unit I 00 52 049		0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105		2 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612		7 FRU
Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613		3 FRU
Repair kit, brake pads asbestos-free Part I 34 11 6 858 047		1
Brake cleaner, acetone-free Part I 83 19 2 413 695		1
Brake pad paste Part I 83 19 2 158 851		2
Brake pad wear sensor, front left Part I 34 35 6 791 958		1
Brake disc, lightweight, ventilated Part I 34 11 6 896 652		2
Inner hex bolt Part I 34 21 1 161 806		2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Elektronisches Serviceheft eintragen
Flat rate unit I 00 00 699

Local










0 FRU

— 07/11/2019 Key

104471 km

01548

Key 0












— 04/09/2019 Key

98663 km

01548

Key 0



— 04/09/2019 Repair

98663 km

01548
Autohaus Euler
GmbH ,
Frankfurt am
Main

Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung Standard im Wert von 19,00 EURO für unsere
Werkstattkunden kostenlos
Flat rate unit I 01 00 001

Local

2 FRU

Keine Mobilität gewünscht
Flat rate unit I 00 99 101

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Eingel. Sommerräder montieren
Flat rate unit I 01 10 360

Local

6 FRU

Winterräder einlagern inkl. Datenerfassung BWDM
Flat rate unit I 36 10 363

Local

2 FRU

Räderhotel-Einlagerung Winterräder
Part I FL3610359

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

AZ without specification/maintenance
Flat rate unit I 00 99 000

0 FRU

Scheibenklar
Part I FT99 99 9 999 1










Local

1

— 11/20/2018 Key

95060 km










Key 0



— 11/17/2018 Key

94982 km

Key 0



— 11/17/2018 Repair

94982 km

01548
Autohaus Euler
GmbH,
Frankfurt am
Main

Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung Standard im Wert von 19,00 EURO für unsere
Werkstattkunden kostenlos
Flat rate unit I 01 00 001

Local

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Angelieferte Winterräder montieren
Flat rate unit I 01 10 359

Local

6 FRU

Sommerräder einlagern BNYR
Flat rate unit I 36 10 362

Local

1 FRU

Räderhotel-Einlagerung Sommerräder
Part I FL3610360

Local

1

— 06/18/2018 Key 87411 km 01548 Key 0

									
23000	23000	23000	23000	70000	0	60000	23000		0
02/2020	621	621	621		02/2020		02/2020		02/2020

— 05/04/2018 Key 87396 km 01548 Key 0

									
23000	23000	23000	23000	80000	0	80000	23000		0
02/2020	666	666	666		02/2020		02/2020		02/2020

— 05/03/2018 Repair 87397 km 01548 Job
Autohaus Euler
GmbH ,
Frankfurt am
Main

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Detaching and attaching the front and rear wheels
Flat rate unit I 36 10 360

6 FRU

— 05/03/2018 Repair 87397 km 01548 Job
Autohaus Euler
GmbH ,
Frankfurt am
Main

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:







Detaching and attaching the front and rear wheels
Flat rate unit I 36 10 360

-6 FRU

— 02/05/2018 Service 83481 km 40119 Manual
Autohaus Vogl
e. K., Mühlendorf
a. Inn

										
✓		✓		✓	✓	✓				

— 02/03/2018 Key 83481 km 40119 Key 0



—	02/03/2018	Repair	0 km	22075 Autohaus Vogl e. K. , Burghausen	Job
---	------------	--------	------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

360° Check mit Serviceberatung Flat rate unit I -	Local	0 FRU
!!! unknown BMW-Id V011319 Fahrzeug Außenwäsche im Wert von 15,- € kostenlos !!! Flat rate unit I V01 13 19	Local	0 FRU
!!! unknown BMW-Id V099400 Flüssigkeiten kontrolliert & aufgefüllt !!! Flat rate unit I V09 94 00	Local	0 FRU
Service consultation at the vehicle with service ticket Flat rate unit I 00 52 052		0 FRU

—	02/03/2018	Repair	83487 km	40119 Autohaus Vogl e. K. , Mühldorf a. Inn	Job Job Job Job
---	------------	--------	----------	--	--------------------------

— Job

Description: VOGL Service Paket

Is interpreted as a repeat visit: No

Customer's own words:

360° Check mit Serviceberatung Flat rate unit I -	Local	1 FRU
!!! unknown BMW-Id V011319 Fahrzeug Außenwäsche im Wert von 15,- € kostenlos !!! Flat rate unit I V01 13 19	Local	3 FRU
!!! unknown BMW-Id V099400 Flüssigkeiten kontrolliert & aufgefüllt !!! Flat rate unit I V09 94 00	Local	1 FRU
Service consultation at the vehicle with service ticket Flat rate unit I 00 52 052		0 FRU

— Job

Description: Service durchführen

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610		3 FRU
Standard scope of service Flat rate unit I 00 00 105		2 FRU
Service - microfilter Flat rate unit I 00 00 616		3 FRU
Brake fluid service Flat rate unit I 00 00 618		4 FRU
VOLLSYNTH. Motoröl SAE 5W-30 Longlife 04 Part I FT99 99 1 005 0	Local	5
Set oil-filter element Part I 11 42 8 575 211		1
Set, microfilter/activ. charcoal filter Part I 64 11 9 272 642		1
Brake fluid DOT4 LV, low viscosity Part I 83 13 0 443 030		1
Windshield Washer Antifreeze Part I 83 12 2 413 061		1.5

— Job

Description: HU/AU durchführen

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description: Service Bremse vorn und hinten

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612		7 FRU
Rear brakes service Flat rate unit I 00 00 614		8 FRU
Repair kit, brake pads asbestos-free Part I 34 11 6 858 047		1
Brake pad wear sensor, front left Part I 34 35 6 791 958		1
Repair kit, brake pads asbestos-free Part I 34 21 6 862 202		1
Brake pad wear sensor, rear Part I 34 35 6 791 962		1

—	09/04/2017	Repair	74926 km	26842 BMW Mobiler Service Einsatzleitzentrale , München	Job
---	------------	--------	----------	--	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 02/28/2017 Key 74879 km 00027 Key 0

									
10000	0	10000	0	5000	0	11000	38000		0
05/2018		457			01/2018		05/2020		02/2018

— 02/28/2017 Repair 74879 km 00027 Niederlassung
Düsseldorf
BMW AG,
Düsseldorf Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Kundenlegitimation: Personalausweis Herr Guido Stock,

Radsatz auslagern Local 2 FRU
Flat rate unit I AZ36 00 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Tyre protection sleeves 4
Part I 83 19 0 140 584

— 10/05/2016 Key 66906 km 00027 Key 0

									
19000	0	19000	0	5000	0	22000	48000		0
05/2018		603			01/2018		05/2020		02/2018

— 10/05/2016 Repair 66906 km 00027 Niederlassung
Düsseldorf
BMW AG,
Düsseldorf Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Depotservice Rädermontage Flat rate unit I AZ36 00 2	Local	6 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Radsatz einlagern Flat rate unit I AZ36 00 0	Local	2 FRU
---	-------	-------

Einlagerungskosten Part I 0036007	Local	1
--------------------------------------	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sichtkontrolle Flat rate unit I AZ00 00 0	Local	2 FRU
--	-------	-------

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
--	-------	-------









— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 09/06/2016 Key 65831 km 28814 Key 0



— 09/06/2016 Repair 65831 km 28814 STADAC GmbH, Norderstedt Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kleinverbrauchsmaterial	Local	1
-------------------------	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Servicewäsche incl. aussaugen Flat rate unit I -	Local	3 FRU
Zeitzuschlag für eine Haupt- arbeit (Ab- und Aufrüstung) Flat rate unit I 51 00 000	Local	1 FRU
Verkleidung Stoßstange V lackieren Flat rate unit I 99 99 999	Local	1 FRU
Zeitzuschlag für eine Haupt - arbeit Lackierung Flat rate unit I 99 99 999	Local	1 FRU
Lackiermaterial 35% Flat rate unit I 99 99 999	Local	1 FRU
Removing and installing front bumper panel Flat rate unit I 51 11 656		9 FRU
Replace bumper cover, front Flat rate unit I 51 11 592		6 FRU
Additional work with Park Distance Control Flat rate unit I 66 20 610		4 FRU
Badge Part I 51 14 7 057 794		1
Trim cover, bumper, primed, front Part I 51 11 7 332 678		1

— 05/03/2016 Key 56277 km 00027 Key 0

 2600 10/2017	 2600 546	 2600 546	 2600 546	 15000	 0 01/2018	 34000	 2600 10/2017	 0 02/2018
--	--	--	--	--	---	--	---	---

— 05/03/2016 Service 56277 km 00027
Niederlassung
Düsseldorf,
Düsseldorf Manual

 ✓	 ✓	 ✓	 ✓				 ✓			
--	--	--	--	---	---	---	---	---	---	---

— 05/03/2016 Repair 56277 km 00027
Niederlassung
Düsseldorf
BMW AG,
Düsseldorf Job
Job
Job
Job
Job
Job

Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Alphabet Service Incl.,

Vehicle check service	7 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

BMW Engine Oil LL04 5W30	5
Part I 83 21 2 405 948	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service	5 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 7 811 227	

Hose clamp	1
Part I 16 12 1 180 240	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	1 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 570 043	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	3 FRU
Set, microfilter/activ. charcoal filter Part I 64 11 9 272 642	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Depotservice Rädermontage Flat rate unit I AZ36 00 2	Local	6 FRU
Radsatz einlagern Flat rate unit I AZ36 00 0	Local	2 FRU
Einlagerungskosten Part I 0036007	Local	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:** Befund:„Wischer schmieren. Ersetzt„Abblendlicht zu tief. Eingestellt„Mehrere kleine steinschläge Frontscheibe„1 Tag EW über BC gebucht,

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
Zusatz zum Fahrzeugcheck / Inspektion Flat rate unit I AZ10 00 1	Local	2 FRU
Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
kostenlose Fahrzeugoberwäsche Part I 0011319	Local	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Replace left and right wiper blade Flat rate unit I 61 61 541	1 FRU
Set of wiper blades	1

—	10/27/2015	Key	33954 km	00027	Key 0
---	------------	-----	----------	-------	-------

								
27000	27000	27000	27000	36000	0	50000	27000	0
10/2017	735	735	735		01/2018		10/2017	02/2018

—	10/27/2015	Repair	33954 km	00027	Job
				Niederlassung	Job
				Düsseldorf	Job
				BMW AG,	Job
				Düsseldorf	Job
					Job
					Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Arbeitszeit ohne Vorgabe/Bremsen,Kanten brechen der VA Bremsbeläge,Befund:,Kundenbeanstandung überprüft das schabende Geräusch kommt von den,Bremsbelägen der VA. Bremsbeläge sollten ausgebaut Kanten gebrochen und,gereinigt werden.,=> Auftrag vom 07.10.15 9299906,=> Der Kunde bemängelt laut quietschende Bremsen,Nach RS mit Frau Stange am 07.10.15 kann dies aufgrund der hohen,Restlaufleistung der Bremse über GW abgerechnet werden!,Befund:,, - Kanten gebrochen und Bremse gereinigt,- Probefahrt mit kalter und warmer Bremse durchgeführt keine,Quietschgeräusche vorhanden,,,,,

Work time without specification/brakes	2 FRU
Flat rate unit I 34 99 000	

Removing and installing/replacing brake pads on both front disc brakes	9 FRU
Flat rate unit I 34 11 000	

Cleaning both front wheel brakes	6 FRU
Flat rate unit I 34 10 559	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sichtkontrolle Flüssigkeiten nachfüllen	Local	2 FRU
Flat rate unit I AZ00 00 0		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche	Local	1
Part I 0011319		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: AP Hr. Stock,

Vehicle check in frame of acceptance 0 FRU
Flat rate unit I 00 52 054

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug (Anmietung 07-18 Uhr) Local 1
Part I 0000160

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Lichttest ohne Plakette kleben Local 2 FRU
Flat rate unit I AZ12 29 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 10/07/2015 Key 30568 km 00027 Key 0

								
-1100	0	-1100	0	39000	0	50000	30000	0
01/2017		482			01/2018		01/2019	02/2018

— 10/07/2015 Repair 30568 km 00027 Job
Niederlassung Job
Düsseldorf Job
BMW AG, Job
Düsseldorf Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service

Flat rate unit I 00 00 610

3 FRU

Set oil-filter element

Part I 11 42 8 575 211

1

BMW Engine Oil LL04 5W30

Part I 83 21 2 405 948

5

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter

Flat rate unit I 00 00 616

3 FRU

Pollenfiltergehäuse-Reiniger

Part I 99 99 8 888 310

Local

1

Set, microfilter/activ. charcoal filter

Part I 64 11 9 272 642

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: PROBEFAHRT: Der Kunde bemängelt ein zweitweises "metallisch-schabendes",Geräusch beim Bremsen kurz vor Stillstand von der Vorderachse. Bitte,Probefahrt und beurteilen. Info dazu bitte an mich,Befund;
Kundenbeanstandung überprüft das schabende Geräusch kommt von den,Bremsbelägen der VA. Bremsbeläge sollten ausgebaut Kanten gebrochen und,gereinigt werden. Nach Rücksprache mit Sb erstmal keine Reperatur,durchführen.,Neuer Termin am 27.10. für die Bremse,

Sichtkontrolle Flüssigkeiten nachfüllen

Flat rate unit I AZ00 00 0

Local

2 FRU

Windshield Washer Antifreeze

Part I 83 12 2 409 031

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Audacon,

Depotservice Rädermontage

Flat rate unit I AZ36 00 2

Local

6 FRU

Radsatz einlagern - 9299906
Flat rate unit I AZ36 00 0

Local

2 FRU

Einlagerungskosten
Part I 0036007

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche
Part I 0011319

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket
Flat rate unit I 00 52 052

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug (Anmietung 07-18 Uhr)
Part I 0000160

Local

1

— 06/30/2015 Repair

1 km

00027
Niederlassung
Düsseldorf
BMW AG,
Düsseldorf

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug (Anmietung 07-18 Uhr) Haf
Part I 0000160

Local

3

— 06/23/2015 Key

17727 km

00027

Key 0



12000
01/2017



0



12000
587



0



47000



0
01/2018



50000



42000
01/2019



0
02/2018

—

06/23/2015 Repair

17727 km

00027
Niederlassung
Düsseldorf
BMW AG,
Düsseldorf

Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Stoßstange vorne zerlegen und zusammen-
Flat rate unit I AZME000

Local

5 FRU

Remove and install front bumper cover
Flat rate unit I 51 11 156

10 FRU

Additional work with Park Distance Control
Flat rate unit I 66 20 602

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Stoßfänger vorne lackieren
Flat rate unit I AZLA000

Local

42 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Lackmaterial
Part I 0000156

Local

1

Kleinteile
Part I 0000156

Local

1

—

04/14/2015 Repair

1000 km

00027
Niederlassung
Düsseldorf
BMW AG,
Düsseldorf

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Radsatz einlagern Radsatznr.: 210215022,

Radsatz einlagern Radsatznr.: 210215022	Local	2 FRU
Flat rate unit I AZ36 00 0		

Einlagerungskosten	Local	1
Part I 0036007		

—	02/05/2015	Repair	0 km	01548 Autohaus Euler GmbH , Frankfurt am Main	Job
---	------------	--------	------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Free pre-delivery check	9 FRU
Flat rate unit I 00 00 009	

—	02/05/2015	Repair	0 km	01548 Autohaus Euler GmbH , Frankfurt am Main	Job
---	------------	--------	------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterradsatz liefern, bereitstellen und montieren	Local	6 FRU
Flat rate unit I 01 10 366		

Räder ins Fahrzeug legen Sommerräder	Local	0 FRU
Flat rate unit I 01 10 370		

Wheel & tire, winter,light alloy RDC LC	4
Part I 36 11 2 183 500	

—	02/05/2015	Repair	0 km	01548 Autohaus Euler GmbH , Frankfurt am Main	Job
---	------------	--------	------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug ausparken S62	Local	1 FRU
Flat rate unit I 00 00 749		

Installing navigation map(s) Flat rate unit I 65 90 600		2 FRU
WARNWESTE Part I FT82 26 2 311 3	Local	1
Snap-in adapter, Basic Part I 84 21 2 199 395		1
Enable code HU High map, Europe Initial Part I 65 90 2 350 334		1