

Vehicle
BMW 320d, 140kW
WBA8H91000K664623



Development code	F31
Color	black-sapphire metallic
Actual integration level	F020-22-03-552
Start of warranty	February 15, 2016

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map could not be determined.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
-	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2026-1	-

▼ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320d
Body	TOUR
Vehicle identification number (last 7 characters)	K664623
Vehicle identification number (17 characters)	WBA8H91000K664623
Development code	F31
Steering	LL
Engine	B47O
Engine number	65509440
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0210980ZRI
Head unit serial number	HB2140F7734198
Drive	HECK
Integration level	F020-15-11-502
Production date	Nov 17, 2015
Production works	Muenchen
Delivery date	Feb 17, 2016
Delivering Retailers	No information
National-market version	EUR
Paint code	475
Upholstery code	CCL2
Model code	8H01
Base type	8H91
Lead type	8H01

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 EU-specific additional contents
 0258 Tire with run-flat functionality
 02VB Tire pressure display
 02XE Sport leather steering wheel
 0302 Alarm system

Retrofitted optional equipment:

This vehicle has no retrofits.

0322 Comfort access
 03AA Roof railing black
 03AC Trailer coupling
 0402 Electric panoramic roof
 0423 Floor mats, velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0441 Smoker package
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04LU Black, highgloss Perlglanz chrome accent
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometer-calibrated speedometer
 0563 Light package
 0575 Supplementary 12V sockets
 05A1 LED Fog lights
 05A2 LED headlight
 05AC High-beam assistant
 05AL Active Protection
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 0609 Navigation system Professional
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NS Convenience phone, expanded Smartphone
 06WA Instrument cluster, expanded equipment
 07AC Sport Line
 07LD Modell Sport Line
 07XP Navigation package, Connected Drive
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 08TH Road sign detection
 0931 Winter instead of summer tires ex-fact.
 09BD Business Package
 A090 90 AH AGM battery
 POLS Cloth cushion

▾ Vehicle histories

Date	Type	Vehicle mileage			Dealer	Overview	
—	03/03/2026	Key	238013 km			34243	Key 0
							
1200	1200	1200	1200	37000	25000	25000	1200
02/2027	02/2027	02/2027	02/2027	09/2026	09/2026	09/2026	02/2027

—	03/03/2026	Service	238013 km	34243 May&Olde GmbH, Rendsburg	Automatic
---	------------	---------	-----------	---	-----------

							
1200 02/2027	1200 02/2027	1200 02/2027	1200 02/2027	37000	09/2026	25000	1200 02/2027
✓	✓	✓	✓				✓

Comment: -

—	03/03/2026	Repair	238018 km	34243 ,	Job Job Job: Service Standardumfang Job: Service Fahrzeug-Check Job Job Job Job Job Job Job Job
---	------------	--------	-----------	---------	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Abgabe Service Flat rate unit I 00 99 315	Local	2 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

May & Olde Sonderpaketpreise- 5 Jahre+ wurden berücksichtigt Flat rate unit I 00 99 508	Local	1 FRU
--	-------	-------

— Job: Service Standardumfang

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang Package I 0000105		
Standard scope of service Flat rate unit I 00 00 105		2

— Job: Service Fahrzeug-Check

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**Service Fahrzeug-Check
Package I 0000624Vehicle check service
Flat rate unit I 00 00 624

6

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**Engine oil service
Flat rate unit I 00 00 610

3 FRU

Set oil-filter element
Part I 11 42 8 575 211

1

MOTORÖL CASTROL BMW Longlife-19 0W-30
Part I FT99999000027

Local

5

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**Service - microfilter
Flat rate unit I 00 00 616

2 FRU

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**Service - air filter insert
Flat rate unit I 00 00 602

2 FRU

Air filter element
Part I 13 71 8 511 668

1

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**Fuel filter service
Flat rate unit I 00 00 604

3 FRU

Fuel filter cartridge

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Installing navigation map update 2 FRU
Flat rate unit I 72 65 400

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug aussaugen Local 1 FRU
Flat rate unit I 51 99 004

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test including deleting fault memory and recharging batteries 6 FRU
Flat rate unit I 00 20 020

— 02/03/2025 Key 208174 km 34243 Key 0

 4000 02/2026	 4000 02/2026	 4000 02/2026	 160 09/2026	 70000 02/2028	 35000 02/2028
--	--	--	---	---	---

— 02/03/2025 Service 208174 km 34243 Automatic
May&Olde GmbH , Rendsburg

 4000 02/2026 ✓	 4000 02/2026 ✓	 4000 02/2026 ✓	 160 09/2026 ✓	 70000 02/2028 ✓	 35000 02/2028 ✓
---	---	---	--	--	--

Comment: -

— 02/03/2025 Repair 208179 km 34243 , Job: Service Standardumfang
Job: Service Motoröl
Job: Service Mikrofilter
Job
Job
Job

— Job: Service Standardumfang

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang

Package I 0000105

Standard scope of service	2
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs	3 FRU
Flat rate unit I 34 11 613	

Brake disc, ventilated	2
Part I 34 11 8 848 417	

Inner hex bolt	2
Part I 34 21 1 161 806	

Torx screw with washer	4
Part I 34 10 6 864 424	

Service Bremse vorn

Package I 0000612

Service - front brakes	6
Flat rate unit I 00 00 612	

Bremsenreiniger 2.0 50ml	Local	1
Part I FT83192413695		

Repair kit brake pads asbestos-free	1	
Part I 34 11 8 855 010		

Brake pad wear sensor, front left	1	
Part I 34 35 6 792 289		

Bremsklotzpaste 10ML	Local	2
Part I FT99999000004		

— Job: Service Motoröl

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Motoröl

Package I 0000610

Engine oil service	3
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job: Service Mikrofilter

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Mikrofilter
Package I 0000616

Service - microfilter 2
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Treue zahlt sich aus ----- * May & Olde Sonderpaketpreise - 5 Jahre+ Local 1 FRU
wurden berücksichtigt
Flat rate unit I 00 99 508

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Maschinelle Fahrzeugwäsche -- ohne Berechnung inkl.aussaugen Local 1 FRU
Flat rate unit I 51 99 004

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceersatzwagen X3/4-5er IX ----- kostenpflichtig ----- Local 3 FRU
Flat rate unit I 99 99 999

Haftungsreduzierung Serviceersatzwagen Local 3 FRU
Flat rate unit I 99 99 999

— 02/03/2025 Repair 208179 km 34243 , Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment 2 FRU

Flat rate unit I 51 99 000

Removing and installing front bumper panel Flat rate unit I 51 11 656		9 FRU
Replace bumper cover, front Flat rate unit I 51 11 592		11 FRU
Additional work with Park Distance Control Flat rate unit I 66 20 614		5 FRU
Removing and installing/replacing front left or right wheel arch cover Flat rate unit I 51 71 538		4 FRU
Performing vehicle test Flat rate unit I 00 00 556		2 FRU
Work time without specification/body Flat rate unit I 41 99 000		6 FRU
Work time without specification/paintwork Flat rate unit I 99 99 000		0 FRU
Painting the hood Flat rate unit I 99 61 540		0 FRU
Painting bumper cover, front Flat rate unit I 99 68 535		0 FRU
Fahrzeugverbringung zum Lackier rer Flat rate unit I 51 99 001	Local	12 FRU
Lackierung 66AW Flat rate unit I 99 99 999	Local	1 FRU
Trim cover, bumper, primed, front Part I 51 11 7 445 135		1
Set of mounted parts, bumper, front Part I 51 11 2 471 536		1
Set of mounts, front PDC / PMA sensor Part I 51 11 7 445 076		1
Adhesive set K6 Part I 83 19 5 A54 7C4		1
Insert, air intake, center Part I 51 11 7 386 152		1
Closed grid, left Part I 51 11 7 396 885		1
Air inlet finisher, left Part I 51 11 7 396 853		1
Badge Part I 51 76 7 288 752		1
Front fog lamp, LED, left Part I 63 17 7 315 559		1
Support, fog lamp left Part I 51 11 7 386 361		1
Cover, wheelhousing, fr. sec., front lft Part I 51 71 7 260 725		1

Expanding rivet
Part I 51 16 1 881 149

3

Hex head screw with washer
Part I 07 14 7 129 160

10

—	01/08/2025	Key	206016 km	34243	Key 0		
 7000 02/2026		 7000 02/2026		 2800	 09/2026	 70000	 38000 02/2028
—	12/19/2024	Key	205339 km	34243	Key 0		
 7000 02/2026		 7000 02/2026		 27000	 09/2026	 42000	 38000 02/2028
—	12/19/2024	Service	205339 km	34243 May&Olde GmbH , Rendsburg	Automatic		
 7000 02/2026		 7000 02/2026		 27000	 09/2026	 42000	 38000 02/2028
Comment: -							
—	12/19/2024	Repair	205344 km	34243 ,	Job Job: Hauptuntersuchung §29 StV Job Job Job: SEW Mietwagenklasse 1/2er Job Job Job: HU Nachprüfung §29StVZO		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing both spring struts at front Flat rate unit I 31 31 051	33 FRU
Torx screw Part I 31 10 6 793 893	2
Additional shock absorber, front Part I 31 33 6 855 440	2
Spring pad with guard tube, top Part I 31 30 6 791 712	2
Hex nut	2

Attachment set spring strut front M8
Part I 31 35 2 467 063

2

— Job: Hauptuntersuchung §29 StV

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hauptuntersuchung §29 StV
Package I 0107001

Presentation for emission inspection 5
Flat rate unit I 00 00 527

Service Vorab - Check zur Hauptuntersuchung Local 1
Flat rate unit I 00 00 104

HU gemäß §29 StVZO Local 1
Flat rate unit I 99 99 999

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Treue zahlt sich aus ----- -- Bonus-Card May & Olde - 20% ---- Local 1 FRU
Nachlass wurden gewährt
Flat rate unit I 00 99 505

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Maschinelle Fahrzeugwäsche -- ohne Berechnung inkl.aussaugen Local 1 FRU
Flat rate unit I 51 99 004

— Job: SEW Mietwagenklasse 1/2er

Description:

Is interpreted as a repeat visit: No

Customer's own words:

SEW Mietwagenklasse 1/2er Local
Package I MM02700000221

Serviceersatzwagen 1/2er- ----- kostenpflichtig ----- Local 1
Flat rate unit I 99 99 999

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing or replacing both brake shoe expanders for
handbrake shoes, rear 11 FRU
Flat rate unit | 34 41 670

Brake disc, ventilated 2
Part | 34 21 6 864 900

Inner hex bolt 2
Part | 34 21 1 161 806

Repair kit brake pads asbestos-free 1
Part | 34 21 8 855 013

Brake pad wear sensor, rear 1
Part | 34 35 6 792 292

Hex screw with collar 4
Part | 34 20 6 850 536

Repair kit, brake shoe, complete 1
Part | 34 21 2 213 311

— Job: HU Nachprüfung §29StVZO

Description:


Is interpreted as a repeat visit: No

Customer's own words:

HU Nachprüfung §29StVZO Local
Package | MM01090012160

HU Nachprüfung §29StVZO extern Local 1
Flat rate unit | 99 99 999

— 09/04/2024 Key 198565 km 34243 Key 0



— 09/04/2024 Repair 198569 km 34243 , Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing both rear shock absorbers Flat rate unit I 33 52 525	9 FRU
Gasket Part I 33 50 6 866 038	2
Hex nut wiht flange Part I 07 11 9 907 135	2
Star-socket screw Part I 07 11 9 907 137	6
Auxiliary shock absorber, rear Part I 33 53 6 850 537	2
Torx screw with collar Part I 07 11 9 907 372	2
Self-locking collar nut Part I 33 32 6 760 668	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
Bremsflüssigkeit Part I FT 99 1 321 848	Local 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Klima Paket Gold ----- Klima Wartung und Desinfektion zzgl. Material Flat rate unit I 00 99 263	Local 9 FRU
---	-------------

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

M O Service Saison Check Flat rate unit I 00 00 111	Local	8 FRU
--	-------	-------

Windshield Washer Antifreeze Part I 83 12 5 A85 517		1
--	--	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Replacing both ball joints in bottom steering knuckles/wheel carriers Flat rate unit I 33 32 721		19 FRU
---	--	--------

Ball joint Part I 33 32 6 792 553		2
--------------------------------------	--	---

Self-locking collar nut Part I 33 30 6 760 349		2
---	--	---

Hex screw with collar Part I 33 32 6 762 875		2
---	--	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Maschinelle Fahrzeugwäsche -- ohne Berechnung inkl.aussaugen Flat rate unit I 51 99 004	Local	1 FRU
--	-------	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Treue zahlt sich aus ----- * May Olde Sonderpaketpreise - 5 Jahre+ wurden berücksichti Flat rate unit I 00 99 508	Local	1 FRU
---	-------	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Haftungsreduzierung Serviceersatzwagen 00000000 Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

Serviceersatzwagen X1/2-3/ 4er----- kostenpflichtig --- ---00000000 Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

— 08/26/2024 Key 198328 km 34243 Key 0

							
14000		14000		36000		60000	45000
02/2026		02/2026			09/2024		02/2028

— 08/26/2024 Service 198328 km 34243 Automatic
May&Olde GmbH , Rendsburg

							
14000		14000		36000		60000	45000
02/2026		02/2026			09/2024 ✓		02/2028

Comment: -

— 02/21/2024 Key 181124 km 34243 Key 0

							
-8000 25.8 %	-8000	-8000	-8000	45000		5000	-8000 12.9 %
05/2024	05/2024	05/2024	05/2024		09/2024		05/2024

— 02/21/2024 Service 181124 km 34243 Automatic
May&Olde GmbH , Rendsburg

							
-8000	-8000	-8000	-8000	45000		5000	-8000
05/2024 ✓	05/2024 ✓	05/2024 ✓	05/2024 ✓		09/2024		05/2024 ✓

Comment: -

— 02/21/2024 Repair 181133 km 34243 May & Olde GmbH , Rendsburg
Job
Job
Job
Job
Job
Job
Job

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610		3 FRU
Scheibenklar mit Frostschutz 5000ml Part I FT 99 1 224 090	Local	0.2
MOTORÖL CASTROL BMW Longlife-19 0W-30 Part I FT 99 9 990 000	Local	5
Screw plug Part I 11 13 7 535 106		1
Battery Part I 61 31 9 217 643		1
Set oil-filter element Part I 11 42 8 575 211		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604		3 FRU
Fuel filter cartridge Part I 13 32 7 822 497		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602		2 FRU
Air filter element Part I 13 71 8 511 668		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616		2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service 6 FRU
Flat rate unit I 00 00 624

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service 7 FRU
Flat rate unit I 00 00 614

Bremsenreiniger 2.0 50ml Local 1
Part I FT 83 1 924 136

Bremsklotzpaste 10ML Local 2
Part I FT 99 9 990 000

Brake pad wear sensor, rear 1
Part I 34 35 6 792 292

Repair kit brake pads asbestos-free 1
Part I 34 21 8 855 013

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:


Serviceersatzwagen X3 / X4 -- ----- kostenpflichtig --- ---00000000 Local 1 FRU
Flat rate unit I 99 99 999

Maschinelle Fahrzeugwäsche ohne Berechnung inklusive Fußraum Local 1 FRU
aussaugen
Flat rate unit I 51 99 004


Treue zahlt sich aus * May Olde Sonderpaketpreise 5 Jahre+ wurden Local 1 FRU
berücksichtigt
Flat rate unit I 00 99 508

Haftungsreduzierung für SEW 21.02.2024 00000000 Local 1 FRU
Flat rate unit I 99 99 999

— 02/12/2024 Key 180800 km 34243 Remote KeyRead



— 09/07/2023 Key 170373 km 34243 Key 0



—	09/07/2023	Repair	170382 km	34243 May & Olde GmbH , Rendsburg	Job Job
---	------------	--------	-----------	-----------------------------------	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing the auxiliary turn signal lamp, mirror, left	4 FRU
Flat rate unit I 63 13 250	

Housing lower section, grained, left	1
Part I 51 16 7 284 127	

Holder, black grained, left	1
Part I 51 16 7 284 123	

Auxiliary turn signal, mirror, left	1
Part I 63 13 7 280 771	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Maschinelle Fahrzeugwäsche -- ohne Berechnung inkl.aussaugen	Local	1 FRU
Flat rate unit I 51 99 004		

—	02/17/2023	Key	158190 km	Key 0
---	------------	-----	-----------	-------

							
15000	15000	15000	15000	-1400 2.6 %		8000	15000
05/2024	05/2024	05/2024	05/2024	09/2024			05/2024

—	02/17/2023	Service	158190 km	34243 May&Olde GmbH , Rendsburg	Automatic
---	------------	---------	-----------	---------------------------------	-----------

							
15000	15000	15000	15000	-1400		8000	15000
05/2024	05/2024	05/2024	05/2024	09/2024			05/2024
				✓			

Comment: -

—	02/17/2023	Repair	158190 km	34243 May & Olde GmbH , Rendsburg	Job Job Job
---	------------	--------	-----------	-----------------------------------	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Treue zahlt sich aus * May Olde Sonderpaketpreise 5 Jahre+ wurden berücksichtigt Flat rate unit I 00 99 508	Local	1 FRU
Standard scope of service Flat rate unit I 00 00 105		2 FRU

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613		3 FRU
Service - front brakes Flat rate unit I 00 00 612		6 FRU
Bremsklotzpaste Part I FT 99 9 990 000	Local	2
Bremsenreiniger 2.0 50ml Part I FT 83 1 924 136	Local	1
Torx screw with washer Part I 34 10 6 864 424		4
Inner hex bolt Part I 34 21 1 161 806		2
Brake disc, ventilated Part I 34 11 8 848 417		2
Repair kit, brake pads asbestos-free Part I 34 10 6 859 181		1
Brake pad wear sensor, front left Part I 34 35 6 792 289		1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Serviceersatzwagen 1/2er-X1 /2 ----- kostenpflichtig --- ---00000000 Flat rate unit I 99 99 999	Local	1 FRU
Pflegepaket Bronze Flat rate unit I 99 99 999	Local	1 FRU
Klima Paket Gold Klima Wartung und Desinfektion zzgl. Material Flat rate unit I 00 99 263	Local	9 FRU
Treue zahlt sich aus May Olde Bonus-Card 20% 20% Nachlass wurden gewährt Flat rate unit I 00 99 505	Local	0 FRU

							
16000	16000	16000	16000	-500 0.9 %		9000	16000
05/2024	05/2024	05/2024	05/2024		09/2024		05/2024

— 09/27/2022 Key 149378 km 34243 Key 0

							
24000	24000	24000	24000	25000	-26 3.6 %	16000	24000
05/2024	05/2024	05/2024	05/2024				05/2024

— 09/27/2022 Service 149378 km 34243 Automatic
May&Olde GmbH , Rendsburg

							
24000	24000	24000	24000	25000		16000	24000
04/2024	04/2024	04/2024	04/2024		09/2022 ✓		04/2024

Comment: -

— 09/27/2022 Repair 149379 km 34243 May & Olde GmbH , Rendsburg Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service 4 FRU
Flat rate unit I 00 00 618

Bremsflüssigkeit Local 1
Part I FT 99 1 321 848

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

May Olde Bonus-Card 20% Local 1 FRU

— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fahrzeugwäsche inklusive aussaugen
Flat rate unit I 51 99 004

Local 2 FRU


— 06/15/2022 Key 143254 km 34243 Key 0



— 05/18/2022 Key 141475 km 34243 Key 0



— 05/18/2022 Service 141475 km 34243 Automatic
May&Olde GmbH , Rendsburg



Comment: -

— 05/18/2022 Repair 141479 km 34243 May & Olde GmbH , Rendsburg
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

MOTORÖL CASTROL Longlife-04 BMW	Local	5
Part I FT 99 9 990 000		

Scheibenklar mit Frostschutz 5000ml	Local	0.2
Part I FT 99 1 224 090		

Set oil-filter element	1
Part I 11 42 8 575 211	

Battery	1
Part I 61 31 9 217 643	

Screw plug	1
Part I 11 13 7 535 106	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fahrzeugwäsche inklusive aussaugen	Local	2 FRU
Flat rate unit I 51 99 004		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

* May Olde Sonderpaketpreise 5 Jahre + wurden berücksichtigt	Local	1 FRU
Flat rate unit I 00 99 508		

— 09/14/2020 Key 112055 km 34243 Key 0



900
05/2021



900
260



900
260



900
260



-350



0
10/2020



9000



900
05/2021

—	09/14/2020	Service	112055 km	34243 May & Olde GmbH, Rendsburg	Automatic
---	------------	---------	-----------	----------------------------------	-----------

							
900	900	900	900	-350	0	9000	900
06/2021	06/2021	06/2021	06/2021	11/2020	11/2020	06/2021	06/2021
✓	✓	✓	✓	✓	✓	✓	✓

Comment: Bremsflüssigkeit + Bremse hinten auch fällig

—	09/14/2020	Repair	112085 km	34243 May & Olde GmbH, Rendsburg	Job Job Job Job Job Job Job Job Job Job
---	------------	--------	-----------	----------------------------------	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle Flat rate unit I 00 52 050	0 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Scheibenklar mit Frostschutz 5000ml Part I FT 83 1 224 090	Local	0.2
---	-------	-----

MOTORÖL CASTROL 1L Dose Longlife-04 BMW / MINI Part I FT 99 9 990 000	Local	5
--	-------	---

Set oil-filter element Part I 11 42 8 575 211		1
--	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602	2 FRU
---	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Front brake/rear brake service Flat rate unit I 00 00 613	13 FRU
--	--------

Bremsenreiniger 2.0 50ml Part I FT 83 1 924 136	Local	2
--	-------	---

Bremsklotpaste Part I FT 99 9 990 000	Local	4
--	-------	---

Brake disc, ventilated	2
Part I 34 21 6 864 900	

Repair kit, brake pads asbestos-free	1
Part I 34 21 6 873 093	

Brake pad wear sensor, rear	1
Part I 34 35 6 792 292	

Inner hex bolt	2
Part I 34 21 1 161 806	

Hex screw with collar	4
Part I 34 20 6 850 536	

Repair kit, brake pads asbestos-free	1
Part I 34 10 6 859 181	

Brake pad wear sensor, front left	1
Part I 34 35 6 792 289	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Bremsflüssigkeit	Local	1
Part I FT 83 1 321 848		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing rubber mounts of both tension struts	11 FRU
Flat rate unit I 31 12 644	

Hydrobearing	2
Part I 31 12 6 855 743	

Hexagon screw with flange	2
Part I 31 10 6 885 777	

Combination nut	2
Part I 33 30 6 787 062	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fahrzeugwäsche inklusive aussaugen	Local	2 FRU
Flat rate unit I 51 99 004		

1000	1000	1000	1000	-250	0	9000	1000	1000
05/2021	261	261	261		10/2020		05/2021	

— 05/08/2019 Key 83095 km 34243 Key 0

-1500	0	-1500	0	60000	0	48000	30000	30000
04/2020		358			10/2020		04/2022	

— 05/08/2019 Service 83095 km 34243 May & Olde GmbH, Rendsburg Manual

✓		✓								

Comment: -

— 05/08/2019 Repair 83098 km 34243 May & Olde GmbH, Rendsburg Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket 0 FRU
Flat rate unit I 00 52 052

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Castrol Edge Prof. 0W30 LL04 Leichtlauföl
Part I FT 99 9 990 000

Local

5

Scheibenklar mit Frostschutz 1000ml
Part I FT 83 1 224 090

Local

1

Set oil-filter element
Part I 11 42 8 575 211

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter
Flat rate unit I 00 00 616

2 FRU

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash
Flat rate unit I 00 11 319

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug (E) 08.05.2019 00000000
Flat rate unit I 99 99 999

Local







1 FRU

— 04/30/2019 Key

82678 km

34243








Key 0



— 10/10/2018 Key

63527 km

Key 0



— 10/10/2018 Service

63527 km

34243 May &
Olde GmbH,
Rendsburg

Automatic

							
19000	0	19000	0	60000	0	5000	50000
04/2020		04/2020			11/2018		04/2022
				✓	✓	✓	

Comment: Auftrag erweitert

—	10/10/2018	Repair	63527 km	34243 May & Olde GmbH, Rendsburg	Job Job Job Job Job Job Job Job Job
---	------------	--------	----------	----------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with customer without service ticket	0 FRU
Flat rate unit I 00 52 053	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service	7 FRU
Flat rate unit I 00 00 614	

Bremsenschutz	Local	2
Part I FT 99 9 990 000		

Brake pad wear sensor, rear	1
Part I 34 35 6 792 292	

Brake cleaner, acetone-free	1
Part I 83 19 2 413 695	

Repair kit, brake pads asbestos-free	1
Part I 34 21 6 873 093	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618		4 FRU
Bremsflüssigkeit Part I FT 83 1 321 848	Local	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Work time without specification/brakes Flat rate unit I 34 99 000		6 FRU
Repair kit, brake pads asbestos-free Part I 34 10 6 859 181		1
Brake disc, ventilated Part I 34 11 6 792 219		2
Inner hex bolt Part I 34 21 1 161 806		2
Brake pad wear sensor, front left Part I 34 35 6 792 289		1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Replace left and right wiper blade Flat rate unit I 61 61 541		1 FRU
Set of wiper blades Part I 61 61 2 241 375		1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Replacing the wiper blade for the rear wiper Flat rate unit I 61 62 520		1 FRU
Wiper blade Part I 61 62 7 356 763		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash 2 FRU
Flat rate unit I 00 11 319

— Job


Description:

Is interpreted as a repeat visit: No


Customer's own words:

Removing and installing/replacing both brake calipers, front 8 FRU
Flat rate unit I 34 11 529

— 10/02/2018 Key 62977 km Key 0



— 06/01/2018 Key 54535 km 34243 Key 0



— 04/20/2018 Repair 50604 km 34243 May & Olde GmbH , Rendsburg Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with customer without service ticket 0 FRU
Flat rate unit I 00 52 053

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

-2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service		-3 FRU
Flat rate unit I 00 00 610		

Castrol Edge Prof. 0W30 LL04 Leichtlauföl	Local	-5
Part I FT 99 9 990 000		

Scheibenklar mit Frostschutz 1000ml	Local	-1
Part I FT 83 1 224 090		

Set oil-filter element		-1
Part I 11 42 8 575 211		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter		-2 FRU
Flat rate unit I 00 00 616		

Microfilter/activated Carbon container		-1
Part I 64 11 9 237 555		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service		-6 FRU
Flat rate unit I 00 00 624		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert		-2 FRU
Flat rate unit I 00 00 602		

Air filter element		-1
Part I 13 71 8 511 668		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service
Flat rate unit I 00 00 604

-3 FRU

Fuel filter cartridge
Part I 13 32 8 572 522

-1

Hose clamp
Part I 07 12 9 952 104

-1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes
Flat rate unit I 00 00 612

-6 FRU

Bremsenschutz
Part I FT 99 9 990 000

Local-2

Repair kit, brake pads asbestos-free
Part I 34 10 6 859 181

-1

Brake pad wear sensor, front left
Part I 34 35 6 792 289

-1

Brake cleaner, acetone-free
Part I 83 19 2 413 695

-1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Radwechsel ohne Einlagerung
Flat rate unit I 36 00 014

Local-6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash
Flat rate unit I 00 11 319

-2 FRU

—04/20/2018Repair50604 km34243 May & Olde GmbH , RendsburgJobJobJobJobJobJobJobJobJob

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with customer without service ticket	0 FRU
Flat rate unit I 00 52 053	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge Part I 13 32 8 572 522	1
Hose clamp Part I 07 12 9 952 104	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612	6 FRU
Bremsenschutz Part I FT 99 9 990 000	Local 2
Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
Brake pad wear sensor, front left Part I 34 35 6 792 289	1
Brake cleaner, acetone-free Part I 83 19 2 413 695	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Radwechsel ohne Einlagerung Flat rate unit I 36 00 014	Local 6 FRU
---	-------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash Flat rate unit I 00 11 319	2 FRU
--	-------

—	04/20/2018	Repair	50604 km	34243 May & Olde GmbH , Rendsburg	Job
---	------------	--------	----------	-----------------------------------	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Castrol Edge Prof. 0W30 LL04 Leichtlauföl	Local 5

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610		3 FRU
Castrol Edge Prof. 0W30 LL04 Leichtlauföl Part I FT99999000027	Local	5
Scheibenklar mit Frostschutz 1000ml Part I FT83122409031	Local	1
Set oil-filter element Part I 11 42 8 575 211		1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter Flat rate unit I 00 00 616		2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555		1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check service Flat rate unit I 00 00 624		6 FRU
---	--	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - air filter insert Flat rate unit I 00 00 602		2 FRU
Air filter element Part I 13 71 8 511 668		1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Fuel filter service Flat rate unit I 00 00 604		3 FRU
Fuel filter cartridge Part I 13 32 8 572 522		1

Hose clamp	1
Part I 07 12 9 952 104	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes	6 FRU
Flat rate unit I 00 00 612	

Bremsenschutz	Local	2
Part I FT99999000004		

Repair kit, brake pads asbestos-free	1
Part I 34 10 6 859 181	

Brake pad wear sensor, front left	1
Part I 34 35 6 792 289	

Brake cleaner, acetone-free	1
Part I 83 19 2 413 695	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Radwechsel ohne Einlagerung	Local	6 FRU
Flat rate unit I 36 00 014		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash	2 FRU
Flat rate unit I 00 11 319	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:


— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	12/06/2016	Service	18109 km	37100 May & Olde GmbH, Kaltenkirchen	Manual
---	------------	---------	----------	--	--------



Comment: -

—	12/06/2016	Repair	18171 km	37100 May & Olde GmbH , Kaltenkirchen	Job Job Job
---	------------	--------	----------	---------------------------------------	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

FRU specification for wage calculation in workshop	2 FRU
Flat rate unit I 00 00 900	

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Castrol Edge Prof. 0W30 LL04 Leichtlauföl	Local	5
Part I FT 99 9 990 000		

Set oil-filter element	1
Part I 11 42 8 575 211	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Statutory emission test	5 FRU
Flat rate unit I 00 00 442	

RDCi wheel & tire, summer, light alloy	1
Part I 36 11 2 287 885	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Verauslagte TÜV GEBÜHREN INTERN	Local	1 FRU
Flat rate unit I 99 99 999		

—	12/06/2016	Repair	18171 km	37100 May & Olde GmbH , Kaltenkirchen	Job
---	------------	--------	----------	---------------------------------------	-----

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Premium Selection Check
Flat rate unit I 51 99 003

Local

12 FRU

—	12/05/2016	Key	18109 km	37100	Key 0
---	------------	-----	----------	-------	-------

								
8000	0	8000	0	41000	0	34000	33000	0
11/2017		360			11/2018		11/2019	02/2019